


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1607D
 Ref. No : BUS/11/17/7007
 Reg. Date : 08/11/2017
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Mohd Azrin Bin Othman
 Type of Accident : OTHERS
 Date / Time of Accident : 05/11/2017 10:55:00 AM
 Accident Reported Date / Time : 06/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC,if any :
 smb1607d - right rear portion
 skx4434z (tp) - insured with China Taiping
 Prepared Date : 08/11/2017 05:21:29 PM



Sebastian
 17/4/18
 - Lump Sum Repair
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 1,200.00	0.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
TOTAL	: 2,260.00	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 22/11/2017 12:16:38 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 22/11/2017 12:16:38 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
 Quotation Date : Invoice Date :
 Invoice Amount : Prepared Date :

The Repair of the following:
 • To remove paint after spray painting
 • To spray paint the damaged area
 • To apply the primer to the damaged area
 • To apply the top coat to the damaged area
 • To apply the clear coat to the damaged area
 • To apply the wax to the damaged area
 • To apply the polish to the damaged area
 Approved by Repairer
 Signature:
 Date:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,060.00	0.00- 530
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	0.00- 892 .
Total Spray Painting & Panel Beating	1,200.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos. Attached	
TOTAL MATERIALS											
TOTAL MATERIALS(Discounted)								0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									