

ASS. REC. BY:

REF:

CS / SMO18007194 / Urbnz

Special Instruction:

Surveyor:

MURUS.

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

18042018 11:42am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 5759T

Insured:

SLD 9299H

at Workshop m/s

Auto N Cars.

Tel:

6555 2909

of

Blk 1 Kaki Bukit Ave 6 #01-04

Policy No:

Claim No:

CMTD1801659 / NSW

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17042018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

18042018 125pm

Person Contacted:

Daria

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 5759T - x

SLD 9299H - CS / SMO18003470 / Urbnz

DUA: 170218

19/4/18

Informed Grace Teo pending workshop est by email

3/5/18

Email preli revised to Grace Teo

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLC 5759Tat Workshop n/s And. N Gar

of: _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

ID/C Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC 5759T Yr Regn: 11 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: New Beitz C18 C.C. 1595Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 57959 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050 402 R21 P538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 Rear 7R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 17/4/18 D.O.I. 18/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
3/5/18	L/S # 13,000 confirmed with Berle (Rec 16,312.79, 56%)

* Note seatbelt no stock have to indent.

RECEIVED 05 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 3/5 - typistReport Format: TPLump Sum / I.B.I: (\$) 13,000/2Days Of Repair: 7Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ ~ RS. \$

Photos

Others

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18007194/Uvb		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 18-04-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 9299H	Veh. Inspected	SLE 5759T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801659/NSW	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/04/2018	Inspection Date	18/04/2018	
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.			
5a. Remarks				



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your ref: CMTD1801659/NSW

Our ref: CS/SMO18007194/Uvb

Date: 3/5/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SLE 5759T


We thank for your instruction on 18/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/4/2018 at the premises of M/s AUTO N CARS SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$29,312.79
Revised Estimate Amount	: S\$13,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 May 2018 12:26 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002841MFSH/1, SKQ 7878T
Attachments: SKQ 7878T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKQ 7878T
Date of survey: 2/5/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 13 April 2018 11:07 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002841MFSH/1

Dear Sir / Madam,

Thank you for your email.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 April, 2018 3:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002841MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 19 April 2018 2:29 PM
To: 'Teo, Grace'
Cc: 'Ngo, Sau Wei Shawn'; 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1801659/NSW - SUV(LKK)/ SLD9299H & SLE5759T ACC ON 17.04.18

Dear Grace,

Please be informed that we have inspected the vehicle SLE 5759T on 18/4/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 18 April 2018 1:26 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801659/NSW - SUV(LKK)/ SLD9299H & SLE5759T ACC ON 17.04.18

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 18 April, 2018 11:42 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Darla Balingit <darla@autoncars.com.sg>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801659/NSW - SUV(LKK)/ SLD9299H & SLE5759T ACC ON 17.04.18

Our Reference: CMTD1801659/NSW

Dear LKK AUTO/MARCUS,

Please make arrangement to conduct the survey for SLE5759T.

Please be informed that Shawn Ngo the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Darla Balingit [<mailto:darla@autoncars.com.sg>]

Sent: Wednesday, April 18, 2018 11:26 AM

To: Teo, Grace

Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin

Subject: Re: CMTD1801659/NSW - PRI/ SLD9299H & SLE5759T ACC ON 17.04.18

Dear Grace,

We would like to appoint Marcus Chua from LKK Auto Consultants to survey our client's vehicle.

Thank you!

On Tue, Apr 17, 2018 at 2:44 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1801659/NSW
Your Reference: SLE5759T

Without Prejudice

Date: 17th April 2018

Attention:

M/S AUTO N CARS SERVICES PTE LTD

Dear Darla/ Jaden,

ACCIDENT INVOLVING SLD9299H & SLE5759T ON 17.04.2018

We refer to your Notice of Accident dated 17/04/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Darla Balingit [mailto:darla@autoncars.com.sg]

Sent: Tuesday, April 17, 2018 1:43 PM

To: Claims - Motor Survey

Subject: Pre-Notification for vehicle - SLE5759T

Dear officer-in-charge,

ACCIDENT INVOLVING OUR CLIENT'S VEHICLE SLE5759T AND YOUR INSURED'S VEHICLE SLD9299H ON 17/04/2018

We refer to the above matter.

Our client's vehicle will be ready for survey
Failing which we shall proceed with the repair after the expiry of 48 hours notice.

Thank you.

--
Best Regards,
Darla Balingit
Auto N Cars Services Pte Ltd

m: +65 8499 3326
o : +65 6555 2909 Fax : 6841 7181
e: darla@autoncars.com.sg
web site : www.autoncars.com.sg
office: Auto Bay@ Kaki Bukit Avenue 6
Blk 1 #01-04
Singapore 417883

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 18 April, 2018 11:42 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Darla Balingit; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: CMTD1801659/NSW - SUV(LKK)/ SLD9299H & SLE5759T ACC ON 17.04.18

Our Reference: CMTD1801659/NSW

Dear LKK AUTO/MARCUS,

Please make arrangement to conduct the survey for SLE5759T.

Please be informed that Shawn Ngo the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Darla Balingit [mailto:darla@autoncars.com.sg]
Sent: Wednesday, April 18, 2018 11:26 AM
To: Teo, Grace
Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: Re: CMTD1801659/NSW - PRI/ SLD9299H & SLE5759T ACC ON 17.04.18

Dear Grace,

We would like to appoint Marcus Chua from LKK Auto Consultants to survey our client's vehicle.

Thank you!

On Tue, Apr 17, 2018 at 2:44 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1801659/NSW

Your Reference: SLE5759T

Without Prejudice

Date: 17th April 2018

Attention:

M/S AUTO N CARS SERVICES PTE LTD

Dear Darla/ Jaden,

ACCIDENT INVOLVING SLD9299H & SLE5759T ON 17.04.2018

We refer to your Notice of Accident dated 17/04/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Darla Balingit [mailto:darla@autoncars.com.sg]

Sent: Tuesday, April 17, 2018 1:43 PM

To: Claims - Motor Survey

Subject: Pre-Notification for vehicle - SLE5759T

Dear officer-in-charge,

ACCIDENT INVOLVING OUR CLIENT'S VEHICLE SLE5759T AND YOUR INSURED'S VEHICLE SLD9299H ON 17/04/2018

We refer to the above matter.

Our client's vehicle will be ready for survey
Failing which we shall proceed with the repair after the expiry of 48 hours notice.

Thank you.

--

Best Regards,

Darla Balingit

Auto N Cars Services Pte Ltd

m: +65 8499 3326

o : +65 6555 2909 Fax : 6841 7181

e: darla@autoncars.com.sg

web site : www.autoncars.com.sg

office: Auto Bay@ Kaki Bukit Avenue 6

Blk 1 #01-04

Singapore 417883

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5814D
Vehicle Details	
Vehicle No.:	SLE5759T
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	27491030732290
Chassis No.:	WDD2050402R218538
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,663.00
Original Registration Date:	14 Nov 2016
First Registration Date:	14 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$36,929.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2026
PARF Rebate Amount:	\$27,696.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$49,274.00
Total Rebate Amount:	\$76,970.00

The information contained herein is correct as at 19 Apr 2018

OK

MSME18051321 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 18/04/2018 12:32
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2018 12:32
Date Of Accident	17/04/2018 08:00
Exact Location Of Accident	ECP TWDS CITY (10KM) L/P150
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE5759T
Insured/Policyholder	
Name Of Registered Owner	CHOO KEAT THIN
NRIC No	S1845814D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96668985
Alternative Phone No	OFFICE-96668985

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100489555
Cover Note Number	

Driver

Name of Driver	CHOO KEAT THIN
NRIC No	S1845814D
Date Of Birth	24/10/1957
Occupation	INDOOR
Date Of Driving Pass	01/04/1977
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96668985
Fax Number	
Contact Number	OFFICE-96668985
EEmail Address	NOEMAIL

Address BLK 201E TAMPINES ST 23 #04-72
 Postcode 527201
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180418/7002.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD9299H
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver TOH ENG HOCK
 NRIC/Passport Number
 Contact Number 98507239
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD487M
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category TAXI
Name of Driver KOH HOCK LAM
NRIC/Passport Number
Contact Number 98627110
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHOO KEAT THIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE5759T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name PASSENGER
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE5759T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTO NCMRS

SKETCH PLAN

A: SLES759T
B: SLD9299H
C: SHDAB7M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(if driver is not the policyholder)
Date & Time:

18/4/18 10.53 AM
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180418/7002

1 of 5

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180418/7002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/04/2018 10:16	Vide Report No.: G/20180417/0052	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: CHOO KEAT THIN	Address: APT BLK 201E TAMPINES STREET 23 #04-72 SINGAPORE 527201
ID Type / ID No.: NRIC NO / S1845814D	Contact No.: Home/Office: Mobile: 96668985
Nationality: SINGAPORE CITIZEN	Email: chookt@autoncars.com.sg
Sex: Male Age: 60 Date of Birth: 24/10/1957	Type of Informant: Driver
Race: Chinese	Language: English Institution / School Name:
Occupation: Managing director/Chief executive officer	Driving Licence Information: Class: Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/04/2018 08:01	Type of Location: Straight Road
Location: EAST COAST PARKWAY ECP TOWARDS CITY Lamp Post Number: 150				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 90 Km/h		
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: CHAIN COLLISION	Anyone conveyed by ambulance: Yes			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD487M	TAXI			Red		1
SLD9299H	Car	MAZDA	MAZDA 3	Black		2
SLE5759T	Car	MERCEDES BENZ	C180 AVANTGARDE (R17 LED)	Grey		1

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180418/7002

2 of 5

Report No. T/20180418/7002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLE5759T	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100489555-01	14/11/2017	13/11/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KOH HOCK LAM	ID No.	NIL
Related Vehicle	SHD487M (TAXI)	Contact No.	98627110
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	N/A	ID No.	NIL
Related Vehicle	SHD487M (TAXI)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	17/04/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
Passenger			
Name	N/A	ID No.	NIL
Related Vehicle	SLD9299H (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	17/04/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180418/7002

3 of 5

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180418/7002

CONTINUATION OF REPORT

Driver			
Name	TOH ENG HOCK	ID No.	NIL
Related Vehicle	SLD9299H (Car)	Contact No.	98507239
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHOO KEAT THIN	ID No.	S1845814D
Related Vehicle	SLE5759T (Car)	Contact No.	96668985
Hospital/Clinic	SINGHEALTH POLYCLINICS - BEDOK	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	17/04/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On 17/4/2018 at about 0801hrs, I was travelling along ECP towards city (10km). The traffic flow was heavy and, at times, I managed to travel at speed of 80km per hour. Somewhere along 10 km, on the 1st lane, the vehicle in front of me braked to a full stop. I followed suit by braking and bringing my vehicle to a complete stop. After stopping for about 1 to 2 second, I heard loud screeching sound from the back and immediately felt a strong impact on the rear of my vehicle. I was momentarily thrown forward and as I was wearing the seat belt, it had restrained me from further harm of hitting my steering wheel/dashboard. Upon alighting from my car, I realised that my car was rear ended by 2 cars (SLD 9299H & SHD 487 M). I was informed by both the drivers that their passengers were injured and they have called for police and ambulance. I also informed that I was also injured and my passenger (wife) was also slightly injured. We decided not to move our vehicles and wait for the arrival of the Police.

We then got out of our car to wait for the police and ambulance to arrive. Upon the arrival of the Police and ambulances (2), a brief statement was given to the officer at scene. Two ambulances conveyed 2 passengers to hospital.

As my car was badly damaged (rear), and the "collision assist" was activated, it was immobilized and cannot be driven, I requested my car to be towed to the fringe carpark (C2) and subsequently I engaged my own towing crew to have my car towed to workshop.

On the same morning, after realising that the pain on my neck, leg, hands and back was getting excruciating painful, I decided to seek medical attention at Bedok Singhealth Polyclinics. I was given 3 days medical leave and with follow up consultations.

18/04 2018 WED 12:47 FAX

009/010

Sketch Plan #6 Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin;
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180418/7002

4 of 5

Report No. T/20180418/7002

CONTINUATION OF REPORT

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180418/7002

5 of 5

Report No. T/20180418/7002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
RASHIDAH BINTE AZMAN
Contact No.: 65476216

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
18/04/2018 10:16

Classification Of Case:



Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04/151 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 19/04/2018

Total Pages :

TO: AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 Chartis Building
Singapore 079120

Our Customer : Choo Keat Thin
Vehicle No : SLE5759T
Model : Mercedes Benz C180

Manufacture Year : 2016
Date of Accident : 17/04/2018

Total Estimate Repair Days : 10

Attn : Motor Claim Department
Fax : 68357416

Re: Repair Estimate For Third Party Claim against SLD9299H

P-14914.56 16km-2870
10%
13423.10 TOTAL-16382.1
S.N-90 20%

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear number plate	1	\$50.00	\$50.00	Ref 405.2
2	Rear bumper	1	\$1,688.20	\$1,688.20	Des
3	Rear bumper tow cover	1	\$69.50	\$69.50	rm
4	Rear bumper lower extension	1	\$298.80	\$298.80	grnd
5	Rear bumper lower chrome moulding	1	\$258.20	\$258.20	rm
6	Rear bumper centre right parking sensor	1	\$285.50	\$285.50	shut
7	Rear bumper centre left parking sensor	1	\$285.50	\$285.50	shut
8	Rear bumper RH side bracket	1	\$110.20	\$110.20	one
9	Rear bumper LH side bracket	1	\$110.20	\$110.20	one
10	Rear bumper clips	10	\$6.00	\$60.00	rm
11	Rear bumper rivet	10	\$8.00	\$80.00	rm
12	Rear bumper RH lower cover	1	\$98.50	\$98.50	11 X
13	Rear bumper LH lower cover	1	\$98.50	\$98.50	11 X
14	Rear bumper RH lower bracket	1	\$45.50	\$45.50	rm
15	Rear bumper LH lower bracket	1	\$45.50	\$45.50	rm
16	Rear bumper parking sensor wire harness	1	\$125.50	\$125.50	rm
17	Rear bumper centre lower bracket	1	\$95.20	\$95.20	rm
18	Rear bumper centre lower cover	1	\$112.10	\$112.10	11 X
19	Rear bumper lower sensor module bracket	1	\$58.10	\$58.10	11 X
20	Rear bumper lower sensor module	1	\$398.50	\$398.50	11 X
21	Rear switch module wire harness	1	\$238.50	\$238.50	11 X
22	Rear bumper retainer RH	1	\$38.20	\$38.20	rm
23	Rear bumper retainer LH	1	\$38.20	\$38.20	rm
24	Rear bumper reinforcement	1	\$75.50	\$75.50	rm
25	Rear end panel assembly	1	\$1,330.10	\$1,330.10	rm
26	Rear end panel inner top garnish	1	\$235.20	\$235.20	rm
27	RH rear fender assembly	1	\$2,450.10	\$2,450.10	rm
28	RH rear fender top garnish	1	\$197.20	\$197.20	11 X
29	LH rear fender top garnish	1	\$197.20	\$197.20	11 X
30	RH & LH rear fender top garnish clips	8	\$6.00	\$48.00	11 X
31	Rear boot lid assembly	1	\$2,365.10	\$2,365.10	rm
32	Rear boot hinge RH	1	\$298.20	\$298.20	rm
33	Rear boot hinge LH	1	\$298.20	\$298.20	rm
34	Rear boot weatherstrip	1	\$295.10	\$295.10	rm
35	Rear boot lock assembly	1	\$290.10	\$290.10	rm
36	Rear boot inner handle cover	1	\$72.10	\$72.10	11 X
37	Rear boot trim	1	\$310.50	\$310.50	11 X
38	Rear boot trim clips	8	\$8.00	\$64.00	11 X
39	Rear boot C180 emblem	1	\$78.10	\$78.10	rm
40	Rear boot cycle and carriage badge	1	\$72.10	\$72.10	rm
41	Rear boot logo	1	\$80.50	\$80.50	rm
42	Rear boot outer chrome moulding	1	\$298.20	\$298.20	rm
43	RH taillamp assembly	1	\$785.90	\$785.90	one

Not Allowed
date
taken photo before repair
7 day.
19/4/18
2/5 @ 13.000



Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

44	LH taillamp assembly	1	\$785.90	\$785.90	One ✓
45	Rear windscreen with weatherstrip assembly	1	\$1,598.20	\$1,598.20	1 x
46	RH taillamp panel	1	\$298.90	\$298.90	1 x
47	LH taillamp panel	1	\$298.90	\$298.90	1 x
48	Rear windscreen inner side trim RH	1	\$198.50	\$198.50	1 x
49	Rear windscreen inner side trim LH	1	\$198.50	\$198.50	1 x
50	RH front safety belt	1	\$890.10	\$890.10	1 x
51	LH front safety belt	1	\$890.10	\$890.10	1 x
52	RH front safety belt tensioner	1	\$230.10	\$230.10	1 x
53	LH front safety belt tensioner	1	\$230.10	\$230.10	1 x
54	RH rear safety belt	1	\$890.10	\$890.10	1 x
55	LH rear safety belt	1	\$890.10	\$890.10	1 x
56	RH rear cushion seat	1	\$720.10	\$720.10	1 x
57	LH rear cushion seat	1	\$720.10	\$720.10	1 x
58	Rear boot camera	1	\$1,878.20	\$1,878.20	1 x
59	battery terminal fuse	1	\$80.10	\$80.10	1 x
60	Rear bumper RH lower inner bracket	1	\$39.50	\$39.50	1 x
61	Rear bumper LH lower inner bracket	1	\$39.50	\$39.50	1 x
62	Rear end panel inner garnish clips	8	\$8.00	\$64.00	1 x
63	RH rear fender inner side trim	1	\$295.10	\$295.10	1 x
64	LH rear fender inner side trim	1	\$295.10	\$295.10	1 x
65	Rear boot power closing system	1	\$92.10	\$92.10	1 x
			Sub Total	\$26,153.10	
			Less 10%	\$2,615.31	
			Sub Total 1	\$23,537.79	
B. Spare Parts (\$/Nett)					
1	Rear windscreen inner seal	1	\$50.00	\$50.00	1 x
2	Rear windscreen sealant	2	\$25.00	\$50.00	1 x
3	Body sealant	3	\$25.00	\$75.00	1 x
			Sub Total 2	\$175.00	
			Total Spare Parts	\$23,712.79	
C. Labour					
1	To knock and straighten the affected areas. Cut and weld damaged panel. Adjust and realign the same		\$1,800.00		1200
2	To putty and spray RH rear fender, LH rear fender, boot assembly, rear end panel, rear bumper, rear boot and boot carpet		\$1,500.00		1100
3	To jack and straighten rear chassis		\$350.00		1 x
4	To remove and refit petrol tank pipes, hoses to facilitate body work repair. Final checking and testing		\$200.00		80
5	To remove and renew rear windscreen glass		\$120.00		1 x
6	To transfer rear boot fitting and fixture. Conduct water seepage test		\$200.00		80
7	To remove and refit rear seat, back seat, trimming, garnish, roof lining and speaker shelfboard to enable body work repair		\$380.00		100
8	To remove and renew RH rear, RH front, LH rear, LH front safety belt, RH front and LH front safety belt tensioner		\$350.00		100
9	To rust proof the affected areas		\$100.00		80
10	To check all lighting and wiring		\$150.00		30
11	To diagnose and troubleshoot, check engine, warning light on, to configure, clear and reset service light and to set default setting		\$450.00		100
			Total Labour	\$5,600.00	2870
			(* The above quoted are exclusive of GST.)	Total Repair Cost	\$29,312.79

14914.56
13423.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18007194/Uvbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 10-05-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 9299H	Veh. Inspected	SLE 5759T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801659/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	18/04/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050402R218538	Colour	GREY
Odometer	57959	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/04/2018	Inspection Date	18/04/2018
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5759T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	1,688.20	1,676.05
1	REAR BUMPER TOW COVER	TWISTED	69.50	69.50
1	REAR BUMPER LOWER EXTENSION	GRAZED	298.80	298.80
1	REAR BUMPER LOWER CHROME MOULDING	NECESSARY	258.20	258.20
1	REAR BUMPER CENTRE RIGHT PARKING SENSOR	SHORTED	285.50	258.00
1	REAR BUMPER CENTRE LEFT PARKING SENSOR	SHORTED	285.50	258.00
1	REAR BUMPER RH SIDE BRACKET	CRACKED	110.20	110.20
1	REAR BUMPER LH SIDE BRACKET	CRACKED	110.20	110.20
10	REAR BUMPER CLIPS @\$6.00 }	NECESSARY	60.00	60.00
10	REAR BUMPER RIVET @\$8.00 }		80.00	-
1	REAR BUMPER RH LOWER COVER	NOT NECESSARY	98.50	-
1	REAR BUMPER LH LOWER COVER	NOT NECESSARY	98.50	-
1	REAR BUMPER RH LOWER BRACKET	BENT	45.50	45.50
1	REAR BUMPER LH LOWER BRACKET	BENT	45.50	45.50
1	REAR BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	125.50	-
1	REAR BUMPER CENTRE LOWER BRACKET	DISTORTED	95.20	95.20
1	REAR BUMPER CENTRE LOWER COVER	NOT NECESSARY	112.10	-
1	REAR BUMPER LOWER SENSOR MODULE BRACKET	NOT NECESSARY	58.10	-
1	REAR BUMPER LOWER SENSOR MODULE	NOT NECESSARY	398.50	-
1	REAR SWITCH MODULE WIRE HARNESS	NOT NECESSARY	238.50	-
1	REAR BUMPER RETAINER RH	BENT	38.20	38.20
1	REAR BUMPER RETAINER LH	BENT	38.20	38.20
1	REAR BUMPER REINFORCEMENT	BENT	75.50	75.50
1	REAR END PANEL ASSEMBLY	DENTED	1,330.10	1,330.10
1	REAR END PANEL INNER TOP GARNISH	TWISTED	235.20	235.20
1	RH REAR FENDER ASSEMBLY	TO REPAIR SEE LABOUR	2,450.10	-
1	RH REAR FENDER TOP GARNISH	NOT NECESSARY	197.20	-
1	LH REAR FENDER TOP GARNISH	NOT NECESSARY	197.20	-
8	RH & LH REAR FENDER TOP GARNISH CLIPS @\$6.00	NOT NECESSARY	48.00	-
1	REAR BOOT LID ASSEMBLY	DENTED / BUCKLED	2,365.10	2,049.31
1	REAR BOOT HINGE RH	TO REPAIR SEE LABOUR	298.20	-

Report Ref No. CS/SMO18007194/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT HINGE LH	TO REPAIR SEE LABOUR	298.20	-
1	REAR BOOT WEATHERSTRIP	TWISTED	295.10	295.10
1	REAR BOOT LOCK ASSEMBLY	TWISTED	290.10	290.10
1	REAR BOOT INNER HANDLE COVER	NOT NECESSARY	72.10	-
1	REAR BOOT TRIM	NOT NECESSARY	310.50	-
8	REAR BOOT TRIM CLIPS @\$8.00	NOT NECESSARY	64.00	-
1	REAR BOOT C180 EMBLEM	NECESSARY	78.10	78.10
1	REAR BOOT CYCLE AND CARRIAGE BADGE	NECESSARY	72.10	72.10
1	REAR BOOT LOGO	NECESSARY	80.50	80.50
1	REAR BOOT OUTER CHROME MOULDING	NECESSARY	298.20	298.20
1	RH TAILLAMP ASSEMBLY	CRACKED	785.90	785.90
1	LH TAILLAMP ASSEMBLY	CRACKED	785.90	785.90
1	REAR WINDSCREEN WITH WEATHERSTRIP ASSEMBLY	NOT NECESSARY	1,598.20	-
1	RH TAILLAMP PANEL	TO REPAIR SEE LABOUR	298.90	-
1	LH TAILLAMP PANEL	TO REPAIR SEE LABOUR	298.90	-
1	REAR WINDSCREEN INNER SIDE TRIM RH	NOT NECESSARY	198.50	-
1	REAR WINDSCREEN INNER SIDE TRIM LH	NOT NECESSARY	198.50	-
1	RH FRONT SAFETY BELT	ACTIVATED	890.10	890.10
1	LH FRONT SAFETY BELT	ACTIVATED	890.10	890.10
1	RH FRONT SAFETY BELT TENSIONER	NOT NECESSARY	230.10	-
1	LH FRONT SAFETY BELT TENSIONER	NOT NECESSARY	230.10	-
1	RH REAR SAFETY BELT	ACTIVATED	890.10	890.10
1	LH REAR SAFETY BELT	ACTIVATED	890.10	890.10
1	RH REAR CUSHION SEAT	NOT NECESSARY	720.10	-
1	LH REAR CUSHION SEAT	NOT NECESSARY	720.10	-
1	REAR BOOT CAMERA	SHORTED	1,878.20	1,536.50
1	BATTERY TERMINAL FUSE	ACTIVATED	80.10	80.10
1	REAR BUMPER RH LOWER INNER BRACKET	NOT NECESSARY	39.50	-
1	REAR BUMPER LH LOWER INNER BRACKET	NOT NECESSARY	39.50	-
8	REAR END PANEL INNER GARNISH CLIPS @\$8.00	NOT NECESSARY	64.00	-
1	RH REAR FENDER INNER SIDE TRIM	NOT NECESSARY	295.10	-
1	LH REAR FENDER INNER SIDE TRIM	NOT NECESSARY	295.10	-
1	REAR BOOT POWER CLOSING SYSTEM	NOT NECESSARY	92.10	-

Report Ref No. CS/SMO18007194/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2,610.31	-1,491.46
			23,492.79	13,423.10
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
	LESS 10% DISCOUNT		-5.00	-
			45.00	40.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	50.00	-
2	REAR WINDSCREEN SEALANT @\$25.00 (SN)	NOT NECESSARY	50.00	-
3	BODY SEALANT @\$25.00 (SN)	NECESSARY	75.00	50.00
			175.00	50.00
	<u>LABOUR</u>			
	TO KNOCK AND STRAIGHTEN THE AFFECTED AREAS.CUT AND WELD DAMAGED PANEL.ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF RH REAR FENDER ASSEMBLY,REAR BOOT HINGE RH,REAR BOOT HINGE LH,RH TAILLAMP PANEL AND LH TAILLAMP PANEL.		1,800.00	1,200.00
	TO PUTTY AND SPRAY RH REAR FENDER,LH REAR FENDER,BOOT ASSEMBLY,REAR END PANEL,REAR BUMPER,REAR BOOT AND BOOT CARPET.		1,500.00	1,100.00
	TO JACK AND STRAIGHTEN REAR CHASSIS.	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIT PETROL TANK PIPES,HOSES TO FACILITATE BODY WORK REPAIR.FINAL CHECKING AND TESTING.		200.00	80.00
	TO REMOVE AND RENEW REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR BOOT FITTING AND FIXTURE.CONDUCT WATER SEEPAGE TEST.		200.00	80.00
	TO REMOVE AND REFIT REAR SEAT,BACK SEAT,TRIMMING,GARNISH,ROOF LINING AND SPEAKER SHELBORD TO ENABLE BODY WORK REPAIR.		380.00	100.00
	TO REMOVE AND RENEW RH REAR,RH FRONT,LH REAR,LH FRONT SAFETY BELT,RH FRONT AND LH FRONT SAFETY BELT TENSIONER.		350.00	100.00
	TO RUST PROOF THE AFFECTED AREAS.		100.00	80.00
	TO CHECK ALL LIGHTING AND WIRING.		150.00	30.00

Report Ref No. CS/SMO18007194/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSE AND TROUBLESHOOT, CHECK ENGINE, WARNING LIGHT ON, TO CONFIGURE, CLEAR AND RESET SERVICE LIGHT AND TO SET DEFAULT SETTING.		450.00	100.00
			5,600.00	2,870.00
GRAND TOTAL			29,312.79	16,383.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/SMO18007194/Uvbn2

NOTE: SEATBELT NO STOCK HAVE TO INDENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.