

ASSIGNMENT

Subject:

Kenneth

DOI:

18/4/18

Date / Time:

18/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 8683R

Name of Insured:

LOH KIM Yoon

Insured Tel No.:

HP:

91694311

Excess Sec II :S\$

D.O.A.:

18/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

DMR2009997/ST

Policy No.:

CMPPTA.18-00558

Make / Model:

7-MCH

Place of Accident:

Amk Ave 6

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFS 1888C

SJH 8683R

SGE 8953M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

25/6
VC

SGE 8953M - X

SJH 8683R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 18/3/19 CELINA

After call ltr to OI: 20/3/19 CELINA VC-OK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

17/4

Sent By:

An

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

30/7/19

Confirm with:

June

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost:

S\$ 4939.55

(B VEH. O.C., OI 2ND CASE)

Loss of Rental (LOR):

S\$ 608.00

(

6 days) X 100.00

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 5547.55

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5547.55

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 1/8/19

18/4/18

ASS. REC. BY:

REF:

2Q1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGE 8953M Yr Regn: 03, 16

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Accord c.c. 1496

Colour:

M. Brown A/C: Insured / Std / NI / NA

Sp. Reading

45586 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUI 1110773

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inop / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inop / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16

R:

BS / ☒ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

d mm

R/Bal.

d mm

L/Bal.

d mm

L/Bal.

d mm

D.O.A.

14/4/18

D.O.I.

17/4/18

Survey held at

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/4 Rk pass to Carharm

30/1/19

Confirm 2.B.2 \$4616.40 with 6 working days

(Net \$437.60
9%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGE8953M
7P/6Q

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

Not Authorized

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

*1. B.1
Assured B4 pain*

6 days

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD
Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	230.00 ✓	1 PC	230.00	✓
2 REAR BUMPER LH SIDE PAD	80.00 ✓	1 PC	80.00	✓
3 REAR BUMPER LH SIDE RETAINER	10.00 ✓	1 PC	10.00	✓
4 REAR BUMPER REFLECTORS	38.00 ✓	2 PCS	76.00	248.38 ✓
5 REAR BUMPER CLIPS	2.00 ✓	6 PCS	12.00	✓
6 REAR LH FENDER WHEEL ARP GARNISH	60.00 ✓	1 PC	60.00	✓
7 REAR TAILGATE	610.00 ✓	1 PC	610.00	✓
8 TAILGATE INNER LOCK	78.00 ✓	1 PC	78.00	✓
9 TAILGATE INNER RUBBER	55.00 ✓	1 PC	55.00	✓
10 TAILGATE LH SHOCK ABSORBER	90.00 ✓	1 PC	90.00	✓
11 TAILGATE EMBLEM 'VEZEL'	28.00 ✓	1 PC	28.00	✓
12 REAR WINDSCREEN GLASS MOULDING	68.00 ✓	1 PC	68.00	✓
13 REAR CENTRE PANEL	310.00 ✓	1 PC	310.00	✓
14 REAR CENTRE PANEL INNER TOP GARNISH	40.00 ✓	1 PC	40.00	✓
15 REAR TOOL BOX	120.00 ✓	1 PC	120.00	✓
16 REAR TOOL BOX TOP COVER	160.00 ✗	1 PC	160.00	✗
17 REAR COMPARTMENT UNDER COVER	90.00 ✓	1 PC	90.00	✓
18 REAR COMPARTMENT UNDER COVER CLIPS	2.00 ✓	4 PCS	8.00	✓
19 REAR EXHAUST PIPE	320.00 ✓	1 PC	320.00	✓
			2247	2445.00
			Add 20%	489.00
				2934.00
				2696.40
Special Net				
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
21 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
				240.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGE8953M

7/1/20

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD
Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
23 PANEL BEATING ON REAR PORTION	800.00	1 LA	800.00	7700 ✓
24 PUTTY & RESPRAY ON REAR AFFECTED AREAS	800.00	1 LA	800.00	700 ✓
25 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
26 RUSTPROOFING	60.00	1 LA	60.00	✓
27 REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	60.00	1 PC	60.00	✓
				1680
				1,880.00

Total S\$ 5,054.00

Add GST @ 7% 353.78

Total Amount payable S\$ 5,407.78

#2247
Add 20% 449.40
240 snl
Labour 1680
4616.40 ✓ ok

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGE8953M
7/1/20

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

Not Authorised
1.B.1
Presurvey B4 pain
6 days

Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 REAR BUMPER	230.00	1 PC	230.00	✓
2 REAR BUMPER LH SIDE PAD	80.00	1 PC	80.00	✓
3 REAR BUMPER LH SIDE RETAINER	10.00	1 PC	10.00	✓
4 REAR BUMPER REFLECTORS	38.00	2 PCS	76.00	2+
5 REAR BUMPER CLIPS	2.00	6 PCS	12.00	✓
6 REAR LH FENDER WHEEL ARP GARNISH	60.00	1 PC	60.00	✓
7 REAR TAILGATE	610.00	1 PC	610.00	✓
8 TAILGATE INNER LOCK	78.00	1 PC	78.00	✓
9 TAILGATE INNER RUBBER	55.00	1 PC	55.00	✓
10 TAILGATE LH SHOCK ABSORBER	90.00	1 PC	90.00	✓
11 TAILGATE EMBLEM 'VEZEL'	28.00	1 PC	28.00	✓
12 REAR WINDSCREEN GLASS MOULDING	68.00	1 PC	68.00	✓
13 REAR CENTRE PANEL	310.00	1 PC	310.00	✓
14 REAR CENTRE PANEL INNER TOP GARNISH	40.00	1 PC	40.00	✓
15 REAR TOOL BOX	120.00	1 PC	120.00	?
16 REAR TOOL BOX TOP COVER	160.00	1 PC	160.00	?
17 REAR COMPARTMENT UNDER COVER	90.00	1 PC	90.00	?
18 REAR COMPARTMENT UNDER COVER CLIPS	2.00	4 PCS	8.00	?
19 REAR EXHAUST PIPE	320.00	1 PC	320.00	✓
			2,445.00	
	Add 20%		489.00	2,934.00
Special Net				
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
21 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓

240.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD
Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
23 PANEL BEATING ON REAR PORTION	800.00	1 LA	800.00	?
24 PUTTY & RESPRAY ON REAR AFFECTED AREAS	800.00	1 LA	800.00	700/
25 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
26 RUSTPROOFING	60.00	1 LA	60.00	?
27 REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	60.00	1 PC	60.00	✓
				1,880.00

Total	SS 5,054.00
Add GST @ 7%	353.78
Total Amount payable	SS 5,407.78

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

SGE 8953M
TP/ER**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1364B
Vehicle Details	
Vehicle No.:	SGE8953M
Vehicle to be Exported:	No
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	L15B4030776
Chassis No.:	RU11110773
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,049.00
Original Registration Date:	15 Mar 2016
First Registration Date:	15 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$10,069.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2026
PARF Rebate Amount:	\$7,551.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$35,581.00
Total Rebate Amount:	\$43,132.00

The information contained herein is correct as at 16 Apr 2018

OK

Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 22 June, 2018 12:24 PM
To: Mei Kwan (LKKAuto)
Cc: Admin A
Subject: FW: Direct Settlement - Accident Involving SJH8683R (OI : EQI -DM18HO00997/JT) AND SGE8953M (TP : LKK REF - CC6/EQI18007196/Kha3) on 14/04/2018
Attachments: TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf; Preliminary Advice.pdf; SJH8683R.PDF

Categories: HMK

Dear Mei Kwan

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, April 19, 2018 10:36 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SJH8683R (OI : EQI - TBA) AND SGE8953M (TP : LKK REF - CC6/EQI18007196/Kha3) on 14/04/2018


WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SGE 8953M at M/s Cheng Hoe Motor Pte Ltd (Yishun).



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 22 FEB 2019

EQ Insurance Co Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SGE8953M & SJH8683R ON 14/04/2018
AMK AVE 6.**

We are authorized by SGE8953M for their above matter.

Record reveals that you are the insurer of SJH8683R. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 4939.55
2. Loss of Use	S\$ 0.00
3. Hire of Vehicle	S\$ 600.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 5547.55

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Our Ref: CC6/EQ118007196/Kha3

20 March 2019

KOH KIAN YOONG

589 Woodlands Dr 16

#10-26

Singapore 730589

Dear Sir/Madam,

ACCIDENT INVOLVING SJH 8683R / SGE 8953M / OTHERS ON 14/04/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,



Cecilia Chong

Case Handler

DID: 6749 4274

FAX: 6741 4108

EMAIL: Ceciliachong@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

LETTER OF AUTHORISATION
(FOR PROPERTY DAMAGE CLAIM ONLY)

Re: Motor Insurance Claim SGE8953M
in respect of the traffic accident on 14/4/2018
at/along Ang Mo Kio Ave 6

I/We, Tan Cher Thong
NRIC S1761364B of Blk 714 Woodlands Drive 70 #11-174
Singapore 730714

owner of motor vehicle SCE8953M, insured by NTUC Income Insurance
Co-operative Ltd under policy no. 5078341193-02 (Classic)

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle SJH8683R in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 
Date : 16/4/18

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

NO: CL8190031
Date: 23 Jan 2019
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG 2WD

Job No: JC1599038

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

Description

To Supply all replaced parts, all necessary and agreed labour &
miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity

1 PC

List Price

SS
S\$ 4,616.40

PAGE:1

Amount

SS
S\$ 4,616.40

Total S\$ 4,616.40
Add GST @ 7% 323.15
Total Amount payable S\$ 4,939.55

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

(ROC/GST NO. 53068927L)

(9AM TO 6PM)

Joint Hirer's/ Guarantor's Signature

38 WOODLANDS IND PARK E1
#05-05, SINGAPORE 757700
TEL : 64595278

GST Reg No. : 53068927L

DATE : 21-Apr-18

PERFECT DRIVING & SERVICE



A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 068358

TEL : 6538 7411 & FAX : 8534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B038/ 2018																																																																																																																																			
YOUR REF:																																																																																																																																					
OUR REF : ACS.CH.LTA.2018 (APRIL 2018)		DATE : 7/5/18																																																																																																																																			
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusal, attendance preparation examination of documents relating thereto; correspondence, attendance, perusal, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.																																																																																																																																					
LTANET SEARCHES FOR THE MONTH APRIL 2018 <table border="1"> <thead> <tr> <th>S/NO</th> <th>DATE</th> <th>TP NO.</th> <th>CHM</th> <th>DOA</th> </tr> </thead> <tbody> <tr><td>1</td><td>2/4/2018</td><td>FY5529G</td><td>SJL9502C</td><td>28/3/2018</td></tr> <tr><td>2</td><td>2/4/2018</td><td>YN5547L</td><td>GBC2091J</td><td>2/4/2018</td></tr> <tr><td>3</td><td>2/4/2018</td><td>SGL72X</td><td>SLV6435G</td><td>30/3/2018</td></tr> <tr><td>4</td><td>3/4/2018</td><td>SKA9833T</td><td>SGM7899B</td><td>30/3/2018</td></tr> <tr><td>5</td><td>5/4/2018</td><td>YP8210C</td><td>SLL1041U</td><td>30/3/2018</td></tr> <tr><td>6</td><td>5/4/2018</td><td>SKK8178E</td><td>SKC7289R</td><td>1/4/2018</td></tr> <tr><td>7</td><td>6/4/2018</td><td>SJS6475E</td><td>GBF582G</td><td>5/4/2018</td></tr> <tr><td>8</td><td>6/4/2018</td><td>GBA5391J</td><td>SJZ6338G</td><td>5/4/2018</td></tr> <tr><td>9</td><td>6/4/2018</td><td>SLS7923Z</td><td>SLR2233U</td><td>6/4/2018</td></tr> <tr><td>10</td><td>9/4/2018</td><td>SLF 5331M</td><td>SJH 2056R</td><td>8/4/2018</td></tr> <tr><td>11</td><td>9/4/2018</td><td>SLE1657E</td><td>SJS8537Y</td><td>17/8/2017</td></tr> <tr><td>12</td><td>9/4/2018</td><td>SFS7732D</td><td>SFK6204S</td><td>4/8/2017</td></tr> <tr><td>13</td><td>9/4/2018</td><td>SDU8868A</td><td>SLQ1323E</td><td>17/10/2017</td></tr> <tr><td>14</td><td>9/4/2018</td><td>SLP7517D</td><td>SJL3853D</td><td>8/9/2017</td></tr> <tr><td>15</td><td>10/4/2018</td><td>SKQ7715E</td><td>SLG8993C</td><td>5/4/2018</td></tr> <tr><td>16</td><td>11/4/2018</td><td>SLG6098A</td><td>SCK6228C</td><td>5/10/2017</td></tr> <tr><td>17</td><td>11/4/2018</td><td>SFE919C</td><td>SJS2861A</td><td>11/4/2018</td></tr> <tr><td>18</td><td>11/4/2018</td><td>SKC6525B</td><td>PC4270E</td><td>11/4/2018</td></tr> <tr><td>19</td><td>12/4/2018</td><td>GU7019H</td><td>SKW3159E</td><td>12/4/2018</td></tr> <tr><td>20</td><td>13/4/2018</td><td>SFM96J</td><td>SJL1396U</td><td>6/11/2018</td></tr> <tr><td>21</td><td>13/4/2018</td><td>PC3888E</td><td>SFX43D</td><td>12/4/2018</td></tr> <tr><td>22</td><td>14/4/2018</td><td>FBJ278P</td><td>SKA3709J</td><td>13/4/2018</td></tr> <tr><td>23</td><td>16/4/2018</td><td>SJH8683R</td><td>SGE8953M</td><td>14/4/2018</td></tr> <tr><td>24</td><td>18/4/2018</td><td>GR1525T</td><td>SGQ1801B</td><td>9/6/2017</td></tr> <tr><td>25</td><td>18/4/2018</td><td>SJY6193L</td><td>SGY2092G</td><td>12/7/2017</td></tr> </tbody> </table>				S/NO	DATE	TP NO.	CHM	DOA	1	2/4/2018	FY5529G	SJL9502C	28/3/2018	2	2/4/2018	YN5547L	GBC2091J	2/4/2018	3	2/4/2018	SGL72X	SLV6435G	30/3/2018	4	3/4/2018	SKA9833T	SGM7899B	30/3/2018	5	5/4/2018	YP8210C	SLL1041U	30/3/2018	6	5/4/2018	SKK8178E	SKC7289R	1/4/2018	7	6/4/2018	SJS6475E	GBF582G	5/4/2018	8	6/4/2018	GBA5391J	SJZ6338G	5/4/2018	9	6/4/2018	SLS7923Z	SLR2233U	6/4/2018	10	9/4/2018	SLF 5331M	SJH 2056R	8/4/2018	11	9/4/2018	SLE1657E	SJS8537Y	17/8/2017	12	9/4/2018	SFS7732D	SFK6204S	4/8/2017	13	9/4/2018	SDU8868A	SLQ1323E	17/10/2017	14	9/4/2018	SLP7517D	SJL3853D	8/9/2017	15	10/4/2018	SKQ7715E	SLG8993C	5/4/2018	16	11/4/2018	SLG6098A	SCK6228C	5/10/2017	17	11/4/2018	SFE919C	SJS2861A	11/4/2018	18	11/4/2018	SKC6525B	PC4270E	11/4/2018	19	12/4/2018	GU7019H	SKW3159E	12/4/2018	20	13/4/2018	SFM96J	SJL1396U	6/11/2018	21	13/4/2018	PC3888E	SFX43D	12/4/2018	22	14/4/2018	FBJ278P	SKA3709J	13/4/2018	23	16/4/2018	SJH8683R	SGE8953M	14/4/2018	24	18/4/2018	GR1525T	SGQ1801B	9/6/2017	25	18/4/2018	SJY6193L	SGY2092G	12/7/2017
S/NO	DATE	TP NO.	CHM	DOA																																																																																																																																	
1	2/4/2018	FY5529G	SJL9502C	28/3/2018																																																																																																																																	
2	2/4/2018	YN5547L	GBC2091J	2/4/2018																																																																																																																																	
3	2/4/2018	SGL72X	SLV6435G	30/3/2018																																																																																																																																	
4	3/4/2018	SKA9833T	SGM7899B	30/3/2018																																																																																																																																	
5	5/4/2018	YP8210C	SLL1041U	30/3/2018																																																																																																																																	
6	5/4/2018	SKK8178E	SKC7289R	1/4/2018																																																																																																																																	
7	6/4/2018	SJS6475E	GBF582G	5/4/2018																																																																																																																																	
8	6/4/2018	GBA5391J	SJZ6338G	5/4/2018																																																																																																																																	
9	6/4/2018	SLS7923Z	SLR2233U	6/4/2018																																																																																																																																	
10	9/4/2018	SLF 5331M	SJH 2056R	8/4/2018																																																																																																																																	
11	9/4/2018	SLE1657E	SJS8537Y	17/8/2017																																																																																																																																	
12	9/4/2018	SFS7732D	SFK6204S	4/8/2017																																																																																																																																	
13	9/4/2018	SDU8868A	SLQ1323E	17/10/2017																																																																																																																																	
14	9/4/2018	SLP7517D	SJL3853D	8/9/2017																																																																																																																																	
15	10/4/2018	SKQ7715E	SLG8993C	5/4/2018																																																																																																																																	
16	11/4/2018	SLG6098A	SCK6228C	5/10/2017																																																																																																																																	
17	11/4/2018	SFE919C	SJS2861A	11/4/2018																																																																																																																																	
18	11/4/2018	SKC6525B	PC4270E	11/4/2018																																																																																																																																	
19	12/4/2018	GU7019H	SKW3159E	12/4/2018																																																																																																																																	
20	13/4/2018	SFM96J	SJL1396U	6/11/2018																																																																																																																																	
21	13/4/2018	PC3888E	SFX43D	12/4/2018																																																																																																																																	
22	14/4/2018	FBJ278P	SKA3709J	13/4/2018																																																																																																																																	
23	16/4/2018	SJH8683R	SGE8953M	14/4/2018																																																																																																																																	
24	18/4/2018	GR1525T	SGQ1801B	9/6/2017																																																																																																																																	
25	18/4/2018	SJY6193L	SGY2092G	12/7/2017																																																																																																																																	
			sub-total c/f \$ 200.00																																																																																																																																		
M/s. A.C. SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.																																																																																																																																					



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 13/08/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJH 8683R (Insd Veh)	Your Ref. No. : DM18HO00997/JT
	SGE 8953M (TP Veh)	Our Ref. No. : CC6/EQI18007196/Kwa3q2
Date of Accident	14/4/2018	

Liability	100%	
Final Repair Cost	: \$ 4,939.55	
Loss of Use	: \$	days
Rental (If any)	: \$ 600.00	6 days
Others:	: \$ 8.00	
	: \$	
	5,547.55	
Final Settlement Sum	: \$ 5,547.55	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	CHENG HOE MOTOR PTE LTD	: \$ 5,547.55
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18007196/Kwa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 13-08-2019		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 8683R	Veh. Inspected	SGE 8953M	
Policy No.	DMPPHQ18-000587	Coverage (\$)	0.00	
Claim No.	DM18HO00997/JT	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11110773	Colour	METALLIC MAROON	
Odometer	45586	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/04/2018	Inspection Date	17/04/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 8953M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (WCP)	BENT	230.00	230.00
1	REAR BUMPER LH SIDE PAD (WCP)	BUCKLED	80.00	80.00
1	REAR BUMPER LH SIDE RETAINER (WCP)	DISTORTED	10.00	10.00
2	REAR BUMPER REFLECTORS @\$38.00 (WCP)	N/S CUT	76.00	38.00
6	REAR BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	12.00	12.00
1	REAR LH FENDER WHEEL ARP GARNISH (WCP)	DISTORTED	60.00	60.00
1	REAR TAILGATE (WCP)	BENT	610.00	610.00
1	TAILGATE INNER LOCK (WCP)	DENTED	78.00	78.00
1	TAILGATE INNER RUBBER (WCP)	DISTORTED / DENTED	55.00	55.00
1	TAILGATE LH SHOCK ABSORBER (WCP)	PUNCTURE	90.00	90.00
1	TAILGATE EMBLEM 'VEZEL' (WCP)	NECESSARY	28.00	28.00
1	REAR WINDSCREEN GLASS MOULDING (WCP)	NECESSARY	68.00	68.00
1	REAR CENTRE PANEL (WCP)	BENT	310.00	310.00
1	REAR CENTRE PANEL INNER TOP GARNISH (WCP)	DENTED	40.00	40.00
1	REAR TOOL BOX (WCP)	CRACKED	120.00	120.00
1	REAR TOOL BOX TOP COVER (WCP)	SERVICEABLE	160.00	-
1	REAR COMPARTMENT UNDER COVER (WCP)	BUCKLED	90.00	90.00
4	REAR COMPARTMENT UNDER COVER CLIPS @\$2.00 (WCP)	NECESSARY	8.00	8.00
1	REAR EXHAUST PIPE (WCP)	BENT	320.00	320.00
	COST PLUS 20%		489.00	449.40
			2,934.00	2,696.40
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
			240.00	240.00
<u>LABOUR</u>				
	REMOVE AND REFIX REAR WINDSCREE GLASS.		100.00	100.00
	PANEL BEATING ON REAR PORTION.		800.00	700.00
	PUTTY & RESPRAY ON REAR AFFECTED AREAS.		800.00	700.00

Report Ref No. CC6/EQI18007196/Kwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM.		60.00	60.00
	RUSTPROOFING.		60.00	60.00
	REMOVE & REFIX REVERSE CAMERA ,RESET SYSTEM.		60.00	60.00
			1,880.00	1,680.00
GRAND TOTAL			5,054.00	4,616.40
RECOMMENDED COST OF REPAIRS				4,616.40

Report Ref.No. CC6/EQ118007196/Kwa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Thursday, 15 August 2019 2:09 PM
To: 'janet.tan@eqinsurance.com.sg'
Cc: 'vivianlau@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving SJH 8683R (OI) and SGE 8953M (TP) on 14/04/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933