

KIM CHWEE AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorized
N/A
P/P \$3733.30
3 day.

VEHICLE NO: SLL 251L

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE	11 \$1,400.30 X
1 PCS	TAILGATE REAR LOGO	11 \$68.10 X
1 PCS	TAILGATE HARRIER EMBLEM	11 \$68.10 X
1 PCS	TAILGATE WEATHERSTRIP 322.10	11 \$429.10 /
1 PCS	REAR BUMPER 1381.10	m/pe \$1,533.10 /
1 PCS	REAR BUMPER LOWER SKIRTING 589.10	myth \$866.30 /
1 PCS	REAR BUMPER REFLECTOR	11 \$66.80 X
1 PCS	REAR BUMPER SPONGE	11 \$295.40 /
2 PCS	REAR BUMPER SIDE REATINERS @\$85.10	11 \$170.20 /
1 SET	REAR BUMPER CLIPS	11 \$60.00 /
1 PCS	REAR END PANEL	11 \$820.10 X
1 PCS	REAR END PANELTOP GARNISH	11 \$366.50 /
2 PCS	TAILLAMPS @\$850.10	11 \$1,700.20 X
1 set	REAR REVERSE SENSOR	11 \$260.00 /
		3444.4
		2883.30
LABOUR CHARGES:		
TO CHECK WIRING		\$80.00 20
TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00 50
TO DISMENTLE & REFIX SEAT,CUSHIONUPHOLSTREY		\$120.00 60
TO SPRAY RUST PROOFING		11 \$100.00 X
TO DISMENTLE & REFIX REAR WINDSCREEN		11 \$150.00 X
LABOUR FOR PANELBEATING & REPLACING PARTS		\$980.00 520
TO PUTTY & SPRAY PAINTING		\$1,200.00 500
TOTAL		\$10,814.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: