

INS. CASE OWNER:

CC 4/ASM1800

7703, Kpa3

LKK:

IDAC:

40342

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

28(3ce01200)

If NO or B 28, Ass. Lia. U6

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Lim Yew Bo Spray Paint Co

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: ASM(AXA)

ASSIGNMENT

From: Date: 18042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 9594m

at Workshop m/s: Lim Yew BOO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 71k

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKS 9594m Yr Regn: 05 / 15

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota A175

c.c. 1598

Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 51342

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR033REH104523422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 5 mm

L/Bal. 4 mm

L/Bal. 5 mm

D.O.A. 14/4/18

D.O.I. 18/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/4 15h pass to Cathrine

① 14105.34

US \$ 735w CR. 10/12.18 437

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Not Authorized
1/31
Repair Bk paint
10 days

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BONNET		
2.	1	FRONT BONNET SEAL (CENTRE)		
3.	1	FRONT SUPPORT PANEL		
4.	1	FRONT BRACE PANEL		
5.	1	FRONT RADIATOR MOUNTING		
6.	1	FRONT RADIATOR ASSY		
7.	1	FRONT AIR-CON CONDENSER		
8.	1	FRONT GRILLE (CHROME)		
9.	1	FRONT EMBLEM		
10.	1	FRONT NO PLATE (EMBOSS) + HOLDER		
11.	1	FRONT BUMPER		
12.	1	FRONT BUMPER SPONGE		
13.	1	FRONT BUMPER LOWER GRILLE/CENTRE		
14.	1	FRONT BUMPER REINFORCEMENT		
15.	2	FRONT BUMPER RETAINER		
16.	2	FRONT BUMPER CLIPS		
17.	2	FRONT HEADLAMP		
18.	2	FRONT HEADLAMP TOP CHROME		
19.	1	REAR LID		
20.	1	REAR LID HINGES		
21.	1	REAR LID OUTER HANDLE		
22.	1	REAR LID LOCK		
23.	1	REAR LID RUBBER		
24.	1	REAR EMBLEM 'COROLLA'		

o/s mgmt

o/s mgmt

<i>B</i>	1,028.10	✓
<i>Sm</i>	84.70	x
<i>R</i>	1,074.10	x
<i>R</i>	155.00	x
<i>Sm</i>	33.40	x
<i>Sm</i>	1,764.90	x
<i>Sm</i>	1,291.11	x
<i>CM</i>	564.00	✓
<i>Me</i>	54.54	✓
<i>Me</i>	45.00	✓
<i>Bul</i>	627.54	✓
<i>Sm</i>	178.00	x
<i>Me</i>	247.30	✓
<i>R</i>	408.85	x
<i>Dis</i>	82.00	✓
<i>Me</i>	5.00	✓
<i>Me</i>	10.00	✓
<i>Me</i>	2,410.30	✓
<i>Me</i>	240.50	✓
<i>Me</i>	4,820.60	✓
<i>Me</i>	481.00	✓
<i>Me</i>	754.70	✓
<i>Me</i>	157.10	x
<i>Sm</i>	231.30	x
<i>R</i>	379.20	x
<i>Dis</i>	266.40	✓
<i>Me</i>	57.33	✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

25.	1	REAR EMBLEM 'ALTIS'		50.80
26.	2	REAR EMBLEM 'TOYOTA' IN LOGO FONT	67.80	135.60
27.	2	REAR REFLECTORS	401.10	802.20
28.	2	REAR TAILLAMP	486.60	973.20
29.	1	REAR BUMPER		639.90
30.	2	REAR BUMPER RETAINER	105.90	211.80
31.	2	REAR BUMPER BRACKET	104.60	209.20
32.	1	REAR BUMPER BEAM		389.00
33.	1	REAR TAILEND PANEL		581.20
34.	1	REAR TAILEND TOP GARNISH		271.40
35.	1	REAR SPARE TYRE FLOOR PANEL		702.93
36.	1	REAR SILENCER		645.20

List TotalS\$:

25.00% Discount S\$:

20,490.60

5,122.65

15,367.95

SPECIAL NETT ITEMS :

1.	1	REAR NO PLATE (EMBOSS) + HOLDER
2.	2	REAR TAILEND PANEL TEROSTAT SEALANT
3.	2	REAR TAILEND TOP GARNISH CLIPS
4.	2	REAR SPARE TYRE PANEL SEALANT
5.	1	REAR SPARE TYRE PANEL INSULATOR PADDING
6.	1	REAR SPARE TYRE BOARD (CARPET)
7.	1	REAR REVERSE CAMERA

	54.20		55.00
	5.00		108.40
	120.00		10.00
			240.00
			200.00
			248.83
			300.00

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
8.	1	REAR REVERSE SENSOR	<i>Net</i>	<i>200.00</i> 220.00
		Special Nett Total S\$:		1,382.23
		LABOUR :		
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED FRT PANELS		120.00 <i>300</i>
		TO CHECK FRONT WIRING FUNTION		50.00 <i>200</i>
		TO FOCUS HEADLAMP		60.00 <i>200</i>
		LABOUR TO REPLACE FRT AIR CON CONDENSER PARTS AND VACUM & TOP UP GAS	<i>nm</i>	180.00 <i>X</i>
		TO REPAIR, PANEL BEAT ON FRT AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS		900.00 <i>500</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT ENFORCEMENT, FRT SUPPORT PANEL, BRACE PANEL & TOUCH UP ON FRT AFFECTED FENDER USING 2K PAINT		1,600.00 <i>800</i>
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB		350.00 <i>2500</i>
		TO APPLY RUST-PROOFING ON REPAIRED/REPLACED REAR PANELS		120.00 <i>600</i>
		TO CHECK REAR WIRING FUNCTION		50.00 <i>200</i>

CONTINUE / ...

LIM YEOW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPLACE EXHAUST SILENCER		120.00 <i>601</i>
		TO CHECK WATER LEAKAGE		80.00 <i>20</i>
		TO REPAIR, PANEL BEAT ON LEFT REAR AFFECTED FENDER, CUT & WELD ON REPLACED REAR PANEL, SPARE TYRE HOUSING & LABOUR TO REPLACE THE ABOVE PARTS		1,500.00 <i>900</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR PANEL, REAR SPARE TYRE PANEL, REAR BEAM, REAR BUMPER, REAR AFFECTED FENDER, REAR REVERSE SENSOR USING 2K PAINT		1,800.00 <i>1000</i>
		Labour Total S\$:		6,930.00

E. & O.E.

Total S\$: 23,680.18

=====



for LIM YEOW BOO SPRAY PAINT CO.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00E85
Our ref: CC4/ASM18007203/Kpa3

Date: 20.04.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKS 9594M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.04.2018 at the premises of M/s Lim Yew Boo Spray Paint Co - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	23,680.18
Revised Estimate Amount	: S\$	9,092.25
"Check" Items Amount	: S\$	4,704.12
Total (Including Check Items)	: S\$	13,796.37
Market Value	: S\$	71,000.00 (est.)
LTA Reimbursement Value	: S\$	57,134.00 (est.)
Nett Value	: S\$	13,866.00 (est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Yours faithfully,


KENNETH KONG
Licensed Appraiser

Service Request Details

Claim

S8M00E85

Reference

None 

Loss Date

April 14, 2018

Request Date

April 17, 2018

Due Date

April 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17/04/2018 @ 237pm
Serene veh not in, estimate not done
arrange 18/04/2018

Lim Yew Boo

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SKS9594M

Make

TPVD TOYOTA

Service Address

...

Primary Contact/Insured

PARDI MOHAMED NAINI BIN

BLK 539 WOODLANDS DRIVE 16, #06-117, 730539, Singapore

63447667

BELINDACHAN78@HOTMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<SEEK MANDATE> - S8M00E85 [ACCIDENT INVOLVING SJK 1086U(OI)/ SKS 9594M(TP)/ OTHERS ON 14/04/2018]

Type

Question

Message

Liability: 3 vehicle c.c. OI was 2nd car. We are of the view that BOLA S28 is apply as Malaysia veh was the last car. Spoken to insured, agreed to settle and aware NCD(if any) is affected. We seek your approval to offer Third Party repairer "LIM YEW BOO SPRAY PAINT CO" is as follows: - 1)COR: \$13,796.37 + 2) Loss of Rental(14daysx\$100.00): \$1,400.00 + 3)LTA Search fee: \$7.49 =Total: \$15,203.86. **10days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. Hsiao Tong - 28 June 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28.06.2018

Survey Details:

Date of loss	14.04.2018
Date of appointment	17.04.2018
Date of survey	18.04.2018
Location of survey	LIM YEW BOO SPRAY PAINT CO

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS 9594M
Make and Model	TOYOTA ALTIS (1598CC)
Date of registration	18.05.2015
Excess	
Market Value	\$ 71,000.00
Part Rebate	\$ 57,134.00
Nett Loss	\$ 13,866.00

Repair details:

Initial Estimate	\$ 23,680.18
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,682.25
Check items (estimate)	\$ 4,704.12
Labour	\$ 3,410.00
Total	\$ 13,796.37
Lump Sum(if applicable)	

Number of days for repair	<u>10</u>
---------------------------	-----------



Axiata
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564311

Date: 28.06.2018

Remarks:

Hi KC, No video footage from third party. Third party had submitted accident scene photos. We have uploaded TP scene photos in Smartclaims for your easy reference. We are of the view that BOLA S28 is apply as Malaysia veh was the last car.

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	13,796.37	
Loss of use		-	
Loss of rental	\$	1,400.00	(14days x \$100.00)
Loss of income		-	
LTA search fees	\$	7.49	
Others		-	
Proposed Total	\$	15,203.86	

<< **Re:<SEEK MANDATE> - S8M00E85 [ACCIDENT INVOLVING SJK 1086U(OI)/ SKS 9594M(TP)/ OTHERS ON 14/04/2018]**

Type

🔍 Question

Message

PLS VERIFY ON TO CHECK ITEMS COR:\$9,100.00 LOR: \$1,400.00 LTA:\$7.49= \$10,507.49

Reply



RE: Re:<SEEK MANDATE> - S8M00E85 [ACCIDENT INVOLVING SJK 1086U(OI)/ SKS 9594M(TP)/ OTHERS ON 14/04/2018]

Type

🔔 Question

Message

Hi KC, For COR, Third party rejected our offer at \$9,100.00 and proposed \$14,105.31(part by part basis as third party vehicle was less than 3 years old). Kindly let us have your further mandate on COR. Thank you.

Hsiao Tong - 26 Jan 2019

Reply



Re:RE: Re:<SEEK MANDATE> - S8M00E85 [ACCIDENT INVOLVING SJK 1086U(OI)/ SKS 9594M(TP)/ OTHERS ON 14/04/2018]

Type

🔗 Question

Message

PLS LET US HAVE YOUR BREAKDOWN ON YOUR PROPOSED SETTLEMENT MANDATE

Reply



**RE: Re:RE: Re:<SEEK MANDATE> - S8M00E85
[ACCIDENT INVOLVING SJK 1086U(OI)/ SKS
9594M(TP)/ OTHERS ON 14/04/2018]**

Type

🔗 Question

Message

Liability: 3 vehicle c.c. OI was 2nd car. We are of the view that BOLA 528 is apply as Malaysia veh was the last car. Spoken to insured, agreed to settle and aware NCD(if any) is affected. We seek your mandate at \$14,713.49(if claim LOU) -\$15,371.49(if claim LOR). Mandate IA DD 020219 had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 02 Feb 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/02/2019

Survey Details:

Date of loss	14.04.2018
Date of appointment	17.04.2018
Date of survey	18.04.2018
Location of survey	LIM YEW BOO SPRAY PAINT CO

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS 9594M
Make and Model	Toyota Altis (1598cc)
Date of registration	18.05.2015
Excess	NIL
Market Value/ Book Value	\$ 71,000.00 (est)
Parf/COE Rebate	\$ 57,134.00 (est)
Nett Value/ ERV	\$ 13,866.00 (est)

Repair details:

Initial Estimate	\$ 23,680.18
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,445.31
Check items (estimate)	NIL
Labour	\$ 3,660.00
Supplementary	NIL
Total	\$ 14,105.31
Lump Sum(if applicable)	\$ 13,866.00 (ERV)

Number of days for repair	<u>10</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 13,866.00	\$ 13,866.00
Loss of use (14days x \$60.00)	\$ 840.00	NIL
Loss of rental (14days x \$100.00)(w/GST)	NIL	\$ 1,498.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.49	\$ 7.49
Others	NIL	NIL
Proposed Total	\$ 14,713.49	\$ 15,371.49



Re:RE: Re:RE: Re:<SEEK MANDATE> - S8M00E85
[ACCIDENT INVOLVING SJK 1086U(OI)/ SKS
9594M(TP)/ OTHERS ON 14/04/2018]

Type

🔍 Question

Message

PLS PROCEED FOR SETTLEMENT AS FOLLOWS: COR \$13,500 LOR \$1,498.00 LTA \$7.49 TOTAL
\$15,005.49

Reply

\$ 13500.00 ✓

Lm: \$ 840.00 (14days x \$60.00)

\$ 14340.00 + 7.45 = 14347.45.



林偉武噴漆公司

LIM YEW BOO SPRAY PAINT CO.

Blk 10 Sin Ming Industrial Estate Sector C #01-10 Singapore 575645
No. 176 Sin Ming Drive #03-05 Sin Ming AutoCare Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg Website: www.limyewboo.com
Co. Reg. No.: 200514/00L

Our Ref: LYB/SKS9594M/AXA/tp/sl

Your Ref: SJK1086U (AXA)

28 February 2019

BY HAND

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933 Attn : Motor Claims Dept

Dear Sirs

ACC INVLG SKS9594M & SJK1086U ALONG SG – JOHOR CAUSEWAY ON 14/04/2018

We are the repairers of vehicle nos. SKS9594M and understand that you were the appointed surveyor by the insurer of vehicle nos. SJK1086M involved in the aforesaid accident. Our investigations reveal that the accident was caused by the negligence of the vehicle insured by you. As such, we are looking to you for reimbursement calculated as follows;

1) Repair Costs	S\$14,662.73
2) Loss of use at \$60 per day	840.00
3) LTA Search	7.45
	=====
TOTAL:	S\$15,510.18
	=====


To substantiate our claim, we enclosed the following;

- 1) Final Repair bill
- 2) SAS Statement
- 3) Copy of CI
- 4) LTA Search/ Receipt
- 5) Copy of IC & Driving License
- 6) Authorisation to Act

We look forward to your favorable reply in due course.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

Yours faithfully


Serene Lim
Claims Section

Encl.



Auto-
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

29 JUNE 2018

MOHAMED HAINI BIN PARDI
BLK 539 WOODLANDS DRIVE 16
#06-117
SINGAPORE 730539

Dear Sir/ Mdm

OUR REF : CC4/ASM18007203/Kpa3
YOUR REF : GA 219341/1 (SJK 1086U)
ACCIDENT INVOLVING SJK 1086U/ SKS 9594M/ OTHERS ALONG/AT BEFORE
MALAYSIA CUSTOM TWDS SINGAPORE ON 14/04/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from LIM YEW BOO SPRAY PAINT CO acting on behalf of the owner of SKS 9594M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed loss adjuster of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.


This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT



I/We, NELSON INTERNATIONAL (S) PTE LTD (the third party claimant") of BLK 415 SEMBAWANG DRIVE #06-736 SINGAPORE 750415 (address), owner of SKS9594M (vehicle no.) hereby authorize LIM YEW BOO SPRAY PAINT CO ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKS9594M that was damaged pursuant to the accident which occurred on 14/04/2018 (date) along S.G - JOHOR CAUSEWAY 300M BLF MALAYSIA CUSTOM (location) involving vehicle no/s SJK1086U ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 18 (day) of 04 (month) 2018 (year)

X  
Signed by "the third party claimant"
(with company stamp if applicable)

 
Signed by "the workshop"
(with company stamp)



redefining / insurance

CLAIM REF
INSURED

: SGM00685
: Mohamed Hani Bin Pardi

DISCHARGE VOUCHER

We/I, NELSON INTERNATIONAL (S) PTE LTD, NRIC NO. 200607194G hereby agree to accept the sum of dollars Fourteen thousand three hundred forty-seven r cts forty-five (S\$14,347.45) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SJK1086U as a result of an accident along S.G - JOHOR CAUSEWAY 300M BLF MALAYSIA CUSTOM on 14/04/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SKS9594M.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SJK1086U in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SJK1086U.

Dated this

28

day of

Feb

2017

19

Claimant's Signature

: X

NRIC no./ Company Stamp

: 200607194G

Occupation/ Business

:

Address

:

Telephone No.

:

Witness's Name

:

Serene Lim

Witness's Signature

:

SJK1086U
Bik 10, Shuang Ind. Est.
Tel: 64534177 Fax: 6453724

Witness's NRIC No.

:

*Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721

Tel No. : 64534177 Fax No. : 64593724

E-Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Final Repair Bill : TP18/023

Date : 27/11/2018
Vehicle Num. : SKS 9594M ✓
Make/Model : TOYOTA ALTIS-2015
Chassis/Eng# : MR053REH104523422/1ZRY136567
Accident Date : 14/04/2018
Claim No. :
Reference : LYB/SKS9594M/AXA/tp/sl
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET		1,028.10
2.	1	FRONT GRILLE (CHROME)		564.00
3.	1	FRONT EMBLEM		54.54
4.	1	FRONT NO PLATE (EMBOSS) + HOLDER		45.00
5.	1	FRONT BUMPER		627.54
6.	1	FRONT BUMPER LOWER GRILLE/CENTRE		247.30
7.	2	FRONT BUMPER RETAINER	82.00	164.00
8.	2	FRONT BUMPER CLIPS	5.00	10.00
9.	2	FRONT HEADLAMP	2,410.30	4,820.60
10.	2	FRONT HEADLAMP TOP CHROME	240.50	481.00
11.	1	REAR LID		754.70
12.	1	REAR LID RUBBER		266.40
13.	1	REAR EMBLEM 'COROLLA'		57.33
14.	1	REAR EMBLEM 'ALTIS'		50.80
15.	2	REAR EMBLEM 'TOYOTA' IN LOGO FONT	67.80	135.60
16.	2	REAR REFLECTORS	401.10	802.20
17.	2	REAR TAILLAMP	486.60	973.20
18.	1	REAR BUMPER		639.90
19.	2	REAR BUMPER RETAINER	105.90	211.80
20.	1	REAR BUMPER BEAM		389.00
21.	1	REAR TAILEND PANEL		581.20
22.	1	REAR TAILEND TOP GARNISH		271.40
23.	1	REAR SPARE TYRE FLOOR PANEL		702.93
List TotalS\$:				13,878.54
25.00% Discount S\$:				3,469.64
				10,408.90

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Final Repair Bill : TP18/023

Date : 27/11/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1	REAR NO PLATE (EMBOSS) + HOLDER		45.00
2.	2	REAR TAILEND PANEL TEROSTAT SEALANT	30.00	60.00
3.	2	REAR TAILEND TOP GARNISH CLIPS	5.00	10.00
4.	1	REAR SPARE TYRE BOARD (CARPET)		248.83
5.	1	REAR REVERSE SENSOR		200.00
Special Nett Total S\$:				563.83
LABOUR :				
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED FRT PANELS				30.00
TO FOCUS HEADLAMP & CHECK WIRING FUNCTION				20.00
TO REPAIR, PANEL BEAT ON FRT AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS				500.00
TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER FRT ENFORCEMENT, FRT SUPPORT PANEL, BRACE PANEL & TOUCH UP ON FRT AFFECTED FENDER USING 2K PAINT				800.00
MOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR JOB				280.00
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS				60.00

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Final Repair Bill : TP18/023

Date : 27/11/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/si
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK REAR WIRING FUNCTION		20.00
		TO CHECK & REPAIR, ALIGN EXHAUST SILENCER		60.00
		TO CHECK WATER LEAKAGE		20.00
		TO REPAIR, PANEL BEAT ON LEFT REAR AFFECTED FENDER, CUT & WELD ON REPLACED REAR PANEL, SPARE TYRE HOUSING & LABOUR TO REPLACE THE ABOVE PARTS		900.00
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR PANEL, REAR SPARE TYRE PANEL, REAR BEAM, REAR BUMPER, REAR AFFECTED FENDER, REAR REVERSE SENSOR USING 2K PAINT		1,000.00
		Labour Total S\$:		3,690.00

E. & O.E.

Total S\$:

14,662.73



for LIM YEW BOO SPRAY PAINT CO.

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 Apr 2018 / 17:25:21

Receipt Date/Time : 16 Apr 2018 / 17:25:13

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180416-001887

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJK1086U As at 14 Apr 2018/13:35:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SJK1086U Enquiry Fee 20180416172431128326	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180416172444501 Direct Debit: eNETS Debit (Internet Banking)			7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJK 1086U (Insd veh)	Model:	TOYOTA ALTIS (A)
	SKS 9594M (TP veh)		
Date of Accident:	14/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	23,680.18
Final Repair Cost	:	\$	13,500.00
Loss of Use	:	\$	840.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	14,347.45

Is Third Party Workshop GIA Registered?		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	LIM YEW BOO SPRAY PAINT CO.	:	\$ 14,347.45

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

04/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007203/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-03-2019



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 1086U	Veh. Inspected	SKS 9594M
Policy No.	GA219341/1	Coverage (\$)	0.00
Claim No.	S8M00E85	Excess (\$)	0.00
Assign From		Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104523422	Colour	METALLIC GREY
Odometer	51342	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	4 mm
L/H Front Tyre	205/55 R16	DUNLOP	4 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/04/2018	Inspection Date	18/04/2018
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9594M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	BENT	1,028.10	1,028.10
1	FRONT BONNET SEAL (CENTRE) (CONSISTENT)	SERVICEABLE	84.70	-
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,074.10	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	155.00	-
1	FRONT RADIATOR MOUNTING (CONSISTENT)	SERVICEABLE	33.40	-
1	FRONT RADIATOR ASSY (CONSISTENT)	SERVICEABLE	1,764.90	-
1	FRONT AIR-CON CONDENSER (CONSISTENT)	SERVICEABLE	1,291.11	-
1	FRONT GRILLE (CHROME) (CONSISTENT)	CRACKED	564.00	564.00
1	FRONT EMBLEM (CONSISTENT)	NECESSARY	54.54	54.54
1	FRONT NO PLATE (EMBOSS)+HOLDER (CONSISTENT)	BENT	45.00	45.00
1	FRONT BUMPER (CONSISTENT)	BUCKLED	627.54	627.54
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	178.00	-
1	FRONT BUMPER LOWER GRILLE /CENTRE (CONSISTENT)	DENTED	247.30	247.30
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	408.85	-
2	FRONT BUMPER RETAINER @\$82.00 (CONSISTENT)	DISTORTED	164.00	164.00
2	FRONT BUMPER CLIPS @\$5.00 (CONSISTENT)	NECESSARY	10.00	10.00
2	FRONT HEADLAMP @\$2410.30 (CONSISTENT)	MTG CRACKED	4,820.60	4,820.60
2	FRONT HEADLAMP TOP CHROME @\$240.50 (CONSISTENT)	NECESSARY	481.00	481.00
1	REAR LID (CONSISTENT)	BENT	754.70	754.70
1	REAR LID HINGES (CONSISTENT)	TO REPAIR SEE LABOUR	157.10	-
1	REAR LID OUTER HANDLE (CONSISTENT)	SERVICEABLE	231.30	-
1	REAR LID LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	379.20	-
1	REAR LID RUBBER (CONSISTENT)	DISTORTED / DENTED	266.40	266.40
1	REAR EMBLEM 'COROLLA' (CONSISTENT)	NECESSARY	57.33	57.33
1	REAR EMBLEM 'ALTIS' (CONSISTENT)	NECESSARY	50.80	50.80

Report Ref No. CC4/ASM18007203/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EMBLEM 'TOYOTA' IN LOGO FONT @\$67.80 (CONSISTENT)	NECESSARY	135.60	135.60
2	REAR REFLECTORS @\$401.10 (CONSISTENT)	CRACKED	802.20	802.20
2	REAR TAILLAMP @\$486.60 (CONSISTENT)	DENTED / CUT	973.20	973.20
1	REAR BUMPER (CONSISTENT)	BENT	639.90	639.90
2	REAR BUMPER RETAINER @\$105.90 (CONSISTENT)	DISTORTED	211.80	211.80
2	REAR BUMPER BRACKET @\$104.60 (CONSISTENT)	TO REPAIR SEE LABOUR	209.20	-
1	REAR BUMPER BEAM (CONSISTENT)	BENT	389.00	389.00
1	REAR TAILEND PANEL (CONSISTENT)	BENT	581.20	581.20
1	REAR TAILEND TOP GARNISH (CONSISTENT)	MTG DISTORTED	271.40	271.40
1	REAR SPARE TYRE FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	702.93	-
1	REAR SILENCER (CONSISTENT)	TO REPAIR SEE LABOUR	645.20	-
	LESS 25% DISCOUNT		-5,122.65	-3,293.90
			15,367.95	9,881.71
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NO PLATE (EMBOSS)+HOLDER (SN) (CONSISTENT)	NECESSARY	55.00	45.00
2	REAR TAILEND PANEL TEROSTAT SEALANT @\$54.20 (SN) (CONSISTENT)	NECESSARY	108.40	60.00
2	REAR TAILEND TOP GARNISH CLIPS @\$5.00 (SN) (CONSISTENT)	NECESSARY	10.00	10.00
2	REAR SPARE TYRE PANEL SEALANT @\$120.00 (SN) (CONSISTENT)	NOT NECESSARY	240.00	-
1	REAR SPARE TYRE PANEL INSULATOR PADDING (SN) (CONSISTENT)	NOT NECESSARY	200.00	-
1	REAR SPARE TYRE BOARD (CARPET) (SN) (CONSISTENT)	CRACKED	248.83	248.83
1	REAR REVERSE CAMERA (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	DENTED	220.00	200.00
			1,382.23	563.83
	<u>LABOUR</u>			
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED FRT PANELS.		120.00	30.00

Report Ref No. CC4/ASM18007203/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK FRONT WIRING FUNCTION.}	NOT NECESSARY	50.00	20.00
	TO FOCUS HEADLAMP.}		60.00	-
	LABOUR TO REPLACE FRT AIR CON CONDENSER PARTS AND VACUUM & TOP UP GAS.		180.00	-
	TO REPAIR ,PANEL BEAT ON FRT AFFECTED AREA,CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS.		900.00	500.00
	TO PUTTY,PRIMER & SPRAY PAINT ON FRT BONNET ,FRT BUMPER FRT ENFORCEMENT ,FRT SUPPOT PANEL,BRACE PANEL & TOUCH UP ON FRT AFFECTED FENDER USING 2K PAINT.		1,600.00	800.00
	MOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR JOB.		350.00	250.00
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED REAR PANELS.		120.00	60.00
	TO CHECK REAR WIRING FUNCTION.		50.00	20.00
	TO REPLACE EXHAUST SILENCER.		120.00	60.00
	TO CHECK WATER LEAKAGE.		80.00	20.00
	TO REPAIR ,PANEL BEAT ON LEFT REAR AFFECTED FENDER ,CUT & WELD ON REPLACED REAR PANEL,SPARE TYRE HOUSING & LABOUR TO REPLACE THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL,FRONT BRACE PANEL,FRONT BUMPER REINFORCEMENT,REAR LID HINGES,REAR LID LOCK,REAR BUMPER BRACKET,REAR SPARE TYRE FLOOR PANEL AND REAR SILENCER.		1,500.00	900.00
	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR BOOT LID ,REAR PANEL,REAR SPARE TYRE PANEL,REAR BEAM ,REAR BUMPER,REAR AFFECTED FENDER ,REARREVERSE SENSOR USING 2K PAINT.		1,800.00	1,000.00
			6,930.00	3,660.00
	GRAND TOTAL		23,680.18	14,105.54
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,500.00

Report Ref No. CC4/ASM18007203/Kpa3q2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SERVICE REQUESTS MESSAGES CLAIMS

Service Request Details

Claim	S8M00EB5
Reference	CC4/ASM18007203/Kaa3a2 
Loss Date	14 April 2018
Report Date	17 Apr 2018 9:08:05 AM
Request Date	27 August 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Vehicle Information	
Incident Vehicle Registration #	SKS9594M
Make	TPVD TOYOTA
Model	ALTIS
Service Address	

Primary Contact/Insured	
PARDI MOHAMED NAINI BIN BLK 539 WOODLANDS DRIVE 16, #06-117, 730539, Singapore 63447667 BELINDACHAN78@HOTMAIL.COM	
Claim Handler	
CHAN Kian Chuan 6568804269 kianchuan.chan@axa.com.sg	

Actions

Next Step Wait for Approve Invoice

[Add Invoice](#)

Additional Instructions







Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice 1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	15 March 2019
MANDATE IA DO 020219.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 February 2019
TP ESTIMATE_MARKED[FINAL].pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	26 January 2019
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 January 2019
Immediate Advice (with mandatel dd 280618.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident picture FROM TP.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	28 June 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	20 April 2018
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 April 2018
 Preliminary Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 April 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2018
 EMAIL RECEIVED FROM WORKSHOP WITH G/A REPROT.msg	Other	Other	DHIMAR Namrala	17 April 2018