

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Not Authorized

1-21

Heavy Blk paint

10 days

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | |
|-----|---|----------------------------------|
| 1. | 1 | FRONT BONNET |
| 2. | 1 | FRONT BONNET SEAL (CENTRE) |
| 3. | 1 | FRONT SUPPORT PANEL |
| 4. | 1 | FRONT BRACE PANEL |
| 5. | 1 | FRONT RADIATOR MOUNTING |
| 6. | 1 | FRONT RADIATOR ASSY |
| 7. | 1 | FRONT AIR-CON CONDENSER |
| 8. | 1 | FRONT GRILLE (CHROME) |
| 9. | 1 | FRONT EMBLEM |
| 10. | 1 | FRONT NO PLATE (EMBOSS) + HOLDER |
| 11. | 1 | FRONT BUMPER |
| 12. | 1 | FRONT BUMPER SPONGE |
| 13. | 1 | FRONT BUMPER LOWER GRILLE/CENTRE |
| 14. | 1 | FRONT BUMPER REINFORCEMENT |
| 15. | 2 | FRONT BUMPER RETAINER |
| 16. | 2 | FRONT BUMPER CLIPS |
| 17. | 2 | FRONT HEADLAMP |
| 18. | 2 | FRONT HEADLAMP TOP CHROME |
| 19. | 1 | REAR LID |
| 20. | 1 | REAR LID HINGES |
| 21. | 1 | REAR LID OUTER HANDLE |
| 22. | 1 | REAR LID LOCK |
| 23. | 1 | REAR LID RUBBER |
| 24. | 1 | REAR EMBLEM 'COROLLA' |

<i>Bn</i>	1,028.10	✓
<i>Sm</i>	84.70	X
<i>R</i>	1,074.10	X
<i>Bn</i>	155.00	?
<i>Sm</i>	33.40	X
<i>Sm</i>	1,764.90	X
	1,291.11	?
<i>CM</i>	564.00	✓
<i>Me</i>	54.54	✓
<i>Bn</i>	45.00	✓
<i>Bul</i>	627.54	✓
	178.00	?
<i>Me</i>	247.30	✓
	408.85	?
<i>Dis</i>	164.00	✓
<i>Na</i>	10.00	✓
<i>Dis</i>	2,410.30	✓
	240.50	✓
<i>Bn</i>	481.00	✓
<i>R</i>	754.70	✓
<i>Sm</i>	157.10	X
<i>Sm</i>	231.30	X
<i>Dis/Re</i>	379.20	?
<i>Na</i>	266.40	✓
<i>Na</i>	57.33	✓

ols?

als mgmt

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	REAR EMBLEM 'ALTIS'		50.80
26.	2	REAR EMBLEM 'TOYOTA' IN LOGO FONT	67.80	135.60
27.	2	REAR REFLECTORS	401.10	802.20
28.	2	REAR TAILLAMP	486.60	973.20
29.	1	REAR BUMPER		639.90
30.	2	REAR BUMPER RETAINER	105.90	211.80
31.	2	REAR BUMPER BRACKET	104.60	209.20
32.	1	REAR BUMPER BEAM		389.00
33.	1	REAR TAILEND PANEL		581.20
34.	1	REAR TAILEND TOP GARNISH		271.40
35.	1	REAR SPARE TYRE FLOOR PANEL		702.93
36.	1	REAR SILENCER		645.20
List TotalS\$:				20,490.60
25.00% Discount S\$:				5,122.65
				15,367.95
SPECIAL NETT ITEMS :				
1.	1	REAR NO PLATE (EMBOSS) + HOLDER		55.00
2.	2	REAR TAILEND PANEL TEROSTAT SEALANT	54.20	108.40
3.	2	REAR TAILEND TOP GARNISH CLIPS	5.00	10.00
4.	2	REAR SPARE TYRE PANEL SEALANT	120.00	240.00
5.	1	REAR SPARE TYRE PANEL INSULATOR PADDING		200.00
6.	1	REAR SPARE TYRE BOARD (CARPET)		248.83
7.	1	REAR REVERSE CAMERA		300.00

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
8.	1	REAR REVERSE SENSOR	<i>Net</i>	<i>200.00</i> 220.00
		Special Nett Total S\$:		1,382.23
		LABOUR :		
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED FRT PANELS		120.00 <i>300</i>
		TO CHECK FRONT WIRING FUNTION		50.00 <i>200</i>
		TO FOCUS HEADLAMP		60.00 <i>200</i>
		LABOUR TO REPLACE FRT AIR CON CONDENSER PARTS AND VACUM & TOP UP GAS		180.00 ?
		TO REPAIR, PANEL BEAT ON FRT AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS		900.00 <i>500</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER FRT ENFORCEMENT, FRT SUPPORT PANEL, BRACE PANEL & TOUCH UP ON FRT AFFECTED FENDER USING 2K PAINT		1,600.00 <i>800</i>
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB		350.00 ?
		TO APPLY RUST-PROOFING ON REPAIRED/REPLACED REAR PANELS		120.00 <i>600</i>
		TO CHECK REAR WIRING FUNCTION		50.00 <i>200</i>

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPLACE EXHAUST SILENCER	120.00	601
		TO CHECK WATER LEAKAGE	80.00	20
		TO REPAIR, PANEL BEAT ON LEFT REAR AFFECTED FENDER, CUT & WELD ON REPLACED REAR PANEL, SPARE TYRE HOUSING & LABOUR TO REPLACE THE ABOVE PARTS	1,500.00	900
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR PANEL, REAR SPARE TYRE PANEL, REAR BEAM, REAR BUMPER, REAR AFFECTED FENDER, REAR REVERSE SENSOR USING 2K PAINT	1,800.00	1000
		Labour Total S\$:		6,930.00


 for LIM YEW BOO SPRAY PAINT CO.



E. & O.E.

Total S\$: 23,680.18

=====