

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

Not authorized
1-131
Heavy Blue paint
10 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BONNET		1,028.10 ✓
2.	1	FRONT BONNET SEAL (CENTRE)		84.70 X
3.	1	FRONT SUPPORT PANEL		1,074.10 X
4.	1	FRONT BRACE PANEL		155.00 X
5.	1	FRONT RADIATOR MOUNTING		33.40 X
6.	1	FRONT RADIATOR ASSY		1,764.90 X
7.	1	FRONT AIR-CON CONDENSER		1,291.11 X
8.	1	FRONT GRILLE (CHROME)		564.00 ✓
9.	1	FRONT EMBLEM		54.54 ✓
10.	1	FRONT NO PLATE (EMBOSS) + HOLDER		45.00 ✓
11.	1	FRONT BUMPER		627.54 ✓
12.	1	FRONT BUMPER SPONGE		178.00 X
13.	1	FRONT BUMPER LOWER GRILLE/CENTRE		247.30 ✓
14.	1	FRONT BUMPER REINFORCEMENT		408.85 X
15.	2	FRONT BUMPER RETAINER	82.00	164.00 ✓
16.	2	FRONT BUMPER CLIPS	5.00	10.00 ✓
17.	2	FRONT HEADLAMP	2,410.30	4,820.60 ✓
18.	2	FRONT HEADLAMP TOP CHROME	240.50	481.00 ✓
19.	1	REAR LID		754.70 ✓
20.	1	REAR LID HINGES		157.10 X
21.	1	REAR LID OUTER HANDLE		231.30 X
22.	1	REAR LID LOCK		379.20 X
23.	1	REAR LID RUBBER		266.40 ✓
24.	1	REAR EMBLEM 'COROLLA'		57.33 ✓

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721

Tel No. : 64534177 Fax No. : 64593724

E-Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018

Vehicle Num. : SKS 9594M

Make/Model : TOYOTA ALTIS-2015

Chassis/Eng# : MR053REH104523422/1ZRY136567

Accident Date : 14/04/2018

Claim No. :

Reference : LYB/SKS9594M/AXA/tp/sl

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	REAR EMBLEM 'ALTIS'		50.80
26.	2	REAR EMBLEM 'TOYOTA' IN LOGO FONT	67.80	135.60
27.	2	REAR REFLECTORS	401.10	802.20
28.	2	REAR TAILLAMP	486.60	973.20
29.	1	REAR BUMPER		639.90
30.	2	REAR BUMPER RETAINER	105.90	211.80
31.	2	REAR BUMPER BRACKET	104.60	209.20
32.	1	REAR BUMPER BEAM		389.00
33.	1	REAR TAILEND PANEL		581.20
34.	1	REAR TAILEND TOP GARNISH		271.40
35.	1	REAR SPARE TYRE FLOOR PANEL		702.93
36.	1	REAR SILENCER		645.20
List TotalS\$:				20,490.60
25.00% Discount S\$:				5,122.65
				15,367.95
SPECIAL NETT ITEMS :				
1.	1	REAR NO PLATE (EMBOSS) + HOLDER		55.00
2.	2	REAR TAILEND PANEL TEROSTAT SEALANT	54.20	108.40
3.	2	REAR TAILEND TOP GARNISH CLIPS	5.00	10.00
4.	2	REAR SPARE TYRE PANEL SEALANT	120.00	240.00
5.	1	REAR SPARE TYRE PANEL INSULATOR PADDING		200.00
6.	1	REAR SPARE TYRE BOARD (CARPET)		248.83
7.	1	REAR REVERSE CAMERA		300.00

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
8.	1	REAR REVERSE SENSOR	<i>Net</i>	<i>200.00</i> 220.00
		Special Nett Total S\$:		1,382.23
		LABOUR :		
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED FRT PANELS		120.00 <i>30%</i>
		TO CHECK FRONT WIRING FUNTION		50.00 <i>20%</i>
		TO FOCUS HEADLAMP		60.00 <i>20%</i>
		LABOUR TO REPLACE FRT AIR CON CONDENSER PARTS AND VACUM & TOP UP GAS	<i>nn</i>	180.00 <i>X</i>
		TO REPAIR, PANEL BEAT ON FRT AFFECTED AREA, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE ABOVE PARTS		900.00 <i>50%</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON FRT BONNET, FRT BUMPER FRT ENFORCEMENT, FRT SUPPORT PANEL, BRACE PANEL & TOUCH UP ON FRT AFFECTED FENDER USING 2K PAINT		1,600.00 <i>80%</i>
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB		350.00 <i>250%</i>
		TO APPLY RUST-PROOFING ON REPAIRED/REPLACED REAR PANELS		120.00 <i>60%</i>
		TO CHECK REAR WIRING FUNCTION		50.00 <i>20%</i>

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288 Fax No. : 68804838

Estimate : TP18/023

Date : 17/04/2018
 Vehicle Num. : SKS 9594M
 Make/Model : TOYOTA ALTIS-2015
 Chassis/Eng# : MR053REH104523422/1ZRY136567
 Accident Date : 14/04/2018
 Claim No. :
 Reference : LYB/SKS9594M/AXA/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPLACE EXHAUST SILENCER	120.00	601
		TO CHECK WATER LEAKAGE	80.00	201
		TO REPAIR, PANEL BEAT ON LEFT REAR AFFECTED FENDER, CUT & WELD ON REPLACED REAR PANEL, SPARE TYRE HOUSING & LABOUR TO REPLACE THE ABOVE PARTS	1,500.00	9001
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR PANEL, REAR SPARE TYRE PANEL, REAR BEAM, REAR BUMPER, REAR AFFECTED FENDER, REAR REVERSE SENSOR USING 2K PAINT	1,800.00	10001
		Labour Total S\$:		6,930.00

E. & O.E.

Total S\$: 23,680.18

for LIM YEW BOO SPRAY PAINT CO.

