

2/10/2002

ASS. REC. BY:

REF:

CG/FCI18007207 / Kgbnz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): WS Sithara

of

FCI

Date/Time: 17/04/2018 5:12pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 1102P

Insured:

SNC 7272A

at Workshop m/s

Lai Huat (Mung Kee)

Tel:

6453 8110

of

160 Sin Ming Drive #04-01

Policy No:

Claim No:

D18002919M FSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS '100'

H.O.D. Endorsement:

Date/Time: 18/04/2018 10:04am

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 1102P - X
	SNC 7272A - CCU / AXA / 17011287 / 1104302
12/4/18 @ 2:10pm	revised to Sithara by email.
	Final fig \$ 5636.70, 9 days (Red \$ 250, 4%)

DOA: 200817

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 861k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 1.13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE 1102P Yr Regn: 07, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT Attrage c.c. 1183

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading 12915 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NMBST / A13 / H11 / 000 654

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 15/4/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 18/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/10 File sent to Catherine

RECEIVED 07 NOV 2018

7/11/2018

Date/Time, File Pass to?

11/02/18 Transfer

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 5636.70

☐ : Prel. Report☐ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

145

50

50

31

276



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007207/Kqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7272A	Veh. Inspected	SLE 1102P
Policy No.		Coverage (\$)	0.00
Claim No.	D18002919MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/04/2018	Inspection Date	18/04/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

--	--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002919MFSH

Date: 19 April 2018

Our Ref: CS/FCI18007207/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 1102P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/04/2018 at the premises of M/s LAI HUAT MENG KEE, and have the following to report:-

Workshop Estimate Amount	: S\$ 5,802.50 .
Revised Estimate Amount	: S\$ 5,402.50 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-04-2018	Our Ref No. D18002919MFSH
Accident Date	15-04-2018	Claim Type. Third Party
Insured Vehicle	SHC7272A	Third Party Vehicle. SLE1102P
Survey Location	160 Sin Ming Drive #04-01/02 and #07-03 Sin Ming Autocity	
Contact Person.	JENNY LIM	
Contact No.	64538110/ 0	Fax No. 64596267
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 April 2018 3:10 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002919MFSH/1
Attachments: CSFCI18007207Kqb.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLE 1102P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 18 April 2018 10:06 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002919MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 April, 2018 5:12 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002919MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8903997E**
Name:

LIM KUAN LOONG, BRYAN
(LIN GUANGLONG)

Birth Date: **01 Feb 1989**

Issue Date: **22 Dec 2009**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

FAS3 DATE

Class 3 Motor Cars= $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 22 Dec 2009



NP 428A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

92361

Vehicle Details

Vehicle No.:

SLE1102P

Vehicle to be Exported:

No

Intended De-registration Date:

16 Apr 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

ATTRAGE 1.2 CVT

Primary Colour:

Red

Manufacturing Year:

2016

Engine No.:

3A92UDD7713

Chassis No.:

MMBSTA13AHH000654

Maximum Power Output:

57.0 kW (76 bhp)

Open Market Value:

\$13,983.00

Original Registration Date:

08 Jul 2016

First Registration Date:

08 Jul 2016

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 Jul 2026

PARF Rebate Amount:

\$3,750.00

Intended COE Rebate Details

COE Expiry Date:

07 Jul 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$47,300.00

COE Rebate Amount:

\$38,901.00

Total Rebate Amount:

\$42,651.00

The information contained herein is correct as at 16 Apr 2018

OK

Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 16 Apr 2018, 16:39:13.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SHC7272A-		18.32 Insurance Enquiry (GIRO Payment)	7.49	16 Apr 2018 / 16:39:31

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019050
Tan Bee Lian

Page 1 of 2
Your ref. TP-SHC 7272A FC
Job No. 69415
Our ref. 18.04.24
Payment
Date 17/4/2018

Attn

Vehicle No SLE 1102P
Vehicle Model Mitsubishi Attrage 1.2 CVT (A)
Accident on 15/4/2018

Not Authorized
1-B.1
Resurvey B4 pain

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear boot lid	828.00	10.00	745.20
1.00	Pc	Rear boot lid lock	206.00	10.00	185.40
1.00	Pc	Rear boot lid weatherstrip	148.00	10.00	133.20
1.00	Pc	Rear tail lamp LH	276.00	10.00	248.40
1.00	Pc	Rear tail lamp RH	276.00	10.00	248.40
1.00	Pc	Rear bumper	708.00	10.00	637.20
1.00	Pc	Rear bumper side retainer RH	28.00	10.00	25.20
1.00	Pc	Rear end panel	402.00	10.00	361.80
1.00	Pc	Rear end panel top garnish	62.00	10.00	55.80
1.00	Pc	Rear end panel air duct	38.00	10.00	34.20
2.00	Pcs	Rear bumper lower clips	3.50	10.00	6.30
1.00	Pc	Rear luggage board	185.00	10.00	166.50
1.00	Pc	Rear Attrage emblem	20.00	10.00	18.00
1.00	Pc	Rear logo emblem	41.00	10.00	36.90
Special nett item:					
1.00	Pc	Rear Mivec Technology emblem	50.00		50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019050
Tan Bee Lian

Page 2 of 2
Your ref. TP-SHG 7272A FC
Job No 69415
Our ref 18.04.24
Payment
Date 17/4/2018

Attn

Vehicle No SLE 1102P
Vehicle Model : Mitsubishi Attrage 1.2 CVT (A)
Accident on ... 15/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Set	Rear reversing sensor with installation	50.00		50.00
		Labour & Misc.	200		200
1.00		To straighten rear body including cutting and welding, to knock dents on rear fender LH & RH, rear luggage panel, tail lamp panel LH & RH and renew of parts	1,500.00		1,500.00
1.00		To spray paint	1,300.00		1,300.00

6036.70

Sub-Total	5,802.50
GST 7.00%	406.18
Total	S\$ 6,208.68

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

5886.70

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No. EST0019050
Tan Bee Lian

Page 1 of 2
Your ref. TP-SHC 7272A FC
Job No. 69415
Our ref. 18.04.24
Payment
Date 17/4/2018

Attn

Vehicle No. SLE 1102P
Vehicle Model Mitsubishi Attrage 1.2 CVT (A)
Accident on 15/4/2018

Not Authorized
I-B1
Assure B4 part
9 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item.					
			828.00	10.00	B ₁ 745.20 ✓
1.00	Pc	Rear boot lid	206.00	10.00	B ₁ 185.40 ✓
1.00	Pc	Rear boot lid lock	148.00	10.00	B ₁ 133.20 ✓
1.00	Pc	Rear boot lid weatherstrip	276.00	10.00	C ₁ 248.40 ✓
1.00	Pc	Rear tail lamp LH	276.00	10.00	C ₁ 248.40 ✓
1.00	Pc	Rear tail lamp RH	708.00	10.00	B ₁ 637.20 ✓
1.00	Pc	Rear bumper	28.00	10.00	B ₁ 25.20 ✓
1.00	Pc	Rear bumper side retainer RH	402.00	10.00	B ₁ 361.80 ✓
1.00	Pc	Rear end panel	62.00	10.00	B ₁ 55.80 ✓
1.00	Pc	Rear end panel top garnish	38.00	10.00	C ₁ 34.20 ✓
1.00	Pc	Rear end panel air duct X	3.50	10.00	B ₁ 6.30 ✓
2.00	Pcs	Rear bumper lower clips	185.00	10.00	C ₁ 166.50 ✓
1.00	Pc	Rear luggage board	20.00	10.00	B ₁ 18.00 ✓
1.00	Pc	Rear Attrage emblem	41.00	10.00	B ₁ 36.90 ✓
1.00	Pc	Rear logo emblem			
Special nett item					
			50.00		B ₁ 50.00 ✓
1.00	Pc	Rear Miveo Technology emblem			

2902.50

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No: EST0019050
Tan Bee Lian

Page 2 of 2
Your ref: TP-SHC 7272A FG
Job No: 69415
Our ref: 18.04.24
Payment
Date: 17/4/2018

Attn:

Vehicle No: SLE 1102P
Vehicle Model: Mitsubishi Attrage 1.2 CVT (A)
Accident on: 15/4/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00	Set	Rear reversing sensor with installation WRONG PRICE	50.00	200	50.00 200 ✓
		Labour & Misc			(250) 1200/
1.00		To straighten rear body including cutting and welding, to knock dents on rear fender LH & RH, rear luggage panel, tail lamp panel LH & RH and renew of parts	1,500.00		1,500.00
1.00		To spray paint	1,300.00		1,300.00
					(2400)

Sub-Total 5,802.50
GST 7.00% 406.18
Total S\$ 6,208.68

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 嘛哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

SUPPLEMENTARY ESTIMATE

EST. No EST0019050
Tan Bee Lian

Page 1 of 1
Your ref. TP-SHC 7272A FC
Job No. 69415
Our ref 18.04.24
Payment
Date 23/4/2018

Attn

Vehicle No ... : SLE 1102P
Vehicle Model : Mitsubishi Attrage 1.2 CVT (A)
Accident on ... : 15/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
SUPPLEMENTARY ITEM:					
1.00	Pc	Rear air duct cover	38.00	10.00	<i>CM</i> <i>Per</i> 34.20 ✓
Special nett item:					
1.00	Pc	Rear luggage panel sound insulation	50.00		<i>M</i> 50.00 ✓

Sub-Total		84.20
GST 7.00%		5.89
Total	S\$	90.09

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007207/Kqbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-11-2018



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SHC 7272A	Veh. Inspected	SLE 1102P
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18002919MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	17/04/2018

Vehicle Particulars & Condition

2.	Make & Model	mitsubishi attrage (A)	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MMBSTA13AHH000654	Colour	METALLIC RED
	Odometer	12915	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre	185/55 R15	BRIDGESTONE	8 mm
	L/H Front Tyre	185/55 R15	BRIDGESTONE	8 mm
	R/H Rear Tyre	185/55 R15	BRIDGESTONE	8 mm
	L/H Rear Tyre	185/55 R15	BRIDGESTONE	8 mm

Description of Damages

4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
----	--

General Information

5.	Accident Date	15/04/2018	Inspection Date	18/04/2018
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

Remarks

5a.	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	--

Estimate Days of Repair

5b.	ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-----	-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1102P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (N)	BENT	828.00	828.00
1	REAR BOOT LID LOCK (N)	DISTORTED	206.00	206.00
1	REAR BOOT LID WEATHERSTRIP (N)	DENTED / CUT	148.00	148.00
1	REAR TAIL LAMP LH (N)	CRACKED	276.00	276.00
1	REAR TAIL LAMP RH (N)	CRACKED	276.00	276.00
1	REAR BUMPER (N)	BENT	708.00	708.00
1	REAR BUMPER SIDE RETAINER RH (N)	DISTORTED	28.00	28.00
1	REAR END PANEL (N)	BENT	402.00	402.00
1	REAR END PANEL TOP GARNISH (N)	MTG DISTORTED	62.00	62.00
1	REAR END PANEL AIR DUCT (N)	CRACKED	38.00	38.00
2	REAR BUMPER LOWER CLIPS @\$3.50 (N)	NECESSARY	7.00	7.00
1	REAR LUGGAGE BOARD (N)	CRACKED	185.00	185.00
1	REAR ATTRAGE EMBLEM (N)	NECESSARY	20.00	20.00
1	REAR LOGO EMBLEM (N)	NECESSARY	41.00	41.00
1	REAR AIR DUCT COVER (N)(ADDITIONAL)	CRACKED	38.00	38.00
	LESS 10% DISCOUNT		-326.30	-326.30
			2,936.70	2,936.70
SPECIAL NETT ITEMS				
1	REAR MIVEC TECHNOLOGY EMBLEM (SN)	NECESSARY	50.00	50.00
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	DENTED	200.00	200.00
1	REAR LUGGAGE PANEL SOUND INSULATION (SN) (ADDITIONAL)	NECESSARY	50.00	50.00
			300.00	300.00
LABOUR				
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING, TO KNOCK DENTS ON REAR FENDER LH & RH, REAR LUGGAGE PANEL, TAIL LAMP PANEL LH & RH AND RENEW OF PARTS.		1,500.00	1,200.00
	TO SPRAY PAINT.		1,300.00	1,200.00
			2,800.00	2,400.00

Report Ref No. CS/FCI18007207/Kqbn2



GRAND TOTAL		6,036.70	5,636.70
RECOMMENDED COST OF REPAIRS			5,636.70

Report Ref No. CS/FCI18007207/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.