



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD  
CO. REG. No.: 1995-01140-D

INSURER: ECICS Limited (HQ)

**PARTICULARS OF CLAIM**

|                     |                 |                       |             |
|---------------------|-----------------|-----------------------|-------------|
| Claim Type:         | OD (OWN DAMAGE) | Ref. No:              |             |
| Policy No:          | MPC17900391101  | Date of Loss:         | 14/04/2018  |
| Vehicle Reg. No.:   | <b>SKP2789E</b> | Driveable?            |             |
| Driver Age/Info:    | 44 / FEMALE     | Party At Fault:       | UNKNOWN     |
| TP Injury Involved? | NO              | Third Party Involved? | YES         |
| Insured/Claimant:   | TAN BOON PENG   | Contact No:           | +6582230665 |
| Driver:             | TAN BOON PENG   |                       |             |

|                               |                                                                    |                    |                   |
|-------------------------------|--------------------------------------------------------------------|--------------------|-------------------|
| Make/Model:                   | VOLKSWAGEN PASSAT, 1.4 TSI (B7) (A)                                | Vehicle Reg. Date: | 18/04/2014        |
| Vehicle Colour:               | BLUE                                                               | Chassis No:        | WVWZZZ3CZFE022341 |
| Engine No:                    | CAXF08206                                                          |                    |                   |
| Odometer:                     | 5 KM                                                               |                    |                   |
| Paint Type:                   |                                                                    |                    |                   |
| Total Loss?                   | <b>NO</b>                                                          |                    |                   |
| Est. Duration of Repair (day) | 6                                                                  |                    |                   |
| Description of Accident/Loss  | REFER TO SKETCH PLANS                                              |                    |                   |
| Remarks:                      | KINDLY ARRANGE OD SURVEY. VEHICLE IN PANDAN WORKSHOP TEL #67795665 |                    |                   |
| Present Location:             | FALCON-AIR AUTO SERVICES PTE LTD (PANDAN)                          |                    |                   |

Tanphn 97445749  
Ev \$ 500  
Revert  
18/4/18 @ 1615  
Resurvey before paint.  
Sur @ 11kauto.com.  
Gedays

**COST OF CLAIMS**

|                          | Amount          |
|--------------------------|-----------------|
| Parts                    | 7,419.50        |
| Miscellaneous Items      | 0.00            |
| Labour                   | 1,750.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>9,169.50</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>641.87</b>   |
| <b>Nett Amount (S\$)</b> | <b>9,811.37</b> |

This claim is handled by: ANDY

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 17 Apr 2018)

**Parts:** 143      VOLKSWAGEN PASSAT 1.4 TSI (B7) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Falcon-Air Auto Services Pte Ltd/SKP2789E/17/04/2018 13:10

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                        | %Disc | %Depr | Amount           |
|-----|-----|----------|------------------------------------|-------|-------|------------------|
| 1   | 1   |          | *BONNET                            | 0.00  | 0.00  | bt ✓ *710.00 F   |
| 2   | 1   |          | *BONNET LOCK                       | 0.00  | 0.00  | ? *135.00 F      |
| 3   | 2   |          | *HEADLAMP LH/RH LH-? RH-orig ✓     | 0.00  | 0.00  | *860.00 F        |
| 4   | 1   |          | *RADIATOR SUPPORT PANEL            | 0.00  | 0.00  | orig ✓ *690.00 F |
| 5   | 1   |          | *FRONT GRILLE                      | 0.00  | 0.00  | orig ✓ *290.00 F |
| 6   | 1   |          | *FRONT GRILLE LOGO                 | 0.00  | 0.00  | orig ✓ *55.00 F  |
| 7   | 1   |          | *FRONT BUMPER CENTRE RETAINER      | 0.00  | 0.00  | de ✓ *85.00 F    |
| 8   | 1   |          | *WIPER WASHER TANK                 | 0.00  | 0.00  | ? *125.00 F      |
| 9   | 1   |          | *WIPER WASHER TANK MOTOR           | 0.00  | 0.00  | mis ✓ *70.00 F   |
| 10  | 2   |          | *FRONT FENDER LH/RH LH-RP, RH-h1 ✓ | 0.00  | 0.00  | *780.00 F        |
| 11  | 1   |          | *AIRGUIDE RH                       | 0.00  | 0.00  | de ✓ *42.00 F    |
| 12  | 1   |          | *FRONT BUMPER                      | 0.00  | 0.00  | de ✓ *760.00 F   |
| 13  | 2   |          | *FRONT BUMPER SIDE RETAINER LH/RH  | 0.00  | 0.00  | orig ✓ *70.00 F  |
| 14  | 1   |          | *FRONT BUMPER REINFORCEMENT        | 0.00  | 0.00  | bt ✓ *395.00 F   |
| 15  | 1   |          | *FRONT BUMPER LOWER BEAM           | 0.00  | 0.00  | bb ✓ *125.00 F   |
| 16  | 1   |          | *FRONT BUMPER LOWER GRILLE CENTRE  | 0.00  | 0.00  | wt ✓ *280.00 F   |
| 17  | 1   |          | *FOG LAMP RH                       | 0.00  | 0.00  | wt ✓ *95.00 F    |
| 18  | 1   |          | *FOG LAMP GARNISH RH               | 0.00  | 0.00  | wt ✓ *125.00 F   |
| 19  | 1   |          | *RH FRONT FENDERSHIELD             | 0.00  | 0.00  | h ✓ *105.00 F    |
| 20  | 1   |          | *HORN                              | 0.00  | 0.00  | ? *88.00 F       |
| 21  | 1   |          | *RADIATOR                          | 0.00  | 0.00  | ? *290.00 F      |
| 22  | 1   |          | *AIRCON CONDENSER                  | 0.00  | 0.00  | ? *470.00 F      |

F=Franchise part.

|                                     |                 |
|-------------------------------------|-----------------|
| Sub Total (\$\$)                    | 6,745.00        |
| + Margin on L,N Items 10.00% (\$\$) | 674.50          |
| <b>Total Parts (\$\$)</b>           | <b>7,419.50</b> |

Falcon-Air Auto Services Pte Ltd/SKP2789E/17/04/2018 13:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

- Tow cover - mis ✓  
- Front number plate - mis ✓

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                                                               | Lab.Type | Amount      |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------|----------|-------------|
| <b>Labour Items</b>     |                                                                                                                           |          |             |
| 1                       | TO FOCUS HEADLAMP CHECK LIGHT SYSTEM                                                                                      | New      | 30.00 ✓     |
| 2                       | TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS                                                                         | New      | 120.00 100  |
| 3                       | TO REMOVE/REPLACE RADIATOR SUPPORT PANEL REPAIR FRONT CHASSIS ,<br>BONNET HINGES INCLUDES KNOCKING & REPLACEMENT OF PARTS | New      | 650.00 550. |
| 4                       | SPRAY PAINTING                                                                                                            | New      | 950.00 800  |
| Gross Labour Cost (S\$) |                                                                                                                           |          | 1,750.00    |

Falcon-Air Auto Services Pte Ltd/SKP2789E/17/04/2018 13:10. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

### FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7852  
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6780-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128225) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg