

ASS. REC. BY:

REF:

CS/CTU18007218 / Stbn2

Special Instruction:

SURVAYOR

Sebastian

ASSIGNMENT (Office)

From (Person):

Trene Tuy

of

CTL

Date/Time:

17042018 423pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 3750P

Insured:

SJD 527Y

at Workshop m/s

Sm Yew Hup

Tel:

6760 0819

of

Blk DH Yew Tee Ind Est 393m

Policy No:

0MPCSN1514191702

Claim No:

SNM1800183802

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI

H.O.D. Endorsement:

Date/Time:

18042018 9:09am

Person Contacted:

Jing Yee

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (☒) Estimate

SJV 3750P - x

SJD 527Y - x

Lump Sum \$4800 (red: 1800', 27%)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TPRES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No.

SJV 3750P

Yr Regn:

25/1/2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

C.C.

1591

Colour

Purple

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Sp. Reading

83754

Eng/No:

G4FC9U799810

C/No:

KMH4U41B2MAH 765535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R 15V

R: 195/65 R 15V

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/4/18

D.O.I.

18/4/18

Survey held at

Sin Yew Hong

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 MAR 2010

Date/Time: File Pass to?

10/5 Typast

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.L: (\$

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18007218/Stb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 18-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 5227Y	Veh. Inspected	SVJ 3750P	
Policy No.	DMPCSN1514191702	Coverage (\$)	0.00	
Claim No.	SNM18D01838C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/04/2018	Inspection Date	18/04/2018	
Survey held at	SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2018 Sendback Est	17 Apr 2018 14:33 S\$6,600.00	17 Apr 2018 16:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	SOH WEN HAN JONATHAN, ID: S8228807D		
Main Claimant:	LOH PENG SOON, ID: S2532382C		
Vehicle Reg. No.:	SJV3750P	Date of Loss:	07/04/2018 00:00 - :59 [98 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01838C02	Policy/Cover Note No.:	DMPCSN1514191702 (Comprehensive)
Vehicle Reg. No. (Insured):	SJQ5227Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2018]		
Adj Asg. Remarks:	EST \$7062, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

MINI Cooper 1.5A 5-Door.

Low Mileage, Agent Maintained,
Warranty Till Nov '18,
Direct Owner. Stand

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

14 vehicles

Hyundai Avante

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Avante	Any	Any	2010	Any	Any	Any	Available
	Hyundai Avante 1.6A	\$21,800	\$9,450 /yr	02-Jan-2010	1,591 cc	-	Sedan	Available
Down Payment \$2.3k Monthly \$796, Showroom Condition, Serviced Regularly, Accident Free, Well Maintained By Retiree Owner, Call Now. Quality Used Cars You Can Trust Only At Choon Bee.								
Posted: 11-Feb-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A S	\$20,800	\$8,540 /yr	25-Jan-2010	1,591 cc	99,000 km	Sedan	Available
1 Lady Owner! Very Well Maintained. Super Low Mileage, An Accident Free. Always Parked Under Shelter. Stylish Yet Spacious To Fit Your Family Size. No Repairs Needed We Deliver Our Promise. Suitable F...								
Posted: 13-Apr-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A	\$22,000	\$9,200 /yr	26-Jan-2010	1,591 cc	170,000 km	Sedan	Available
Well Maintained By Previous Owners! Smooth And Quiet Engine, Clean And Neat Interior, First Owner, Car In Good Working Condition. Well Maintained Through Regular Servicing Over The Years. No Major Pro...								
Carro								
Posted: 13-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A S	\$21,800	\$8,410 /yr	16-Mar-2010	1,591 cc	-	Sedan	Available
(New Arrived Buy With Confidence!), Low Mileage Unit, Come With 6 Months Engine And Gearbox Warranty, All Our Quality Preowned Car Are Selling At Low Depreciation Price. STA/VICOM/AA Are Welcome, Bank...								
Car World Automobile								
Posted: 14-Apr-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
Car Buying	Car Selling	Car Ownership		Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation				
Car Aftermarket	On The Move	Lifestyle						
	Hyundai Avante 1.6A S	\$20,888	\$7,930 /yr	16-Mar-2010	1,591 cc	-	Sedan	Available
Nice Silver Color. New Paint Job.								
Posted: 17-Feb-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A	\$19,800	\$7,260 /yr	27-Mar-2010	1,591 cc	146,604 km	Sedan	Available
10% Down Payment. \$820 /Month. Good Condition. Flexible Loan Package. Instant Approval, Ex Bankrupt Welcome. High Trade In.								
Posted: 19-Mar-2018 Tags: 2010 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A S	\$23,800	\$9,040 /yr	12-May-2010	1,591 cc	-	Sedan	Available

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2382C
Vehicle Details	
Vehicle No.:	SJV3750P
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9U799810
Chassis No.:	KMHDU41BMAU965535
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,422.00
Original Registration Date:	25 Jan 2010
First Registration Date:	25 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$11,422.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2020
PARF Rebate Amount:	\$6,282.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$1,509.00
COE Rebate Amount:	\$264.00
Total Rebate Amount:	\$6,546.00

The information contained herein is correct as at 19 Apr 2018

OK



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapi@singnet.com.sg

Ce./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/04/2018
Vehicle Reg. No.:	SJV3750P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH PENG SOON		
Make/Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	25/01/2010
Vehicle Colour:	PURPLE	Chassis No:	KMH DU41BMAU965535
Engine No:	G4FC9U799810		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE DOCUMENT ATTACHED.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	3,630.00
Miscellaneous Items	0.00
Labour	2,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,600.00
+ GST 7.00% (\$\$)	462.00
Nett Amount (\$\$)	7,062.00

This claim is handled by: LIM JING YEE

Generated using Merimen e-Claims Internet Estimation & Adjusting System



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677961

Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

car. No. 2009210705 Specialise in Insurance Claims and General Motor Repair Work.

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/04/2018
Vehicle Reg. No.:	SJV3750P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOH PENG SOON		
Make/Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	25/01/2010
Vehicle Colour:	PURPLE	Chassis No:	KMH DU41BMAU965535
Engine No:	G4FC9U799810		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE DOCUMENT ATTACHED.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,630.00
Miscellaneous Items	0.00
Labour	2,970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,600.00
+ GST 7.00% (S\$)	462.00
Nett Amount (S\$)	7,062.00

This claim is handled by: LIM JING YEE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

RÉPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2018)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAIL LAMP ✓ SCR	0.00	0.00	*125.00 F ✓
2	1		*REAR BUMPER ✓ Deform.	0.00	0.00	*300.00 F ✓
3	1		*REAR BUMPER REINFORCEMENT ? ✓ CRK	0.00	0.00	*145.00 F ✓
4	1		*REAR BUMPER SPONGE ? ✓ CRK	0.00	0.00	*55.00 F ✓
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH ? NM	0.00	0.00	*55.00 F ✓
6	1		*REAR BUMPER REINFORCEMENT SIDE BRACKET TOP RH ? NM	0.00	0.00	*20.00 F ✓
7	1		*REAR BUMPER SIDE RETAINER RH ✓ NEC	0.00	0.00	*20.00 F ✓
8	1		*REAR FENDER RH ✓ DT	0.00	0.00	*625.00 F ✓
9	1		*REAR FENDER INNER SHIELD RH ? Deform	0.00	0.00	*15.00 F ✓
10	1		*REAR FENDER INNER TRIM ? ✓ TN	0.00	0.00	*125.00 F ✓
11	1		*QUARTER GLASS MOULDING ✓ NEC	0.00	0.00	*130.00 F ✓
12	1		*QUARTER GLASS SEALANT ✓ NEC	0	0.00	*40.00 FS ✓
13	1		*QUARTER GLASS INNERSEAL ✓ NEC	0	0.00	*20.00 FS ✓
14	1		*REAR WINDSCREEN MOULDING ✓ NEC	0.00	0.00	*55.00 F ✓
15	1		*REAR WINDSCREEN SEALANT ✓ NEC	0	0.00	*40.00 FS ✓
16	1		*REAR WINDSCREEN INNERSEAL ✓ NEC	0	0.00	*20.00 FS ✓
17	1		*REAR SHOCK ABSORBER RH ? ✓ BT	0.00	0.00	*155.00 F ✓
18	1		*KNUCKLE ? ✓ BT	0.00	0.00	*325.00 F ✓
19	1		*KNUCKLE BEARING ? ✓ DMG	0.00	0.00	*145.00 F ✓
20	1		*SPORT RIM ✓ CRK	0.00	0.00	*650.00 F ✓
21	1		*TYRE ✓ CRK 70%	0	0.00	*200.00 FS ✓ 140
22	1		*LOGO AVANTE ✓ NEC	0.00	0.00	*15.00 F ✓
23	1		*LOGO HYUNDAI ✓ NEC	0.00	0.00	*25.00 F ✓
24	1		*LOGO S ✓ NEC	0.00	0.00	*55.00 F ✓
25	1		*TRAILING ARM TOP ARM ? ✓ BT	0.00	0.00	*85.00 F ✓
26	1		*TRAILING ARM LOWER ARM ? ✓ BT	0.00	0.00	*185.00 F ✓

F=Franchise part. S=SpcNett.

Total Parts (S\$)

3,630.00

Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00 ✓
2	TO REMOVE AND REFIT FENDER INNER TRIM, REAR END PANEL GARNISH, REAR CUSHION SEAT, SPEAKER BOX, SIDE GARNISH X2	New	140 160.00
3	TO REMOVE AND REFIT QUARTER GLASS	New	40 60.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	200 250.00
5	TO CHECK WHEEL ALIGNMENT X2	New	120 60.00 ✓
6	TO ANTIRUST THE AFFECTED PORTION	New	80 120.00
7	TO PUTTY AND SPRAY PAINT FENDER IN AND OUT, REAR BOOT, REAR BUMPER, REAR END PANEL, FLOOR PANEL	New	800 1,000.00
8	TO REMOVE AND REFIT TAIL LAMP RH, REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR BUMPER SPONGE, REAR BUMPER REINFORCEMENT BRACKET, CUT AND WELD REAR FENDER RH, PANEL BEAT REAR END PANEL, FLOOR PANEL	New	1000 1,200.00
Gross Labour Cost (S\$)			2,970.00

Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8 days

Sebastian
18/4/18.

- Lmp Smr Repair.
- Question Mark Item Photo
- Photo After Paint

90036121

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2018)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAIL LAMP ✓ SCR	0.00	0.00	*125.00 F
2	1		*REAR BUMPER ✓ Deform.	0.00	0.00	*300.00 F
3	1		*REAR BUMPER REINFORCEMENT ? ✓ CRK	0.00	0.00	*145.00 F
4	1		*REAR BUMPER SPONGE ? ✓ CRK	0.00	0.00	*55.00 F
5	1		*REAR BUMPER REINFORCEMENT-BRACKET RH ? X	0.00	0.00	*55.00 F n
6	1		*REAR BUMPER REINFORCEMENT-SIDE-BRACKET-TOP RH ? X	0.00	0.00	*20.00 F n
7	1		*REAR BUMPER SIDE RETAINER RH ✓ NEC	0.00	0.00	*20.00 F
8	1		*REAR FENDER RH ✓ DT	0.00	0.00	*625.00 F
9	1		*REAR FENDER INNER SHIELD RH ? ✓ Deform	0.00	0.00	*15.00 F
10	1		*REAR FENDER INNER TRIM ? ✓	0.00	0.00	*125.00 F
11	1		*QUARTER GLASS MOULDING ✓ NEC	0.00	0.00	*130.00 F
12	1		*QUARTER GLASS SEALANT ✓ NEC	0	0.00	*40.00 FS
13	1		*QUARTER GLASS INNERSEAL ✓ NEC	0	0.00	*20.00 FS
14	1		*REAR WINDSCREEN MOULDING ✓ NEC	0.00	0.00	*55.00 F
15	1		*REAR WINDSCREEN SEALANT ✓ NEC	0	0.00	*40.00 FS
16	1		*REAR WINDSCREEN INNERSEAL ✓ NEC	0	0.00	*20.00 FS
17	1		*REAR SHOCK ABSORBER RH ? ✓ BT	0.00	0.00	*155.00 F
18	1		*KNUCKLE ? ✓ BT	0.00	0.00	*325.00 F
19	1		*KNUCKLE BEARING ? ✓ DMG.	0.00	0.00	*145.00 F
20	1		*SPORT RIM ✓ Cut	0.00	0.00	*650.00 F
21	1		*TYRE ✓ Cut 70%	0	0.00	*200.00 FS-140
22	1		*LOGO AVANTE ✓ NEC	0.00	0.00	*15.00 F
23	1		*LOGO HYUNDAI ✓ NEC	0.00	0.00	*25.00 F
24	1		*LOGO S ✓ NEC	0.00	0.00	*55.00 F
25	1		*TRAILING ARM TOP ARM ? ✓ BT	0.00	0.00	*85.00 F
26	1		*TRAILING ARM LOWER ARM ? ✓ BT	0.00	0.00	*185.00 F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 3,495.00 3,630.00

Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Sebastian

re survey

19/04/18

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00 ✓
2	TO REMOVE AND REFIT FENDER INNER TRIM, REAR END PANEL GARNISH, REAR CUSHION SEAT, SPEAKER BOX, SIDE GARNISH X2	New	140 160.00
3	TO REMOVE AND REFIT QUARTER GLASS	New	40 60.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	200 250.00
5	TO CHECK WHEEL ALIGNMENT X2	New	120 60.00 ✓
6	TO ANTIRUST THE AFFECTED PORTION	New	80 120.00
7	TO PUTTY AND SPRAY PAINT FENDER IN AND OUT, REAR BOOT, REAR BUMPER, REAR END PANEL, FLOOR PANEL	New	800 1,600.00
8	TO REMOVE AND REFIT TAIL LAMP RH, REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR BUMPER SPONGE, REAR BUMPER REINFORCEMENT BRACKET, CUT AND WELD REAR FENDER RH, PANEL BEAT REAR END PANEL, FLOOR PANEL	New	1000 1,200.00
Gross Labour Cost (S\$)			2,500 2,970.00

Sin Yew Hup Auto Pte Ltd/SJV3750P/17/04/2018 14:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Total part 3,495.00

Labour : 2,500.00

5,995.00

1/p 20% 1,199.00

4,796.00

~ 4,800.00 #

Sebastian
18/4/18.

- Imp Sum Repair.

- Question Mark Item
Photo

- Photo After Paint

9003612.1

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastianyeang@lkkauto.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18007218/STBN2

Date: 11/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1514191702
Claimant Vehicle No :	SJV3750P	Insured Vehicle No :	SJQ5227Y
Date of Loss:	07/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01838C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV3750P	Engine No:	G4FC9U799810
Make & Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Chassis No:	KMH DU41BMAU965535
Reg. Date:	25/01/2010 (Man. Year: 2009)	Odometer:	83754 km
Colour:	Purple		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15V	Rear Tyre Size:	195/65 R15V
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,630.00	3,495.00	135.00	3.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	2,500.00	470.00	15.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,600.00	5,995.00	605.00	9.17
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	6,600.00	4,800.00	1,800.00	27.27
+ GST 7.00/7.00% (\$\$)	462.00	336.00	126.00	27.27
Nett Amount (\$\$)	7,062.00	5,136.00	1,926.00	27.27

INSPECTION

Date of Assignment:	17/04/2018	Present Location:	Sin Yew Hup Auto Pte Ltd (HQ)
Date Inspected:	18/04/2018	Inspected At:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate Singapore 677981

Estimated Period of Repair: 8.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2018)
Parts:	143	HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV3750P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP	Scratched	125.00 F	*125.00 F
2	1		*REAR BUMPER	Deformed	300.00 F	*300.00 F
3	1		*REAR BUMPER REINFORCEMENT	Cracked	145.00 F	*145.00 F
4	1		*REAR BUMPER SPONGE	Cracked	55.00 F	*55.00 F
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	55.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT SIDE BRACKET TOP RH	Not Necessary	20.00 F	*- F
7	1		*REAR BUMPER SIDE RETAINER RH	Necessary	20.00 F	*20.00 F
8	1		*REAR FENDER RH	Dented	625.00 F	*625.00 F
9	1		*REAR FENDER INNER SHIELD RH	Deformed	15.00 F	*15.00 F
10	1		*REAR FENDER INNER TRIM	Torn	125.00 F	*125.00 F
11	1		*QUARTER GLASS MOULDING	Necessary	130.00 F	*130.00 F
12	1		*QUARTER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*QUARTER GLASS INNERSEAL	Necessary	20.00 FS	*20.00 FS
14	1		*REAR WINDSCREEN MOULDING	Necessary	55.00 F	*55.00 F
15	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR WINDSCREEN INNERSEAL	Necessary	20.00 FS	*20.00 FS
17	1		*REAR SHOCK ABSORBER RH	Bent	155.00 F	*155.00 F
18	1		*KNUCKLE	Bent	325.00 F	*325.00 F
19	1		*KNUCKLE BEARING	Damaged	145.00 F	*145.00 F
20	1		*SPORT RIM	Cut	650.00 F	*650.00 F
21	1		*TYRE (70%)	Cut	200.00 FS	*140.00 FS
22	1		*LOGO AVANTE	Necessary	15.00 F	*15.00 F
23	1		*LOGO HYUNDAI	Necessary	25.00 F	*25.00 F
24	1		*LOGO S	Necessary	55.00 F	*55.00 F
25	1		*TRAILING ARM TOP ARM	Bent	85.00 F	*85.00 F
26	1		*TRAILING ARM LOWER ARM	Bent	185.00 F	*185.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,630.00** **3,495.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REFIT FENDER INNER TRIM, REAR END PANEL GARNISH, REAR CUSHION SEAT, SPEAKER BOX, SIDE GARNISH X2	New	160.00	140.00
3	TO REMOVE AND REFIT QUARTER GLASS	New	60.00	40.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	250.00	200.00
5	TO CHECK WHEEL ALIGNMENT	New	60.00	120.00
6	TO ANTIRUST THE AFFECTED PORTION	New	120.00	80.00
7	TO PUTTY AND SPRAY PAINT FENDER IN AND OUT, REAR BOOT, REAR BUMPER, REAR END PANEL, FLOOR PANEL	New	1,000.00	800.00
8	TO REMOVE AND REFIT TAIL LAMP RH, REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR BUMPER SPONGE, REAR BUMPER REINFORCEMENT BRACKET, CUT AND WELD REAR FENDER RH, PANEL BEAT REAR END PANEL, FLOOR PANEL	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			2,970.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >