

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/114/2018
DATE : 14-APR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : ANG REI-WAN,KAREN(HONG RUIWAN,KAREN)
ADDRESS : 6 DOVER RISE
#17-08
S(138678)
TELEPHONE NO : 9005 2122

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SKQ1054T
MODEL CODE : GP3RKEC
MODEL/YEAR : SUBARU XV 1.6I AWD CVT
ENGINE NO : FB161451182(5Y100K)
CHASSIS NO : JF1GP3KC5EG146518(*)
MILEAGE : 1 KM
DATE IN : 14/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 14/04/2018

Print Date : 16/04/2018
Print Time : 10:19:20

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ1054T

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	GASKET RM	44011AE010	24.00	na /		
2	MUFFLER AY	44300FJ040	576.00	BT /		
3	FLOOR PAN R	CKD-XV 52129FJ0009P	540.00	R		
4	REAR END PANEL	52401FJ0009P	288.00	na R		
5	BUMPER FACE R XUV	57704FJ041	594.00	DE -		
6	BRKT RRH BUMP	57707FJ160	14.40	na /		
7	BRKT RLH BUMP	57707FJ170	14.40	na /		
8	BEAM COMPL R EU	57711FJ0229P	259.20	BT /		
9	COVER-REAR BUMPER	57731FG010I6	14.40	na		
10	LENS & BODY-R COMBI LAMP RH	84912FJ040	377.40	?		
11	LENS & BODY-FOG LIGHT,REAR	84913FG420	102.00	?		
12	ORNAMENT ASSY F SIX	91174SA005	75.60	na /		
13	LETTER MARK-REAR	93079FJ060	68.00	na /		
14	LETTER MARK-REAR	93079FJ100	40.80	na /		
SUB TOTAL			2988.20	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			597.64	0.00	0.00	0.00
GRAND TOTAL			2390.56	0.00	0.00	0.00
OVERALL TOTAL			2390.56			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKQ1054T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER,BRKT BUMPER,BUMPER BEAM AND EXHAUST	2900.00	1400
2	ZZ/002	RESPRAY TAILGATE,REAR BUMPER,END PANEL,SPARE TYRE PAN	1920.00	1380
3	ZZ/003	SUNDRIES	100.00	20
TOTAL LABOUR CHARGES			4920.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKQ1054T

TOTAL LABOUR CHARGES	4920.00
TOTAL SPARE PARTS CHARGES	2390.56
GRAND TOTAL	7310.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 900 100 68
SURVEYED DATE	:	20/04/18 @ 1610
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 6 days
LIABILITY	:	0.00
REMARKS	:	Resurvey 64 panel

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: