

2000/0000

ASS. REC. BY:

REF:

CS/ED18007238 / Av ber

Special Instruction:

SAVVOY
Merimen

Admin

ASSIGNMENT (Office)

From (Person): Joel Goh

of

ED1

Date/Time: 18042018 425pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 6865B

Insured:

at Workshop in/s

Progressive Automotive

Tel:

6741 5336

of

Blk 302A Ubi Rd 1 #01-45/46

Policy No:

DMCPH218-000643

Claim No:

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

16042018

(Client's Record)

24042018 @ 9:30am - 12pm

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18042018 558pm

Person Contacted:

Pai Wen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 6865B - x

25/4/18

Revert by merimen

25/4/18

Rare approved from Joel Goh by merimen

25/4/18

@ 957am Informed Ray c/A ex \$500

24/5/18

Final fig \$ 5145 confirmed by email (Ref 649143, 5613)

REF: EQ1

ASSIGNMENT

From: Date: 24042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 6865B

at Workshop n/s:

of Blk 3022A Ubi Rd 1 # 01-45

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$ 500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection,

Bal. or Market Value: 65K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBF6865B. Yr Regn: 2017 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna. cc 2982

Colour: Blue. A/C: Insured / Std / NI / NA

Sp. Reading: 46640. Ti/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KDY2318024583

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/75R15C

R: 145 R13.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal: 06 mm

L/Bal: 06 mm

D.O.A. D.O.I 24/04/18

Survey held at Progressive

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

OD EQ.

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report

ii)

☐ : Final Report

Date/Time, File Return to?

24/5- typist

Report Format: merimen

Lump Sum / I.B.E: 5145/2

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Insp (\$)☐ : Workshop (\$)

Survey Fee

Transportation

I. S + R. S.

Phone

Fax

TOTAL

230

230



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI18007238/Avb

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-04-2018



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBF 6865B
Policy No.	DMCPHQ18-000643	Coverage (\$)	0.00
Claim No.		Excess (\$)	500.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	18/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/04/2018	Inspection Date	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 14:24 Sendback Est	18 Apr 2018 14:35 \$511,003.93	18 Apr 2018 16:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HARCO ENGINEERING PTE LTD, Co. Reg. No.: 198303544E		
Vehicle Reg. No.:	GBF6865B	Date of Loss:	16/04/2018 17:00 - :59 [14 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	DMCPHQ18-000643 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Bldg 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... (Handled by Joel Goh)		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/04/2018]		
Driver/Custodian:	THOZAPPAN JAYABAL (), NRIC: G7797963N		
Adj Ass. Remarks:	EXCESS: \$500.00 NO WAIVER SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 25 April 2018 10:03 AM
To: peiwen@progauto.com.sg
Cc: SUR; Ray Progressive
Subject: GBF 6865B-DOA: 16/4/2018 (EQI OD)

Dear Pei Wen,

As instructed by our client EQI , please proceed to repair the insured vehicle **GBF 6865B (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

GBF6865B (DM18HO01009-JG)

OD

Apr 16 2018 5:00PM

[HARCO ENGINEERING PTE LTD]

Progressive Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on 25/04/2018 09:28 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9785.93) - GBF6865B - Claim Handler: Joel Goh

Approved:9785.93.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 25 Apr 2018

Preliminary Advice

Vehicle No	: GBF6865B	Accident Date	: 16/04/2018
Make	: TOYOTA DYNA 150 D	Policy No.	: DMCPHQ18-000643
Assignment Date	: 18/04/2018	Excess	: S\$500.00
Date of Inspection	: 24/04/2018	Est. Duration of Repair	: 8.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,003.93
Revised Amount	:S\$	5,158.00
Check Items (Estimated)	:S\$	4,627.93
Total	:S\$	9,785.93

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	35,821.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,179.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3544E
Vehicle Details	
Vehicle No.:	GBF6865B
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 M
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	1KD2609762
Chassis No.:	KDY2318024583
Maximum Power Output:	-
Open Market Value:	\$32,824.00
Original Registration Date:	09 Feb 2017
First Registration Date:	09 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$1,642.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$40,753.00
COE Rebate Amount:	\$35,821.00
Total Rebate Amount:	\$35,821.00

The information contained herein is correct as at 25 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 13:47
Date Of Accident	16/04/2018 17:40
Exact Location Of Accident	ALONG LENTOR AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF6865B
Insured/Policyholder	
Name Of Registered Owner	HARCO ENGINEERING PTE LTD
Co Reg No	198303544E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97787142
Alternative Phone No	OFFICE-97787142

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 3.0 M
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-000643
Cover Note Number	

Driver

Name of Driver	THOZAPPAN JAYABAL
Passport No/FIN	G7797963N
Date Of Birth	07/06/1978
Occupation	OUTDOOR
Date Of Driving Pass	12/11/2014
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97787142
Fax Number	
Contact Number	
EMail Address	HARCO@SINGNET.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : P1
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving along Lentor Ave making a U-turn. I waited for traffic on my left to clear before U-turning. After checking traffic was clear, I proceed to U-turn into the right lane of the 3 lane road. As I was turning, I noticed from my left side mirror a fast approaching vehicle on the center lane swerved across into my lane. I then turned my steering wheel to the right and my vehicle hit onto the side road curb and went into the drain. Damages to my vehicle were on the front right portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	ROAD SIDE CURB
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Bin Pabla

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving along Lentor Ave making a U-turn. I waited for traffic on my left to clear before U-turning. After checking traffic was clear, i proceed to U-turn into the right lane of the 3 lane road. As i was turning, i noticed from my left side mirror a fast approaching vehicle on the centre lane swerved across into my lane. I then turned my steering wheel to the right and my vehicle hit onto the side road curb and went into the drain. Damages to my vehicle were on the front right portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 April 2018 at 1:02 PM

Date/Time:

17 April 2018 at 1:02 PM



PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0418-6448
Policy No:	DMCPHQ18-000643	Date of Loss:	16/04/2018
Vehicle Reg. No.:	GBF6865B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HARCO ENGINEERING PTE LTD		
Driver:	THOZAPPAN JAYABAL		

Make/Model:	TOYOTA DYNA 150 D, 3.0 D (M)	Vehicle Reg. Date:	09/02/2017
Vehicle Colour:	BLUE		
Engine No:	1KD2609762	Chassis No:	KDY2318024583
Odometer:	46292 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	HIT SIDE ROAD KERB
Remarks:	VEHICLE IS NOT IN WORKSHOP
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	7,278.93
Miscellaneous Items	595.00
Labour	2,180.00
Paintwork Labour	950.00
Towing	0.00
Gross Total (S\$)	11,003.93
+ GST 7.00% (S\$)	770.28
Nett Amount (S\$)	11,774.21

This claim is handled by: **NG PEI WEN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Apr 2018)

Parts: N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT WINDSCREEN PILLAR; OUTER - RH <i>Sealed</i>	0.00	0.00	*170.00 F ✓
2	1	NA	*FRONT WINDSCREEN PILLAR; INNER - RH <i>Repair</i>	0.00	0.00	*130.00 F +
3	1	NA	*CORNER PANEL - RH <i>Repair</i>	0.00	0.00	*75.00 F +
4	1	NA	*FRONT GRILLE <i>Missing</i>	0.00	0.00	*350.00 F ✓
5	1	NA	*FRONT GRILLE LOGO <i>Missing</i>	0.00	0.00	*40.00 F ✓
6	8	NA	*FRONT GRILLE CLIP - WHITE <i>for new</i>	0.00	0.00	*20.00 F ✓
7	8	NA	*FRONT GRILLE CLIP - BLACK <i>for new</i>	0.00	0.00	*20.00 F ✓
8	1	NA	*FRONT BUMPER <i>Best</i>	0.00	0.00	*250.00 F ✓
9	1	NA	*FRONT BUMPER REINFORCEMENT <i>Not New</i>	0.00	0.00	*100.00 F ? X
10	1	NA	*FRONT BUMPER BRACKET - RH <i>Best</i>	0.00	0.00	*95.00 F ✓
11	1	NA	*FRONT BUMPER FOG LAMP - RH <i>at</i>	0.00	0.00	*110.00 F ✓
12	1	NA	*FRONT BUMPER FOG LAMP COVER - RH <i>at</i>	0.00	0.00	*50.00 F ✓
13	2	NA	*HEAD LAMP ASSY - RH <i>cracked</i>	0.00	0.00	*350.00 F ✓
14	1	NA	*HEAD LAMP LOWER RUBBER - RH <i>at</i>	0.00	0.00	*15.00 F X X
15	1	NA	*FRONT DOOR - RH <i>Distorted</i>	0.00	0.00	*560.00 F ✓
16	1	NA	*FRONT DOOR RUBBER - RH <i>at</i>	0.00	0.00	*80.00 F ✓
17	1	NA	*FRONT DOOR HINGE; TOP - RH <i>are new</i>	0.00	0.00	*50.00 F + X
18	1	NA	*FRONT DOOR HINGE; LOWER - RH <i>Best</i>	0.00	0.00	*50.00 F ✓
19	1	NA	*FRONT DOOR SIGNAL LAMP - RH <i>cracked</i>	0.00	0.00	*35.00 F ✓
20	1	NA	*FRONT DOOR LOCK - RH <i>for new</i>	0.00	0.00	*130.00 F X X
21	1	NA	*FRONT DOOR EYE - RH <i>for new</i>	0.00	0.00	*70.00 F X X
22	1	NA	*FRONT DOOR STEP GARNISH - RH <i>missing</i>	0.00	0.00	*90.00 F ✓
23	1	NA	*FRONT DOOR BOARD - RH <i>Not New</i>	0.00	0.00	*380.00 F ?
24	1	NA	*FRONT DOOR REGULATOR GEAR - RH <i>Not New</i>	0.00	0.00	*105.00 F ?
25	1	NA	*FRONT DOOR REGULATOR GEAR MOTOR - RH <i>Not New</i>	0.00	0.00	*210.00 F ?
26	1	NA	*FRONT ABSORBER - RH <i>for new</i>	0.00	0.00	*55.00 F ?
27	1	NA	*FRONT LOWER ARM - RH <i>for new</i>	0.00	0.00	*190.00 F ?
28	1	NA	*FRONT TOP ARM - RH <i>for new</i>	0.00	0.00	*420.00 F ?
29	1	NA	*FRONT KNUCKLE ARM - RH <i>for new</i>	0.00	0.00	*350.00 F ?
30	1	NA	*FRONT KNUCKLER ARM BEARING - RH <i>for new</i>	0.00	0.00	*65.00 F ?
31	1	NA	*FRONT STAY LINK - RH - NO STOCK <i>for new</i>	0.00	0.00	*79.20 F ?
32	1	NA	*FRONT CROSSMEMBER - NO STOCK <i>for new</i>	0.00	0.00	*1,635.30 F ?

F=Franchise part.

Sub Total (S\$)	6,329.50
+ Margin on L,N Items 15.00% (S\$)	949.43
Total Parts (S\$)	7,278.93

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

- Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT DOOR COMPANY STICKER - RH <i>New</i>	30.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>Carb</i>	35.00 ✓
3	1	FRONT TYRE - RH <i>2pc new</i>	280.00 X
4	1	FRONT TYRE RIM	250.00 X
Sub Total (S\$)			595.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00 <i>800</i>
Labour Items			
2	TO KNOCK OUT DENTS; RH FRONT FLOOR PANEL; RH FRONT WHEEL ARCH PANEL; RH CHASSIS; CUT/WELD; RH FRONT DOOR PILLAR; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 <i>800</i>
3	TO CHECK WIRING	New	20.00 ✓
4	TO REMOVE; REFIX DASHBOARD	New	X 300.00 <i>250</i>
5	TO REMOVE; REFIX FRONT WINDSCREEN	New	120.00 <i>100</i>
6	TO 4 WHEEL ALIGNMENT	New	60.00 ✓
7	TO TRANSFER DOOR AND DOOR FITTING	New	80.00 ✓
8	TO REMOVE; REPLACE FRONT UNDERCARRIAGE AND FRONT CROSSMEMBER	New	X 500.00 X
Gross Labour Cost (S\$)			3,130.00

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
7/7 24/04/18

08 Days.

Excess \$800

Not Authorised.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 May 2018)

Parts: N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF6865B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE RUBBER <i>Missing</i>	0.00	0.00	*25.00 F ✓
2	1		*DOOR RUBBER - RH <i>at</i>	0.00	0.00	*45.00 F ✓
3	1		*VACUUM PUMP <i>sent</i>	0.00	0.00	*130.00 F ✓
Sub Total (S\$)						200.00
+ Margin on L,N Items 15.00% (S\$)						30.00
Total Parts (S\$)						230.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Adrian Lij
03/05/18
888

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 24 May 2018 9:16 AM
To: 'Ray Progressive'
Cc: 'Wayne Lim'; msho@progauto.com.sg; 'Peiwen PROGAUTO';
siewwei@progauto.com.sg; SUR
Subject: RE: GBF6865B - TO FINALIZE

Dear Ray,

Confirmed \$5145 before excess \$500 and GST @ 8 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [mailto:ray@progauto.com.sg]
Sent: Wednesday, 23 May 2018 4:21 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: 'Wayne Lim' <wayne@progauto.com.sg>; msho@progauto.com.sg; 'Peiwen PROGAUTO'
<peiwen@progauto.com.sg>; siewwei@progauto.com.sg
Subject: GBF6865B - TO FINALIZE

Hi Adrian/ Veron,

Please refer to finalize

Supp	\$230.00
Parts	\$2990.00
Sn	\$65.00
Lab	\$1860.00
Total	\$5145.00

Thank you

Best regard,

Ray

Progressive Automotive Pte Ltd

Tel: 6741-5336 Fax: 6741-7208

REPAIR DETAILS

Reference

Part Source: Last Synchronised: 18 Apr 2018
 Parts: 18A 10YOTA DYNIA 150 D 3.0 D (M) (Model not available in database)
 Labour: Repetitive Price-Standardised Standard List
 Print Code: Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, marking page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk

006448

Estimates on Parts

No	Qty	Part No	Particulars	Disc	Adapt	Amount	
1	1		FRONT WINDSCREEN PILLAR OUTER - RH			5,100	✓
2	1		FRONT WINDSCREEN PILLAR INNER - RH			5,100	✓
3	1		CORNER PANEL - RH			5,100	✓
4	1		FRONT GRILLE			5,100	✓
5	1		FRONT GRILLE LOGO			5,100	✓
6	1		FRONT GRILLE CLIP - WHITE			5,100	✓
7	1		FRONT GRILLE CLIP - BLACK			5,100	✓
8	1		FRONT BUMPER			14,100	✓
9	1		FRONT BUMPER REINFORCEMENT			5,100	✓
10	1		FRONT BUMPER BRACKET - RH			5,100	✓
11	1		FRONT BUMPER FOR LAMP - RH			5,100	✓
12	1		FRONT BUMPER FOR LAMP COVER - RH			5,100	✓
13	2		HEAD LAMP ASSY - RH - LH/RH		700	54,000	✓
14	1		HEAD LAMP LOWER RUBBER - RH			5,100	✓
15	1		FRONT DOOR - RH			54,000	✓
16	1		FRONT DOOR RUBBER - RH			5,100	✓
17	1		FRONT DOOR HINGE - TOP - RH			5,100	✓
18	1		FRONT DOOR HINGE - LOWER - RH			5,100	✓
19	1		FRONT DOOR SIGNAL LAMP - RH			5,100	✓
20	1		FRONT DOOR LOCK - RH			5,100	✓
21	1		FRONT DOOR EYE - RH			5,100	✓
22	1		FRONT DOOR STEP GARNISH - RH			5,100	✓
23	1		FRONT DOOR BOARD - RH			5,100	✓
24	1		FRONT DOOR REGULATOR - TOP - RH			5,100	✓
25	1		FRONT DOOR REGULATOR - GEAR - RH			5,100	✓
26	1		FRONT ABSORBER - RH			5,100	✓
27	1		FRONT LOWER ARM - RH			5,100	✓
28	1		FRONT TOP ARM - RH			5,100	✓
29	1		FRONT KNUCKLE ARM - RH			5,100	✓
30	1		FRONT KNUCKLE ARM BEARING - RH			5,100	✓
31	1		FRONT STRUT - RH - NO STOCK			5,100	✓
32	1		FRONT CROSSMEMBER - NO STOCK			5,100	✓

Sub Total: 329.50
 GST: 19.17
 Total Price (GST): 348.67

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35 Not valid without Reference section
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT DOOR COMPANY STICKER - RH <i>New</i>	30.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>Cracked</i>	35.00 ✓
3	1	FRONT TYRE - RH <i>2nd run</i>	280.00 X
4	1	FRONT TYRE RIM	250.00 X
Sub Total (S\$)			595.00 <i>65</i>

006448

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00 <i>800</i>
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; RH FRONT FLOOR PANEL; RH FRONT WHEEL ARCH PANEL; RH CHASSIS; CUT/WELD; RH FRONT DOOR PILLAR; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 <i>800</i>
3	TO CHECK WIRING	New	30.00 ✓
4	TO REMOVE, REFIX DASHBOARD	New	300.00 <i>2</i>
5	TO REMOVE, REFIX FRONT WINDSCREEN	New	120.00 <i>100</i>
6	TO 4 WHEEL ALIGNMENT	New	60.00 ✓
7	TO TRANSFER DOOR AND DOOR FITTING	New	80.00 ✓
8	TO REMOVE, REPLACE FRONT UNDERCARRIAGE AND FRONT CROSSMEMBER	New	950.00
Gross Labour Cost (S\$)			3,130.00 <i>1860</i>

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35 Not valid without Reference section

Generated using Merimen e-Claims IEAS

END OF ESTIMATES

This is a computer generated estimate and is valid for 30 days from the date of issue. It is not valid for use as a receipt. It is not valid for use as a receipt. It is not valid for use as a receipt.

Adrian Lim
7/2 24/04/18

08 Days.

Excess \$800

Not Authorised.

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 03 May 2018)

Parts: N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF68658)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

00 6448

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE RUBBER <i>Missing</i>	0.00	0.00	*25.00 F
2	1		*DOOR RUBBER - RH <i>at</i>	0.00	0.00	*45.00 F
3	1		*VACUUM PUMP <i>Best</i>	0.00	0.00	*130.00 F
Sub Total (S\$)						200.00
+ Margin on L,N Items 15.00% (S\$)						30.00
Total Parts (S\$)						230.00 <i>230</i>

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

SUPP >30.00

PARTS >990.00

SN 65.00

LAB. 1860.00

5145.00

Adrian Lij
03/05/18
888



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

WIPERBLADE BLADE
Dept Direct: 6417 9701 / 6743 9928



Dept Direct: 6205 9919

Dept Direct: 6325 9911

Dept Direct: 6417 9702



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blades: HWD (Japan Wiper blades), Siiper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-01051

DATE : 03/05/2018

CUSTOMER ID : PRO005

VEH REG. NO. : GBF6865B

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T67863-37010/1 KDY2231 LY235	DOOR RUBBER RH NO.2	U1 L2-C11-B	1	45.00	45.00

SUB-TOTAL : 45.00

ADD GST 7.00 % 3.15

E. & O.E

TOTAL AMOUNT SGD : 48.15

[P] 03/05/2018 10:17:39

[E] 03/05/2018 10:17:20AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN :

OP 6448

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6718 2333



Dept Direct: 6501 6618

Dept Direct: 6008 5611

Dept Direct: 6417 9722

TOYOTA

LEXUS

SAATCHI



Dept Direct: 6417 9724

Dept Direct: 6417 9723

Dept Direct: 6417 9796

Dept Direct: 6417 9723

Wiper blade: NNG (Nippon Wiper blade), Silex (Made in Korea),
Foron (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-00640
DATE : 02/05/2018
CUSTOMER ID : PRO005
VEH REG. NO. : GBF6865B
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCK ID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. T44704-25160 KDY231	VACCUUM PUMP RESERVOIR	U1 SUPPLIER	1	130.00	130.00

SUB-TOTAL : 130.00
ADD GST 7.00 % 9.10

E. & O.E TOTAL AMOUNT SGD : 139.10

[P] 02/05/2018 14:43:46

[E] 02/05/2018 2:43:27PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO



* AR 201805-00640 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

C02-05.18

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1


BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

00 6448



Dept Direct 6417 8731

Dept Direct 6417 8732

Dept Direct 6417 8733

Dept Direct 6417 8734

Wiper blades: NWD (Nippon Wiper blades, Silex (Made in Korea)).

Forch (Made in Germany)

Spark plugs: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-01044

DATE : 03/05/2018

CUSTOMER ID : PRO005

VEH REG. NO. : GBF6865B

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T53119-37080-B0 KDY231	FRT GRILLE RUBBER	U1 L2-ZZ-18	1	25.00	25.00
2.	T53111-37710-B0 KDY231/08	RAD GRILLE ASSY	U1 SUPPLIER	1	350.00	350.00

SUB-TOTAL : 375.00

ADD GST 7.00 % 26.25

E. & O.E TOTAL AMOUNT SGD : 401.25

[P] 03/05/2018 10:17:50

[E] 03/05/2018 10:12:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO



* AR 201805-01044 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

4BA SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

00 6448

WIPER BLADES
Dept Direct 6417 8781 / 6745 0629



Dept Direct 6305 0010

Dept Direct 6305 0011

Dept Direct 6417 9722



Dept Direct 6417 9724

Dept Direct 6417 9725



Dept Direct 6417 9726



Dept Direct 6417 9728

Wiper blades: HVB (Japan) Wiper blades: S&P (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-00790

DATE : 02/05/2018

CUSTOMER ID : PRO005

VEH REG. NO. : GBF6865B

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52111-37501-B1 KDY231	FRT BUMPER	U1 SUPPLIER	1	250.00	250.00 ✓

SUB-TOTAL : 250.00
ADD GST 7.00 % 17.50

E & O.E TOTAL AMOUNT SGD : 267.50

[P] 02/05/2018 16:06:24

[E] 02/05/2018 4:05:57PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAO



* AR201805-00790 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

02.05.18

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0110201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct 6417 9791 / 6745 0822

Dept Direct 6365 0018

Dept Direct 6363 0011

Dept Direct 6417 9791



Dept Direct 6417 9791

Dept Direct 6417 9795

Dept Direct 6417 9795

Dept Direct 6417 9795

Wiper blades: HWB (Japan) Wiper blades: Silex (Made in Korea)

Forch (Made in Germany)

Spark plug: Nissan Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WAYNE

006448

TAX INVOICE : AR201805-00292
 DATE : 02/05/2018
 CUSTOMER ID : PRO005
 VEH REG. NO. : GBF6865B
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 2
 CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T61131-37062/63 KDY231	FRT PILLAR RH	U1 L1-H16	1	170.00	170.00 ✓
2.	T53111-37720 KDY231	FRT GRILLE	U1 L3-H1	1	350.00	350.00 X change
3.	T75315-37010/1 KDY231	FRT EMBLEM	U1 L2-ZZ-8	1	40.00	40.00 ✓
4.	T52111-37301 KDY231	FRT BUMPER	U1 L3-E11	1	250.00	250.00 X change
5.	T81210-0W050 CT200H-ZWA10	FOG LAMP RH 11"	U1 L2-E4-A	1	110.00	110.00 ✓
6.	T52030-37010 DYNA 14"	FOG LAMP COVER RH	U1 L2-A5-B	1	50.00	50.00 X change
7.	T81110-37463/81130 KDY231	HEAD LAMP RH ASSY	U1 L2-F18	1	350.00	350.00 ✓
8.	T67001-25081 KDY231	FRT DOOR RH	U1 L1-G6	1	560.00	560.00 ✓
9.	T81731-25040 KDY231 2014	DOOR SIGNAL LAMP	U1 L2-D14-K	1	35.00	35.00 ✓
10.	T52011-37052 KDY231	FRT BUMPER STAY RH	U1 SUPPLIER	1	95.00	95.00 ✓
11.	T68730-37010 LY235 DYNA'02	DR HINGE LWR RH/UPPER LH	U1 SUPPLIER	1	50.00	50.00 ✓
12.	T81150-37464/5 KDY231	HEAD LAMP LH	U1 L2-E1-BA	1	350.00	350.00 ✓

CONTINUE NEXT PAGE
 ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450518 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WAYNE

006448

WINDSHIELD GLASS
Dept Direct: 6412 8701 / 6743 0939



Dept Direct: 6383 9818

Dept Direct: 6208 9311

Dept Direct: 6417 9702



Dept Direct: 6417 8734

Dept Direct: 6412 9725

Dept Direct: 6417 9736

Dept Direct: 6417 9723

Wiper blade: NNB (Nippon Wiper blade), Siper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-00292

DATE : 02/05/2018

CUSTOMER ID : PRO005

VEH REG. NO. : GBF6865B

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
------------	-------------	--------	-----	---------	--------

SUB-TOTAL : 2,410.00
ADD GST 7.00 % 168.70

E & O E TOTAL AMOUNT SGD : 2,578.70

[P] 02/05/2018 12:49:35

[E] 02/05/2018 10:48:25AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADE
Dept Direct 6417 8761 / 6445 0029



Dept Direct 6417 8761

Dept Direct 6417 8762

Dept Direct 6417 8763

Dept Direct 6417 8764

Wiper blade: HVG (Nippon Wiper blade) Slicer (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

EXCHANGE

TAX INVOICE : AR201805-01126

DATE : 03/05/2018

CUSTOMER ID : PRO005

VEH REG. NO. : GBF6865B

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52030-37010 DYNA 14"	FOG LAMP COVER RH	PA PL2-H1-04K	1	50.00	50.00

SUB-TOTAL : 50.00

ADD GST 7.00 % 3.50

E & OE

TOTAL AMOUNT SGD : 53.50

[F] 03/05/2018 11:04:16AM

[F] 03/05/2018 11:04:46AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAO

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaaauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN BLADE
Dept Direct: 6417 9791 / 6743 5829

Arrange By

Driver

Low



Wiper blades: IAWD (Nippon Wiper blades, Siper (Made in Korea))
Porch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY
ATTN: WAYNE

00 6448

TAX INVOICE : AR201805-00297
DATE : 02/05/2018
CUSTOMER ID : PRO005
VEH REG. NO. : GBF6865B
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T90467-10161/2 RAV4,LY235DYNA	CLIPS-RAD GRILLE-LOW	PA PL2-P1-05D	8	2.50	20.00 ✓
2.	T67861-37020/1 KDY231 LY235	DOOR RUBBER RH	PA PL1-A1-15F	1	80.00	80.00 ✓
3.	T51771-25021 KDY231 17"	STEP BOARD RH	PA PL2-Q1-07B	1	90.00	90.00 ✓

SUB-TOTAL : 190.00
ADD GST 7.00 % 13.30

E & O E

TOTAL AMOUNT SGD : 203.30

[P] 02/05/2018 11:01:07AM

[R] 02/05/2018 10:51:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAO

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 Sendback Est	18 Apr 2018 14:35 \$511,003.93	18 Apr 2018 16:25 Edit Adj Rpt	\$55,145.00 Edit Estimates	\$55,145.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	03 May 2018 15:19	09 May 2018 12:49 \$5230.00	09 May 2018 12:49			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	HARCO ENGINEERING PTE LTD, Co. Reg. No.: 198303544E		
Vehicle Reg. No.:	GBF6865B	Date of Loss:	16/04/2018 17:00 - :59 [14 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM18HO01009-JG	Policy/Cover Note No.:	DMCPHQ18-000643 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/04/2018]		
Driver/Custodian:	THOZAPPAN JAYABAL (), NRIC: G7797963N		
Adj Asg. Remarks:	EXCESS: \$500.00 NO WAIVER SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- EQI_HQ (25/04/2018): Alert - Adj Mandate Approved (\$59785.93) - GBF6865B - Claim Handler: Joel Goh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBF6865B (DM18HO01009-JG)
OD
Apr 16 2018 5:00PM
[HARCO ENGINEERING PTE LTD]
Progressive Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	18/04/18 14:35	Repairer Estimates		Load HTM	
2	09/05/18 12:49	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/18 08:40	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	18/04/18 14:33	1		Load JPG	☒
2	18/04/18 14:33	2		Load JPG	☒
3	18/04/18 14:33	3		Load JPG	☒
4	18/04/18 14:33	4		Load JPG	☒
5	18/04/18 14:33	5		Load JPG	☒
6	18/04/18 14:33	6		Load JPG	☒
7	18/04/18 14:33	7		Load JPG	☒
8	18/04/18 14:33	8		Load JPG	☒
9	18/04/18 14:33	9		Load JPG	☒
10	18/04/18 14:33	10		Load JPG	☒
11	18/04/18 14:33	11		Load JPG	☒
12	18/04/18 14:33	12		Load JPG	☒
13	18/04/18 14:33	13		Load JPG	☒
14	18/04/18 14:33	14		Load JPG	☒
15	18/04/18 14:33	15		Load JPG	☒
16	18/04/18 14:33	16		Load JPG	☒
17	18/04/18 14:33	17		Load JPG	☒
18	18/04/18 14:33	18		Load JPG	☒
19	18/04/18 14:33	19		Load JPG	☒
20	18/04/18 14:33	20		Load JPG	☒
21	18/04/18 14:33	21		Load JPG	☒
22	18/04/18 14:33	22		Load JPG	☒
23	18/04/18 14:33	23		Load JPG	☒
24	18/04/18 14:33	24		Load JPG	☒
25	18/04/18 14:33	25		Load JPG	☒
26	18/04/18 14:33	26		Load JPG	☒
27	18/04/18 14:33	27		Load JPG	☒
28	18/04/18 14:33	28		Load JPG	☒
29	18/04/18 14:33	29		Load JPG	☒
30	18/04/18 14:33	30		Load JPG	☒
31	18/04/18 14:33	31		Load JPG	☒
32	18/04/18 14:33	32		Load JPG	☒
33	18/04/18 14:33	33		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
34	18/04/18 14:33	34		☒
35	18/04/18 14:33	35		☒
36	18/04/18 14:33	36		☒
37	18/04/18 14:33	37		☒
38	18/04/18 14:33	38		☒
39	18/04/18 14:33	39		☒
40	18/04/18 14:33	40		☒
41	18/04/18 14:33	41		☒
42	18/04/18 14:33	42		☒
43	18/04/18 14:33	43		☒
44	18/04/18 14:33	44		☒
45	18/04/18 14:33	45		☒
46	18/04/18 14:33	46		☒
47	18/04/18 14:33	47		☒
48	18/04/18 14:33	48		☒
49	18/04/18 14:33	49		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 08:40	General View		☒
2	25/04/18 08:40	General View		☒
3	25/04/18 08:40	General View		☒
4	25/04/18 08:40	General View		☒
5	25/04/18 08:40	General View		☒
6	25/04/18 08:40	General View		☒
7	25/04/18 08:40	General View		☒
8	25/04/18 08:40	General View		☒
9	25/04/18 08:40	General View		☒
10	25/04/18 08:40	General View		☒
11	25/04/18 08:40	General View		☒
12	25/04/18 08:40	General View		☒
13	25/04/18 08:40	General View		☒
14	25/04/18 08:40	General View		☒
15	25/04/18 08:40	General View		☒
16	25/04/18 08:40	General View		☒
17	25/04/18 08:40	General View		☒
18	25/04/18 08:40	General View		☒
19	25/04/18 08:40	General View		☒
20	25/04/18 08:40	General View		☒
21	25/04/18 08:40	General View		☒
22	25/04/18 08:40	General View		☒
23	25/04/18 08:40	General View		☒
24	25/04/18 08:40	General View		☒
25	25/04/18 08:40	General View		☒
26	25/04/18 08:40	General View		☒
27	25/04/18 08:40	General View		☒
28	25/04/18 08:40	General View		☒
29	25/04/18 08:41	General View		☒
30	25/04/18 08:41	General View		☒
31	25/04/18 08:41	General View		☒
32	25/04/18 08:41	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
33	25/04/18 08:41	General View	Load JPG	☒
34	25/04/18 08:41	General View	Load JPG	☒
35	25/04/18 08:41	General View	Load JPG	☒
36	25/04/18 08:41	General View	Load JPG	☒
37	25/04/18 08:41	General View	Load JPG	☒
38	25/04/18 08:41	General View	Load JPG	☒
39	25/04/18 08:41	General View	Load JPG	☒
40	25/04/18 08:41	General View	Load JPG	☒
41	25/04/18 08:41	General View	Load JPG	☒
42	25/04/18 08:41	General View	Load JPG	☒
43	25/04/18 08:41	General View	Load JPG	☒
44	25/04/18 08:41	General View	Load JPG	☒
45	24/05/18 08:55	Reinspection Photo	Load JPG	☒
46	24/05/18 08:55	Reinspection Photo	Load JPG	☒
47	24/05/18 08:55	Reinspection Photo	Load JPG	☒
48	24/05/18 08:55	Reinspection Photo	Load JPG	☒
49	24/05/18 08:55	Reinspection Photo	Load JPG	☒
50	24/05/18 08:55	Reinspection Photo	Load JPG	☒
51	24/05/18 08:55	Reinspection Photo	Load JPG	☒
52	24/05/18 08:55	Reinspection Photo	Load JPG	☒
53	24/05/18 08:55	Reinspection Photo	Load JPG	☒
54	24/05/18 08:55	Reinspection Photo	Load JPG	☒
55	24/05/18 08:55	Reinspection Photo	Load JPG	☒
56	24/05/18 08:55	Reinspection Photo	Load JPG	☒
57	24/05/18 08:55	Reinspection Photo	Load JPG	☒
58	24/05/18 08:55	Reinspection Photo	Load JPG	☒
59	24/05/18 08:55	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 14:31	E-filed GIA report	Load PDF	
2	18/04/18 14:31	Certificate of Insurance	Load TIF	
3	18/04/18 14:31	Driver's NRIC & LICENSE	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 08:47	MARK ESTIMATE	Load PDF	
2	30/05/18 11:31	Parts Invoice	Load PDF	
3	30/05/18 11:35	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ118007238/AVBE2

Date: 30/05/2018

REFERENCE

Insured/Claimant: HARCO ENGINEERING PTE LTD Policy No: DMCPHQ18-000643

Date of Loss: 16/04/2018

Nature of Claim: OD

Claim No: DM18HO01009-JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF6865B**

Make & Model: TOYOTA DYNA 150 D, 3.0 D (M)

Engine No: 1KD2609762

Reg. Date: 09/02/2017 (Man. Year: 2016)

Chassis No: KDY2318024583

Colour: Blue

Odometer: 46640 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$65,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75 R15C

Rear Tyre Size: 145 R13

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,508.93	3,220.00	4,288.93	57.12
Miscellaneous Items	595.00	65.00	530.00	89.08
Labour	2,180.00	1,060.00	1,120.00	51.38
Paintwork Labour	950.00	800.00	150.00	15.79
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,233.93	5,145.00	6,088.93	54.20
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	11,233.93	4,645.00	6,588.93	58.65
+ GST 7.00/7.00% (S\$)	786.38	325.15	461.23	58.65
Nett Amount (S\$)	12,020.31	4,970.15	7,050.16	58.65

INSPECTION

Date of Assignment: 18/04/2018 Present Location:

Progressive Automotive Pte Ltd (HQ)

Date Inspected: 24/04/2018 Inspected At:

Blk 3022A Ubi Road 1, #01-45/46

Singapore 408716

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 May 2018)	
Parts:	N/A	TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6865B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT WINDSCREEN PILLAR; OUTER - RH (WCP)	Dented	170.00 F	*170.00 F
2	1	NA	*FRONT WINDSCREEN PILLAR; INNER - RH (WCP)	Repair	130.00 F	*- F
3	1	NA	*CORNER PANEL - RH (WCP)	Repair	75.00 F	*- F
4	1	NA	*FRONT GRILLE (WCP)	Missing	350.00 F	*350.00 F
5	1	NA	*FRONT GRILLE LOGO (WCP)	Missing	40.00 F	*40.00 F
6	8	NA	*FRONT GRILLE CLIP - WHITE (WCP)	Necessary	20.00 F	*20.00 F
7	8	NA	*FRONT GRILLE CLIP - BLACK (WCP)	Not Necessary	20.00 F	*- F
8	1	NA	*FRONT BUMPER (WCP)	Bent	250.00 F	*250.00 F
9	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	100.00 F	*- F
10	1	NA	*FRONT BUMPER BRACKET - RH (WCP)	Bent	95.00 F	*95.00 F
11	1	NA	*FRONT BUMPER FOG LAMP - RH (WCP)	Cut	110.00 F	*110.00 F
12	1	NA	*FRONT BUMPER FOG LAMP COVER - RH (WCP)	Cut	50.00 F	*50.00 F
13	2	NA	*HEAD LAMP ASSY - RH (WCP)	Cracked	350.00 F	*700.00 F
14	1	NA	*HEAD LAMP LOWER RUBBER - RH (WCP)	Not Necessary	15.00 F	*- F
15	1	NA	*FRONT DOOR - RH (WCP)	Distorted	560.00 F	*560.00 F
16	1	NA	*FRONT DOOR RUBBER - RH (WCP)	Cut	80.00 F	*80.00 F
17	1	NA	*FRONT DOOR HINGE; TOP - RH (WCP)	Not Necessary	50.00 F	*- F
18	1	NA	*FRONT DOOR HINGE; LOWER - RH (WCP)	Bent	50.00 F	*50.00 F
19	1	NA	*FRONT DOOR SIGNAL LAMP - RH (WCP)	Cracked	35.00 F	*35.00 F
20	1	NA	*FRONT DOOR LOCK - RH (WCP)	Not Necessary	130.00 F	*- F
21	1	NA	*FRONT DOOR EYE - RH (WCP)	Not Necessary	70.00 F	*- F
22	1	NA	*FRONT DOOR STEP GARNISH - RH (WCP)	Missing	90.00 F	*90.00 F
23	1	NA	*FRONT DOOR BOARD - RH (WCP)	Not Necessary	380.00 F	*- F
24	1	NA		Not Necessary	105.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT DOOR REGULATOR GEAR - RH (WCP)			
25	1	NA	*FRONT DOOR REGULATOR GEAR MOTOR - RH (WCP)	Not Necessary	210.00 F	*- F
26	1	NA	*FRONT ABSORBER - RH (WCP)	Not Necessary	55.00 F	*- F
27	1	NA	*FRONT LOWER ARM - RH (WCP)	Not Necessary	190.00 F	*- F
28	1	NA	*FRONT TOP ARM - RH (WCP)	Not Necessary	420.00 F	*- F
29	1	NA	*FRONT KNUCKLE ARM - RH (WCP)	Not Necessary	350.00 F	*- F
30	1	NA	*FRONT KNUCKLER ARM BEARING - RH (WCP)	Not Necessary	65.00 F	*- F
31	1	NA	*FRONT STAY LINK - RH - NO STOCK (WCP)	Not Necessary	79.20 F	*- F
32	1	NA	*FRONT CROSSMEMBER - NO STOCK (WCP)	Not Necessary	1,635.30 F	*- F
Supplementary #1						
33	1		*FRONT GRILLE RUBBER (WCP)	Missing	25.00 F	*25.00 F
34	1		*DOOR RUBBER - RH (WCP)	Cut	45.00 F	*45.00 F
35	1		*VACUUM PUMP (WCP)	Bent	130.00 F	*130.00 F
F=Franchise part.						
					Sub Total (\$\$)	6,529.50 2,800.00
+ Margin on L,N Items 15.00/15.00% (\$\$)					979.43	420.00
					Total Parts (\$\$)	7,508.93 3,220.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT DOOR COMPANY STICKER - RH (NECESSARY)	30.00	30.00
2	1	FRONT NUMBER PLATE WITH CASING (CRACKED)	35.00	35.00
3	1	FRONT TYRE - RH (NOT NECESSARY)	280.00	0.00
4	1	FRONT TYRE RIM (NOT NECESSARY)	250.00	0.00
Sub Total (S\$)			595.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00	800.00
Labour Items				
2	TO KNOCK OUT DENTS; RH FRONT FLOOR PANEL; RH FRONT WHEEL ARCH PANEL; RH CHASSIS; CUT/WELD; RH FRONT DOOR PILLAR; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00	800.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REFIX DASHBOARD	New	300.00	0.00
5	TO REMOVE; REFIX FRONT WINDSCREEN	New	120.00	100.00
6	TO 4 WHEEL ALIGNMENT	New	60.00	60.00
7	TO TRANSFER DOOR AND DOOR FITTING	New	80.00	80.00
8	TO REMOVE; REPLACE FRONT UNDERCARRIAGE AND FRONT CROSSMEMBER	New	500.00	0.00
Gross Labour Cost (S\$)			3,130.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >