

ASS. REC. BY:

REF:

TMI/

CC3/TML18007250/Kvbzn

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKT 7906E

Policy No. MI 001390

Claims No. M1802050

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

S14092386

Yr Regn:

11, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make:

Chevrolet Epica

c.c.

1991

Colour:

White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

582700

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL1LA69RTB3 064744

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

16/4/18

D.O.I.

18/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/4

Mk para to Carman

L1 Rmp @ 29501 (Red 17,637.43, 86%)

SHD 923861 - X

SKT 9906E - CC3/TML18000356/6463m2

2018 DU017

19/4/18

Email GIA to TMI

RECEIVED 20 APR 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 2 1/2

Resurvey No. of Trip: -

Survey Fee:

250

Transportation:

10

S - RS, \$

Photos

Others

TOTAL

260

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

29501



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/TMI18007250/Kvb

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 19-04-2018



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 7906E	Veh. Inspected	SHD 9238G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/04/2018	Inspection Date	18/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Apr 2018		19 Apr 2018 14:47 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																																																		
<div style="display: flex; justify-content: space-between;"> <div> CLAIM SUBFOLDER DETAILS </div> <div>[Created by insurer]</div> </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Insured:</td> <td colspan="4">ASCOTT CAR RENTAL PTE LTD, Co. Reg. No.: 201431143G</td> </tr> <tr> <td>Main Claimant:</td> <td colspan="4">TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td style="width: 30%;">SHD9238G</td> <td>Date of Loss:</td> <td colspan="2">16/04/2018 16:00 - :59</td> </tr> <tr> <td>Claim Type:</td> <td>TP / M1802050</td> <td>Policy/Cover Note No.:</td> <td colspan="2">MI001390 Coverage: 07/09/2017 - 06/09/2018</td> </tr> <tr> <td>Vehicle Reg. No. (Insured):</td> <td>SKT7906E</td> <td>Policy No. (Claimant):</td> <td colspan="2"></td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td colspan="2">S\$1,500.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="4">Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="4">Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="4">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/04/2018]</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="4">OU INSD HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.</td> </tr> </table> <div style="text-align: right; margin-top: 5px;"> View All Compose Case Mail </div>					Insured:	ASCOTT CAR RENTAL PTE LTD, Co. Reg. No.: 201431143G				Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K				Vehicle Reg. No.:	SHD9238G	Date of Loss:	16/04/2018 16:00 - :59		Claim Type:	TP / M1802050	Policy/Cover Note No.:	MI001390 Coverage: 07/09/2017 - 06/09/2018		Vehicle Reg. No. (Insured):	SKT7906E	Policy No. (Claimant):					Excess:	S\$1,500.00		Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666				Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]				Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/04/2018]				Adj Asg. Remarks:	OU INSD HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.			
Insured:	ASCOTT CAR RENTAL PTE LTD, Co. Reg. No.: 201431143G																																																					
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K																																																					
Vehicle Reg. No.:	SHD9238G	Date of Loss:	16/04/2018 16:00 - :59																																																			
Claim Type:	TP / M1802050	Policy/Cover Note No.:	MI001390 Coverage: 07/09/2017 - 06/09/2018																																																			
Vehicle Reg. No. (Insured):	SKT7906E	Policy No. (Claimant):																																																				
		Excess:	S\$1,500.00																																																			
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666																																																					
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]																																																					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/04/2018]																																																					
Adj Asg. Remarks:	OU INSD HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.																																																					
ASSOCIATED MAIL RECEIVED There are no mail for this case.																																																						
ALL ASSOCIATED TASKS <div style="text-align: right; margin-top: 5px;"> View All Search Tasks Create New Task Complete </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																																							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																																													
No results.																																																						

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 19 April 2018 12:40 PM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 16/4/2018, SHD 9238G(TP VEHICLE), SKT 7906E (OI VEHICLE)
Attachments: EST.pdf, GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9238G M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 18/4/2018

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9238G
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1446986K
Chassis No.:	KL1LA69RJB064744
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,811.00
Original Registration Date:	11 Nov 2011
First Registration Date:	11 Nov 2011
Transfer Count:	0
Actual ARF Paid:	\$13,811.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2019
PARF Rebate Amount:	\$8,977.00

Intended COE Rebate Details

COE Expiry Date:	10 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$39,041.00
COE Rebate Amount:	\$7,639.00
Total Rebate Amount:	\$16,616.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 09:27
Date Of Accident	16/04/2018 16:40
Exact Location Of Accident	KITCHENER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9238G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	CHUA SIONG SEAH
NRIC No	S1114092J
Date Of Birth	05/05/1955
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1979
Driving Experience	38 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91553783
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 631 HOUGANG AVENUE 8 #12-06
Postcode	530631
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 16.04.2018 at about 1640hours, I was Stationary straight on the extreme right lane along Kitchener Road when the traffic was red. While stationary, suddenly I felt an impact. Vehicle B (SKT7906E) hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT7906E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach G.A Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9238G**AAD1804-171***Not Authorized
11 Sep @ 2950h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9238G

KL1LA69RJBB064744

CHEVROLET

EPICA 2.0

14.4.2018

*Popio***PART****LIST**

1	1	Rear Bumper	\$	<i>Actual</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>BT</i> 239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>SL</i> 260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>DIY</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>DIY</i> 68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>SL</i> 119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>SL</i> 119.74	X
8	1	Rear Bumper Tow Hook Cover	\$	<i>SL</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>R</i> 623.76	X
10	1	Rear End Panel Inner Trim	\$	<i>SL</i> 263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>SL</i> 63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>SL</i> 378.00	X
14	1	Bootlid	\$	<i>BT</i> 973.00	✓
15	1	Bootlid inner trim board	\$	<i>SL</i> 400.00	X
16	1	Bootlid Weatherstrip	\$	<i>SL</i> 344.28	X
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>SL</i> 120.62	✓
19	1	Bootlid Logo	\$	<i>SL</i> 138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>SL</i> 119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>SL</i> 217.97	} X
22	1	Bootlid Reflector RH	\$	<i>SL</i> 128.40	
23	1	Bootlid Reflector LH	\$	<i>SL</i> 128.40	
24	1	Rear Tail Lamp RH	\$	<i>SL</i> 479.30	
25	1	Rear Tail Lamp LH	\$	<i>SL</i> 479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	} X
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00	
28	1	Rear Fender Inner Trim RH	\$	<i>SL</i> 418.44	
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00	

Trans-cab Auto Services Pte Ltd

AAD1804-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9238G

30	1	Rear Fender Inner Trim LH	\$	418.44	X
----	---	---------------------------	----	--------	---

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	300.00	X
3	1Set	Rear Bumper Fastener Clip	\$	44.00	
4	1Set	Rear Fender Inner Trim Clip LH	\$	30.00	X
5	1Set	Rear Bumper End Dust Cover Clip	\$	30.00	X
6	1	Rear Boot Sticker 'Trans-cab'	\$	30.00	
7	1	Rear Boot Sticker '6555-3333'	\$	30.00	
8	1	Rear Exhaust Mounting	\$	10.00	X
9	2	Rear Windscreen Sealant	\$	80.00	X
10	1	Rear Windscreen Inner Sponge Seal	\$	100.00	X
11	1	Spare Tyre	\$	180.00	X
12	1	Spare Wheel Rim	\$	126.74	X

TOTAL	\$	1,000.74
--------------	----	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	----	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	4000
----	----------	------

To Check Electrical Lighting Concerned.

\$	170.00	200
----	--------	-----

To Rust-Proofing Of The Affected Areas.

\$	170.00	300
----	--------	-----

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	4000
----	----------	------

To reinstall rear bumper parking sensor.

\$	170.00	600
----	--------	-----

Trans-cab Auto Services Pte Ltd

AAD1804-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9238G

To transfer of end panel fittings and conduct
water seepage test.\$ *nn* 170.00 XTo transfer of boot fittings and conduct water
seepage test.\$ 170.00 *601*To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.\$ *nn* 380.00 XTo check steering geometry and computer
wheel alignment\$ *nn* 220.00 X

\$ 8,150.00

TOTAL \$ 20,587.43

Repair Days~~10 Days~~
*2 1/2 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18007250/KVBN2
Date: 25/04/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI001390
Claimant Vehicle No :	SHD9238G	Insured Vehicle No :	SKT7906E
Date of Loss:	16/04/2018	Nature of Claim:	TP
		Claim No:	M1802050

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9238G	Engine No:	Z20S1446986K
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJB064744
Reg. Date:	11/11/2011 (Man. Year: 2011)	Odometer:	582700 km
Colour:	Red/White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Giti 7 mm	Rear Left Side:	Linglong 5 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,437.43	2,742.58	9,694.85	77.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,150.00	970.00	7,180.00	88.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,587.43	3,712.58	16,874.85	81.97
Approved Total (Overridden) (\$\$)		2,950.00		
	20,587.43	2,950.00	17,637.43	85.67
+ GST 7.00/7.00% (\$\$)	1,441.12	206.50	1,234.62	85.67
Nett Amount (\$\$)	22,028.55	3,156.50	18,872.05	85.67

INSPECTION

Date of Assignment:	19/04/2018	
Date Inspected:	18/04/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts:	143	CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9238G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Buckled/Cracked	1,202.00 FL	*1,202.00 FL
2	1	*REAR BUMPER BEAM	Bent	239.94 FL	*239.94 FL
3	1	*REAR BUMPER CENTRE ABSORBER	Serviceable	260.00 FL	*- FL
4	1	*REAR BUMPER SIDE RETAINER RH	Distorted	68.76 FL	*68.76 FL
5	1	*REAR BUMPER SIDE RETAINER LH	Distorted	68.76 FL	*68.76 FL
6	1	*REAR BUMPER REFLECTORS RH	Serviceable	119.74 FL	*- FL
7	1	*REAR BUMPER REFLECTORS LH	Serviceable	119.74 FL	*- FL
8	1	*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*- FL
9	1	*REAR END PANEL OUTER	Repair	623.76 FL	*- FL
10	1	*REAR END PANEL INNER TRIM	Serviceable	263.84 FL	*- FL
11	1	*REAR LUGGAGE FLOOR PANEL	Repair	973.00 FL	*- FL
12	1	*REAR LUGGAGE FLOOR PANEL INSULATOR	Serviceable	63.50 FL	*- FL
13	1	*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	378.00 FL	*- FL
14	1	*BOOTLID	Bent	973.00 FL	*973.00 FL
15	1	*BOOTLID INNER TRIM BOARD	Serviceable	400.00 FL	*- FL
16	1	*BOOTLID WEATHERSTRIP	Serviceable	344.28 FL	*- FL
17	1	*BOOTLID LOCK-TOP	Repair	466.56 FL	*- FL
18	1	*BOOTLID CHEVROLET BADGE	Necessary	120.62 FL	*120.62 FL
19	1	*BOOTLID LOGO	Necessary	138.84 FL	*138.84 FL
20	1	*BOOTLID EPICA LT BADGE	Necessary	119.84 FL	*119.84 FL
21	1	*BOOTLID REFLECTOR CENTRE	Serviceable	217.97 FL	*- FL
22	1	*BOOTLID REFLECTOR RH	Serviceable	128.40 FL	*- FL
23	1	*BOOTLID REFLECTOR LH	Serviceable	128.40 FL	*- FL
24	1	*REAR TAIL LAMP RH	Serviceable	479.30 FL	*- FL
25	1	*REAR TAIL LAMP LH	Serviceable	479.30 FL	*- FL
26	1	*REAR EXHAUST BOX (MUFFLER A-EXH,RR)	Repair	1,110.00 FL	*- FL
27	1	*REAR FENDER RH	Repair	1,145.00 FL	*- FL
28	1	*REAR FENDER INNER TRIM RH	Serviceable	418.44 FL	*- FL
29	1	*REAR FENDER LH	Repair	1,145.00 FL	*- FL
30	1	*REAR FENDER INNER TRIM LH	Serviceable	418.44 FL	*- FL
31	1	*SET BOOTLID INNER TRIM BOARD CLIP	Not Necessary	40.00 FS	*- FS
32	1	*SET REAR BUMPER PARKING SENSOR	Serviceable	300.00 FS	*- FS
33	1	*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
34	1	*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*- FS
35	1	*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*- FS
36	1	*REAR BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
37	1	*REAR BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
38	1	*REAR EXHAUST MOUNTING	Not Necessary	10.00 FS	*- FS
39	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
40	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
41	1	*SPARE TYRE	Serviceable	180.00 FS	*- FS
42	1	*SPARE WHEEL RIM	Serviceable	126.74 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,708.17 3,035.76

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,270.74	293.18
Total Parts (S\$)					12,437.43	2,742.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	400.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,200.00	400.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
7	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	60.00
8	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (S\$)			8,150.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >