

22/03/2002

ASS. REC. BY:

REF:

CS/EG118007263/D+bnz

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pui Li

of

EG1

Date/Time:

19042018 1037am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 3800H

Insured:

GBD 7486R

at Workshop m/s

Teamwork

Tel:

6844 2475

of

53 Ubi Ave 1 #D1-24

Policy No:

Claim No:

GBD7486R / SL / PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19042018

(Client's Record)

CA / REV / REP. / REV 24 HRS. wpi

H.O.D. Endorsement:

Date/Time:

19042018 12:11pm

Person Contacted:

Sue

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBF 3800H - RG/EG1/7006820/Dth3e2	Out: 030217
	GBD 7486R - NA / ANA 18007147 / 24	Out: 170418

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lump Sum:

20 %

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF 3800H

Y Regn:

2016 Sgt.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C.

2982

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading:

34522

T/Radio: Insured / Std / NI / NA

Eng/No:

1KD2607048

C/No:

KDH2015021842

Gen. Cond:

Good

Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/80 R.15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

17/04/2018

D.O.I:

24/04/2018

Survey held at

Teamwork Paya Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Brgo GBD 7486R

02/01/19 Jnand 4/5 1500/- with 3 days of rep (Red: 2841.48, 65%)

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

21 Typist

Date/Time, File Return to?



Preli. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1. S + RS 31

1. Photos

1. Copies

1. 1

TOTAL

250

Report Format:

TP

Lump Sum / I.B.L. (\$) 1500/-

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 19 April, 2018 10:37 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBD7486R / TP : GBF3800H/LKK / DOA : 17/04/2018
Attachments: GBD7486R - SAS.pdf; GBF3800H - SAS.pdf; GBF3800H - PRS FORM.pdf; RE: PRE-REPAIR INSPECTION FOR GBF3800H (18.0 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TEAMWORK GARAGE PTE LTD,**

ADDRESS : BLK 53 UBI AVENUE 1
#01-24 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : SUE @ 6844 2475

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe, Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 19.04.2018
Our Reference: GBD 7486R/SL/pl
Your Reference: 1804-32

Sent via Fax

or

Email

claims@teamworkgarage.com

To: **TEAMWORK GARAGE PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBF 3800H
Insured's Vehicle: GBD 7486R
Date Of Accident: 17.04.2018


We acknowledge receipt of your request for PRS on: 18.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



Pte Ltd

ERGO Insurance Pte Ltd
302 Orchard Road #09-01
Tong Building

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	GBF3800H
Make / Model	TOYOTA/HIACE
Chassis number	KDH2015021842
Accident date	17 April 2018
Reference	1804-32

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER RETAINER <i>SLC</i>	150.00 X
1	FRONT BUMER REINFORCMENT <i>NH</i>	345.30 X
		495.30
	Less 25 %	123.83
	Subtotal	371.48
	Balance C/F	371.48
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	371.48
1	FRONT BUMPER <i>CLADE</i>	1500.00
1 SET	FRONT BUMPER CLIP <i>SLC</i>	2500.00
		60.00 X
	Subtotal	2560.00
	Balance C/F	2931.48
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	2931.48
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 <i>NH</i>
2	PANEL BEATING ON AFFECTED AREAS	600.00 <i>200/-</i>
3	SPRAY PAINTING ON AFFECTED AREAS	600.00 <i>200/-</i>
4	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>NH</i>
		400.00
	Subtotal	1410.00
	Grand total	4341.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 dgs.

1900.00
L/S 1500/-




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18007263/Dtbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-01-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 7486R	Veh. Inspected	GBF 3800H	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBD7486R/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	19/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDH2015021842	Colour	SILVER	
Odometer	34522	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	5 mm	
L/H Front Tyre	195/80 R15	DUNLOP	5 mm	
R/H Rear Tyre	195/80 R15	DUNLOP	5 mm	
L/H Rear Tyre	195/80 R15	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2018	Inspection Date	24/04/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3800H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER RETAINER	SERVICEABLE	150.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	345.30	-
	LESS 25% DISCOUNT		-123.82	-
			371.48	-
SPECIAL NETT ITEMS				
1	FRONT BUMPER (SN)	CRACKED	2,500.00	1,500.00
1	SET FRONT BUMPER CLIP (SN)	SERVICEABLE	60.00	-
			2,560.00	1,500.00
LABOUR				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	PANEL BEATING ON AFFECTED AREAS.		600.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,410.00	400.00
GRAND TOTAL			4,341.48	1,900.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/EGI18007263/Dtbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.