

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5919G**AAD1804-173***Not Autharized
11 May 8?*

Vehicle No.:	SHC 5919G
Chassis No.:	VF1ABL15AUC280983
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	16.4.2018
Third Party Insurer :	III

PART		LIST	
1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>B</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH L70Y	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69
1	DOOR LOCK FRT LH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>N</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT LH	\$	505.19 ?
1	DOOR REGUALTOR MOTOR FRT LH	\$	796.46 ?
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97 ?
1	DOOR PANEL REAR LH L70Y	\$	<i>Rollway</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH L70Y	\$	<i>Sn</i> 176.82
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85
1	DOOR HINGE UPPER LH L70Y	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER L70Y	\$	<i>N</i> 300.55
1	DOOR HINGE BOLT	\$	<i>Sn</i> 10.85
1	DOOR HINGE NUT L70Y	\$	<i>Sn</i> 14.60
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69
1	DOOR CHECK NUT	\$	<i>Sn</i> 3.75

Trans-cab Auto Services Pte Ltd**AAD1804-173**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5919G

1	DOOR LOCK REAR LH L70Y	\$	908.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06
1	DOOR HANDLE OUTER REAR LH L70Y	\$	126.49
1	DOOR HANDLE CAP REAR LH L70Y	\$	35.52
1	DOOR HANDLE SEAL REAR LH L70Y	\$	7.89
1	DOOR HANDLE COVER REAR LH L70Y	\$	13.22
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.60
1	DOOR REGULATOR REAR LH L70Y	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH L70Y	\$	423.10
1	DOOR MOULDING REAR LH L70Y	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH L70Y	\$	1,509.06
1	DOOR WATER SHIELD REAR LH L70Y	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH L70Y	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR GRAB HANDLE REAR LH L70Y	\$	210.96
1	DOOR BLIND REAR LH L70Y	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	410.66
1	DOOR SEAL REAR LH L70Y	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47

Trans-cab Auto Services Pte Ltd

AAD1804-173

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5919G

1	BUMEPR RETAINER LH REAR	\$	44.99	X
1	BUMPER BEAM REAR	\$	777.52	X
1	BUMPER BEAM BRACKET LH REAR	\$	225.95	X
1	DOOR MIRROR ASSY LH	\$	1,483.40	X
1	TAILLAMP LH	\$	552.55	X

	\$	30,847.89
10%	\$	3,084.79
	\$	27,763.10

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	}
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT LH	\$	30.50	}
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	
1	REAR DOOR STICKER '6555 3333'	\$	80.00	

TOTAL	\$	518.00
--------------	----	---------------

TOTAL PARTS	\$	28,281.10
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	3,500.00
----	----------

Putty and spray painting of the affected portion.

\$	3,200.00
----	----------

To rust-proofing of the affected areas.

\$	170.00
----	--------

Trans-cab Auto Services Pte Ltd

AAD1804-173

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5919G

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	801
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	380.00	1201
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
TOTAL	\$	9,290.00	
Over All Total	\$	37,571.10	

LUMP SUM (REPAIR DAY)**10 DAYS**

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: