

23/03/2007

ASS. REC. BY:

REC:

CS/FCI18007269/Kvbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

WS May Chua

of

FCI

Date/Time:

19/04/2018 10:55am

Estimated Cost:

Bill to:

OD / TRWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHV 8318H

Insured:

SHD 4200Y

at Workshop m/s

BH Auto

Tel:

6559 8944

of

Blk 1 Sm Nying Ind Est #01-115

Policy No:

Claim No:

D18002956MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DSI

25/04/2018 @ 10am - 11am

H.O.D. Endorsement:

Date/Time:

19/04/2018 10:46am

Person Contacted:

Jaclyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHV 8318H - CS / ALH11016966 / Rjrlg2

Dn: 18081011

SHD 4200Y - CS / FCI130114796 / Yru2

Dn: 110813

24/4/18

Email preli revised to FCI

9/7

8 6956.20 email & confirm (Red 8602.05, 55% (No LS)

ASS. REC. BY:

REF: F-121Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 8686

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1-131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGV 831814Yr Regn: 06, 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Bmw523ic.c. 2491Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 122576

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1-P320500864817Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 225/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 17/4/18

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 23/4/18Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
R N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/4 File pass to Catherine

RECEIVED 12 JUL 2018

11/7/2018

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1) Date/Time, File Return to?

2) 11/7 - typistDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

5x15=75

170+75

50

50

18

363

Report Format: CWSLump Sum / I.B.I. (\$) 6956.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007269/Kvb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4200Y	Veh. Inspected	SGV 8318H
Policy No.		Coverage (\$)	0.00
Claim No.	D18002956MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	19/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/04/2018	Inspection Date	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002956MFSH

Our ref: CS/FC18007269/Kvb

Date : 24/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGV 8318H


We thank for your instruction on 19/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on
23/4/2018 at the premises of M/s BH AUTO SERVICES PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$12,937.05
Revised Estimate Amount	: S\$4,435.00
"Check" Items Amount	: S\$1,592.20
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front n/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-04-2018	Our Ref No. D18002956MFSH
Accident Date	17-04-2018	Claim Type. Third Party
Insured Vehicle	SHD4200Y	Third Party Vehicle. SGV8318H
Survey Location	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115	
Contact Person.	JACELYN LOH	
Contact No.	65598944/ 0	Fax No. 65153144
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BH AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 24 April 2018 2:06 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002956MFSH/1, SGV 8318H
Attachments: SGV 8318H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGV 8318H
Date of survey: 23/4/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 April 2018 10:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002956MFSH/1

Dear Sir / Madam,

Thank you for the assignment,

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 19 April, 2018 10:35 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002956MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

- New Subaru XV
- This is the redesigned new-for-2015 KIA Sorento.
- Buying used Car tips

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.8A



\$2800 Down payment Monthly
From 500k Onwards. Lowest
3.68% P.A. (G.V. Credit Pte Ltd. 500k)

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [View our cars](#)

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted ▾ 20 results/page ▾

105 vehicles

bmw 523

Basic Search

Price Any price **Depre** Any depre **Reg Date** Any date **Eng Cap** Any ▾ **Veh Type** All types
Fuel Any fuel ▾ **Mileage** Any **OMV** Any **Gear** Any Gear ▾ **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer ▾ **Location** Any **Status** Available ▾



Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--------------	-------	--------------	----------	---------	---------	----------	--------

**BMW 5 Series 523i****\$70,800****\$15,640 /yr****25-May-2011****2,497 cc****112,000 km****Luxury****Available**

Guaranteed Lowest Price And Best Condition In Market! Only 1 Owner! Well Maintained, Highest Trade In With Lowest In House Interest Easy Loan, \$3k Deposit, Low Down Payment. Call Now To View!

Posted: 18-Apr-2018 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$52,800****\$15,760 /yr****20-May-2010****2,497 cc****96,000 km****Luxury****Available**

1 Of The Best Conditioned 523i In Market, New Engine And Gearbox Mounts, No Sticky Or Fading Buttons. Accident Free. Call Us For More Information.

Posted: 17-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$53,800****\$16,240 /yr****20-May-2010****2,497 cc****-****Luxury****Available**

Hottest Selling Executive Sedan In The Market! Price Negotiable. Regularly Serviced. Pristine Condition. For That Responsive, Smooth And Quiet Drive, Don't Miss, View By Appointment!

Car Search

Posted: 17-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$50,800****\$14,160 /yr****24-Jun-2010****2,497 cc****111,114 km****Luxury****Available**

Best Selling Model For BMW, Agent Unit, Well-Maintained, Low Mileage. Buy With Peace Of Mind! Call For Viewing Appointment.

Posted: 17-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

**BMW 5 Series 523i****\$53,777****\$16,280 /yr****18-May-2010****2,497 cc****-****Luxury****Available**

Luxurious & Sporty 523i Executive Sedan, For Your True Driving Pleasure! At Affordable Price. Nice Bidded Plate. Regularly Serviced. Pristine Condition, For That Responsive, Smooth And Quiet Drive, Do...

Posted: 17-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$56,800****\$15,150 /yr****09-Sep-2010****2,497 cc****108,200 km****Luxury****Available**

One Of The Best Maintained And Reliable 6 Cylinder Naturally Aspirated Engine 523i In The Market, Regularly Serviced And Done Up By Previous Owner, Viewing Is Highly Recommend For This Unit! Hurry Cal...

Posted: 17-Apr-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

**BMW 5 Series 523i****\$58,800****\$14,990 /yr****24-Nov-2010****2,497 cc****71,202 km****Luxury****Available**

1 Single Owner! Low Mileage! Extremely Underutilized Unit! Previous Owner Who Uses This Unit Works In The Town Area And Only Uses It On Weekend. Interior / Like Day 1! Car Is As Good As New...

Car House Pte Ltd

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1505Z

Vehicle Details

Vehicle No.: SGV8318H
Vehicle to be Exported: No
Intended De-registration Date: 18 Apr 2018
Vehicle Make: B.M.W.
Vehicle Model: 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour: Silver
Manufacturing Year: 2011
Engine No.: 08597701N52B25AF
Chassis No.: WBAFP32050C864817
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$46,758.00
Original Registration Date: 29 Jun 2011
First Registration Date: 29 Jun 2011
Transfer Count: 1
Actual ARF Paid: \$46,758.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jun 2021
PARF Rebate Amount: \$30,392.00

Intended COE Rebate Details

COE Expiry Date: 28 Jun 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$63,000.00
COE Rebate Amount: \$20,124.00
Total Rebate Amount: \$50,516.00

The information contained herein is correct as at 18 Apr 2018

OK

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

First Capital Insurance Ltd

30 Robinson Road

#16-01 City House

Singapore (068877)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6507 3848 Fax : 6507 3849

Not Authorised
1. B. 1, 1. Hong 87
86956.20

4 days

ACCIDENT REPAIR ON : SGV8318H

MODEL : BMW523I

POLICY NO : GA224246

CHASSIS NO : WBAFP32050C864817

YOM : 2011

DATE / TIME OF ACCIDENT: 17/04/2018 Time: 1145Hrs ALONG MARINA ONE DRIVEWAY

THIRD PARTY VEHICLE NO : SHD4200Y

Date: 19/04/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Bonnet	1	2225.00	R	2,225.00 X
2	Bonnet Hinge LH	1	78.00	R	78.00 X
3	Bonnet Hinge RH	1	78.00	R	78.00 X
4	Bonnet Insulator	1	217.00	Sn	217.00 X
5	Front Bumper	1	1278.00	R	1,278.00 X
6	Front Bumper Side Retainer LH	1			-
7	Front Bumper Side Bracket LH	1		Sn	-
8	Front Bumper Nozzle Cover LH	1	48.00	Sn	48.00 X
9	Front Bumper Sensor Set	1	240.00	Sn	240.00 X
10	Front Bumper Lower Side Grille LH	1	75.00	Sn	75.00 X
11	Front Bumper Lower Side Grille Lining Chrome LH	1	35.00	Sn	35.00 X
12	Front Fender LH	1	865.00	R	865.00 ✓
13	Front Fender inner Shield LH	1	128.00	Sn	128.00 X
14	Front Fender Outer Shield LH	1	128.00	Sn	128.00 X
15	Front Fender Side Signal	1		Sn	-
16	Front Head Lamp LH	1	2635.00	CM	2,635.00 ✓
17	Front Head Lamp Bracket LH	1	128.00	R	128.00 X
18	Front Head Lamp ECU	1	678.00	Sn	678.00 X
19	Front Head Lamp Ballast Module LH	1	870.00	Sn	870.00 X
20	Front Fog Lamp LH	1	260.00	Sn	260.00 X
21	Front Bumper Nozzle LH	1	180.00	Sn	180.00 X
22	Front Bumper Reinforcement	1	685.00	R	685.00 X
23	Front Bumper Sponge	1	48.00	Sn	48.00 X
Sub-Total:					10,879.00
Less Discount 5%					543.95
Total Parts:					10,335.05

Special Nett Items

1	Anti-rust coating	2	80.00		160.00 301
2	Front Bumper Clips	10	6.00	na	60.00 X
3	Front Fender Shield Clips	12	6.00	na	72.00 X
Total Parts:					292.00

Labour Charges For Front and Side Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 6 Remove and replace bumper sensors

Total Labour:

4000
1,200.00
8601
1,000.00
30.00
201
22 80.00 x
15,558.25
2,310.00
Total Parts & Labour: 12,937.05
GST 7% 905.59
Grand Total: 13,842.64

Estimate Repair Duration

8 days

4 days

ACCIDENT VEHICLE OF : SGV8318H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kennerh

Company : LICIC

Date : 23/4/18

Time : 11.10am

Contact No : 96910663

Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

First Capital Insurance Ltd

30 Robinson Road

#16-01 City House

Singapore (068877)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6507 3848 Fax : 6507 3849

SUPPLEMENTARY

ACCIDENT REPAIR ON : SGV8318H

MODEL : BMW523I

POLICY NO : GA224246

CHASSIS NO : WBAFP32050C864817

YOM : 2011

DATE / TIME OF ACCIDENT: 17/04/2018 Time: 1145Hrs ALONG MARINA ONE DRIVEWAY

THIRD PARTY VEHICLE NO : SHD4200Y

Date: 25/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Headlamp control unit LH	1	867.00	Malfunction	867.00
2 Headlamp led ballast module LH set	1	487.00	Malfunction	487.00
3 Headlamp sign lamp insert control unit LH	1	368.00	Malfunction	368.00
4 Headlamp control unit xenon light LH	1	774.00	Malfunction	774.00
Sub-Total:				2,496.00
Less Discount 5%				124.80
Total Parts:				2,371.20

$\$2496.00 - 5\%$
 $= \$2,371.20$

Special Nett Items

Total Parts: -

Labour Charges For Front Portion

1	Provide skill labour to reset headlamp management system with diagnostic and reprogram ,data coding	250.00	150
---	---	--------	-----

$\$250$

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

250.00

2,621.20

183.48

2,804.68



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18007269/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4200Y	Veh. Inspected	SGV 8318H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002956MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	19/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 523I (A)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP32050C864817	Colour	METALLIC GREY	
Odometer	122576	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	MICHELIN	6 mm	
L/H Front Tyre	225/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R17	MICHELIN	7 mm	
L/H Rear Tyre	225/55 R17	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2018	Inspection Date	23/04/2018	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 8318H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	2,225.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	78.00	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	78.00	-
1	BONNET INSULATOR	SERVICEABLE	217.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,278.00	-
1	FRONT BUMPER NOZZLE COVER LH	SERVICEABLE	48.00	-
1	FRONT BUMPER SENSOR SET	SERVICEABLE	240.00	-
1	FRONT BUMPER LOWER SIDE GRILLE LH	SERVICEABLE	75.00	-
1	FRONT BUMPER LOWER SIDE GRILLE LINING CHROME LH	SERVICEABLE	35.00	-
1	FRONT FENDER LH	BENT	865.00	865.00
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	128.00	-
1	FRONT FENDER OUTER SHIELD LH	SERVICEABLE	128.00	-
1	FRONT FENDER SIDE SIGNAL (NPA)	SERVICEABLE	-	-
1	FRONT HEAD LAMP LH	CRACKED	2,635.00	2,635.00
1	FRONT HEAD LAMP BRACKET LH	TO REPAIR SEE LABOUR	128.00	-
1	FRONT HEAD LAMP ECU	SERVICEABLE	678.00	-
1	FRONT HEAD LAMP BALLAST MODULE LH	SERVICEABLE	870.00	-
1	FRONT FOG LAMP LH	SERVICEABLE	260.00	-
1	FRONT BUMPER NOZZLE LH	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	685.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	48.00	-
1	HEADLAMP CONTROL UNIT LH (ADDITIONAL)	SHORTED	867.00	867.00
1	HEADLAMP LED BALLAST MODULE LH SET (ADDITIONAL)	SHORTED	487.00	487.00
1	HEADLAMP SIGN LAMP INSERT CONTROL UNIT LH (ADDITIONAL)	SHORTED	368.00	368.00

Report Ref No. CS/FCI18007269/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP CONTROL UNIT XENON LIGHT LH (ADDITIONAL) LESS 5% DISCOUNT	SHORTED	774.00 -668.75 12,706.25	774.00 -299.80 5,696.20
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
12	FRONT FENDER SHIELD CLIPS (SN)	NOT NECESSARY	72.00	-
			132.00	-
	<u>LABOUR</u>			
	ANTI-RUST COATING.		160.00	30.00
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS INCLUSIVE OF THE REPAIR OF BONNET,BONNET HINGE LH,BONNET HINGE RH,FRONT BUMPER,FRONT HEAD LAMP BRACKET LH AND FRONT BUMPER REINFORCEMENT.		1,200.00	400.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WIYH OVEN SPRAY BOOTH FACILITIES.		1,000.00	660.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		30.00	20.00
	REMOVE AND REPLACE BUMPER SENSORS.	NOT NECESSARY	80.00	-
	PROVIDE SKILL LABOUR TO RESET HEADLAMP MANAGEMENT SYSTEM WITH DIAGNOSTIC AND REPROGRAM,DATA CODING (ADDITIONAL).		250.00	150.00
			2,720.00	1,260.00
	GRAND TOTAL		15,558.25	6,956.20
	RECOMMENDED COST OF REPAIRS			6,956.20

Report Ref No. CS/FCI18007269/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.