

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

First Capital Insurance Ltd

30 Robinson Road

#16-01 City House

Singapore (068877)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6507 3848 Fax : 6507 3849

SUPPLEMENTARY

ACCIDENT REPAIR ON : SGV8318H

MODEL : BMW523I

POLICY NO : GA224246

CHASSIS NO : WBAFP32050C864817

YOM : 2011

DATE / TIME OF ACCIDENT: 17/04/2018 Time: 1145Hrs ALONG MARINA ONE DRIVEWAY

THIRD PARTY VEHICLE NO : SHD4200Y

Date: 25/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Headlamp control unit LH	1	867.00	Malfunction	867.00
2 Headlamp led ballast module LH set	1	487.00	Malfunction	487.00
3 Headlamp sign lamp insert control unit LH	1	368.00	Malfunction	368.00
4 Headlamp control unit xenon light LH	1	774.00	Malfunction	774.00
Sub-Total:				2,496.00
Less Discount 5%				124.80
Total Parts:				2,371.20

\$2496.00 - 5%
= \$ 2,371.20

Special Nett Items

Total Parts: -

Labour Charges For Front Portion

1	Provide skill labour to reset headlamp management system with diagnostic and reprogram ,data coding	250.00
---	---	--------

\$ 250

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

250.00

2,621.20

183.48

2,804.68