

LH Express Motor Trading

Blk 5038 Ang Mo Kio Industrial Park 2 #01-405 Singapore 569541.
 Email: dyeo.lhmotortrading@gmail.com Fax: 64816131 Tel: 64817221

*Not Withain
 11 Days @?
 Purvey After Paint
 10 days*

Goh Yeow Koon

Blk 619 A Punggol Drive #15-781
 Singapore 821619.

Vehicle No : SJT 8834J
 Chassis No : JN1BAAG11Z0110242
 Make : Nissan SYLPHY
 Year : 2010

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair- Nett Items

QTY	Description	Unit Price	Amount	Notes
1	Bootlid		\$821.10	✓
1	Bootlid Weather Strip		\$126.30	50% ✓
1	Bootlid Lock		\$122.00	✓
2	Bootlid Lamp RH/LH	\$130.90	\$261.80	✓
1	Bootlid Logo		\$56.90	✓
1	Bootlid 'SYLPHY'		\$95.50	✓
1	Bootlid Lower Chrome		\$162.70	✓
1	Bootlid Upper Chrome		\$280.60	✓
2	Bootlid Hinge	\$60.40	\$128.80	X
1	Bootlid Insulator		\$158.90	X
1 set	Bootlid Insulator Clip		\$50.00	✓
2	Tail Lamp RH/LH	\$239.80	\$479.60	✓
1	Rear Bumper		\$690.60	✓
1	Rear Bumper Chrome Strip		\$250.00	✓
1	Rear Bumper Bracket		\$53.90	✓
1 set	Rear Bumper Clip		\$40.00	✓
2	Rear Bumper Side Retainer RH/LH	\$46.60	\$93.20	✓
2	Rear Bumper Side Splash Guard RH/LH	\$27.60	\$55.20	X
2	Rear Bumper Reflector RH/LH	\$65.00	\$130.00	X
2	Rear Fender RH/LH	\$996.40	\$1,992.80	X
2	Rear Fender Inner Trim RH/LH	\$251.70	\$503.40	✓
1 set	Rear Fender Inner Trim Clip		\$45.00	✓
1	Rear End Panel		\$458.70	✓
1	Rear End Panel Garnish		\$252.80	✓
1 set	Rear End Panel Garnish Clip		\$35.00	✓
1	Spare Tyre Panel		\$702.20	X

1

Spare Tyre Board

	<u>\$511.00</u>
	\$8,558.00
Less 10%	\$855.80
	<u>\$7,702.20</u>

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

1200l
\$1,500.00

Supply Paint Material and necessary items. To respray replaced and other affected panels

1000l
\$1,500.00

Reconnect wiring at the damage section and check for proper functions.

\$75.00 *20l*

To carry out antirust treatment on affected panels.

\$200.00 *90l*

Carry out all wheel alignment and reset settings where necessary to specifications.

nn \$80.00 *X*

To remove/refix rear windscreen to facilitate repair and check water leakage.

\$150.00 *120l*

To re,move/replace exhaust pipe. To realign exhaust system.

\$150.00 *60l*

To remove and refix boot compartment fitting to facilitate repair.

\$150.00 *50l*

To install rear bumper sensor and check for proper function.

\$120.00 *60l*

Special Nett Item

- Rear Video Camera
- Rear Bumper Sensor
- Rear Number Plate
- Rear Number Plate Holder
- Rear Absorber RH/LH @ 165.30
- Exhaust End Pipe
- Exhaust Mounting @22.60
- Rear Windscreen Sealant
- Body Panel Sealant

300m 200m
shot 18450-00
shot \$300.00 *200m*
nd \$45.00 } *45m*
 \$45.00 }
sn \$330.60 *X*
 \$524.00 *?*
 \$45.20 *?*
nn \$60.00 *405m*
nn \$60.00 *305m*

Grand Total :

\$13,037.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: