

ASS. REC. BY:

REF:

CS/MIS(718007276/Avb2

Special Instruction:

SUPERVISOR:

Adrian

ASSIGNMENT (Office)

Merimen

From (Person):

Monica Chung

of

MSH

Date/Time:

19/04/2018 11:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ 2255Z

Insured:

FBL 4208E

at Workshop m/s

Speed Auto Works

Tel:

6842 2035

of

8 Kuda Bukit Ave 4 #08-46

Policy No:

27638761VMT

Claim No:

B55914

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time:

19/04/2018 1:18pm

Person Contacted:

Susan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGZ 2255Z - C66/ATG 12011359 / Kst112

DCA 020612

FBL 4208E - X

20/4/18

Informed Monica pending workshop by merimen

19/11/18

Adrian confirmed LS \$4700 (Red 11,159.25, 70%)

19/11/18

Send preli revised via merimen

ASS. REC. BY: Adrian King

REF: _____

ASSIGNMENT

28/08/08
Yr Regn: 2008 / Aynt

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGZ2255Z
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Rush c.c. 1495
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 195983 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: J200E0002957
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/50R17
 R: 225/50R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

/	
N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: **Yes** or No
 GIA / PR Seen: _____ Consistent?: **Yes** or No
 Est. Repairs: _____ days Res.: **Yes** or No
 Lum Sum: _____ % 3 Val.: **Yes** or No
CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: **IN / OUT**

<u>Front</u>		<u>Rear</u>
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm
D.O.I. _____		D.O.I. <u>19/04/18</u>

Survey held at Speed Auto
 Des. of Damages: **Fr** / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPMS(6)</u>
	<u>MV: 125k</u>
	<u>PV: 781k</u>
	<u>Nett: 4.7k</u>

RECEIVED 20 NOV 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 20/11 - typist
 Report Format: merimen
 Lump Sum / I.B.I: (\$ 4700)

Days Of Repair: 6
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>200</u>
Transportation:	_____
_____ S + RS _____ SI	_____
Photos	_____
Others	<u>10</u>
TOTAL	<u>210</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2018		19 Apr 2018 11:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Wilson Parking (Singapore) Pte Ltd , Co. Reg. No.: 197903256M								
Main Claimant:	Hui Yoke Kheng , ID: S1702791C								
Vehicle Reg. No.:	SGZ2255Z	Date of Loss:	17/04/2018 00:00 - :59 [115 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555914	Policy/Cover Note No.:	27638761VMF Coverage: 29/01/2018 - 28/01/2019						
Vehicle Reg. No. (Insured):	FBL4208E	Policy No. (Claimant):							
		Excess:							
Repairer:	Speed Auto Works - Kaki Bukit (HQ) 8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 6842-2035								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/04/2018]								
Adj Asg. Remarks:	Please assign Adrian Ling to conduct the survey. Kindly contact Susan @ 6842-2035								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 19 Nov 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: FBL4208E		
TP Vehicle No	: SGZ2255Z	Accident Date	: 17/04/2018
Make	: TOYOTA RUSH	Assignment Date	: 19/04/2018
Date of Inspection	: 19/04/2018	Est. Duration of Repair	: 6.00
Inspection At	: SPEED AUTO WORKS - KAKI BUKIT (HQ) 8 KAKI BUKIT AVE 4 #08-46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,859.25
Revised Amount	:S\$	4,700.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,700.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2791C
Vehicle Details	
Vehicle No.:	SGZ2255Z
Vehicle to be Exported:	No
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5X A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	3SZ2083070
Chassis No.:	J200E0020957
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,651.00
Original Registration Date:	28 Aug 2008
First Registration Date:	28 Aug 2008
Transfer Count:	4
Actual ARF Paid:	\$14,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2018
PARF Rebate Amount:	\$7,325.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$13,289.00
COE Rebate Amount:	\$475.00
Total Rebate Amount:	\$7,800.00

The information contained herein is correct as at 18 Apr 2018

OK

MALP16051249 / Alpine Motors Pte Ltd - HQ
 ENTRY DATE & TIME: 16/04/2018 10:59
 SUBMITTED BY: RONNIE TAN GUAN HIN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2018 10:59
Date Of Accident	17/04/2018 13:40
Exact Location Of Accident	CTE TWDS TOWN (NEAR BALESTIER EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ2255Z
Insured/Policyholder	
Name Of Registered Owner	HUI YOKE KHENG
NRIC No	S1702791C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97769922
Alternative Phone No	OFFICE-60000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	RUSH-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA277285/1
Cover Note Number	
Driver	
Name of Driver	CAI JIA YI
NRIC No	S8709525H
Date Of Birth	28/03/1987
Occupation	OUTDOOR
Date Of Driving Pass	20/06/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97769922
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 513 JELAPANG ROAD #06-219
 Postcode 670513
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Report Please refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBL4208E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJJ9838U
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CAI JIA YI
Approximate Age	31
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SGZ2255Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescindulate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report as the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my Workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as via the external carrier of envelopes/mail packaging; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above Purposes; and
- (c) my Personal Information may/ can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be located outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature
 Date & Time



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name: Renin
 NRIC No: S71378 D96

 Signature of Reporting Centre Personnel

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 17 APR 2010 AT 1340 HRS. I WAS DRIVING ALONG C16 TOWARDS TOWN WHEN I WAS DRIVING IN MY LANE WHEN SUDDENLY VEHICLE B COLLIDED INTO MY VEHICLE. I ALIGHTED AND FOUND MYSELF INVOLVED IN A 3 VEHICLE COLLISION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature:
 Name: Ashnu
 NRIC/ID No.: 5713090

Speed Auto Works
 (Co Reg. No. 5321801E)
 Blk 90 Bedok North Street 4
 #13-1537 Singapore 460090
 Tel: 6789 5155 Fax : 6783 5155

TO	: MSIG	DATE	: 18-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
	<i>Vexon</i>		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SGZ2255Z
ADDRESS	:	MODEL	: TOYOTA RUSH
TEL. NO.	:	CHASSIS NO	: <i>J200E0020157</i>
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	:	DAUD/93911482	

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,875.60	\$ <u>1,875.60</u> <i>1180</i>
2	TAILGATE HINGE <i>Ne New</i>	2	\$ 124.40	\$ 248.80 <i>x</i>
3	TAILGATE LOCK <i>Ne New</i>	1	\$ 415.95	\$ 415.95 <i>+</i>
4	TAILGATE INNER BOARD <i>Ne m</i>	1	\$ 793.20	\$ 793.20 <i>+</i>
5	TAILGATE WEATHER STRIP <i>Ne m</i>	1	\$ 259.50	\$ 259.50 <i>+</i>
6	TAILGATE EMBLEM'RUSH' <i>Ne m</i>	1	\$ 78.00	\$ 78.00 <i>-</i>
7	TAILGATE WINDSCREEN MOULDING <i>Ne m</i>	1	\$ 110.00	\$ 110.00 <i>-</i>
8	TAILGATE CHECK <i>Ne m</i>	1	\$ 121.55	\$ 121.55 <i>x</i>
9	TAILLAMP <i>Lt ut</i>	2	\$ 389.50	\$ 779.00 <i>389.50</i>
10	TAILLAMP PANEL <i>Ne m</i>	2	\$ 134.90	\$ 269.80 <i>x</i>
11	SPARE TYRE BRACKET <i>Ne m</i>	1	\$ 289.50	\$ 289.50 <i>+</i>
12	SPARE TYRE COVER <i>cracked</i>	1	\$ 1,589.50	\$ 1,589.50 <i>-</i>
13	SPARE TYRE BASE <i>Ne m</i>	1	\$ 654.00	\$ 654.00 <i>+</i>
14	REAR FENDER INNER TRIM <i>Ne New</i>	2	\$ 775.90	\$ 1,551.80 <i>+</i>

15	REAR FENDER INNER TRIM (TOP) <i>Not New</i>	2	\$ 589.50	\$ 1,179.00	x.
16	REAR FENDER COWLING <i>3 new</i>	2	\$ 154.00	\$ 308.00	x
17	REAR FENDER WHEEL ARC LH <i>new</i>	1	\$ 298.00	\$ 298.00	x.
18	REAR BUMPER <i>Deformed</i>	1	\$ 857.60	\$ 857.60	-
19	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 78.60	\$ 157.20	-
20	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 65.90	\$ 65.90	x
21	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 85.90	\$ 171.80	x
22	REAR NO. PLATE LAMP <i>new</i>	2	\$ 68.00	\$ 136.00	x.
23	REAR END PANEL TOP GARNISH <i>3 new</i>	1	\$ 381.80	\$ 381.80	x
24	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 389.50	\$ 389.50	x.
25	EXHAUST PIPE <i>Not New</i>	1	\$ 1,025.00	\$ 1,025.00	x.

26 Rear End Panel *Deformed* . 513 ✓

48748

365610

TOTAL PRICE \$ 14,006.00
 LESS 25% \$ 3,501.50
 SUB TOTAL PRICE \$ 10,504.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NO. PLATE <i>Not New</i>	1	\$ 55.00	\$ 55.00	x
2	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00	30
3	TAILLAMP CLIP <i>Not New</i>	4	\$ 10.00	\$ 40.00	x.
4	REAR FENDER COWLING CLIP <i>3 new</i>	12	\$ 6.00	\$ 72.00	x
5	REAR END PANEL TOP GARNISH CLIPS <i>1 new</i>	4	\$ 6.00	\$ 24.00	x
6	REAR REVERSE SENSOR <i>Damaged</i>	1	\$ 280.00	\$ 280.00	200
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60.
8	REAR FENDER INNER TRIM CLIP <i>Not New</i>	14	\$ 6.00	\$ 84.00	x
9	TAILGATE INNER TRIM BOARD CLIP <i>Not New</i>	10	\$ 6.00	\$ 60.00	x
10	TAILGATE WINDSCREEN INNER SEAL <i>3 new</i>	1	\$ 80.00	\$ 80.00	30
11	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30.

350

TOTAL \$ 990.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	80	
3	TUFF COAT	\$200.00	40	

4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$150.00	50	
7	TRANFER BOOTLID MECHANISM	\$150.00	80	
8	REMOVE AND REFIX REAR WINDSCREEN	\$150.00	120	
9	CONDUCT WATER LEAKAGE TEST	\$100.00	X	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$100.00	X	

TOTAL

\$3,980.00

1980

TOTAL PARTS COST : \$ 11,494.50
 TOTAL LABOUR COST : \$ 3,980.00
 TOTAL REPAIR COST : \$ 15,474.50 X

15,859.25

Adrian King

total: 3980.00

19/04/18

4/5:47K
(Nett Value)

h/s 062cyr

APPROVED DETAILS

EXCESS :
 NO. OF DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

[Signature]
 19/11/2018

LKK Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2018		19 Apr 2018 11:18 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Wilson Parking (Singapore) Pte Ltd , Co. Reg. No.: 197903256M								
Main Claimant:	Hui Yoke Kheng , ID: S1702791C								
Vehicle Reg. No.:	SGZ2255Z	Date of Loss:	17/04/2018 00:00 - :59 [115 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555914	Policy/Cover Note No.:	27638761VMF Coverage: 29/01/2018 - 28/01/2019						
Vehicle Reg. No. (Insured):	FBL4208E	Policy No. (Claimant):							
		Excess:							
Repairer:	Speed Auto Works - Kaki Bukit (HQ) 8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 6842-2035								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/05/2018]								
Adj Asg. Remarks:	Please assign Adrian Ling to conduct the survey. Kindly contact Susan @ 6842-2035								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGZ2255Z (555914)**
[FBL4208E]
TP
Hui Yoke Kheng
Apr 17 2018 12:00AM
[Wilson Parking (Singapore) Pte Ltd]
Speed Auto Works - Kaki Bukit

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	19/04/18 11:16	Non Reporting Letter to OI		 Load HTM			
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	19/11/18 16:04	Adjuster Immediate Advice		 Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
11	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
12	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
13	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
14	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
15	19/11/18 15:33	General View		 Load JPG	<input checked="" type="checkbox"/>		
16	19/11/18 15:34	General View		 Load JPG	<input checked="" type="checkbox"/>		
17	19/11/18 15:34	General View		 Load JPG	<input checked="" type="checkbox"/>		
18	19/11/18 15:34	General View		 Load JPG	<input checked="" type="checkbox"/>		
19	19/11/18 15:34	General View		 Load JPG	<input checked="" type="checkbox"/>		
20	19/11/18 15:34	General View		 Load JPG	<input checked="" type="checkbox"/>		
21	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
22	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
23	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
24	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
25	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
26	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
27	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
28	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
29	19/11/18 15:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>		
Documentation							

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/04/18 11:12	Third Party Accident Report	 Load PDF	
2	19/04/18 11:12	Third Party PRI SGZ2255Z	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007276/AGVBE2

Date: 30/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 27638761VMF
Claimant Vehicle No : SGZ2255Z	Insured Vehicle No : FBL4208E
Date of Loss: 17/04/2018	Nature of Claim: TP Claim No: 555914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ2255Z	Engine No:	3SZ2083070
Make & Model:	TOYOTA RUSH, 1.5 (A)	Chassis No:	J200E0020957
Reg. Date:	28/08/2008 (Man. Year: 2008)	Odometer:	195983 km
Colour:	White		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,879.25	4,006.10	7,873.15	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,980.00	2,000.00	50.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,859.25	5,986.10	9,873.15	62.25
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	15,859.25	4,700.00	11,159.25	70.36

INSPECTION

Date of Assignment:	19/04/2018	
Date Inspected:	19/04/2018 Inspected At:	Speed Auto Works - Kaki Bukit (HQ) 8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2018)	
Parts: M1-SUV	TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SGZ2255Z)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,875.60 FL	*1,180.00 FL
2	2		*TAILGATE HINGE	Not Necessary	248.80 FL	*- FL
3	1		*TAILGATE LOCK	Not Necessary	415.95 FL	*- FL
4	1		*TAILGATE INNER BOARD	Not Necessary	793.20 FL	*- FL
5	1		*TAILGATE WEATHER STRIP	Not Necessary	259.50 FL	*- FL
6	1		*TAILGATE EMBLEM RUSH	Necessary	78.00 FL	*78.00 FL
7	1		*TAILGATE WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
8	1		*TAILGATE CHECK	Not Necessary	121.55 FL	*- FL
9	1		*TAILLAMP	N/S Cut	779.00 FL	*389.50 FL
10	2		*TAILLAMP PANEL	Not Necessary	269.80 FL	*- FL
11	1		*SPARE TYRE BRACKET	Not Necessary	289.50 FL	*- FL
12	1		*SPARE TYRE COVER	Cracked	1,589.50 FL	*1,589.50 FL
13	1		*SPARE TYRE BASE	Not Necessary	654.00 FL	*- FL
14	2		*REAR FENDER INNER TRIM	Not Necessary	1,551.80 FL	*- FL
15	2		*REAR FENDER INNER TRIM (TOP)	Not Necessary	1,179.00 FL	*- FL
16	2		*REAR FENDER COWLING	Not Necessary	308.00 FL	*- FL
17	1		*REAR BUMPER	Deformed	857.60 FL	*857.60 FL
18	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	65.90 FL	*- FL
19	2		*REAR BUMPER REFLECTOR	Not Necessary	171.80 FL	*- FL
20	2		*REAR NO. PLATE LAMP	Not Necessary	136.00 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	381.80 FL	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	389.50 FL	*- FL
23	1		*EXHAUST PIPE	Not Necessary	1,025.00 FL	*- FL
24	1		*REAR END PANEL	Dented	513.00 FL	*513.00 FL
25	1		*REAR NO. PLATE	Not Necessary	55.00 FS	*- FS
26	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
27	4		*TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
28	12		*REAR FENDER COWLING CLIP	Not Necessary	72.00 FS	*- FS
29	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	24.00 FS	*- FS
30	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
31	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
32	14		*REAR FENDER INNER TRIME CLIP	Not Necessary	84.00 FS	*- FS
33	10		*TAILGATE INNER TRIM BOARD CLIP	Not Necessary	60.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
36	1		*REAR FENDER WHEEL ARC LH	Not Necessary	298.00 FL	*- FL
37	2		*REAR BUMPER SIDE RETAINER	Necessary	157.20 FL	*157.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,509.00 5,224.80

- List Item Discount on L Items 25.00/25.00% (\$\$) 3,629.75 1,218.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	11,879.25	4,006.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	200.00	40.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
6	TRANSFER BOOTLID MECHANISM	New	150.00	80.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	100.00	0.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	60.00
Gross Labour Cost (\$\$)			3,980.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >