

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4100T

DATE 18/4/2018 10:37

MAKE :

MODEL : HYUNDAI i40

QBE / LKK
REAR

Fauzy

Fz

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|---------------------------------|
| | Rear Bumper | | | \$ 603.60 |
| | Rear Bumper Reinforcement ? | | | \$ 504.35 |
| | Rear Bumper Reinforcement Bracket (LH/RH)? | | \$ 180.00 | \$ 360.00 |
| | Rear Bumper Side Bracket ? | | | \$ 49.00 |
| | Rear Bumper Clips | | | \$ 22.00 |
| | Rear Bumper Sponge *? | | | \$ 143.40 |
| | Rear Bumper Under Cover x | | | \$ 225.00 |
| | SUB TOTAL | | | \$ 1,907.35 |
| | LESS 20% <i>256</i> | | | \$ 381.47 |
| | DISCOUNTED TOTAL | | | \$ 1,525.88 |
| | | | | |
| | Rear Bumper Reverse Sensor X | | | \$ 135.70 Nett |
| | Rear Bumper Advertisement Logo | | | \$ 50.00 Nett |
| | Rear Fender Advertisement Logo (LH/RH) | | \$ 100.00 | \$ 200.00 Nett |
| | | | | \$ 385.70 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 250.00 <i>200</i> |
| | Spray Painting Charge | | | \$ 250.00 <i>200</i> |
| | Wiring Charge | | | \$ 50.00 X |
| | R/Refix Reverse Sensor | | | \$ 120.00 X |
| | TOTAL LABOUR | | | \$ 670.00 |
| | ESTIMATE TOTAL | | | \$ 2,581.58 |

Kalvin (LKK)
18/4/18 1400L.
2 hrs
4 hrs
After Repair LKK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.