

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6783J

DATE 16/4/2018 11:30

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber ?			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower X <i>Hyundai</i>			\$ 30.30
	Boot Lid Key Lock			\$ 78.20
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH) X		\$ 230.20	\$ 460.40
	Boot Lid Trimboard X			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✓			\$ 10.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) X <i>Hyundai</i>		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) X		\$ 344.00	\$ 688.00
	Rear Panel X <i>Hyundai</i>			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	Spare Tyre Holder ?			\$ 27.60
	Spare Tyre Panel ?			\$ 863.00
	Spare Tyre Panel Cushion ?			\$ 200.30
	SUB TOTAL			\$ 6,202.80
	LESS 20%			\$ 1,240.56
	DISCOUNTED TOTAL			\$ 4,962.24
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate			\$ 25.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Labour Charge			\$ 440.70
	Panel Beating			\$ 1,000.00
	Spray Painting Charge-Bootlid/Bumper/Rear Panel/Spare Tyre			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,220.00
	ESTIMATE TOTAL			\$ 7,622.94

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____ Date: _____

Kabir (LKK) 19/4/18 10504
4 Pgs.
After Repair LK