



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SDV7798YMake & Model : TOYOTA ALTIS 1.6L CVTYear of Manufacture : 2014Chassis No. : MR053REH104002574Ins Company : AIG / Lonpac

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 14/04/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 6,236.28Plus/Less 25% \$ 1,559.07Total of Cost / List \$ 4,677.21(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 425.00**Total Parts Cost (Appendix A)** \$ 5,102.21**Labour (Appendix B)** \$ 3,140.00**Total Repair Cost** \$ 8,242.21

Contact No

Frt Counter Operation

6383 7103 - Patrick Tia

6383 7730 - Brenda Ng

6383 7466 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SDV7798Y Case Owner : Andrew

Make & Model : TOYOTA ALTIS 1.6L CVT Year Manufacture : 2014

Chassis No : MR053REH104002574 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 45.00	40
2	Rear bumper	1	/	\$ 1,083.55	dct		
3	Rear bumper side retainer LH	1	/	\$ 78.33	dts		
4	Rear bumper side retainer RH	1	/	\$ 78.33	dts		
5	Rear bumper upper retainer LH	1	/	\$ 68.25	dts		
6	Rear bumper upper retainer RH	1	/	\$ 68.25	dts		
7	Rear bumper clips	10	X	\$ 78.10			
8	Rear bumper reflector LH	1	X	\$ 74.60	onc		
9	Rear bumper reflector RH	1	X	\$ 74.60	onc		
10	Rear bumper bracket LH	1	/	\$ 43.31	bt		
11	Rear bumper bracket RH	1	/	\$ 43.31	bt		
12	Rear bumper sponge	1	X	TBA	NSP		
13	Rear bumper reinforcement	1	/	\$ 336.50	bt		
14	Rear bumper side seal LH	1	X	\$ 43.57	NSP		
15	Rear bumper side seal RH	1	X	\$ 43.57	NSP		
16	Taillamp LH	1	/	\$ 368.31	onc		
17	Taillamp RH	1	/	\$ 368.31	onc		
18	Taillamp panel LH	1	X	\$ 296.55	R		
19	Taillamp panel RH	1	X	\$ 296.55	R		
20	Bootlid	1	/	\$ 706.85	bt		
21	Bootlid hinge LH	1	X	\$ 68.94	R		
22	Bootlid hinge RH	1	X	\$ 68.94	R		
23	Bootlid lock	1	/	\$ 349.28	bt		
24	Bootlid lock cable	1	X	\$ 86.76	onc		
25	Bootlid emblem logo	1	X	\$ 58.76	nel		
26	Bootlid emblem COROLLA	1	/	\$ 58.58	nel		
27	Bootlid emblem ALTIS	1	/	\$ 43.42	nel		
28	Bootlid chrome moulding	1	/	\$ 310.59	ant		
29	Bootlid lamp LH	1	/	\$ 195.60	onc		
30	Bootlid lamp RH	1	X	\$ 195.60	onc		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SDV7798Y Case Owner : Andrew

Make & Model : TOYOTA ALTIS 1.6L CVT Year Manufacture : 2014

Chassis No : MR053REH104002574 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Rear end panel	1		\$ 339.95	h7		
32	Rear end panel top garnish	1		\$ 282.86	205		
33	Rear end panel top garnish clips	3		\$ 26.16	u.c.		
34	Reverse sensor	1			Chua	\$ 380.00	350
35	0	0					
36	0	0					
37	0	0					
38	0	0					
39	0	0					
40	0	0					
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

; 2014

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.