

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

EQ

VEHICLE NO : SHA 2796Z

DATE 18/4/2018 15:37

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			\$ 562.30	
	Front Bumper Bracket Top (LH) ?			\$ 22.40	
	Front Bumper Bracket (LH) ?			\$ 24.60	
	Front Fender (LH)			\$ 619.00	
	Front Fender Shield (LH) ?			\$ 169.80	
	Front Fender Retainer ?			\$ 9.20	
	Front Door (LH) x repair				
	Rear Door (LH) x repair				
	Rear Fender (LH) x repair				
	SUB TOTAL			\$ 1,407.30	
	LESS 20%			\$ 281.46	
	DISCOUNTED TOTAL			\$ 1,125.84	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Front Door Comfort Logo (LH) ✓			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) ✓			\$ 80.00	Nett
				\$ 555.00	
	Labour Charge				
	Panel Beating			\$ 1,250.00	400
	Spray Painting Charge			\$ 1,250.00	1000
	Tuff Kote			\$ 50.00	20
	TOTAL LABOUR			\$ 2,550.00	
	ESTIMATE TOTAL			\$ 4,230.84	
	Kahri (LKK) 18/4/18 16:00 3 Bgr PIP Before part p hnd LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					