

15/5/2010

INS. CASE OWNER:

CC 4 /EQI1800

LKK:

IDAC:

Surveyor:

Sebastian

DOI:

ASSIGNMENT

Date / Time:

14/11/18

Registered in Merimen:

14/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBG 1361R

Name of Insured:

CSD CONSTRUCTION PLC

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

14/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SHOKANTA

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SOP 36365



INSRS:

WSP:

Tel:

Liability:

RMKS:

STUTTGART



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
14/11/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	ASHER 26/11/18
	After call ltr to OI:	
20.4.18 @ 10.16	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time: 15.8.18	Sent By: ASH	
FINALIZATION Date/Time: 15.8.18	Confirm with: JESSICA	Confirm by: MOK
Repair Cost: PIP \$580,627.55 (27 days) Reduction: 10 %	Email ☒ Call ☐	
FINAL SETTLEMENT Date/Time: 22.11.18	Confirm with: JAMIE	Email ☒ Call ☐
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28	If NO or B 28, Ass. Lia: 100%	
Repair Cost: WLGST \$586,271.48	3 VEH C-L DND LAST	
Loss of Rental (LOR): \$5 (days)		
Loss of Use (LOU): \$5 8,460.00 (\$180 x 47 days)		
Loss of Income (LOI): \$5 (\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)		
GIA/LTA Search: \$50.00		
Medical: \$5 -		
Disbursement: \$5 -	(e.g. Tow/ Independent)	
Legal Cost: \$5 -		
Total: \$5 94,733.48	Global Sum \$5:	
FINAL PAYMENT Date/Time: 22.11.18	Confirm with: JAMIE	Email ☒ Call ☐
Payee 1: \$5 94,733.48	Name 1: STUTTGART AUTO PTE LTD	
Payee 2: (Strike if N.A.) \$5	Name 2:	
Payee 3: (Strike if N.A.) \$5	Name 3:	

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR: Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

7

days

Res.: _____

Yes or No

Lum Sum: _____

-

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDR 3636S Yr Regn: 09 / 12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Porsche 911 Carrera S C.C. 3800
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 78015 T/Radio: Insured / Std / NI / NA
 Eng/No: MA103C 11357
 C/No: WPOZZZ99Z0S1149399
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or
 Tyre Size: F: 245/55 R20
 R: 295/30 R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 19.04.2018
 Survey held at Stuttgart
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & fr.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P: + 80,627.55 (RD: + 9,032.14 10%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S+PS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.F. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18007294/Seb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 19-04-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 1361R	Veh. Inspected	SDF 3636S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/04/2018	Inspection Date		
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE. SINGAPORE 729648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

EQ Insurance 5 Maxwell Road, #17-00 Tower Block, MND Complex, 069110		NAME : Mr Lim Chee Ping ADDRESS : 27 Springleaf Garden Singapore 788187	WIP : 33317 EXCESS : DATE : 18.04.2018
ATTN : MOTOR CLAIMS FAX :		TEL :	
VEH NO : SDF36365	DATE IN :	CONTACT PERSON : RICK	63602445
CHASSIS NO : WPOZZZ99ZCS114939P	MILEAGE :	TYPE OF CLAIM :	TP AGAINST GBG1361R
MODEL : Porsche 911 Carrera S	DATE REG. : 26.07.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT BUMPER 991 ✓ Deform	1		\$ 1,955.00
2	FRONT NUMBER PLATE HOLDER BLACK ✓ CRK	1		\$ 45.90
3	FRONT BUMPER LOWER AIR DUCT CENTRE ? DO ✓	1		\$ 233.60
4	FRONT BUMPER LOWER SPOILER ✓ SCR	1		\$ 170.90
5	SENSOR PARKASSIST ? ✓	25		\$ 509.40
6	SENSOR GASKET ? ✓	2		\$ 8.60
7	FRONT BUMPER CLIP ✓ NEC	2		\$ 64.80
8	FRONT BUMPER BLIND RIVET ✓ NEC	23		\$ 10.40
9	FRONT BUMPER REINFORCEMENT ✓ DT	1		\$ 1,166.20
10	FRONT BUMPER REINFORCEMENT SEAL ✓ NEC	2		\$ 13.60
11	FRONT BUMPER REINFORCEMENT SCREW ✓ NEC	6		\$ 25.20
12	REAR BUMPER ✓ Deform	1		\$ 2,010.30
13	REAR SENSOR PARKASSIST X DMCN	3		\$ 764.10
14	REAR BUMPER TAPPING SCREW ✓ NEC	5		\$ 3.50
15	REAR BUMPER REINFORCEMENT ✓ NEC (NUT)	5		\$ 8.50
16	REAR BUMPER UPPER HEAT PROTECTION CENTRE BIG ✓ Deform	1		\$ 268.60
17	REAR BUMPER HEAT PROTECTION CENTER SMALL ✓ Deform	1		\$ 59.30
18	REAR BUMPER SUPPORT LH X	1		\$ 550.30
19	REAR BUMPER SUPPORT HEAT PROTECTION INNER LH X	1		\$ 181.00
20	REAR BUMPER TOP SUPPORT CENTER X	1		\$ 1,606.30
21	REAR BUMPER LOWER SPOILER BLACK ✓ Deform	1		\$ 168.50
22	REAR BUMPER LOWER RETAINING STRIP ✓ Deform	1		\$ 55.30
23	COVER TAIL PIPE BLACK LH ✓ SCR	1		\$ 62.60
24	COVER TAIL PIPE BLACK RH X CRK	1		\$ 62.60
25	REAR BUMPER LOWER RETAINING STRIP BLIND RIVET X	1		\$ 5.20
26	REAR BUMPER REINFORCEMENT ✓ DT	1		\$ 869.60
27	REAR TOP SPOILER INNER COVER LH ✓ CRK	1		\$ 12.90
28	REAR TOP SPOILER INNER COVER RH ✓ CRK	1		\$ 12.90
29	LOGO PORSCHE GALVANO SILVER ✓ NEC	1		\$ 189.50
30	LOGO CARRERA GALVANO SILVER ✓ NEC	1		\$ 122.90
31	LOGO S GALVANO SILVER 991 ✓ NEC	1		\$ 94.40
32	LOGO "911" SMALL ✓ NEC	1		\$ 129.00
33	BONETT LOGO ADHESIVE FILM X N/A	1		\$ 2.20
34	REAR BUMPER WIRING HARNESS ✓ CRK	1		\$ 297.70
35	REAR LIGHT (LH) ✓ CRK	1		\$ 1,382.90
36	LICENSE PLATE LIGHT ✓ DMC	2		\$ 170.20

37	REAR REFLECTOR LEFT ✓ CRK	1	/	P991-631-485-02-	\$	32.30
38	AIR BOX HOUSING COVER OUTER ✓ CRK	1	/	P991-110-231-01-	\$	425.00
39	AIR CLEANER CARTRIDGE X NH	2	/	P991-110-130-00-	\$	217.60
40	AIR BOX CENTER GASKET ✓ NEC	1	/	P991-110-131-00-	\$	58.10
41	AIR BOX HOUSING COVER INNER ✓ CRK	1	/	P991-110-212-02-	\$	493.00
42	AIR BOX HOUSING CENTER AIR GUIDE X NH	1	/	P991-110-261-03-	\$	245.20
43	HIGH-PRESSURE PUMP ✓ LCRK	1	/	P9A1-110-315-06-	\$	2,160.80
44	O-RING ✓ NEC	1	/	P999-707-643-40-	\$	10.10
45	HIGH-PRESSURE PUMP TORX SCREW M6X25 ✓ NEC	4	/	P900-385-072-01-	\$	4.40
46	TORX SCREW ✓ NEC	1	/	P900-385-045-01-	\$	2.00
47	SCREW PLUG ✓ NEC	4	/	P900-385-041-01-	\$	4.40
48	REAR ENGINE HYDRAULIC MOUNT ? AC ✓	2	/	P991-375-059-08-	\$	5,654.00
49	REAR ENGINE CARRIER ✓ DT	1	/	P9A1-375-014-08-	\$	821.70
50	REAR ENGINE CARRIER SCREW ✓ NEC	1	/	P900-378-332-01-	\$	5.50
51	REAR ENGINE CARRIER HEXAGON NUT ✓ NEC	2	/	PN -102-861-10-	\$	3.40
52	REAR ENGINE CARRIER HEXAGON-HEAD BOLT ✓ NEC	1	/	P900-378-286-01-	\$	9.40
53	REAR ENGINE CARRIER HEAT SHIELD BOLT ✓ NEC	3	/	PN -100-988-08-	\$	3.60
54	REAR ENGINE CARRIER HEAT PROTECTION ✓ Deform	1	/	P9A1-102-251-01-	\$	74.20
55	REAR ENGINE MOUNTING NUT ✓ NEC	2	/	PN -908-484-05-	\$	11.40
56	REAR ENGINE MOUNTING SCREW BIG ✓ NEC	4	/	P900-385-168-01-	\$	12.40
57	REAR ENGINE MOUNTING SCREW SMALL ✓ NEC	4	/	P900-385-167-01-	\$	8.40
58	REAR ENGINE CARRIER SPACER SLEEVE ✓ NEC	1	/	P9A1-375-245-01-	\$	27.90
59	MAIN EXHAUST MUFFLER LH ✓ DT	1	/	P991-111-321-03-	\$	2,469.70
60	MAIN EXHAUST MUFFLER CLAMP ✓ NEC	2	/	P997-111-520-00-	\$	163.80
61	GASKET FRONT MUFFLER ✓ NEC	2	/	P991-111-482-00-	\$	53.00
62	REAR CENTER MUFFLER SUPPORT REAR ✓ DT	1	/	P991-111-473-01-	\$	202.70
63	REAR CENTER MUFFLER HEXAGON NUT ✓ NEC	8	/	PN -104-355-01-	\$	16.80
64	TAIL PIPE CLAMP ✓ NEC	2	/	P997-111-240-30-	\$	116.80
65	TAIL PIPE LH ✓ DT	1	/	P991-111-361-03-	\$	1,040.50
66	REAR CENTER MUFFLER CLAMP ✓ NEC	2	/	P991-111-481-01-	\$	265.40
67	MAIN EXHAUST MUFFLER SUPPORT LH ✓ NEC	1	/	P991-111-471-03-	\$	283.80
68	MUFFLER SUPPORT NUT ✓ NEC	4	/	P900-380-006-02-	\$	28.00
69	REAR CENTER MUFFLER BRACE LH ? DT ✓	1	/	P991-111-475-00-	\$	76.60
70	REAR END MEMBER ✓ DT	1	/	P991-501-903-01-GRV	\$	3,954.20
71	ADHESIVE ✓	4	/	P000-043-305-41-	\$	1,632.40
72	MIXING TUBE ✓	3	/	P000-043-206-32-	\$	77.10
73	ACTIVATOR ✓	43	/	P000-043-305-31-	\$	686.40
74	THREADED INSERT	5	/	P999-504-262-01-	\$	526.50
75	THREADED INSERT	5	/	P999-504-263-01-	\$	526.50
76	THREADED INSERT	5	/	P999-504-268-01-	\$	446.50
77	LENS-HEAD SCREW	50	/	P999-073-917-01-	\$	85.00
78	WASHER	5	/	P999-025-285-31-	\$	61.50
79	THREADED INSERT	5	/	P999-504-267-01-	\$	503.00
80	NUT	5	/	P999-500-196-01-	\$	26.50
81	COOLANT	6	/	PASL-043-301-48	\$	113.40
82	BRAKE FLUID DOT 4 0.5L	3	/	PASL-043-203-88	\$	75.00
TOTAL PARTS					\$	37,009.80
LESS 10%					\$	3,700.98
TOTAL PARTS COST					\$	33,308.82
Labour Description						

1	TO REPLACE FRONT / REAR BUMPER, REAR END CENTER MEMBER, 1560/day & OTHER DAMAGED PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 18,220.00	
			17160	
2	TO RESPRAY FRONT / REAR BUMPER, BONNET, REAR END CENTER MEMBER. REAR LH/RH FENDER INNER PANEL. bumper 1300 other 1100 / panel		\$ 7,200.00	
			5900	
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS. N/C		\$ 350.00	
			100	
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 336.00	
			200	
5	TO MOUNT VEHICLE ONTO CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC	NETT	\$ 3,120.00	✓
6	TO REPLACE HIGH PRESSURE PUMP & ASSY		1560 \$ 2,340.00	
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	NETT	\$ 500.00	✓
			2340	
8	TO REMOVE & REFIT REAR UNDER CARRIAGE.		\$ 3,120.00	
			3900	
9	TO REMOVE & REFIT THE ENGINE ASSY INCLUDING REPLACE ENGINE MOUNTING		\$ 4,680.00	
10	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 1,560.00	✓
11	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00	✓
12	TO SUPPLY 1 SET NUMBER PLATE FRONT / REAR WITH CASING. N/C	NETT	\$ 140.00	✓
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 250.00	✓
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00	✓
15	SUNDRIES. N/C	NETT	\$ 50.00	✓

Sebastian. 19/4/18.

- Part by part repair.
- Question mark Inter Photo.
- Photo Before Paint.

9003621

Sebastianyang@lkkauto.com.

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 43,540.00
TOTAL PARTS	\$ -	\$ 33,308.82
TOTAL	\$ -	\$ 76,848.82
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

89496.70

22 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
SUPPLEMENTARY LIST

EUROKARS GROUP

2nd Survey
Supplementary
Items

EQ Insurance 5 Maxwell Road, #17-00 Tower Block, MND Complex, 069110		NAME : Mr Lim Chee Ping		WIP : 33317	
ATTN. : MOTOR CLAIMS		ADDRESS : 27 Springleaf Garden Singapore 788187		EXCESS :	
FAX :		TEL :		DATE : 21.05.2018	
VEH NO :	SDF3636S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ99ZCS114939P	MILEAGE :		TYPE OF CLAIM :	TP AGAINST GBG1361R
MODEL :	Porsche 911 Carrera S	DATE REG.:	26.07.2012	POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description		QTY	REVISED	PRICES
1	FRONT BUMPER SENSOR SUPPORT	rec	1		\$ 41.50
2	AIR BOX GROMMET	rec	2		\$ 10.20
3	AIR BOX FRAME	cut / TORX	4		\$ 227.20
4	CATALYTIC CONVERTER LH	PA	1		\$ 3,144.30
5	CATALYTIC CONVERTER GASKET LH	rec	1		\$ 40.30
6	REAR CENTER MUFFLER	PA	1		\$ 2,516.00
7	CATALYTIC CONVERTER TORX SCREW	rec	9		\$ 28.80
8	FRONT BUMPER LOWER SUPPORT SPEED NUT	rec	1		\$ 1.10
9	TIMING BELT COVER	cut	1		\$ 56.90
10	FRONT BUMPER LOWER SUPPORT SCREW	rec	2		\$ 5.20
11	FRONT BUMPER LOWER SUPPORT	rec	1		\$ 7.40
12	HEATER PIPE RETURN O-RING	rec	6		\$ 63.60
13	COMPRESSOR O-RING 16.7 X 2.5	rec	2		\$ 33.00
14	AIR CON PRESSURE LINE O-RING	rec	2		\$ 10.20
15	COMPRESSOR PRESSURE LINE O-RING	rec	1		\$ 12.70
16	ENGINE TIMING BELT	cut	1		\$ 137.10
17	THERMOSTAT O-RING	rec	2		\$ 33.00
18	SHOCK ABSORBER SCREW	rec	2		\$ 40.00
19	SHOCK ABSORBER NUT	rec	2		\$ 15.60
20	DRIVE SHAFT SCREW	rec	12		\$ 70.80
21	DRIVE SHAFT SPACER	rec	6		\$ 54.00
22	REAR SUSPENSION SUPPORT BOLT LH	rec	4		\$ 42.00
23	REAR SUSPENSION SUPPORT BOLT RH	rec	4		\$ 42.00
24	REAR CROSS MEMBER NUT		4		\$ 24.80
25	WISHBONE BOLT		2		\$ 13.40
26	WISHBONE LOCKING NUT		4		\$ 20.40
27	WISHBONE ECCENTRIC SCREW		2		\$ 57.40
28	WISH BONE ECCENTRIC WASHER		2		\$ 53.80
29	SUB-FRAME BRACKET SCREW		4		\$ 17.60
30	SUB-FRAME BRACKET NUT		2		\$ 10.20
31	ANTI-ROLL BAR NUT		2		\$ 13.80
32	FRONT AXLE HEX. NUT		2		\$ 10.20
33	TRANSMISSION MOUNTING SCREW		2		\$ 8.80
34	BRACE NUT (WF57)		6		\$ 30.60
35	REAR SUSPENSION-STRUT BAR SCREW		2		\$ 20.20
36	REAR SUSPENSION-STRUT BAR SOCKET BOLT		2		\$ 10.20

[illegible]



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



EQ Insurance		NAME :	Mr Lim Chee Ping	WIP :	33317
5 Maxwell Road, #17-00		ADDRESS :	27 Springleaf Garden	EXCESS :	
Tower Block, MND Complex, 069110			Singapore 788187	DATE :	18.04.2018
ATTN. :	MOTOR CLAIMS	TEL :			
FAX :					
VEH NO :	SDF3636S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WPOZZZ99ZCS114939P	MILEAGE :		TYPE OF CLAIM :	TP AGAINST G8G1361R
MODEL :	Porsche 911 Carrera S	DATE REG.:	26.07.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	FRONT BUMPER 991	1	P991-505-010-51-	\$ 1,955.00	\$ 1,955.00
2	FRONT NUMBER PLATE HOLDER BLACK	1	P991-701-051-00-1E0	\$ 45.90	\$ 45.90
3	FRONT BUMPER LOWER AIR DUCT CENTRE	1	P991-505-569-00-1E0	\$ 233.60	\$ 233.60
4	FRONT BUMPER LOWER SPOILER	1	P991-505-557-02-1E0	\$ 170.90	\$ 170.90
5	SENSOR PARKASSIST	5	P150-919-275-C -G2L	\$ 1,273.50	\$ 509.40
6	SENSOR GASKET	2	P7PP-919-133- -	\$ 8.60	\$ 8.60
7	FRONT BUMPER CLIP	2	P997-505-719-00-	\$ 64.80	\$ 64.80
8	FRONT BUMPER BLIND RIVET	3	P999-190-191-30-	\$ 15.60	\$ 10.40
9	FRONT BUMPER REINFORCEMENT	1	P991-505-121-00-	\$ 1,166.20	\$ 1,166.20
10	FRONT BUMPER REINFORCEMENT SEAL	2	P991-505-771-00-	\$ 13.60	\$ 13.60
11	FRONT BUMPER REINFORCEMENT SCREW	6	P900-378-351-01-	\$ 25.20	\$ 25.20
12	REAR BUMPER	1	P991-505-020-22-	\$ 2,010.30	\$ 2,010.30
13	REAR SENSOR PARKASSIST	3	P150-919-275-C -G2L	\$ -	\$ 764.10
14	REAR BUMPER TAPPING SCREW	5	P9A7-007-517-00-	\$ 3.50	\$ 3.50
15	REAR BUMPER REINFORCEMENT	5	P999-507-181-01-	\$ 8.50	\$ 8.50
16	REAR BUMPER UPPER HEAT PROTECTION CENTRE BIG	1	P991-505-471-00-	\$ 268.60	\$ 268.60
17	REAR BUMPER HEAT PROTECTION CENTER SMALL	1	P991-505-473-00-	\$ 59.30	\$ 59.30
18	REAR BUMPER SUPPORT LH	1	P991-505-631-00-	\$ -	\$ 550.30
19	REAR BUMPER SUPPORT HEAT PROTECTION INNER LH	1	P991-505-477-00-	\$ -	\$ 181.00
20	REAR BUMPER TOP SUPPORT CENTER	1	P991-505-821-01-OK1	\$ -	\$ 1,606.30
21	REAR BUMPER LOWER SPOILER BLACK	1	P991-505-811-00-1E0	\$ 168.50	\$ 168.50
22	REAR BUMPER LOWER RETAINING STRIP	1	P991-505-837-00-	\$ 55.30	\$ 55.30
23	COVER TAIL PIPE BLACK LH	1	P991-505-651-00-1E0	\$ 62.60	\$ 62.60
24	COVER TAIL PIPE BLACK RH	1	P991-505-652-00-1E0	\$ 62.60	\$ 62.60
25	REAR BUMPER LOWER RETAINING STRIP BLIND RIVET	1	P999-190-191-30-	\$ -	\$ 5.20
26	REAR BUMPER REINFORCEMENT	1	P991-505-141-00-	\$ 869.60	\$ 869.60
27	REAR TOP SPOILER INNER COVER LH	1	P991-504-661-01-	\$ 12.90	\$ 12.90
28	REAR TOP SPOILER INNER COVER RH	1	P991-504-662-01-	\$ 12.90	\$ 12.90
29	LOGO PORSCHE GALVANO SILVER	1	P991-559-235-00-	\$ 189.50	\$ 189.50
30	LOGO CARRERA GALVANO SILVER	1	P991-559-237-01-	\$ 122.90	\$ 122.90
31	LOGO S GALVANO SILVER 991	1	P991-559-243-01-	\$ 94.40	\$ 94.40
32	LOGO "911" SMALL	1	P991-559-231-02-	\$ 129.00	\$ 129.00
33	BONETT LOGO ADHESIVE FILM	1	P999-911-756-41-	\$ -	\$ 2.20
34	REAR BUMPER WIRING HARNESS	1	P991-612-896-03-	\$ 297.70	\$ 297.70

35	REAR LIGHT (LH)	1		P991-631-143-14-	\$ 1,382.90	\$ 1,382.90
36	LICENSE PLATE LIGHT	2		P1K8-943-021-C -	\$ 170.20	\$ 170.20
37	REAR REFLECTOR LEFT	1		P991-631-485-02-	\$ 32.30	\$ 32.30
38	AIR BOX HOUSING COVER OUTER	1		P991-110-231-01-	\$ 425.00	\$ 425.00
39	AIR CLEANER CARTRIDGE	2		P991-110-130-00-	\$ -	\$ 217.60
40	AIR BOX CENTER GASKET	1		P991-110-131-00-	\$ 58.10	\$ 58.10
41	AIR BOX HOUSING COVER INNER	1		P991-110-212-02-	\$ 493.00	\$ 493.00
42	AIR BOX HOUSING CENTER AIR GUIDE	1		P991-110-261-03-	\$ -	\$ 245.20
43	HIGH-PRESSURE PUMP	1		P9A1-110-315-06-	\$ 2,160.80	\$ 2,160.80
44	O-RING	1		P999-707-643-40-	\$ 10.10	\$ 10.10
45	HIGH-PRESSURE PUMP TORX SCREW M6X25	4		P900-385-072-01-	\$ 4.40	\$ 4.40
46	TORX SCREW	1		P900-385-045-01-	\$ 2.00	\$ 2.00
47	SCREW PLUG	4		P900-385-041-01-	\$ 4.40	\$ 4.40
48	REAR ENGINE HYDRAULIC MOUNT	2		P991-375-059-08-	\$ 5,654.00	\$ 5,654.00
49	REAR ENGINE CARRIER	1		P9A1-375-014-08-	\$ 821.70	\$ 821.70
50	REAR ENGINE CARRIER SCREW	1		P900-378-332-01-	\$ 5.50	\$ 5.50
51	REAR ENGINE CARRIER HEXAGON NUT	2		PN -102-861-10-	\$ 3.40	\$ 3.40
52	REAR ENGINE CARRIER HEXAGON-HEAD BOLT	1		P900-378-286-01-	\$ 9.40	\$ 9.40
53	REAR ENGINE CARRIER HEAT SHIELD BOLT	3		PN -100-988-08-	\$ 3.60	\$ 3.60
54	REAR ENGINE CARRIER HEAT PROTECTION	1		P9A1-102-251-01-	\$ 74.20	\$ 74.20
55	REAR ENGINE MOUNTING NUT	2		PN -908-484-05-	\$ 11.40	\$ 11.40
56	REAR ENGINE MOUNTING SCREW BIG	4		P900-385-168-01-	\$ 12.40	\$ 12.40
57	REAR ENGINE MOUNTING SCREW SMALL	4		P900-385-167-01-	\$ 8.40	\$ 8.40
58	REAR ENGINE CARRIER SPACER SLEEVE	1		P9A1-375-245-01-	\$ 27.90	\$ 27.90
59	MAIN EXHAUST MUFFLER LH	1		P991-111-321-03-	\$ 2,469.70	\$ 2,469.70
60	MAIN EXHAUST MUFFLER CLAMP	2		P997-111-520-00-	\$ 163.80	\$ 163.80
61	GASKET FRONT MUFFLER	2		P991-111-482-00-	\$ 53.00	\$ 53.00
62	REAR CENTER MUFFLER SUPPORT REAR	1		P991-111-473-01-	\$ 202.70	\$ 202.70
63	REAR CENTER MUFFLER HEXAGON NUT	8		PN -104-355-01-	\$ 16.80	\$ 16.80
64	TAIL PIPE CLAMP	2		P997-111-240-30-	\$ 116.80	\$ 116.80
65	TAIL PIPE LH	1		P991-111-361-03-	\$ 1,040.50	\$ 1,040.50
66	REAR CENTER MUFFLER CLAMP	2		P991-111-481-01-	\$ 265.40	\$ 265.40
67	MAIN EXHAUST MUFFLER SUPPORT LH	1		P991-111-471-03-	\$ 283.80	\$ 283.80
68	MUFFLER SUPPORT NUT	4		P900-380-006-02-	\$ 28.00	\$ 28.00
69	REAR CENTER MUFFLER BRACE LH	1		P991-111-475-00-	\$ 76.60	\$ 76.60
70	REAR END MEMBER	1		P991-501-903-01-GRV	\$ 3,954.20	\$ 3,954.20
71	ADHESIVE	4		P000-043-305-41-	\$ 1,632.40	\$ 1,632.40
72	MIXING TUBE	3		P000-043-206-32-	\$ 77.10	\$ 77.10
73	ACTIVATOR	3		P000-043-305-31-	\$ 514.80	\$ 686.40
74	THREADED INSERT	5		P999-504-262-01-	\$ 526.50	\$ 526.50
75	THREADED INSERT	5		P999-504-263-01-	\$ 526.50	\$ 526.50
76	THREADED INSERT	5		P999-504-268-01-	\$ 446.50	\$ 446.50
77	LENS-HEAD SCREW	50		P999-073-917-01-	\$ 85.00	\$ 85.00
78	WASHER	5		P999-025-285-31-	\$ 61.50	\$ 61.50
79	THREADED INSERT	5		P999-504-267-01-	\$ 503.00	\$ 503.00
80	NUT	5		P999-500-196-01-	\$ 26.50	\$ 26.50
81	COOLANT	6		PASL-043-301-48	\$ -	\$ 190.80
82	BRAKE FLUID DOT 4 0.5L	3		PASL-043-203-66	\$ 75.00	\$ 75.00
SUPPLEMENTARY						
1	SUPPORT	1		P991-505-781-00-	\$ 41.50	
2	GROMMET	2		P999-702-246-40-	\$ 10.20	

3	TO SUPPLY SPRAY THEROSTAT SEALANT ON THE CUTTING AREAS.	\$ 200.00	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 200.00	\$ 350.00
5	TO MOUNT VEHICLE ONTO CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC	\$ 3,120.00	\$ 3,120.00
6	TO REPLACE HIGH PRESSURE PUMP & ASSY	\$ 1,560.00	\$ 2,340.00
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	\$ 500.00	\$ 500.00
8	TO REMOVE & REFIT REAR UNDER CARRIAGE.	\$ 2,340.00	\$ 3,120.00
9	TO REMOVE & REFIT THE ENGINE ASSY INCLUDING REPLACE ENGINE MOUNTING	\$ 3,900.00	\$ 4,680.00
10	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	\$ 1,560.00	\$ 1,560.00
11	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 560.00	\$ 560.00
12	TO SUPPLY 1 SET NUMBER PLATE FRONT / REAR WITH CASING.	\$ 140.00	\$ 140.00
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 250.00	\$ 250.00
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
15	SUNDRIES.	\$ 50.00	\$ 50.00
		TOTAL LABOUR	\$ 38,040.00 \$ 43,540.00
		TOTAL PARTS	\$ 42,587.55 \$ 33,378.48
		TOTAL	\$ 80,627.55 \$ 76,918.48
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ 80,627.55
		GST 7%	\$ 5,643.93 \$ -
		GRAND TOTAL	\$ 86,271.48 \$ -

Number of days: 27 working days (Exclude waiting for Survey,authorization,Parts, Saturday,Sunday and Public Holiday)

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 19 April, 2018 11:29 AM
To: assignments
Subject: FW: YOUR REF: GBG1361R / OUR REF: SDF3636S THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)
Attachments: ESTIMATE- SDF3636S.PDF

19042018 C 11:45am

Eva vth in

Sebastian

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: Thursday, 19 April 2018 11:19 AM

To: eva.kok@eurokars.com.sg

Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg; janice.syn@porsche.com.sg; Admin A <admin-a@lkkauto.com>

Subject: RE: YOUR REF: GBG1361R / OUR REF: SDF3636S THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Without Prejudice

Dear Eva

We will appoint LKK to handle this matter.

Dear LKK

Kindly assist to take over this direct settlement.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: eva.kok@eurokars.com.sg [<mailto:eva.kok@eurokars.com.sg>]
Sent: Wednesday, April 18, 2018 3:58 PM
To: Joel Goh
Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg; janice.syn@porsche.com.sg
Subject: RE: YOUR REF: GBG1361R / OUR REF: SDF3636S THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Joel,

Is your Ref GBG1361R and my Ref SDF3636S (new case).

Thank you

Eva Kok
Insurance Claims Officer
Trans Eurokars Pte Ltd
12 Sungei Kadut Avenue
Singapore 729648
Dir: +65 6360 2846 | Fax: +65 63602899 | Email: eva.kok@eurokars.com.sg
Website: www.eurokarsgroup.com



DISCLAIMER

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.
Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]
Sent: Wednesday, April 18, 2018 3:50 PM
To: Eva Kok <eva.kok@eurokars.com.sg>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo Fu Shen <rickteo@eurokars.com.sg>; Janice Syn <janice.syn@porsche.com.sg>
Subject: RE: YOUR REF: GBG1361R / OUR REF: SDF3636S THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Without Prejudice

Dear Eva

Kindly advise if you are submitting a claim against GBG1361R or GBC5482U

Best Regards,

Joel Goh
Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



5

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]

Sent: Wednesday, April 18, 2018 3:38 PM

To: Elaine Cheong; Janet Tan

Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg; janice.syn@porsche.com.sg

Subject: YOUR REF: GBG1361R / OUR REF: SDF3636S THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

YOUR REF: GBC5482U / OUR REF: SGD1919P THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle ASAP. (**Vehicle in workshop**)

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal

Thank you

Eva Kok

Insurance Claims Officer

Trans Eurokars Pte Ltd

12 Sungei Kadut Avenue

Singapore 729648

Dir: +65 6360 2846 | Fax: +65 63602899 | Email: eva.kok@eurokars.com.sg

Website: www.eurokarsgroup.com



*****DISCLAIMER*****

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

PORSCHE

DISCHARGE VOUCHER

I/We hereby acknowledge having received from the under-mentioned
Repairers my/our vehicle No: SDF 36368 which has been
repaired to my satisfaction and I/we admit that the payment for such repairs
by Stuttgart Auto Pte Ltd is in full and final discharge of my claim under
policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
14/04/2018 at CTE Slip Road toward PIE.

Janice Syn



Witnessed by Repairers

04/06/2018

Date:

[Signature]

Signature by Insured

04/06/2018

Date:

Porsche Centre Singapore
Stuttgart Auto Pte Ltd
Bankers Group of Companies
Company Reg. No. 198403740N

Corporate Head office & Postal add:

Bankers Centre

12 Raffles Place
Singapore 729648

Tel: (65) 6363 0911
Fax: (65) 6363 3911

Website:

www.porsche.com.sg

City Centre:

29 Lang Kiat Road
Singapore 159099

Tel: (65) 6472 4433
Fax: (65) 6474 3101

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18007294/Seb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-12-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 1361R	Veh. Inspected	SDF 3636S
Policy No.	DMCPHQ17-003147	Coverage (\$)	0.00
Claim No.	DM18HO00991-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	19/04/2018

2. Vehicle Particulars & Condition

Make & Model	PORSCHE 911 CARRERA S	c.c	3800
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WP0ZZZ99ZCS114939	Colour	WHITE
Odometer	78015	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/55R20	PIRELLI	6 mm
L/H Front Tyre	245/55R20	PIRELLI	6 mm
R/H Rear Tyre	295/30R20	PIRELLI	6 mm
L/H Rear Tyre	295/30R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/04/2018	Inspection Date	19/04/2018
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE. SINGAPORE 729648		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	27 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 3636S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER 991	DEFORMED	1,955.00	1,955.00
1	FRONT NUMBER PLATE HOLDER BLACK	CRACKED	45.90	45.90
1	FRONT BUMPER LOWER AIR DUCT CENTRE	DEFORMED	233.60	233.60
1	FRONT BUMPER LOWER SPOILER	SCRATCHED	170.90	170.90
5	SENSOR PARKASSIST	NECESSARY	1,273.50	1,273.50
2	SENSOR GASKET	NECESSARY	8.60	8.60
2	FRONT BUMPER CLIP	NECESSARY	64.80	64.80
3	FRONT BUMPER BLIND RIVET	NECESSARY	15.60	15.60
1	FRONT BUMPER REINFORCEMENT	DENTED	1,166.20	1,166.20
2	FRONT BUMPER REINFORCEMENT SEAL	NECESSARY	13.60	13.60
6	FRONT BUMPER REINFORCEMENT SCREW	NECESSARY	25.20	25.20
1	REAR BUMPER	DEFORMED	2,010.30	2,010.30
3	REAR SENSOR PARKASSIST	NOT NECESSARY	764.10	-
5	REAR BUMPER TAPPING SCREW	NECESSARY	3.50	3.50
5	REAR BUMPER REINFORCEMENT (NUT)	NECESSARY	8.50	8.50
1	REAR BUMPER UPPER HEAT PROTECTION CENTRE BIG	DEFORMED	268.60	268.60
1	REAR BUMPER HEAT PROTECTION CENTER SMALL	DEFORMED	59.30	59.30
1	REAR BUMPER SUPPORT LH	NOT NECESSARY	550.30	-
1	REAR BUMPER SUPPORT HEAT PROTECTION INNER LH	NOT NECESSARY	181.00	-
1	REAR BUMPER TOP SUPPORT CENTER	NOT NECESSARY	1,606.30	-
1	REAR BUMPER LOWER SPOILER BLACK	DEFORMED	168.50	168.50
1	REAR BUMPER LOWER RETAINING STRIP	DEFORMED	55.30	55.30
1	COVER TAIL PIPE BLACK LH	SCRATCHED	62.60	62.60
1	COVER TAIL PIPE BLACK RH	CRACKED	62.60	62.60
1	REAR BUMPER LOWER RETAINING STRIP BLIND RIVET	NOT NECESSARY	5.20	-
1	REAR BUMPER REINFORCEMENT	DENTED	869.60	869.60
1	REAR TOP SPOILER INNER COVER LH	CRACKED	12.90	12.90
1	REAR STOP SPOILER INNER COVER RH	CRACKED	12.90	12.90
1	LOGO PORSCHE GALVANO SILVER	NECESSARY	189.50	189.50
1	LOGO CARRERA GALVANO SILVER	NECESSARY	122.90	122.90
1	LOGO "911" SMALL	NECESSARY	129.00	129.00

Report Ref No. CC4/EQ18007294/Seb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOGO ADHESIVE FILM	NOT NECESSARY	2.20	-
1	REAR BUMPER WIRING HARNESS	CRACKED	297.70	297.70
1	REAR LIGHT (LH)	CRACKED	1,382.90	1,382.90
2	LICENCE PLATE LIGHT	DAMAGED	170.20	170.20
1	REAR REFLECTOR LEFT	CRACKED	32.30	32.30
1	AIR BOX HOUSING COVER OUTER	CRACKED	425.00	425.00
2	AIR CLEANER CARTRIDGE	NOT NECESSARY	217.60	-
1	AIR BOX CENTER GASKET	NECESSARY	58.10	58.10
1	AIR BOX HOUSING COVER INNER	CRACKED	493.00	493.00
1	AIR BOX HOUSING CENTER AIR GUIDE	NOT NECESSARY	245.20	-
1	HIGH-PRESSURE PUMP	LEAK	2,160.80	2,160.80
1	O-RING	NECESSARY	10.10	10.10
4	HIGH-PRESSURE PUMP TORX SCREW M6X25	NECESSARY	4.40	4.40
1	TORX SCREW	NECESSARY	2.00	2.00
4	SCREW PLUG	NECESSARY	4.40	4.40
2	REAR ENGINE HYDRAULIC MOUNT	ACTIVATED	5,654.00	5,654.00
1	REAR ENGINE CARRIER	DENTED	821.70	821.70
1	REAR ENGINE CARRIER SCREW	NECESSARY	5.50	5.50
2	REAR ENGINE CARRIER HEXAGON NUT	NECESSARY	3.40	3.40
1	REAR ENGINE CARRIER HEXAGON-HEAD BOLT	NECESSARY	9.40	9.40
3	REAR ENGINE CARRIER HEAT SHIELD BOLT	NECESSARY	3.60	3.60
1	REAR ENGINE CARRIER HEAT PROTECTION	DEFORMED	74.20	74.20
2	REAR ENGINE MOUNTING NUT	NECESSARY	11.40	11.40
4	REAR ENGINE MOUNTING SCREW BIG	NECESSARY	12.40	12.40
4	REAR ENGINE MOUNTING SCREW SMALL	NECESSARY	8.40	8.40
1	REAR ENGINE CARRIER SPACER SLEEVE	NECESSARY	27.90	27.90
1	MAIN EXHAUST MUFFLER LH	BENT	2,469.70	2,469.70
2	MAIN EXHAUST MUFFLER CLAMP	NECESSARY	163.80	163.80
2	GASKET FRONT MUFFLER	NECESSARY	53.00	53.00
1	REAR CENTER MUFFLER SUPPORT REAR	BENT	202.70	202.70
8	REAR CENTER MUFFLER HEXAGON NUT	NECESSARY	16.80	16.80
2	TAIL PIPE CLAMP	NECESSARY	116.80	116.80
1	TAIL PIPE LH	BENT	1,040.50	1,040.50

Report Ref No. CC4/EQI18007294/Seb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR CENTER MUFFLER CLAMP	NECESSARY	265.40	265.40
1	MAIN EXHAUST MUFFLER SUPPORT LH	NECESSARY	283.80	283.80
4	MUFFLER SUPPORT NUT	NECESSARY	28.00	28.00
1	REAR CENTER MUFFLER BRACE LH	BENT	76.60	76.60
1	REAR END MEMBER	DENTED	3,954.20	3,954.20
4	ADHESIVE	NECESSARY	1,632.40	1,632.40
1	MIXING TUBE	NECESSARY	77.10	77.10
4	ACTIVATOR	NECESSARY 3PCS ONLY	686.40	514.80
5	THREADED INSERT	NECESSARY	526.50	526.50
5	THREADED INSERT	NECESSARY	526.50	526.50
5	THREADED INSERT	NECESSARY	446.50	446.50
50	LENS-HEAD SCREW	NECESSARY	85.00	85.00
5	WASHER	NECESSARY	61.50	61.50
5	THREADED INSERT	NECESSARY	503.00	503.00
1	NUT	NECESSARY	26.50	26.50
6	COOLANT	NECESSARY	113.40	113.40
3	BRAKE FLUID DOT 4 0.5L	NECESSARY	75.00	75.00
1	FRONT BUMPER SENSOR SUPPORT (ADDITIONAL)	NECESSARY	41.50	41.50
2	AIR BOX GROMMET (ADDITIONAL)	NECESSARY	10.20	10.20
4	AIR BOX FRAME (ADDITIONAL)	TORN	227.20	227.20
1	CATALYTIC CONVERTER LH (ADDITIONAL)	BENT	3,144.30	3,144.30
1	CATALYTIC CONVERTER GASKET LH (ADDITIONAL)	NECESSARY	40.30	40.30
1	REAR CENTER MUFFLER (ADDITIONAL)	BENT	2,516.00	2,516.00
9	CATALYTIC CONVERTER TORX SCREW (ADDITIONAL)	NECESSARY	28.80	28.80
1	FRONT BUMPER LOWER SUPPORT SPEED NUT (ADDITIONAL)	NECESSARY	1.10	1.10
1	TIMING BELT COVER (ADDITIONAL)	CUT	56.90	56.90
2	FRONT BUMPER LOWER SUPPORT SCREW (ADDITIONAL)	NECESSARY	5.20	5.20
1	FRONT BUMPER LOWER SUPPORT (ADDITIONAL)	NECESSARY	7.40	7.40
6	HEATER PIPE RETURN O-RING (ADDITIONAL)	NECESSARY	63.60	63.60
2	COMPRESSURE O-RING 16.7 X 2.5 (ADDITIONAL)	NECESSARY	33.00	33.00
2	AIR CON PRESSURE LINE O-RING (ADDITIONAL)	NECESSARY	10.20	10.20

Report Ref No. CC4/EQ18007294/Seb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COMPRESSOR PRESSURE LINE O-RING (ADDITIONAL)	NECESSARY	12.70	12.70
1	ENGINE TIMING BELT (ADDITIONAL)	CUT	137.10	137.10
2	THEMOSTAT O-RING (ADDITIONAL)	NECESSARY	33.00	33.00
2	SHOCK ABSORBER SCREW (ADDITIONAL)	NECESSARY	40.00	40.00
2	SHOCK ABSORBER NUT (ADDITIONAL)	NECESSARY	15.60	15.60
12	DRIVE SHAFT SCREW (ADDITIONAL)	NECESSARY	70.80	70.80
1	DRIVE SHAFT SPACER (ADDITIONAL)	NECESSARY	54.00	54.00
4	REAR SUSPENSION SUPPORT BOLT LH (ADDITIONAL)	NECESSARY	42.00	42.00
4	REAR SUSPENSION SUPPORT BOLT RH (ADDITIONAL)	NECESSARY	42.00	42.00
4	REAR CROSS MEMBER NUT (ADDITIONAL)	NECESSARY	24.80	24.80
2	WISHBONE BOLT (ADDITIONAL)	NECESSARY	13.40	13.40
4	WISHBONE LOCKING NUT (ADDITIONAL)	NECESSARY	20.40	20.40
2	WISHBONE ECCENTRIC SCREW (ADDITIONAL)	NECESSARY	57.40	57.40
2	WISH BONE ECCENTRIC WASHER (ADDITIONAL)	NECESSARY	53.80	53.80
4	SUB-FRAME BRACKET SCREW (ADDITIONAL)	NECESSARY	17.60	17.60
2	SUB-FRAME BRACKET NUT (ADDITIONAL)	NECESSARY	10.20	10.20
2	ANTI-ROLL BAR NUT (ADDITIONAL)	NECESSARY	13.80	13.80
2	FRONT AXLE HEX, NUT (ADDITIONAL)	NECESSARY	10.20	10.20
2	TRANSMISSION MOUNTING SCREW (ADDITIONAL)	NECESSARY	8.80	8.80
6	BRACE NUT (WF7) (ADDITIONAL)	NECESSARY	30.60	30.60
2	REAR SUSPENSION-STRUT BAR SCREW (ADDITIONAL)	NECESSARY	20.20	20.20
2	REAR SUSPENSION-STRUT BAR SOCKET BOLT (ADDITIONAL)	NECESSARY	10.20	10.20
4	REAR SUSPENSION-STRUT BAR HEXAGON-HEAD BOLT (ADDITIONAL)	NECESSARY	45.60	45.60
1	BRAKE CLEANER 200Z (ADDITIONAL)	NECESSARY	14.00	14.00
1	REAR TOP SPOILER DRIVING MECHANISM (ADDITIONAL)	CRACKED	6,300.00	6,300.00
1	LOGO S GALVANO SILVER 991	NECESSARY	94.40	94.40
	LESS 10% DISCOUNT		-5,106.30	-4,731.95
			45,956.70	42,587.55
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE FRONT / REAR WITH CASING (SN)	NECESSARY	140.00	140.00

Report Ref No. CC4/EQ118007294/Seb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
			190.00	190.00
	LABOUR			
	TO REPLACE / REAR BUMPER, REAR END CENTER MEMBER, & OTHER DAMAGED PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		18,720.00	17,160.00
	TO RESPRAY FRONT / REAR BUMPER, REAR CENTER MEMBER, REAR LH/RH FENDER INNER PANEL.		7,200.00	5,900.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		350.00	200.00
	TO CARRY-OUT BODY CAVITY PERSERVATION.		350.00	200.00
	TO MOUNT VEHICLE ONTO CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC.		3,120.00	3,120.00
	TO REPLACE HIGH PRESSURE PUMP & ASSY.		2,340.00	1,560.00
	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.		500.00	500.00
	TO REMOVE & REFIT REAR UNDER CARRIAGE.		3,120.00	2,340.00
	TO REMOVE & REFIT THE ENGINE ASSY INCLUDING REPLACE ENGINE MOUNTING.		4,680.00	3,900.00
	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.		1,560.00	1,560.00
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	560.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	250.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			43,350.00	37,850.00
GRAND TOTAL			89,496.70	80,627.55
RECOMMENDED COST OF REPAIRS				80,627.55

Report Ref No. CC4/EQ18007294/Seb3s2

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.