



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
SUPPLEMENTARY LIST

2nd Survey
Supplyment deck
Items.

ELROKARS GROUP

EQ Insurance

5 Maxwell Road, #17-00
Tower Block, MND Complex, 069110

NAME : Mr Lim Chee Ping
ADDRESS : 27 Springleaf Garden
Singapore 788187

WIP : 33317
EXCESS :
DATE: 21.05.2018

ATTN. : MOTOR CLAIMS
FAX :

TEL :

VEH NO :	SDF3636S	DATE IN :		CONTACT PERSON :	RICK	63602445
CHASSIS NO :	WPOZZ99ZCS114939P	MILEAGE :		TYPE OF CLAIM :	TP AGAINST GBG1361R	
MODEL :	Porsche 911 Carrera S	DATE REG.:	26.07.2012	POLICY NO. :		

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT BUMPER SENSOR SUPPORT <i>new</i>	1		\$ 41.50
2	AIR BOX GROMMET <i>new</i>	2		\$ 10.20
3	AIR BOX FRAME <i>new / TORX</i>	4		\$ 227.20
4	CATALYTIC CONVERTER LH <i>BA</i>	1		\$ 3,144.30
5	CATALYTIC CONVERTER GASKET LH <i>new</i>	1		\$ 40.30
6	REAR CENTER MUFFLER <i>BA</i>	1		\$ 2,516.00
7	CATALYTIC CONVERTER TORX SCREW <i>new</i>	9		\$ 28.80
8	FRONT BUMPER LOWER SUPPORT SPEED NUT <i>new</i>	1		\$ 1.10
9	TIMING BELT COVER <i>cut</i>	1		\$ 56.90
10	FRONT BUMPER LOWER SUPPORT SCREW <i>new</i>	2		\$ 5.20
11	FRONT BUMPER LOWER SUPPORT <i>new</i>	1		\$ 7.40
12	HEATER PIPE RETURN O-RING <i>new</i>	6		\$ 63.60
13	COMPRESSOR O-RING 16.7 X 2.5 <i>new</i>	2		\$ 33.00
14	AIR CON PRESSURE LINE O-RING <i>new</i>	2		\$ 10.20
15	COMPRESSOR PRESSURE LINE O-RING <i>new</i>	1		\$ 12.70
16	ENGINE TIMING BELT <i>cut</i>	1		\$ 137.10
17	THERMOSTAT O-RING <i>new</i>	2		\$ 33.00
18	SHOCK ABSORBER SCREW <i>new</i>	2		\$ 40.00
19	SHOCK ABSORBER NUT <i>new</i>	2		\$ 15.60
20	DRIVE SHAFT SCREW <i>new</i>	12		\$ 70.80
21	DRIVE SHAFT SPACER <i>new</i>	6		\$ 54.00
22	REAR SUSPENSION SUPPORT BOLT LH <i>new</i>	4		\$ 42.00
23	REAR SUSPENSION SUPPORT BOLT RH <i>new</i>	4		\$ 42.00
24	REAR CROSS MEMBER NUT	4		\$ 24.80
25	WISHBONE BOLT	2		\$ 13.40
26	WISHBONE LOCKING NUT	4		\$ 20.40
27	WISHBONE ECCENTRIC SCREW	2		\$ 57.40
28	WISH BONE ECCENTRIC WASHER	2		\$ 53.80
29	SUB-FRAME BRACKET SCREW	4		\$ 17.60
30	SUB-FRAME BRACKET NUT	2		\$ 10.20
31	ANTI-ROLL BAR NUT	2		\$ 13.80
32	FRONT AXLE HEX. NUT	2		\$ 10.20
33	TRANSMISSION MOUNTING SCREW	2		\$ 8.80
34	BRACE NUT (WF57)	6		\$ 30.60
35	REAR SUSPENSION-STRUT BAR SCREW	2		\$ 20.20
36	REAR SUSPENSION-STRUT BAR SOCKET BOLT	2		\$ 10.20



PORSCHE

STUTT GART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



EQ Insurance		NAME : Mr Lim Chee Ping		WIP : 33317	
5 Maxwell Road, #17-00		ADDRESS : 27 Springleaf Garden		EXCESS :	
Tower Block, MND Complex, 069110		Singapore 788187		DATE: 18.04.2018	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SDF3636S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WPOZZZ99ZCS114939P	MILEAGE :		TYPE OF CLAIM :	TP AGAINST GBG1361R
MODEL :	Porsche 911 Carrera S	DATE REG.:	26.07.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT BUMPER 991 ✓ Deform	1		\$ 1,955.00
2	FRONT NUMBER PLATE HOLDER BLACK ✓ CRK	1		\$ 45.90
3	FRONT BUMPER LOWER AIR DUCT CENTRE ? pg ✓	1		\$ 233.60
4	FRONT BUMPER LOWER SPOILER ✓ SCR	1		\$ 170.90
5	SENSOR PARKASSIST ? ✓	2		\$ 509.40
6	SENSOR GASKET ? ✓	2		\$ 8.60
7	FRONT BUMPER CLIP ✓ NEC	2		\$ 64.80
8	FRONT BUMPER BLIND RIVET ✓ NEC	2		\$ 10.40
9	FRONT BUMPER REINFORCEMENT ✓ DT	1		\$ 1,166.20
10	FRONT BUMPER REINFORCEMENT SEAL ✓ NEC	2		\$ 13.60
11	FRONT BUMPER REINFORCEMENT SCREW ✓ NEC	6		\$ 25.20
12	REAR BUMPER ✓ Deform	1		\$ 2,010.30
13	REAR SENSOR PARKASSIST ✓ DMG	3		\$ 764.10
14	REAR BUMPER TAPPING SCREW ✓ NEC	5		\$ 3.50
15	REAR BUMPER REINFORCEMENT ✓ NEC (Nut)	5		\$ 8.50
16	REAR BUMPER UPPER HEAT PROTECTION CENTRE BIG ✓ Deform	1		\$ 268.60
17	REAR BUMPER HEAT PROTECTION CENTER SMALL ✓ Deform	1		\$ 59.30
18	REAR BUMPER SUPPORT LH X	1		\$ 550.30
19	REAR BUMPER SUPPORT HEAT PROTECTION INNER LH X	1		\$ 181.00
20	REAR BUMPER TOP SUPPORT CENTER X	1		\$ 1,606.30
21	REAR BUMPER LOWER SPOILER BLACK ✓ Deform	1		\$ 168.50
22	REAR BUMPER LOWER RETAINING STRIP ✓ Deform	1		\$ 55.30
23	COVER TAIL PIPE BLACK LH ✓ SCR	1		\$ 62.60
24	COVER TAIL PIPE BLACK RH X LRA ✓	1		\$ 62.60
25	REAR BUMPER LOWER RETAINING STRIP BLIND RIVET ✓ NEC	1		\$ 5.20
26	REAR BUMPER REINFORCEMENT ✓ DT	1		\$ 869.60
27	REAR TOP SPOILER INNER COVER LH ✓ CRK	1		\$ 12.90
28	REAR TOP SPOILER INNER COVER RH ✓ CRK	1		\$ 12.90
29	LOGO PORSCHE GALVANO SILVER ✓ NEC	1		\$ 189.50
30	LOGO CARRERA GALVANO SILVER ✓ NEC	1		\$ 122.90
31	LOGO S GALVANO SILVER 991 ✓ NEC	1		\$ 94.40
32	LOGO "911" SMALL ✓ NEC	1		\$ 129.00
33	BONETT LOGO ADHESIVE FILM ✓ NEC	1		\$ 2.20
34	REAR BUMPER WIRING HARNESS ✓ CRK	1		\$ 297.70
35	REAR LIGHT (LH) ✓ CRK	1		\$ 1,382.90
36	LICENSE PLATE LIGHT ✓ DMG	2		\$ 170.20

37	REAR REFLECTOR LEFT ✓ CRK	1	/	P991-631-485-02-	\$	32.30
38	AIR BOX HOUSING COVER OUTER ✓ CRK	1	/	P991-110-231-01-	\$	425.00
39	AIR CLEANER CARTRIDGE X	2	/	P991-110-130-00-	\$	217.60
40	AIR BOX CENTER GASKET ✓ NEC	1	/	P991-110-131-00-	\$	58.10
41	AIR BOX HOUSING COVER INNER ✓ CRK	1	/	P991-110-212-02-	\$	493.00
42	AIR BOX HOUSING CENTER AIR GUIDE X	1	/	P991-110-261-03-	\$	245.20
43	HIGH-PRESSURE PUMP ✓ Leak	1	/	P9A1-110-315-06-	\$	2,160.80
44	O-RING ✓ NEC	1	/	P999-707-643-40-	\$	10.10
45	HIGH-PRESSURE PUMP TORX SCREW M6X25 ✓ NEC	4	/	P900-385-072-01-	\$	4.40
46	TORX SCREW ✓ NEC	1	/	P900-385-045-01-	\$	2.00
47	SCREW PLUG ✓ NEC	4	/	P900-385-041-01-	\$	4.40
48	REAR ENGINE HYDRAULIC MOUNT ? Acc ✓	2	/	P991-375-059-08-	\$	5,654.00
49	REAR ENGINE CARRIER ✓ DT	1	/	P9A1-375-014-08-	\$	821.70
50	REAR ENGINE CARRIER SCREW ✓ NEC	1	/	P900-378-332-01-	\$	5.50
51	REAR ENGINE CARRIER HEXAGON NUT ✓ NEC	2	/	PN -102-861-10-	\$	3.40
52	REAR ENGINE CARRIER HEXAGON-HEAD BOLT ✓ NEC	1	/	P900-378-286-01-	\$	9.40
53	REAR ENGINE CARRIER HEAT SHIELD BOLT ✓ NEC	3	/	PN -100-988-08-	\$	3.60
54	REAR ENGINE CARRIER HEAT PROTECTION ✓ Deform	1	/	P9A1-102-251-01-	\$	74.20
55	REAR ENGINE MOUNTING NUT ✓ NEC	2	/	PN -908-484-05-	\$	11.40
56	REAR ENGINE MOUNTING SCREW BIG ✓ NEC	4	/	P900-385-168-01-	\$	12.40
57	REAR ENGINE MOUNTING SCREW SMALL ✓ NEC	4	/	P900-385-167-01-	\$	8.40
58	REAR ENGINE CARRIER SPACER SLEEVE ✓ NEC	1	/	P9A1-375-245-01-	\$	27.90
59	MAIN EXHAUST MUFFLER LH ✓ DT	1	/	P991-111-321-03-	\$	2,469.70
60	MAIN EXHAUST MUFFLER CLAMP ✓ NEC	2	/	P997-111-520-00-	\$	163.80
61	GASKET FRONT MUFFLER ✓ NEC	2	/	P991-111-482-00-	\$	53.00
62	REAR CENTER MUFFLER SUPPORT REAR ✓ DT	1	/	P991-111-473-01-	\$	202.70
63	REAR CENTER MUFFLER HEXAGON NUT ✓ NEC	8	/	PN -104-355-01-	\$	16.80
64	TAIL PIPE CLAMP ✓ NEC	2	/	P997-111-240-30-	\$	116.80
65	TAIL PIPE LH ✓ DT	1	/	P991-111-361-03-	\$	1,040.50
66	REAR CENTER MUFFLER CLAMP ✓ NEC	2	/	P991-111-481-01-	\$	265.40
67	MAIN EXHAUST MUFFLER SUPPORT LH ✓ NEC	1	/	P991-111-471-03-	\$	283.80
68	MUFFLER SUPPORT NUT ✓ NEC	4	/	P900-380-006-02-	\$	28.00
69	REAR CENTER MUFFLER BRACE LH ? DT ✓	1	/	P991-111-475-00-	\$	76.60
70	REAR END MEMBER ✓ DT	1	/	P991-501-903-01-GRV	\$	3,954.20
71	ADHESIVE ✓	4	/	P000-043-305-41-	\$	1,632.40
72	MIXING TUBE ✓	3	/	P000-043-206-32-	\$	77.10
73	ACTIVATOR ✓	4	/	P000-043-305-31-	\$	686.40
74	THREADED INSERT Photo	5	/	P999-504-262-01-	\$	526.50
75	THREADED INSERT	5	/	P999-504-263-01-	\$	526.50
76	THREADED INSERT NEC	5	/	P999-504-268-01-	\$	446.50
77	LENS-HEAD SCREW	50	/	P999-073-917-01-	\$	85.00
78	WASHER	5	/	P999-025-285-31-	\$	61.50
79	THREADED INSERT	5	/	P999-504-267-01-	\$	503.00
80	NUT	5	/	P999-500-196-01-	\$	26.50
81	COOLANT	6	/	PASL-043-301-48	\$	113.40
82	BRAKE FLUID DOT 4 0.5L	3	/	PASL-043-203-66	\$	75.00
TOTAL PARTS					\$	37,009.80
LESS 10%					\$	3,700.98
TOTAL PARTS COST					\$	33,308.82
Labour Description						

1	TO REPLACE FRONT / REAR BUMPER, REAR END CENTER MEMBER, <i>1560/day</i> & OTHER DAMAGED PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 18,720.00 <i>17160</i>	
2	TO RESPRAY FRONT / REAR BUMPER, BONNET, REAR END CENTER MEMBER. REAR LH/RH FENDER INNER PANEL. <i>bumper 1300 other 1100 / panel</i>		\$ 7,200.00 <i>5900</i>	
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		\$ 350.00 <i>100</i>	
4	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 350.00 <i>200</i>	
5	TO MOUNT VEHICLE ONTO CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC	NETT	\$ 3,120.00	✓
6	TO REPLACE HIGH PRESSURE PUMP & ASSY		\$ 2,340.00 <i>1560</i>	
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	NETT	\$ 500.00	✓
8	TO REMOVE & REFIT REAR UNDER CARRIAGE.		\$ 3,120.00 <i>3900</i>	
9	TO REMOVE & REFIT THE ENGINE ASSY INCLUDING REPLACE ENGINE MOUNTING		\$ 4,680.00	
10	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 1,560.00	✓
11	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00	✓
12	TO SUPPLY 1 SET NUMBER PLATE FRONT / REAR WITH CASING.	NETT	\$ 140.00	✓
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 250.00	✓
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00	✓
15	SUNDRIES.	NETT	\$ 50.00	✓

Sebastian. 19/4/18.

- Part by part repair.
- Question mark Item Photo.
- Photo Before Paint.

90036121

Sebastianyang@lkkauto.com

TOTAL LABOUR	\$ -	\$ 43,540.00
TOTAL PARTS	\$ -	\$ 33,308.82
TOTAL	\$ -	\$ 76,848.82
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

22 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: