

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0222/18

DATE : 14-APR-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AXA INSURANCE S'PORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

S(068811)

TEL : 68804741

FAX : 68804838

ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : LIM PHUAY HOON (LIN PEIYUN)

ADDRESS : BLK 312A ANCHORVALE LANE

#05-52

S(541312)

TELEPHONE NO : 91800673

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SJK1368G

MODEL CODE : FDLARWAK12EYABAA-A

MODEL/YEAR : MARCH 1.4E A/T (II)

ENGINE NO : CR14115000A

CHASSIS NO : JN1FBAK12Z0020019

MILEAGE : 242755 KM

DATE IN : 14/04/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH - 96450079

ACCIDENT DATE : 13/04/2018

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJK1368G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW RH FRONT FENDER AND RH FRONT DOOR.	600.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	
3	ZZ/003	REMOVE AND INSTALL RH FRONT DOOR MECHANISM.	80.00	
		TOTAL LABOUR CHARGES	1280.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1368G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			50.00
2	FRONT DOOR CHECK LINK RH	80430-AX000	47.90		
3	FRONT DOOR LOWER HINGE RH	80420-AX000	56.10		
4	FRONT DOOR UPPER HINGE RH	80400-AX000	56.10		
5	DOOR-FRONT RH	H010M-AZ00A	747.60		
6	FRT FENDER SIGNAL LAMP RH	26100-8990A	48.50		
7	FENDER-FRONT RH	63100-AX030	419.20		
SUB TOTAL			1375.40	0.00	50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			275.08	0.00	0.00
GRAND TOTAL			1100.32	0.00	50.00
OVERALL TOTAL			1150.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJK1368G

TOTAL LABOUR CHARGES 1280.00
TOTAL SPARE PARTS CHARGES 1150.32

GRAND TOTAL 2430.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.