

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

Not Ashairul
1-B.1
Recovery B4 team

ACCIDENT REPAIR ON : SKF5286Y

MODEL : TOYOTA ALTIS 1.6

POLICY NO : GA108410/1

CHASSIS NO : ZNE100327121

YEAR OF MANUFACTURE : 2012

DATE / TIME OF ACCIDENT: 17/04/2018 Time: 1650Hrs ALONG PAYA LEBAR RD TWDS TANJONG

THIRD PARTY VEHICLE NO : GY4428J

Date: 20/04/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount	
		S\$		S\$	
1 Boot Lid	1	754.70	Dented	754.70	✓
2 Boot Lid Emblem	1	59.20	Necessary	59.20	✓
3 Boot Lid Lettering/Plate "Dual"	1		Necessary	-	✓
4 Boot Lid Lettering "1.6"	1		Necessary	-	✓
5 Boot Lid Lettering "VVT-I"	1		Necessary	-	✓
6 Boot Lid Lettering "Corolla"	1	57.40	Necessary	57.40	✓
7 Boot Lid Lettering "Altis"	1	56.13	Necessary	56.13	✓
8 Boot Lid Lettering/Plate "Elegance"	1		Necessary	-	✓
9 Boot Lid Hinge LH	1	158.94	Bented	158.94	X
10 Boot Lid Hinge RH	1	158.94	Bented	158.94	X
11 Boot Lid Finisher Chrome	1	196.59	Cracked	196.59	X
12 Boot Lid Lock Assy	1	194.71	Bented	194.71	X
13 Boot Lid Weatherstrip	1	166.40	Cut	166.40	?
14 Boot Lid Lamp RH	1	261.60	Broken	261.60	✓
15 Rear Windscreen Moulding Set	1	118.80	Necessary	118.80	X
16 Rear Bumper	1	539.60	Broken	539.60	✓
17 Rear Bumper Side Retainer (Long) LH	1	52.30	Necessary	52.30	X
18 Rear Bumper Side Retainer (Short) LH	1	75.20	Necessary	75.20	X
19 Rear Bumper Side Retainer (Long) RH	1	52.30	Necessary	52.30	✓
20 Rear Bumper Side Retainer (Short) RH	1	75.20	Necessary	75.20	✓
21 Rear Bumper Reflector RH	1	136.40	Broken	136.40	?
22 Rear Fender RH	1	918.01	Dented	918.01	X
24 Rear Fender Seal Retainer RH	1	50.31	Broken	50.31	?
25 Tail Lamp RH	1	347.80	Broken	347.80	✓
26 Tail Lamp Bracket RH	1	174.48	Torn	174.48	?
27 Tail lamp panel RH	1	147.48	Dented	147.48	?
28 Rear End Panel	1	580.90	Dented	580.90	?
29 Rear End Panel Top Garnish	1	181.72	Kinked	181.72	X
30 Spare Tyre Panel	1	702.93	Dented	702.93	X

Sub-Total: 6,218.04
Less Discount 25% 1,554.51
Total Parts: 4,663.53

Special Nett Items

1	Anti-rust coating	3	80.00	240.00	301
2	Rear Bumper Clips	10	5.20	52.00	✓
3	Rear Fender Shield Clips	10	3.50	35.00	x
4	Rear End Panel Top Garnish Clips	10	3.50	35.00	x
5	Windscreen sealant	1	80.00	80.00	x
6	Rear fender sealant	1	80.00	80.00	x
7	Rear end panel sealant	1	80.00	80.00	x
8	Spare tyre panel sealant	1	80.00	80.00	x
9	Rear bumper sensor set	1	250.00	250.00	
Total Parts:				932.00	

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	2,200.00	901
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,200.00	881
3	Provide skill labour to disconnect and check electrical wiring	30.00	201
4	Remove and refit rear windscreen	150.00	x
5	Remove and refit rear end panel lining and garnish to facilitate repair	50.00	x
6	Remove and replace bumper sensors	50.00	✓
7	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs	100.00	801
8	Provide skill labour to realign chassis alignment bench	250.00	x
9	Remove and refit exhaust pipe/system to facilitate repair	80.00	x
10	Dismantle and transfer bootlid fittings and mechanism to new/facilitate repair	60.00	501
Total Labour:		4,170.00	
Total Parts & Labour:		9,765.53	
GST 7%		683.59	
Grand Total:		10,449.12	

Estimate Repair Duration17 days

6 days

ACCIDENT VEHICLE OF : **SKF5286Y**

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth
 Company : Lkk
 Date : 24/11/18
 Time : 12.30pm
 Contact No : 96910663
 Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: