

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG18007312/T1UA3S2**Date:** 27/07/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800037501
Claimant Vehicle No :	SJW9125A	Insured Vehicle No :	SLX7951R
Date of Loss:	18/04/2018	Nature of Claim:	TP
		Claim No:	9665320512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW9125A	Engine No:	CDL027423
Make & Model:	AUDI S3 SB, 2.0 TFSI QU (PANORAMIC ROOF) (M)	Chassis No:	WAUZZZ8P7AA139148
Reg. Date:	28/04/2010 (Man. Year: 2010)	Odometer:	111743 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		19,360.00		
Nett Amount (S\$)	0.00	19,360.00	-19,360.00	
+ Loss of Use (14.0 x S\$90.00/day) (S\$)		1,260.00		
Nett Liability (S\$)		20,620.00		

INSPECTION

Date of Assignment:	23/04/2018		
Date Inspected:	23/04/2018	Inspected At:	24 BENOI SECTOR
Estimated Period of Repair:	0.0 days		Repairer: Premium Automobiles Pte Ltd

Adjuster: ADRIAN LING**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/27/2018

Adjuster Report

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$52,000.00

LTA REIMBURSEMENT VALUE (RV) : \$29,968.00

NETT VALUE : \$22,000.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >