

ASS. REG. BY:

REF: CS/ATG18007313/Ggber

Special Instructions:

Surveyor:

GQ

ASSIGNMENT (Office)

Medium

From (Person): Darshene Supramaniam

Alt

Date/Time: 19042018 331pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SV 1902G

Insured:

at Workshop m/s

Sin Tien Seng

Tel:

6748 1231

of

10 Kallang Way

Policy No:

2102186821

Claim No:

694891254656

Sum Insured:

Excess:

600

Make of Veh:

D.O.A. 15042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

20042018

H.O.D. Endorsement:

Date/Time:

19042018 529pm

Person Contacted:

Enc

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SV 1902G - RS3/ATG15011312/Rlgbk3 D.A. 12072013
23/4/18 @ 2:58pm	revert to Darshene via Medium.
25/4/18 @ 9:34am	revert to Darshene via Medium. (Cepher agreed US \$12.5k)
25/4/18 @ 4:48pm	Victor informed C/A not more than US \$12500 via Medium.
25/4/18 @ 5:57pm	Informed Mr Said C/A not more than US \$12500 @ Ex: \$600.

Chassis No: 19026

Xae

REF: MLH

2715C

ASSIGNMENT

From: 20042018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SVV 19026

at Workshop m/s: Sin Tien Seng

of: 10 Kallang Way

Insured: Said 68401143

Policy No:

Claims No:

Sum Insured: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$25K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 18 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SVV 19026 Yr Regn: 14 Jan 2010

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Daihatsu Terios G.C. 1495

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 90814 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JDAJ200 G 001017132

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 65 R16

Front RH / Rear LH " Full

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front RH Rear LH

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 20-04-18 2pm

Survey held at W/S

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

and o/s frt, Rear o/s.

The ☒ U/C Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
23/4	Said agreed repair limit \$11K.
25/4	Said agreed \$12500 L/S repair Max.
11/6	Finalized - \$12500 with Said.
	LRA \$6856.83, 35%.

RECEIVED 19 JUN 2018

Date/Time, File Pass to? ☐ : Preli. Report

11/16 travise ☐ : Final Report

Date/Time, File Return to?

31

Days Of Repair: 18

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

\$ + RS. \$

Phone

Other

TOTAL

Report Format: MER-00

Lump Sum / L.B. (\$): 12500

200

0

200

Catherine Chong (LKK Auto)

From: Supramaniam, Darshene <Darshene.Supramaniam@aig.com>
Sent: Thursday, 19 April, 2018 3:31 PM
To: 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: OD New Assignment - SJV1902G (OI) DOA 15/04/2018
Attachments: SJV1902G - 18 APRIL.TIF

Hi,

Claim number : TO BE ADVISED
Case owner : TO BE ADVISED

Please be informed that the claim is currently pending for registration in system. We will advise the details as soon as possible.

Thank you.

Darshene Supramaniam

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 25 April 2018 5:57 PM
To: 'ACCTCLAIM'
Cc: SUR
Subject: RE: SJV1902G REPAIR LIMIT

Dear Said,

As instructed by our client, please proceed to repair the insured vehicle **SJV 1902G** at repair cost not more than **\$12,500.00 on Lump Sum basis (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ACCTCLAIM [mailto:acctclaim@sts.com.sg]
Sent: Wednesday, 25 April 2018 3:05 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: SJV1902G REPAIR LIMIT

Hi Ms Siew

Guo Qiang already has copies of ci & driver's D/L. Anyway pls find attached.

Regards

Said

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, April 25, 2018 2:41 PM
To: ACCTCLAIM
Subject: RE: SJV1902G REPAIR LIMIT

Dear Said,

Kindly provide driver's (Azhar Bin Ghani) driving license copy.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	16 Apr 2018 11:51	Clim Veh Model Changed	(201704) DAIHATSU TERIOS 1.5 2WD (M).		[] Merimen Administrator
2	16 Apr 2018 11:51	Clim Created	Reg No: SJV1902G, Policy No: 2100186821-08, Acct Date: 2018/04/15, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd, (SG), Ins.Status => Notification, Created from SAS:MSTS18049916		[I] Merimen Administrator
3	19 Apr 2018 18:17	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
4	19 Apr 2018 18:17	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] CATHERINE CHONG KAI LING
5	19 Apr 2018 18:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	19 Apr 2018 18:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/30		[A] CATHERINE CHONG KAI LING
7	19 Apr 2018 18:17	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	19 Apr 2018 18:17	Clim Registration Modified	Rep:1137->200067.		[A] CATHERINE CHONG KAI LING
9	19 Apr 2018 18:17	Adj Adjuster Assigned	[None] -> XING GUO QIANG		[A] CATHERINE CHONG KAI LING
10	20 Apr 2018 10:12	Clim Registration Modified	Acct Time:15:05:00->15:00:00, Pol No:2100186821-08->2100186821.		[I] Kaur, Baljit
11	20 Apr 2018 11:06	Clim Registration Modified	Init.Est.:->5,000 - 6,000.		[I] Tr, Tinesh
12	23 Apr 2018 14:50	Adj Rpt Initiated			[A] SHIAU CHAN
13	23 Apr 2018 14:50	Clim Dtl Modified	JPJ Reg. Date: -> 2010/01/14.		[A] SHIAU CHAN
14	23 Apr 2018 14:50	Clim Details Notified			[A] SHIAU CHAN
15	23 Apr 2018 14:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/30		[A] SHIAU CHAN
16	23 Apr 2018 14:57	Adj Mandate Request	Cur.Req:16722.87:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDER TAKE THE REPAIR COST NOT MORE THAN \$11,000.00 ON PART BY PART BASIS. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
17	25 Apr 2018 09:27	Adj Mandate Request Cancelled			[A] SHIAU CHAN
18	25 Apr 2018 09:33	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/30		[A] SHIAU CHAN
19	25 Apr 2018 09:34	Adj Mandate Request	Cur.Req:16722.87:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. REPAIRER AGREED REPAIR COST NOT MORE THAN \$12,500.00 ON LUMP SUM DUE TO THEY ARE EXPECT HAVE FURTHER SUPPLEMENTARY. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
20	25 Apr 2018 15:32	Clim Registration Modified	Excess: -> 600.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.		[I] Tr, Tinesh
21	25 Apr 2018 15:32	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
22	25 Apr 2018 16:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/30, Mandate Remarks: Repair limit not exceeding \$12,500.00, Re-inspection to be done for damage check and supplementary items / labour.		[I] Koh, Victor-CK
23	25 Apr 2018 16:48	Adj Mandate Set	Approved:12500.00:Repair limit not exceeding \$12,500.00, Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1784496	23/04/2018 14:50	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJV1902G		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 25 Apr 2018

Preliminary Advice

Vehicle No	: SJV1902G	Accident Date	: 15/04/2018
Make	: DAIHATSU TERIOS	Policy No.	: 2100186821
Assignment Date	: 19/04/2018	Excess	: S\$0.00
Date of Inspection	: 20/04/2018	Est. Duration of Repair	: 18.00
Inspection At	: SIN TIEN SENG PTE LTD (KALLANG) 10 KALLANG WAY SINGAPORE 349215		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s front & rear o/s portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	17,960.97
Revised Amount	:S\$	12,662.34
Check Items (Estimated)	:S\$	4,060.53
Total	:S\$	16,722.87
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	12,275.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,725.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED REPAIR COST NOT MORE THAN \$12,500.00 ON LUMP SUM DUE TO THEY ARE EXPECT HAVE FURTHER SUPPLEMENTARY.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 23 Apr 2018

Preliminary Advice

Vehicle No	: SJV1902G	Accident Date	: 15/04/2018
Make	: DAIHATSU TERIOS	Policy No.	: 2100186821
Assignment Date	: 19/04/2018	Excess	: S\$0.00
Date of Inspection	: 20/04/2018	Est. Duration of Repair	: 18.00
Inspection At	: SIN TIEN SENG PTE LTD (KALLANG) 10 KALLANG WAY SINGAPORE 349215		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, o/s front & rear o/s portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	17,960.97
Revised Amount	:S\$	12,662.34
Check Items (Estimated)	:S\$	4,060.53
Total	:S\$	16,722.87

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	12,275.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,725.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILLING TO UNDER TAKE THE REPAIR COST NOT MORE THAN \$11,000.00 ON PART BY PART BASIS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2715C
Vehicle Details	
Vehicle No.:	SJV1902G
Vehicle to be Exported:	No
Intended De-registration Date:	23 Apr 2018
Vehicle Make:	DAIHATSU
Vehicle Model:	TERIOS 1.5L 2WD MANUAL ABS AIRBAG
Primary Colour:	Green
Manufacturing Year:	2008
Engine No.:	2149323
Chassis No.:	JDAJ200G001017132
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,523.00
Original Registration Date:	14 Jan 2010
First Registration Date:	14 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$16,523.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2020
PARF Rebate Amount:	\$9,087.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$3,188.00
Total Rebate Amount:	\$12,275.00

The information contained herein is correct as at 23 Apr 2018

OK

► terios Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Daihatsu Terios 7	\$33,800	\$12,230 /yr	08-Feb-2010	1,495 cc	132,143 km	Benefit Auto Enterprise Pte Ltd	Availat

A Deal Not To Be Missed! 7 Seater SUV, Beautiful Pearl White, Well Groomed And Taken Care Off By Careful Owner, Trade In Welcomed, In House/Bank Loan Available With Flexible Interest Rates, Kindly Con...

Office No. - 68444161

Aris Sidek - 91086131 | Kevin - 90268203 | Ben - 92222719

Daihatsu Terios 1.5M	\$31,800	\$8,580 /yr	23-Dec-2010	1,495 cc	-	William Lee Car Aircon Engineering	Availat
-----------------------------	-----------------	--------------------	--------------------	-----------------	----------	---	----------------

1 Owner. 100% Accident Free. Near Perfect Original Paint With No Door Dent! Extremely Well Maintained Leather And Sport Rims. Unbelievable Condition Low Downpayment. See For Yourself.

Office No. - 63821006

Erik Lee - 87778500 | Ben - 98274488 | William - 94557994 | Keith - 98290368

Daihatsu Terios 7	\$32,800	\$11,050 /yr	16-Mar-2010	1,495 cc	88,000 km	WM Car Pte Ltd	Availat
--------------------------	-----------------	---------------------	--------------------	-----------------	------------------	-----------------------	----------------

SUV With 7 Seats. Low Mileage Well Kept Excellent Condition. Spacious Interior And Boot Space. Accident Free. No Repairs. Powerful Yet Fuel Efficient Engine. Overhead Rear Aircon F Or Second And Third...

Office No. - 64634936

Ivan Choo - 97629200 | Peng Hee - 91761283 | Chris Ong - 91375618

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2018 11:09
Date Of Accident	15/04/2018 15:05
Exact Location Of Accident	ECP CHANGI TOWARDS CITY ROCHOR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV1902G
Insured/Policyholder	
Name Of Registered Owner	TEO HUEI HUEI @AESHA ABDULLAH TEO
NRIC No	S7602715C
Email Address	LAURELTEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82281061
Alternative Phone No	OTHERS-82281061

Vehicle Particulars

Manufacturer	DAIHATSU
Model	TERIOS-1.5 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100186821-08
Cover Note Number	

Driver

Name of Driver	AZHAR BIN GHANI
NRIC No	S6945589A
Date Of Birth	29/12/1969
Occupation	INDOOR
Date Of Driving Pass	31/03/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93691431
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 1 MARINE TERRACE #10-298
Postcode	440001
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TEO HUEI HUEI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	


Circumstances of Accident

WE WERE DRIVING ALONG ECP FROM CHANGI TOWARDS CITY WHEN WE EXITED AT ROCHOR, MIDWAY DOWN THE SLIP ROAD, THE RIGHT TYRE SUFFERED A PUNCTURE. THIS CAUSED THE CAR TO VEER LEFT AND HIT THE LEFT WALL AND RAILING. THE IMPACT THEN CAUSED THE CAR TO SPIN AND SWING RIGHT AND HIT THE RIGHT RAILING. THE CAR SLIDDED AND STOPPED NEAR THE BOTTOM OF THE SLOPE OF THE SLIP ROAD ACROSS THE SUNTEC CITY. THE INCIDENT HAPPENED AT AROUND 3.05 PM. SUNDAY 15TH APRIL 2018. NO OTHER VEHICLES WERE INVOLVED. WEATHER SLIGHT DRIZZLE, ROAD WET AND SLIPPERY. WE CALLED AIG TOW SERVICE AT 3.12 PM, THEY ADVISED NO NEED FOR POLICE REPORT AS DAMAGE TO PUBLIC WAS NOT SEVERE. TOW TRUCK ARRIVED AT ABOUT 4-4.15 PM.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

We were driving along ECP from Changi towards city. When we exited at Rochor, midway down the slip road, the right rear tyre suffered a puncture. This caused the car to veer left and hit the left wall (concrete) and railing. The impact then caused the car to spin and swing right. And hit the right railing. The car slid and stopped near the bottom of the slope of the slip road, across from Suntec City. The incident happened at around 3.05pm, Sunday 15th April 2018. No other vehicles were involved. Weather: light drizzle, road was ~~slightly~~ slippery. We called ~~AAA~~ AIG tow service at 3.12pm. They advised we need for police report as damage to public property was not severe. Tow truck arrived at about 4-4.15pm.

DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature

Date & Time:

16/4/2018

SM/PLC/IncidentForm_V3



Driver's Signature

(If driver is not the policyholder)

Date & Time: 16 Apr 2018 0947



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : Azhar Bin GhaniVEHICLE NUMBER : STV 1902 GDATE/TIME OF ACCIDENT : 15th April 2018, 3.05pmPLACE OF ACCIDENT : ECP Changi towards City, After Exit slip roadTHIRD PARTY VEHICLE (IF ANY): N/A

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

We started from home (Bldg 2 Marine Terrace) and were heading to Arab Street.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

No.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Right rear tyre burst, causing vehicle to spin left and hit left railing of slip road/ramp, impact of collision caused car to swing right and hit right railing. No other vehicles involved. Damage to front and back of own vehicle.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No injury727Name: AZHAR BIN GHANI

I Affirmed The Above Information Is Given To My Best Knowledge.

Name of Policyholder : Teo Huei Huei (Zhang Huihui) @ Alesha Abdullah Teo
Period of Insurance : 14 Jan 2018 To 13 Jan 2019
Engine No. : 2149323
Chassis No. : JDAJ200G001017132

Vehicle No. : SJV1902G
Policy No. : 2100186821-08
Endorsement No. :
Issued Date : 05 Dec 2017

ABOUT THE COVER

Make/Model : DAIHATSU TERIOS 1.5
Engine Capacity/Tonnage : 1,495.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2010
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Teo Huei Huei (Zhang Huihui) @ Alesha Abdullah Teo - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Sin Tian Seng Kallang Centre: Add: 10 Kallang Way, Singapore 349215 67481231 67486708

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0600636010

SIN TIEN SENG PTE LTD

10 KALLANG WAY KALLANG CENTRE

SINGAPORE 349215

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

88CFH

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7602715C



Name
TEO HUEI HUEI
(ZHANG HUIHUI)
@ALESHA ABDULLAH TEO
張 暉 暉
Race
CHINESE
Date of birth: 05-02-1976 Sex: F
Country of birth: SINGAPORE

S7602715C



3834638

NRIC No: S7602715C



Date of issue
10-11-2004

APT BLK 1 MARINE TERRACE #10-298
SINGAPORE 440001

NRIC No: S7602715C

Date: 01-10-2005 No: 5256118

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6945589A



Name
AZHAR BIN GHANI
Race
MALAY
Date of birth: 29-12-1969 Sex: M
Country of birth: SINGAPORE

S6945589A



5947184

NRIC No: S6945589A



Next Group: A+ Date of issue
11-05-1993

APT BLK 1 MARINE TERRACE #10-298
SINGAPORE 440001

NRIC No: S6945589A

Date: 01-10-2005 No: 5256117

REPUBLIC OF SINGAPORE DRIVING LICENCE



AZHAR BIN GHANI

Date of birth: 29 Dec 1969
Valid until: 31 Mar 2009



001725904F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 31 Mar 2009



Licence No: S6945589A

NP 428A

Distributor & Dealer for



DAIHATSU

DENSO PRiXMAX

新天成私人有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PL
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1166
10 Kallang Way, Singapore 349215
Fax: 6748-0707 68401128
E-mail: admin@sts.com.sg
Co Reg No: 197000883D

JILONG CENTRE: Tel: 6561-6611
6 Toban Gardens Crescent, Singapore 600021
Fax: 6561-9539

BOON KENG SHOWROOM: Tel: 6208-1466
Blk 34 Whampoa West #01-75/77, Singapore 330034
Fax: 6208-1462

Your ref: 16.04.2018
Our ref: Dear Sir
Date

ESTIMATE FOR VEHICLE ACCIDENT REPAIR (DOA 15.04.2018)

VEHICLE DETAILS: -

REGISTRATION NUMBER : SJV1902G
VEHICLE MODEL : D-J200RG-GMDFW-H
CHASSIS NUMBER : JDAJ200G001017132
ENGINE NUMBER : 2149323
MILEAGE (KM) : 90814 KM
REGISTRATION DATE : 14.01.2010

INSURANCE DETAILS: -

INSURED'S NAME : TEO HUEI HUEI @ ALESHA ABDULLAH TEO
INSURED'S ADDRESS : BLK 1 MARINE TERRACE
#10-298
SINGAPORE 440001

POLICY NUMBER : 2100186821-08000
EXPIRY DATE : 13.01.2019
EXCESS PAYMENT : \$600/-

We are pleased to enclose to you our estimate for your consideration and approval. Please send your surveyor to our Kallang Service Centre 10 Kallang Way, Singapore 349215 where the above mentioned vehicle is now stored. Kindly contact Mr SAID/ERIC LOH at telephone number 6-748 1231 or E-mail: acctclaim@sts.com.sg or fax: 6-840 1128 for any clarification.

Yours faithfully


for MANAGER
SIN TIEN SENG PTE LTD
(Kallang Service Centre)

SIN TIEN SENG PTE LTD

2018-04-18 09:06 am

GST REG #: M2-0011219-B CO REG #: 197000883D

Page 1 of 2

VEHICLE REPAIR ESTIMATION FOR SJV1902G

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
1	ENGINE MOUNT'G RH	12361 B4020	1	65.00	50.70
2	ENGINE MOUNT'G LH	12362 B4010	1	65.00	50.70
3	ENGINE MOUNT'G RR	12371 B4010	1	72.00	56.16
4	RADIATOR ASSY	16400 B1141	1	595.00	464.10
5	STEP PRIMER	3M868 2	2	62.00	124.00
6	AUTO GLASS URETHANE	3M869 0	2	51.00	102.00
7	WHEEL,DISC ALLOY RHF	42611 BZ350	1	691.00	538.98
8	KNUCKLE,STEERING RH	43211 B0010	1	321.00	250.38
9	HUB FR AXLE RH	43502 87401	1	279.00	217.62
10	TIE ROD END RH	45046 B9320	1	69.00	53.82
11	RH STRG RACK END	45460 87401	1	115.00	89.70
12	COVER,DISC BRAKE RH	47781 87401	1	33.00	25.74
13	RH FRONT LOWER ARM	48068 B4011	1	164.00	127.92
14	ABSORBER SHOCK,RH FR	48510 B4022	1	215.00	167.70
15	SUPPORT,ABSORBER RHF	48609 87402	1	98.00	76.44
16	ROD,STABILIZER RH FR	48822 97503	1	66.00	51.48
17	X-MEMBER ENGINE	51022 B4010	1	139.00	108.42
18	CROSSMEMBER CENTRE	51202 B4010	1	233.00	181.74
19	DAMPER X-MEMBER	51204 B4010	1	79.00	61.62
20	MEMBER, FR SUSP	51210 B4010	1	1,948.00	1,519.44
21	BOLT,ENGINE SUPPORT	51296 87402	4	8.80	27.44
22	COVER,ENGINE UNDER	51410 B4010	1	400.00	312.00
23	REINFORCEMENT FRT	52021 B4040	1	386.00	301.08
24	SUPPORT,FR BUMPER RH	52115 B4011	1	39.00	30.42
25	SUPPORT,FR BUMPER LH	52116 B4011	1	39.00	30.42
26	FRONT BUMPER	52119 B4051	1	402.00	313.56
27	COVER,FR BUMPER HOLE	52128 B4021	1	22.00	17.16
28	SUPPORT,RR BUMPER RH	52155 B4010	1	39.00	30.42
29	SUPPORT,RR BUMPER LH	52156 B4010	1	45.00	35.10
30	REAR BUMPER	52159 B4051	1	472.00	368.16
31	SUPPORT H/LAMP RH	53202 B4020	1	151.00	117.78
32	SUPPORT H/LAMP LH	53203 B4020	1	151.00	117.78
33	SUPPORT RADIATOR TOP	53205 B4011	1	115.00	89.70
34	SUPPORT, HOOD LOCK	53215 B4010	1	12.00	9.36
35	LOCK ASSY, HOOD	53510 BZ200	1	46.00	35.88
36	LINER, FR FENDER, RH	53875 B4010	1	66.00	51.48
37	CUSHION, X-MEMBER RR	57264 B4010	4	9.20	28.72
38	CUSHION, X-MEMBER FR	57265 B4010	4	13.50	42.12
39	RETAINER,QUARTER UPP	62763 B4010	1	10.50	8.19
40	RETAINER,QUARTER LWR	62765 B4010	1	10.50	8.19
41	SPACER,QUARTER GLASS	62785 B2030	2	2.80	4.36
42	SPACER,BACK DR GLASS	62785 B4010	7	1.50	8.19
43	COVER,SPARE TIRE	64770 B4021 G1	1	700.00	700.00
44	CLIP,BACK DOOR GLASS	64827 B4010	2	15.50	24.18
45	LINER,RR WH HOUSE RH	65637 B4010	1	45.00	35.10
46	BACK DOOR	67005 B4080	1	752.00	586.56
47	CHECK, BACK DOOR	68650 B4011	1	66.00	67.08
48	PLATE,TERIOS	75441 B4040	1	34.00	26.52
49	STICKER, DAIHATSU	75444 B4010	1	17.50	13.65
50	MOULD'G,1/4 GLASS RH	75641 B4010	1	19.50	15.21

SIN TIEN SENG PTE LTD

GST REG #: M2-0011219-4 CO REG #: 197000683D

2018-04-18 09:06 am

Page 2 of 2

VEHICLE REPAIR ESTIMATION FOR SJV1902G**Parts Needed:**

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
51	HEADLAMP ASSY RH	81110 B4020	1	659.00	514.02
52	HEADLAMP ASSY LH	81150 B4020	1	659.00	514.02
53	LAMP FOG RH	81210 97229	1	355.00	276.90
54	LAMP ,REAR COMB RH	81550 B4020	1	206.00	160.68
55	REFLECTOR RH	81910 B4010	1	33.00	25.74
56	CONDENSER ASSY	88450 B4020	1	815.00	635.70
57	BOLT, LWR ARM FR	90041 01700	1	12.00	9.36
58	BOLT, LWR ARM RR	90041 19984	1	7.00	5.46
59	BOLT, SUSPN SUPPORT	90041 20207	6	7.50	35.10
60	BEARING,FRT AXLE RH	90043 63369	1	125.00	97.50
61	RING,HOLE SNAP,HUB	90045 21111	1	19.00	14.82
62	BOLT HUB RH FR	90049 12055	5	1.90	7.40
63	215/65 R16 LM704 98H	BC-18 2197	1	160.00	160.00
64	REVERSE SENSOR	EA-89 1920	1	80.00	80.00
65	R-COOLANT RCP-C500	PM-02 1560	1	18.00	18.00
66	P/STRG & GEAR OIL	WSS-10	4	10.00	40.00
67	B/FLUID30485005-8120	WSS-11	2	8.40	16.80
68	SUNDRIES	WSS-12	1	200.00	200.00
Total (1) :			100		\$10,585.97

Labour Charges:

1 R&R/ REPLACE HEADLAMPS & REFOCUS HEADLIGHT	\$30.00
2 R&R RADIATOR	\$40.00
3 R&R AIRCON & REFILL GAS	\$120.00
4 R&R ENGINE ASSY	\$400.00
5 R&R STEERING ASSY/ KNUCKLE/ HUB & W- BEARING/ FRONT SUSPENSION & X- MEMBER/ LOWER ARMS / DRIVESHAFTS ETC.	\$380.00
6 CHECK WHEEL ALIGNMENT	\$65.00
7 REPLACE TIRE & RIM	\$30.00
8 R&R/ REPLACE REVERSE SENSOR	\$30.00
9 R&R BACK DOOR & QUARTER GLASSES	\$250.00
10 REALIGN/ STRAIGHTEN RH REAR & FRONT CHASSIS FRAME/ CUT & WELD RH QUARTER PANEL/ FRONT SUPPORT PANEL & REINFORCEMENT. PANEL BEAT & REPLACE DAMAGED PARTS	\$4,200.00
11 SPRAY PAINT ON AFFECTED AREAS	\$1,800.00
12 RENEW FRONT NUMBER PLATE	\$30.00
13 TOWED FROM ECP (FOC)	

TOTAL (2) \$7,375.00

TOTAL (1) & (2) \$17,960.97

PREPARED BY SAID

TEL : 6-7481231 FAX : 6-8401128 E : acctclaim@sts.com.sg

Validity : 30 days from date of quotation.

Prices are subject to change without prior notice.

Distributor & Dealer for



DAIHATSU

DENSO PRIXMAX

新天成私人有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PL
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1166
10 Kallang Way, Singapore 349215
Fax: 6748-6702 6840-128
E-mail: adms@sts.com.sg
Co Reg No: 187000883D

JURONG CENTRE: Tel: 6561-6611
6 Teluk Gardens Crescent, Singapore 608024
Fax: 6561-9638

DOON KENG SHOWROOM: Tel: 6308-1486
88-91 Whampoa Road #01-25/26, Singapore 330034
Fax: 6308-1486

Your ref
Our ref
Date

16.04.2018

Dear Sir

ESTIMATE FOR VEHICLE ACCIDENT REPAIR (DOA 15.04.2018)

VEHICLE DETAILS: -

REGISTRATION NUMBER : SJV1902G
VEHICLE MODEL : D-J200RG-GMDFW-H
CHASSIS NUMBER : JDAJ200G001017132
ENGINE NUMBER : 2149323
MILEAGE (KM) : 90814 KM
REGISTRATION DATE : 14.01.2010

INSURANCE DETAILS: -

INSURED'S NAME : TEO HUEI HUEI @ ALESHA ABDULLAH TEO
INSURED'S ADDRESS : BLK 1 MARINE TERRACE
#10-298
SINGAPORE 440001

POLICY NUMBER : 2100186821-08000
EXPIRY DATE : 13.01.2019
EXCESS PAYMENT : \$600/-

We are pleased to enclose to you our estimate for your consideration and approval. Please send your surveyor to our Kallang Service Centre 10 Kallang Way, Singapore 349215 where the above mentioned vehicle is now stored. Kindly contact Mr SAID/ERIC LOH at telephone number 6-748 1231 or E-mail: acctclaim@sts.com.sg or fax: 6-840 1128 for any clarification.

Yours faithfully


for MANAGER
SIN TIEN SENG PTE LTD
(Kallang Service Centre)

VEHICLE REPAIR ESTIMATION FOR SJV1902G

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR	
1	ENGINE MOUNT'G RH	12361 B4020	1	65.00	50.70	
2	ENGINE MOUNT'G LH	12362 B4010	1	65.00	50.70	x NN
3	ENGINE MOUNT'G RR	12371 B4010	1	72.00	56.16	
4	RADIATOR ASSY	16400 B1141	1	595.00	464.10	
5	STEP PRIMER	3M868 2	1	62.00	124.00	
6	AUTO GLASS URETHANE	3M869 0	1	51.00	102.00	
7	WHEEL, DISC ALLOY RH	42611 BZ350	1	691.00	538.98	
8	KNUCKLE, STEERING RH	43211 B0010	1	321.00	250.38	x NN
9	HUB FR AXLE RH	43502 87401	1	279.00	217.62	BT
10	TIE ROD END RH	45046 B9320	1	69.00	53.82	
11	RH STRG RACK END	45460 87401	1	115.00	89.70	x NN
12	COVER, DISC BRAKE RH	47781 87401	1	33.00	25.74	
13	RH FRONT LOWER ARM	48068 B4011	1	164.00	127.92	
14	ABSORBER SHOCK, RH FR	48510 B4022	1	215.00	167.70	BT
15	SUPPORT, ABSORBER RH FR	48609 87402	1	98.00	76.44	
16	ROD, STABILIZER RH FR	48822 97503	1	66.00	51.48	
17	X-MEMBER ENGINE	51022 B4010	1	139.00	108.42	x NN
18	CROSSMEMBER CENTRE	51202 B4010	1	233.00	181.74	
19	DAMPER X-MEMBER	51204 B4010	1	79.00	61.62	
20	MEMBER, FR SUSP	51210 B4010	1	1,948.00	1,519.44	BT
21	BOLT, ENGINE SUPPORT	51296 87402	4	8.80	27.44	x NN
22	COVER, ENGINE UNDER	51410 B4010	1	400.00	312.00	
23	REINFORCEMENT FRT	52021 B4040	1	386.00	301.08	
24	SUPPORT, FR BUMPER RH	52115 B4011	1	39.00	30.42	
25	SUPPORT, FR BUMPER LH	52116 B4011	1	39.00	30.42	NA D2
26	FRONT BUMPER	52119 B4051	1	402.00	313.56	
27	COVER, FR BUMPER HOLE	52128 B4021	1	22.00	17.16	
28	SUPPORT, RR BUMPER RH	52155 B4010	1	39.00	30.42	
29	SUPPORT, RR BUMPER LH	52156 B4010	1	45.00	35.10	x NN
30	REAR BUMPER	52159 B4051	1	472.00	368.16	
31	SUPPORT H/LAMP RH	53202 B4020	1	151.00	117.78	
32	SUPPORT H/LAMP LH	53203 B4020	1	151.00	117.78	x NN
33	SUPPORT RADIATOR TOP	53205 B4011	1	115.00	89.70	BT
34	SUPPORT, HOOD LOCK	53215 B4010	1	12.00	9.36	
35	LOCK ASSY, HOOD	53510 BZ200	1	46.00	35.88	BT
36	LINER, FR FENDER, RH	53875 B4010	1	66.00	51.48	BT
37	CUSHION, X-MEMBER RR	57264 B4010	4	9.20	28.72	BT
38	CUSHION, X-MEMBER FR	57265 B4010	4	13.50	42.12	x NN
39	RETAINER, QUARTER UPP	62763 B4010	1	10.50	8.19	
40	RETAINER, QUARTER LWR	62765 B4010	1	10.50	8.19	
41	SPACER, QUARTER GLASS	62785 B2030	2	2.80	4.36	
42	SPACER, BACK DR GLASS	62785 B4010	7	1.50	8.19	
43	COVER, SPARE TIRE	64770 B4021 G1	1	700.00	700.00	
44	CLIP, BACK DOOR GLASS	64827 B4010	2	15.50	24.18	
45	LINER, RR WH HOUSE RH	65637 B4010	1	45.00	35.10	
46	BACK DOOR	67005 B4080	1	752.00	586.56	
47	CHECK, BACK DOOR	68650 B4011	1	86.00	67.08	x NN
48	PLATE, TERIOS	75441 B4040	1	34.00	26.52	
49	STICKER, DAIHATSU	75444 B4010	1	17.50	13.65	
50	MOULD'G, 1/4 GLASS RH	75641 B4010	1	19.50	15.21	x NN

VEHICLE REPAIR ESTIMATION FOR SJV1902G

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
51	HEADLAMP ASSY RH <i>SOA</i>	81110 B4020	1	659.00	514.02 ✓
52	HEADLAMP ASSY LH	81150 B4020	1	659.00	514.02 ✓
53	LAMP FOG RH <i>Q's</i>	81210 97229	1	355.00	276.90 ✓
54	LAMP, REAR COMB RH <i>BR</i>	81550 B4020	1	206.00	160.68 ✓
55	REFLECTOR RH <i>Cut</i>	81910 B4010	1	33.00	25.74 ✓
56	CONDENSER ASSY <i>BT</i>	88450 B4020	1	815.00	635.70 ✓
57	BOLT, LWR ARM FR <i>X</i>	90041 01700	1	12.00	9.36
58	BOLT, LWR ARM RR <i>X</i>	90041 19984	1	7.00	5.46 } <i>x NN</i>
59	BOLT, SUSPN SUPPORT <i>X</i>	90041 20207	6	7.50	35.10
60	BEARING, FRT AXLE RH <i>X</i>	90043 63369	1	125.00	97.50 ✓ <i>NEL</i>
61	RING, HOLE SNAP, HUB <i>X</i>	90045 21111	1	19.00	14.82 } <i>x NN</i>
62	BOLT HUB RH FR <i>X</i>	90049 12055	5	1.90	7.40
63	215/65 R16 LM704 98H <i>Cut</i>	BC-18 2197	1	160.00	160.00 <i>80 (-50%)</i>
64	REVERSE SENSOR <i>DM</i>	EA-89 1920	1	80.00	80.00 ✓
65	R-COOLANT RCP-C500	PM-02 1560	1	18.00	18.00 ✓
66	P/STRG & GEAR OIL	WSS-10	.4	10.00	40.00 ✓
67	B/FLUID 30485005-8120	WSS-11	2	8.40	16.80 ✓
68	SUNDRIES <i>X / NEL</i>	WSS-12	1	200.00	200.00 ✓
Total (1):			100		\$10,585.97

Labour Charges:

1 R&R/ REPLACE HEADLAMPS & REFOCUS HEADLIGHT	\$30.00	<i>SOA</i>
2 R&R RADIATOR	\$40.00	<i>SOA</i>
3 R&R AIRCON & REFILL GAS	\$120.00	
4 R&R ENGINE ASSY	\$400.00	<i>300 ?</i>
5 R&R STEERING ASSY/ KNUCKLE/ HUB & W- BEARING/ FRONT SUSPENSION & X- MEMBER/ LOWER ARMS / DRIVESHAFTS ETC.	\$380.00	<i>250 ?</i>
6 CHECK WHEEL ALIGNMENT	\$65.00	
7 REPLACE TIRE & RIM	\$30.00	
8 R&R/ REPLACE REVERSE SENSOR	\$30.00	<i>NN</i>
9 R&R BACK DOOR & QUARTER GLASSES	\$250.00	<i>150-250</i>
10 REALIGN/ STRAIGHTEN RH REAR & FRONT CHASSIS FRAME/ CUT & WELD RH QUARTER PANEL/ FRONT SUPPORT PANEL & REINFORCEMENT. PANEL BEAT & REPLACE DAMAGED PARTS	\$4,200.00	<i>320 3520</i>
11 SPRAY PAINT ON AFFECTED AREAS	\$1,800.00	<i>1600-1600</i>
12 RENEW FRONT NUMBER PLATE	\$30.00	
13 TOWED FROM ECP (FOC)		
TOTAL (2)	\$7,375.00	

TOTAL (1) & (2)

\$17,960.97

PREPARED BY SAID
 TEL: 6-7481231 FAX: 6-8401128 E: tracclaim@sts.com.sg

• Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary items must be reviewed and
 Prices are subject to change without prior notice.

Acknowledged by Repairer

Signature:

Date:

15 - 18 Days. 19356.83
 Excess: TBA
 Not Authorised
 before paint photos.
 Guo Qiang - 82880282
 Guo Qiang @ lkk auto. com.

Shiau Chan (LKKAUTO)

From: ACCTCLAIM <acctclaim@sts.com.sg>
Sent: Tuesday, 24 April 2018 2:39 PM
To: Guo Qiang (LKKAUTO)
Cc: Shiau Chan (LKKAUTO)
Subject: Re: SJV1902G REPAIR LIMIT
Attachments: DSCN7428.JPG; DSCN7429.JPG; DSCN7431.JPG; DSCN7432.JPG; DSCN7437.JPG; DSCN7439.JPG

Hi Guo Qiang

Damage to SJV1902G very severe. Rear Axle & P/steering distorted. Cannot repair within 11k.
Please advise your next action ASAP

P/Steering assy \$2840/-
Steering Column \$1223/-
Front Stabilizer Bar \$444/-
Rear Axle Housing \$1830/-
Rear Differential Gear \$2076
RH Axle Shaft \$618/-
Rear Stabilizer Bar \$196/-
Related Rear Suspension Arms Est \$656/-

Thanks & Regards

Said

67481231

From: Guo Qiang (LKKAUTO)
Sent: Monday, April 23, 2018 9:18 AM
To: ACCTCLAIM
Cc: Shiau Chan (LKKAUTO)
Subject: SJV1902G REPAIR LIMIT

Dear Said,

SJV1902G repair limit \$11k.

Regards,
Guo Qiang

Distributor & Dealer for



DAIHATSU

DAIHATSU

PrixMax

新天成有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1188

10 Kallang Way, Singapore 349215

Fax: 6748-3767 6840 1128

E-mail: ~~admin@sin-tien-seng.com.sg~~ acctclaim@sts.com.sg

Co Reg No: 197000883D

~~CHONG JEN HONG (PTE) LTD: Tel: 6351-8811~~

~~3 Telok Gajah Road, Singapore 309091~~

~~Fax: 6351-8808~~

~~CHONG JEN HONG (PTE) LTD: Tel: 6351-8811~~

~~3 Telok Gajah Road, Singapore 309091~~

~~Fax: 6351-8808~~

Your ref:
Our ref:
Date:

19.05.2018

Dear Sir

SUPPLEMENTARY PART FOR VEHICLE NO: SJP1902G

Please refer to our estimate dated 18.04.2018, LKK's Mr Guo Qiang inspection on 20.04.2018, we wish to inform that supplementary parts incurred.

1. RH Rear Axle Shaft / BT	42311-B4010	\$618.00	L 22%	\$482.04	lt
2. RH Rr Ax-Shaft Retainer(In) /	42423-97502	\$ 79.00	L 22%	\$ 61.62	lt
3. RH Rr Ax-Shaft Retainer(Out) /	42424-87401	\$ 36.00	L 22%	\$ 28.08	lt
4. RH Rear Axle Bearing / MC	90043-63248	\$ 57.00	L 22%	\$ 44.46	lt
5. RH Rear Wheel Rim / Cut	42611-BZ350	\$691.00	L22%	\$538.98	lt
6. RH Rear Tire(Owner Pays 50%) /	BC-182197	\$160.00	Nett	\$ 80.00	lt
7. Charcoal Cannister / Cut scr	77740-B4010	\$206.00	L22%	\$160.68	lt
Total				\$1,395.86	

Please amend our estimate accordingly.

Yours faithfully


for Manager
SIN TIEN SENG PTE LTD
Kallang Service Centre

VEHICLE REPAIR ESTIMATION FOR SJV1902G

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
1	ENGINE MOUNT'G RH ?	12361 B4020	1	65.00	50.70
2	ENGINE MOUNT'G LH ?	12362 B4010	1	65.00	50.70
3	ENGINE MOUNT'G RR ?	12371 B4010	1	72.00	56.16
4	RADIATOR ASSY - BT	16400 B1141	1	595.00	464.10
5	STEP PRIMER - AC	3M868 2	1	62.00	124.00
6	AUTO GLASS URETHANE	3M869 0 - AC	1	51.00	102.00
7	WHEEL, DISC ALLOY RH	42611 BZ350	1	691.00	538.98
8	KNUCKLE, STEERING RH ?	43211 B0010	1	321.00	250.98
9	HUB FR AXLE RH ?	43502 87401	1	279.00	217.62
10	TIE ROD END RH ?	45046 B9320	1	69.00	53.82
11	RH STRG RACK END ?	45460 87401	1	115.00	89.70
12	COVER, DISC BRAKE RH ?	47781 87401	1	33.00	25.74
13	RH FRONT LOWER ARM ?	48068 B4011	1	164.00	127.92
14	ABSORBER SHOCK, RH FR ?	48510 B4022	1	215.00	167.70
15	SUPPORT, ABSORBER RH ?	48609 87402	1	98.00	76.44
16	ROD, STABILIZER RH FR ?	48822 97503	1	66.00	51.48
17	X-MEMBER ENGINE ?	51022 B4010	1	139.00	108.42
18	CROSSMEMBER CENTRE ?	51202 B4010	1	233.00	184.74
19	DAMPER X-MEMBER ?	51204 B4010	1	79.00	61.82
20	MEMBER, FR SUSP ?	51210 B4010	1	1,948.00	1,519.44
21	BOLT, ENGINE SUPPORT ?	51296 87402	4	8.80	27.44
22	COVER, ENGINE UNDER	51410 B4010	1	400.00	312.00
23	REINFORCEMENT FRT	52021 B4040	1	386.00	301.08
24	SUPPORT, FR BUMPER RH	52115 B4011	1	39.00	30.42
25	SUPPORT, FR BUMPER LH	52116 B4011	1	39.00	30.42
26	FRONT BUMPER - AC	52119 B4051	1	402.00	313.56
27	COVER, FR BUMPER HOLE	52128 B4021	1	22.00	17.16
28	SUPPORT, RR BUMPER RH	52155 B4010	1	39.00	30.42
29	SUPPORT, RR BUMPER LH	52156 B4010	1	45.00	35.10
30	REAR BUMPER - AC	52159 B4051	1	472.00	368.16
31	SUPPORT H/LAMP RH	53202 B4020	1	151.00	117.78
32	SUPPORT H/LAMP LH	53203 B4020	1	151.00	117.78
33	SUPPORT RADIATOR TOP	53205 B4011	1	115.00	89.70
34	SUPPORT, HOOD LOCK	53215 B4010	1	12.00	9.36
35	LOCK ASSY, HOOD - BT	53510 BZ200	1	46.00	35.88
36	LINER, FR FENDER, RH	53875 B4010	1	66.00	51.48
37	CUSHION, X-MEMBER RR ?	57264 B4010	4	9.20	28.72
38	CUSHION, X-MEMBER FR ?	57265 B4010	4	13.50	42.12
39	RETAINER, QUARTER UPP ?	62763 B4010	1	10.50	8.19
40	RETAINER, QUARTER LWR ?	62765 B4010	1	10.50	8.19
41	SPACER, QUARTER GLASS ?	62785 B2030	2	2.80	4.36
42	SPACER, BACK DR GLASS	62785 B4010	7	1.50	8.19
43	COVER, SPARE TIRE - Cut	64770 B4021 G1	1	700.00	700.00
44	CLIP, BACK DOOR GLASS	64827 B4010	2	15.50	24.18
45	LINER, RR WH HOUSE RH	65637 B4010	1	45.00	35.10
46	BACK DOOR	67005 B4080	1	752.00	586.36
47	CHECK, BACK DOOR ?	68650 B4011	1	86.00	67.08
48	PLATE, TERIOS - Spec	75441 B4040	1	34.00	26.52
49	STICKER, DAIHATSU	75444 B4010	1	17.50	13.65
50	MOULD'G, 1/4 GLASS RH ?	75641 B4010	1	19.50	15.21

This page

5,479.68

VEHICLE REPAIR ESTIMATION FOR SJV1902G

Parts Needed:

No.	PART DESC	PARTNO	QTY	U/LIST PR	TTL NET PR
51	HEADLAMP ASSY RH	81110 B4020	1	659.00	514.02
52	HEADLAMP ASSY LH	81150 B4020	1	659.00	514.02
53	LAMP FOG RH	81210 97229	1	355.00	276.90
54	LAMP, REAR COMB RH	81550 B4020	1	206.00	160.68
55	REFLECTOR RH	81910 B4010	1	33.00	25.74
56	CONDENSER ASSY	88450 B4020	1	815.00	635.70
57	BOLT, LWR ARM FR	90041 01700	1	12.00	8.36
58	BOLT, LWR ARM RR	90041 19984	1	7.00	5.48
59	BOLT, SUSPN SUPPORT	90041 20207	6	7.50	35.10
60	BEARING, FRT AXLE RH	90043 63369	1	125.00	97.50
61	RING, HOLE SNAP, HUB	90045 21111	1	19.00	14.82
62	BOLT HUB RH FR	90049 12055	5	1.90	7.40
63	215/85 R16 LM704 98H	BC-18 2197	1	160.00	160.00
64	REVERSE SENSOR	EA-89 1920	1	80.00	80.00
65	R-COOLANT RCP-C500	PM-02 1560	1	18.00	18.00
66	P/STRG & GEAR OIL	WSS-10	.4	10.00	40.00
67	B/FLUID 30485005-8120	WSS-11	2	8.40	16.80
68	SUNDRIES	WSS-12	200.00		200.00
Total (1):			100		\$10,585.97

S/part
This page
3980.32

50m 80m
NCH
22CH
125.10 NCH
9460

Labour Charges:

1 R&R/ REPLACE HEADLAMPS & REFOCUS HEADLIGHT	\$30.00
2 R&R RADIATOR	\$40.00
3 R&R AIRCON & REFILL GAS	\$120.00
4 R&R ENGINE ASSY	\$400.00
5 R&R STEERING ASSY/ KNUCKLE/ HUB & W- BEARING/ FRONT SUSPENSION & X- MEMBER/ LOWER ARMS / DRIVESHAFTS ETC.	\$380.00
6 CHECK WHEEL ALIGNMENT	\$85.00
7 REPLACE TIRE & RIM	\$30.00
8 R&R/ REPLACE REVERSE SENSOR	\$30.00
9 R&R BACK DOOR & QUARTER GLASSES	\$250.00
10 REALIGN/ STRAIGHTEN RH REAR & FRONT CHASSIS FRAME/ CUT & WELD RH QUARTER PANEL/ FRONT SUPPORT PANEL & REINFORCEMENT. PANEL BEAT & REPLACE DAMAGED PARTS	\$4,200.00
11 SPRAY PAINT ON AFFECTED AREAS	\$1,800.00
12 RENEW FRONT NUMBER PLATE	\$30.00
13 TOWED FROM ECP (FOC)	

TOTAL (2)

\$7,375.00

TOTAL (1) & (2)

\$12,960.97

PREPARED BY SAID

TEL : 6-7481231 FAX : 6-8401128 E : acctclaim@sts.com.sg

Validity : 30 days from date of quotation.

Prices are subject to change without prior notice.

15 - 18 Days
Excess : TBA
Not Authorised
before paint photos.
Guo Qiang - 82880282
Guo Qiang @ Ikkauto.com

(Sc)
Distributor & Dealer for



DAIHATSU

DENSO PRIXMAX

新天成私人有限公司
SIN TIEN SENG PTE LTD

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

HEAD OFFICE & KALLANG CENTRE: Tel: 6748-1168

10 Kallang Way, Singapore 349215

Fax: 6748-8767 68401138

E-mail: admin@sate.com.sg

Co Reg No: 197000883D

JURONG CENTRE: Tel: 6561-6611

6 Telok Cardena Crescent, Singapore 606024

Fax: 6561-9638

BOON KENG SHOWROOM: Tel: 6393-1466

34 Whampoa West #01-75/7D, Singapore 330034

Fax: 6393-1466

Your ref
Our ref
Date

12.06.2018

Dear Sir

VEHICLE ACCIDENT REPAIR
VEHICLE NUMBER: **SJV1902G**
REFERENCE NUMBER:

Please refer to our estimate dated 16.04.2018. We wish to inform that the repair has been completed and the following are attached for your necessary action.

Workshop Repair Bill No:282273 for \$12,733.00

Owner's Discharge Voucher dated 19.05.2018

2 We look forward to your early remittance.

Yours faithfully

for MANAGER
SIN TIEN SENG PTE LTD



TAX INVOICE NO 282273

新天成私人有限公司

SIN TIEN SENG PTE LTD

Reg No: 19700883D

HEAD OFFICE & KALLANG CENTRE:

10 KALLANG WAY, SINGAPORE 34015. TEL: 2401100, 2401201

RESEARCH DESIGN

[illegible]

2004-2005-2006-2007

bioRxiv preprint doi: <https://doi.org/10.1101/2019.04.10.333126>; this version posted April 10, 2019. The copyright holder for this preprint (which was not certified by peer review) is the author/funder, who has granted bioRxiv a license to display the preprint in perpetuity. It is made available under aCC-BY-NC-ND 4.0 International license.

CUSTOMER'S NAME & ADDRESS

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PL
78 SHENTON WAY
07-16 AIG BUILDING
SINGAPORE 079120

NOTE: ANY OBJECTION TO THE VALIDITY OF THESE CHARGES MUST BE MADE WITHIN SEVEN (7) DAYS FROM THE DATE OF THIS BILL OTHERWISE IT IS ASSUMED THAT THIS BILL IS ACCEPTED AS CORRECT

DATE 12-06-2018

ACCOUNT NO. A 22458

REPAIR ORDER NO. 299789

VEHICLE REGN NO
SV1902G

MODEL 520026

**CUSTOMER'S
ACKNOWLEDGEMENT OF
REPAIRS & CHARGES.**

DOOMETER READING
90214 KM

54,500

SERVICE ADVISER / EXECUTIVE
S.A.D.

NPRC #

PAYMENT DETAILS

- CASH

• CHEQUE

1

• VISA SALES DRAFT

1

Symptome

CUSTOMER

DISCHARGE VOUCHER

VEHICLE OWNER: TEO HUEI HUEI (ZHANG HUI HUI)

ADDRESS: BLK 1 MARINE TERRACE
#10-298
SINGAPORE 440001

DATE: 19.05.2018

Dear Sir

VEHICLE REGISTRATION NO. : SJV1902G
INSURER : AIG ASIA PACIFIC INSURANCE PTE LTD
INSURANCE POLICY NO. : 2100186821
ACCIDENT CLAIM NO. :
DATE & TIME OF ACCIDENT : 15.04.2018 @ 1505 HRS

I/We hereby certify that the repair to my/our motor vehicle involved in the accident on the above mentioned date and time has been completed by Sin Tien Seng Pte Ltd to my/our entire satisfaction and agree that payment of their account for such repair shall be in full satisfaction and discharge of all claims under this policy.

Yours faithfully



(SIGNATURE OF INSURED)
(COMPANY'S STAMP)

Name : TEO HUEI HUEI

NRIC No.: S7602715C

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2018		19 Apr 2018 18:17 Edit Adj Rpt	S\$12,500.00 Edit Estimates	S\$12,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TEO HUEI HUEI @AESHA ABDULLAH TEO , ID: S7602715C, Tel: +6588888888									
Vehicle Reg. No.: SJV1902G		Date of Loss: 15/04/2018 15:00 - :59	[99 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / 6948912546SG		Policy/Cover Note No.: 2100186821 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Sin Tien Seng Pte Ltd (Kallang) 10 Kallang Way, 349215 Kallang - Tel: 6748 1231									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/04/2018]									
Driver/Custodian: AZHAR BIN GHANI (48 / Male), NRIC: S6945589A, Tel: +6593691431									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (25/04/2018): Alert - Adj Mandate Approved (S\$12500.00) - SJV1902G - Claim Handler: Tr, Tinesh - AIG_SG (25/04/2018): SJV1902G / OD / 15/04/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV1902G (6948912546SG)
 OD
 Apr 15 2018 3:00PM
 [TEO HUEI HUEI @AESHA ABDULLAH TEO]
 Sin Tien Seng Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Videos		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	23/04/18 14:56	Adjuster Immediate Advice										Load HTM		
2	25/04/18 09:33	Adjuster Immediate Advice										Load HTM		
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	23/04/18 14:37	General View										Load JPG	☒	
2	23/04/18 14:37	General View										Load JPG	☒	
3	23/04/18 14:37	General View										Load JPG	☒	
4	23/04/18 14:37	General View										Load JPG	☒	
5	23/04/18 14:37	General View										Load JPG	☒	
6	23/04/18 14:37	General View										Load JPG	☒	
7	23/04/18 14:37	General View										Load JPG	☒	
8	23/04/18 14:37	General View										Load JPG	☒	
9	23/04/18 14:37	General View										Load JPG	☒	
10	23/04/18 14:37	General View										Load JPG	☒	
11	23/04/18 14:37	General View										Load JPG	☒	
12	23/04/18 14:37	General View										Load JPG	☒	
13	23/04/18 14:37	General View										Load JPG	☒	
14	23/04/18 14:37	General View										Load JPG	☒	
15	23/04/18 14:37	General View										Load JPG	☒	
16	23/04/18 14:37	General View										Load JPG	☒	
17	23/04/18 14:37	General View										Load JPG	☒	
18	23/04/18 14:37	General View										Load JPG	☒	
19	23/04/18 14:37	General View										Load JPG	☒	
20	23/04/18 14:37	General View										Load JPG	☒	
21	23/04/18 14:37	General View										Load JPG	☒	
22	23/04/18 14:37	General View										Load JPG	☒	
23	23/04/18 14:37	General View										Load JPG	☒	
24	23/04/18 14:37	General View										Load JPG	☒	
25	23/04/18 14:37	General View										Load JPG	☒	
26	23/04/18 14:37	General View										Load JPG	☒	
27	23/04/18 14:37	General View										Load JPG	☒	
28	23/04/18 14:37	General View										Load JPG	☒	
29	23/04/18 14:37	General View										Load JPG	☒	
30	23/04/18 14:37	General View										Load JPG	☒	
31	23/04/18 14:37	General View										Load JPG	☒	
32	23/04/18 14:37	General View										Load JPG	☒	
33	23/04/18 14:37	General View										Load JPG	☒	
34	23/04/18 14:37	General View										Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	23/04/18 14:37	General View	 Load JPG	☒
36	23/04/18 14:37	General View	 Load JPG	☒
37	23/04/18 14:37	General View	 Load JPG	☒
38	23/04/18 14:37	General View	 Load JPG	☒
39	23/04/18 14:37	General View	 Load JPG	☒
40	23/04/18 14:37	General View	 Load JPG	☒
41	23/04/18 14:37	General View	 Load JPG	☒
42	23/04/18 14:37	General View	 Load JPG	☒
43	23/04/18 14:37	General View	 Load JPG	☒
44	23/04/18 14:37	General View	 Load JPG	☒
45	23/04/18 14:37	General View	 Load JPG	☒
46	23/04/18 14:37	General View	 Load JPG	☒
47	23/04/18 14:37	General View	 Load JPG	☒
48	23/04/18 14:37	General View	 Load JPG	☒
49	23/04/18 14:37	General View	 Load JPG	☒
50	23/04/18 14:37	General View	 Load JPG	☒
51	23/04/18 14:37	General View	 Load JPG	☒
52	23/04/18 14:37	General View	 Load JPG	☒
53	23/04/18 14:37	General View	 Load JPG	☒
54	23/04/18 14:37	General View	 Load JPG	☒
55	23/04/18 14:37	General View	 Load JPG	☒
56	23/04/18 14:37	General View	 Load JPG	☒
57	23/04/18 14:37	General View	 Load JPG	☒
58	23/04/18 14:37	General View	 Load JPG	☒
59	23/04/18 14:37	General View	 Load JPG	☒
60	23/04/18 14:37	General View	 Load JPG	☒
61	23/04/18 14:37	General View	 Load JPG	☒
62	23/04/18 14:37	General View	 Load JPG	☒
63	23/04/18 14:37	Odometer Reading	 Load JPG	☒
64	23/04/18 14:37	Chassis Number	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 14:44	ESTIMATE	 Load PDF	
2	25/04/18 09:28	Certificate of Insurance 1	 Load PDF	
3	25/04/18 09:28	Certificate of Insurance 2	 Load PDF	
4	25/04/18 09:28	Certificate of Insurance 3	 Load PDF	
5	25/04/18 09:28	Driver's Driving License	 Load PDF	
6	25/04/18 15:12	Driver's Driving License - AZHAR BIN GHANI	 Load PDF	
7	25/04/18 15:12	Driver's Driving License - AZHAR BIN GHANI	 Load PDF	
8	12/06/18 10:45	SUPPLEMENTARY LIST	 Load PDF	
9	26/06/18 12:35	Workshop Invoice	 Load PDF	
10	26/06/18 12:35	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	16/04/18 11:51	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	16/04/18 11:38	Accident Photo	 Load JPG	☒
2	16/04/18 11:38	Accident Photo	 Load JPG	☒
3	16/04/18 11:38	Accident Photo	 Load JPG	☒
4	16/04/18 11:38	Accident Photo	 Load JPG	☒
5	16/04/18 11:38	Accident Photo	 Load JPG	☒
6	16/04/18 11:38	Accident Photo	 Load JPG	☒
7	16/04/18 11:38	Accident Photo	 Load JPG	☒
8	16/04/18 11:38	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sin Tien Seng Pte Ltd (Kallang)	Thumbnail	Print
1	16/04/18 11:41	Sketch Plan	 Load TIF	
2	16/04/18 11:48	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG18007313/QQBE2

Date: 26/06/2018

REFERENCE

Insured/Claimant: TEO HUEI HUEI @AESHA ABDULLAH TEO Policy No: 2100186821
Date of Loss: 15/04/2018 Nature of Claim: OD Claim No: 6948912546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV1902G**
Make & Model: DAIHATSU TERIOS, 1.5 2WD (M) Engine No: 2149323
Reg. Date: 14/01/2010 (Man. Year: 2008) Chassis No: JDAJ200G001017132
Colour: Green Odometer: 90814 km
Engine Capacity: 1495 cc
Market Value/New Car Price: S\$25,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
Front Left Side: Pirelli 5 mm Rear Left Side: Toyo 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,061.83	9,460.00	2,601.83	21.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,375.00	6,165.00	1,210.00	16.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,436.83	15,625.00	3,811.83	19.61
Approved Total (Overridden) (S\$)		12,500.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,836.83	11,900.00	6,936.83	36.83
+ GST 7.00/7.00% (S\$)	1,318.58	833.00	485.58	36.83
Nett Amount (S\$)	20,155.41	12,733.00	7,422.41	36.83

INSPECTION

Date of Assignment: 19/04/2018
Date Inspected: 20/04/2018 Inspected At: Sin Tien Seng Pte Ltd (Kallang)
10 Kallang Way
Singapore 349215
Estimated Period of Repair: 18.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE MOUNTING RH	Not Necessary	50.70 F	*- F
2	1		*ENGINE MOUNTING LH	Not Necessary	50.70 F	*- F
3	1		*ENGINE MOUNTING RR	Not Necessary	56.16 F	*- F
4	1		*RADIATOR ASSY	Bent	464.10 F	*464.10 F
5	1		*STEP PRIMER	Necessary-1PC ONLY	124.00 F	*62.00 F
6	1		*AUTO GLASS URETHANE	Necessary-1PC ONLY	102.00 F	*51.00 F
7	1		*WHEEL, DISC ALLOY RHF	Cut	538.98 F	*538.98 F
8	1		*KNUCKLE, STEERING RH	Not Necessary	250.38 F	*- F
9	1		*HUB FR AXLE RH	Bent	217.62 F	*217.62 F
10	1		*TIE ROD END RH	Not Necessary	53.82 F	*- F
11	1		*RH STRG RACK END	Not Necessary	89.70 F	*- F
12	1		*COVER, DISC BRAKE RH	Not Necessary	25.74 F	*- F
13	1		*RH FRONT LOWER ARM	Bent	127.92 F	*127.92 F
14	1		*ABSORBER SHOCK, RH FR	Bent	167.70 F	*167.70 F
15	1		*SUPPORT, ABSORBER RHF	Bent	76.44 F	*76.44 F
16	1		*ROD, STABILIZER RH FR	Not Necessary	51.48 F	*- F
17	1		*X-MEMBER ENGINE	Not Necessary	108.42 F	*- F
18	1		*CROSSMEMBER CENTRE	Not Necessary	181.74 F	*- F
19	1		*DAMPER X-MEMBER	Not Necessary	61.62 F	*- F
20	1		*MEMBER, FR SUSP	Bent	1,519.44 F	*1,519.44 F
21	4		*BOLT, ENGINE SUPPORT	Not Necessary	27.44 F	*- F
22	1		*COVER, ENGINE UNDER	Deformed	312.00 F	*312.00 F
23	1		*REINFORCEMENT FRT	Bent	301.08 F	*150.00 F
24	1		*FRONT BUMPER	Deformed	313.56 F	*160.00 F
25	1		*COVER, FR BUMPER HOLE	Missing	17.16 F	*17.16 F
26	1		*SUPPORT, RR BUMPER RH	Deformed	30.42 F	*30.42 F
27	1		*SUPPORT, RR BUMPER LH	Not Necessary	35.10 F	*- F
28	1		*REAR BUMPER	Deformed	368.16 F	*180.00 F
29	1		*SUPPORT H/LAMP RH	Not Necessary	117.78 F	*- F
30	1		*SUPPORT H/LAMP LH	Not Necessary	117.78 F	*- F
31	1		*SUPPORT RADIATOR TOP	Bent	89.70 F	*89.70 F
32	1		*SUPPORT, HOOD LOCK	Bent	9.36 F	*9.36 F
33	1		*LOCK ASSY, HOOD	Bent	35.88 F	*35.88 F
34	1		*LINER, FR FENDER, RH	Deformed	51.48 F	*51.48 F
35	4		*CUSHION, X-MEMBER RR	Not Necessary	28.72 F	*- F
36	4		*CUSHION, X-MEMBER FR	Not Necessary	42.12 F	*- F
37	1		*RETAINER, QUARTER UPP	Not Necessary	8.19 F	*- F
38	1		*RETAINER, QUARTER LWR	Not Necessary	8.19 F	*- F
39	2		*SPACER, QUARTER GLASS	Not Necessary	4.36 F	*- F
40	1		*SPACER, BACK DR GLASS (7PCS)	Necessary	8.19 F	*8.19 F
41	1		*COVER, SPARE TIRE	Cut	700.00 F	*700.00 F
42	2		*CLIP, BACK DOOR GLASS	Necessary	24.18 F	*24.18 F
43	1		*LINER, RR WH HOUSE RH	Deformed	35.10 F	*35.10 F
44	1		*BACK DOOR	Bent	586.56 F	*350.00 F
45	1		*CHECK, BACK DOOR	Not Necessary	67.08 F	*- F
46	1		*PLATE, TERIOS	Necessary	26.52 F	*26.52 F
47	1		*STICKER, DAIHATSU	Necessary	13.65 F	*13.65 F
48	1		*MOULDING, 1/4 GLASS RH	Not Necessary	15.21 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*HEADLAMP ASSY RH	Cracked	514.02 F	*514.02 F
50	1		*HEADLAMP ASSY LH	Cracked	514.02 F	*514.02 F
51	1		*LAMP FOG RH	Distorted	276.90 F	*276.90 F
52	1		*LAMP, REAR COMB RH	Broken	160.68 F	*160.68 F
53	1		*REFLECTOR RH	Cut	25.74 F	*25.74 F
54	1		*CONDENSER ASSY	Bent	635.70 F	*635.70 F
55	1		*BOLT, LWR ARM FR	Not Necessary	9.36 F	*- F
56	1		*BOLT, LWR ARM RR	Not Necessary	5.46 F	*- F
57	6		*BOLT, SUSPN SUPPORT	Not Necessary	35.10 F	*- F
58	1		*BEARING, FRT AXLE RH	Necessary	97.50 F	*97.50 F
59	1		*RING, HOLE SNAP, HUB	Not Necessary	14.82 F	*- F
60	5		*BOLT HUB RH FR	Not Necessary	7.40 F	*- F
61	1		*215/65 R16 LM704 98H (50%)	Cut	160.00 F	*80.00 F
62	1		*REVERSE SENSOR	Damaged	80.00 F	*80.00 F
63	1		*R-COOLANT RCP-C500	Necessary	18.00 F	*18.00 F
64	4		*P/STRG & GEAR OIL	Necessary	40.00 F	*40.00 F
65	2		*B/FLUID30485005-8120	Necessary	16.80 F	*16.80 F
66	1		*SUNDRIES	Necessary	200.00 F	*125.10 F
67	1		*RH REAR AXLE SHAFT	Bent	482.04 F	*482.04 F
68	1		*RH RR AX-SHAFT RETAINER (IN)	Necessary	61.62 F	*61.62 F
69	1		*RH RR AX-SHAFT RETAINER (OUT)	Necessary	28.08 F	*28.08 F
70	1		*RH REAR AXLE BEARING	Necessary	44.46 F	*44.46 F
71	1		*RH REAR WHEEL RIM	Cut	538.98 F	*538.98 F
72	1		*RH REAR TIRE (OWNER PAYS 50%)	Scratched	160.00 F	*80.00 F
73	1		*CHARCOAL CANNISTER	Cut	160.68 F	*160.68 F
74	1		*SUPPORT, FR BUMPER RH	Deformed	30.42 F	*30.42 F
75	1		*SUPPORT, FR BUMPER LH	Deformed	30.42 F	*30.42 F

F=Franchise part.

Total Parts (\$\$) **12,061.83** **9,460.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R / REPLACE HEADLAMPS & REFOCUS HEADLIGHT	New	30.00	30.00
2	R&R RADIATOR	New	40.00	40.00
3	R&R AIRCON & REFILL GAS	New	120.00	120.00
4	R&R ENGINE ASSY	New	400.00	300.00
5	R&R STEERING ASSY / KNUCKLE / HUB & W-BEARING / FRONT SUSPENSION & X-MEMBER / LOWER ARMS / DRIVESHAFT ETC	New	380.00	250.00
6	CHECK WHEEL ALIGNMENT	New	65.00	65.00
7	REPLACE TIRE & RIM	New	30.00	30.00
8	R&R / REPLACE REVERSE SENSOR	New	30.00	30.00
9	R&R BACK DOOR & QUARTER GLASSES	New	250.00	150.00
10	REALIGN / STRAIGHTEN RH REAR & FRONT CHASSIS FRAME / CUT & WELD RH QUARTER PANEL / FRONT SUPPORT PANEL & REINFORCEMENT. PANEL BEAT & REPLACE DAMAGED PARTS	New	4,200.00	3,520.00
11	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	1,600.00
12	RENEW FRONT NUMBER PLATE	New	30.00	30.00
13	TOWED FROM ECP(FOC) (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			7,375.00	6,165.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >