
























Report No: 0059-18-TCA

12 March 2018

ACCIDENT VEHICLE SURVEY REPORT

Mohamed Salih Shaik Dawood
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJN5456T	<i>Odometer:</i>	116561km
<i>Make & Model:</i>	Honda Freed 1.5G A	<i>Colour:</i>	Red
<i>Chassis number:</i>	GB31027015	<i>Date of accident:</i>	28/07/2017
<i>Year of Regn.:</i>	19/02/2009	<i>Date inspected:</i>	01/08/2017
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	16/08/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

















