

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/463/2018/GW
Date : 18-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Khoo Lay Ping
Address : 93 Mayer Road
#03-01
Singapore 437986
Telephone : HP +65 97351218
Type of Claim : Third Party Claims
Policy No. : 2100441707-02
Vehicle No : **SDV 7585 U**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Nov-15
Engine No : CZC 291365
Chassis No : WAUZZZ8V0G1037584
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Apr-18
Place of Accident : Changi Rd After Junc Of Changi Rd&Telok Kurau Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDV 7585 U.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✓
2	To dismantle and renew rhs front and rear doors, align to position. Repair rhs sill panel, rhs B-pillar and rear fender . Reinstall all parts removed.	\$ 3,000.00 1500 .
3	To respray rhs front and rear doors, rhs sill panel, rhs B- pillar and rhs rear fender . X ✓ ✓ ✓	\$ 3,800.00 2200
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>7,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 7585 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR-RH <i>Distorted</i>	\$ 2,190.00	✓
2	FRONT OUTER DOOR SEAL-RH <i>new</i>	\$ 139.00	✓
3	BONDING AGENT ?	\$ 43.00	?
4	CLEANING SOLUTION ?	\$ 64.00	?
5	FRONT DOOR CATCH <i>new</i>	\$ 92.00	X
6	FRONT DOOR HANDLE-RH <i>not new</i>	\$ 207.00	X
7	FRONT DOOR MOUNTING BAR-RH <i>not new</i>	\$ 143.00	X
8	FRONT WINDOW REGULATOR WITHOUT MOTOR-RH	\$ 232.00	X
9	FRONT WINDOW REGULATOR MOTOR-RH	\$ 212.00	X
10	FRONT DOOR CONTROL UNIT-RH	\$ 438.00	X
11	REAR DOOR-RH <i>Distorted</i>	TBC	✓
12	REAR DOOR OUTER DOOR SEA-RH <i>new</i>	\$ 139.00	✓
13	BONDING AGENT ?	\$ 43.00	?
14	CLEANING SOLUTION ?	\$ 64.00	?
15	REAR DOOR CATCH <i>new</i>	\$ 82.00	X
16	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓
17	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 4,513.00	
TOTAL LABOUR CHARGES		\$ 7,552.00	
GRAND TOTAL		\$ 12,065.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 19/04/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Pys.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant