



樹發汽車修理廠 SHU FATT AUTO WORKS

9.11

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
16th April 2018
TP-AXA-17

SKD 3331 Z MERCEDES BENZ C180

Spare Parts			S\$	
1	Rt fit headlight.	1120.00	Nett	X
1	Rt fit headlight holder	92.00	Nett	X
1	Rt fit fender.	880.00	Nett	bl ✓
1	Rt fit fender cowl.	116.00	Nett	X
1	Set rt fit fender cowl clip.	60.00	Nett	new -
1	Rt fit fender 'Blue Efficient' emblem.	65.00	Nett	new -
1	Frt bumper.	1260.00	Nett	repair
1	Set frt bumper clips.	72.00	Nett	X
2	Frt bumper side retainers. @\$75/-	150.00	Nett	X
2	Frt bumper chrome mouldings. @\$48/-	96.00	Nett	X

3911.00
Less 10% on Nett 391.10

Labour To knock, straighten fit support panel, fit inner panel, fit lower panel, fit side panel, fit wheel house, renew rt fit headlight, fit fender, fit bumper and assembly.
To respray damaged parts.

3519.90
600.00 300

750.00 350

4869.90

Michelin 225/45Z.R17
WDD2040452A579341
105974

Rasul
Hp 90010068

3 days

4/5
25/04/18 @ 1415

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____