







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18007347/Kmb3

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 20-04-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SLQ 4063K | Veh. Inspected | GBF 4348R  |
| Policy No.   |           | Coverage (\$)  | 0.00       |
| Claim No.    |           | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 20/04/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## 5. General Information

|                |                                                                                      |                 |  |
|----------------|--------------------------------------------------------------------------------------|-----------------|--|
| Accident Date  | 18/04/2018                                                                           | Inspection Date |  |
| Survey held at | CHENG HOE MOTOR PL<br>BLK 1019 YISHUN IND. PARK A<br>#01-374/382<br>SINGAPORE 768761 |                 |  |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

GBF 4348R  
TP/Long pac**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business  
Owner ID: 0800C

**Vehicle Details**

Vehicle No.: GBF4348R  
Vehicle to be Exported: No  
Intended De-registration Date: 18 Apr 2018  
Vehicle Make: TOYOTA  
Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR  
MANUAL

Primary Colour: Silver  
Manufacturing Year: 2016  
Engine No.: 1KD2660294  
Chassis No.: JTFHT02P800208896  
Maximum Power Output: -  
Open Market Value: \$27,952.00  
Original Registration Date: 26 Oct 2016  
First Registration Date: 26 Oct 2016  
Transfer Count: 0  
Actual ARF Paid: \$1,398.00

**Intended PARF Rebate Details**

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Oct 2026  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 10  
QP Paid: \$48,702.00  
COE Rebate Amount: \$41,488.00  
**Total Rebate Amount: \$41,488.00**

The information contained herein is correct as at 18 Apr 2018

OK

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBF4348R

TP/LONPAC

M/S : LONPAC INSURANCE BERHAD  
 300 BEACH ROAD  
 #17-04/07 THE CONCOURSE  
 SINGAPORE 199555

TEL: 62507388  
 ATTN: Motor Claim Department

FAX: 62963767

Estimate No: ES1890426/YISHUN

Date: 19 Apr 2018

Policy No:

Veh Reg No: GBF4348R

Make/Model: TOYOTA HIACE VAN  
 TURBO 5 DR MANUAL

Chassis No: JTFHT02P800208896

Engine No: 1KD2660294

Reg. Date: 26/10/2016

WS Ref: TP/LONPAC/YS

Claim Type: Third Party

Accident Date: 18/04/2018

TP Veh Reg No: SLQ4063K

Not Notarised

1.B.1  
 Running Bypass

3722.36

5 days

## Estimate Repair Cost to Vehicle No :GBF4348R

| Description                               | U/Price  | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|-------------------------------------------|----------|----------|-------------------|---------------|
| <b>List Price</b>                         |          |          |                   |               |
| 1 REAR BUMPER                             |          | 1 PC     |                   |               |
| 2 REAR BUMPER CLIP                        |          | 6 PC     |                   |               |
| 3 REAR TAILGATE                           |          | 1 PC     |                   |               |
| 4 TAILGATE LOGO                           |          | 1 PC     |                   |               |
| 5 TAILGATE STICKER (TOYOTA)               |          | 1 PC     |                   |               |
| 6 TAILGATE INNER LOCK                     |          | 1 PC     |                   |               |
| 7 TAILGATE INNER RUBBER                   |          | 1 PC     |                   |               |
| 8 REAR END PANEL OUTER                    |          | 1 PC     |                   |               |
| 9 TAILLAMP RH                             |          | 1 PC     |                   |               |
|                                           |          |          | 0.00              | 0.00          |
| <b>Special Net</b>                        |          |          |                   |               |
| 10 REAR WINDSCREEN GLASS GUM              | 40.0000  | 1 PC     | 40.00             |               |
| 11 REVERSE SENSOR                         | 200.0000 | 1 SET    | 200.00            |               |
| 12 STICKER - 70KM/H                       | 10.0000  | 1 PC     | 10.00             |               |
|                                           |          |          | 250.00            | 250.00        |
| <b>Labour</b>                             |          |          |                   |               |
| 13 REMOVE AND REFIX REAR WINDSCREEN GLASS | 100.0000 | 1 LA     | 100.00            |               |
| 14 PANEL BEATING                          | 800.0000 | 1 LA     | 800.00            |               |
| 15 PUTTY & RESPRAY PAINTING               | 800.0000 | 1 LA     | 800.00            |               |
| 16 RUSTPROOFING                           | 80.0000  | 1 LA     | 80.00             |               |
|                                           |          |          | 1,780.00          | 1,780.00      |
| Total                                     |          |          |                   | S\$ 2,030.00  |
| Add GST @ 7%                              |          |          |                   | 142.10        |
| Total Amount Payable                      |          |          |                   | S\$ 2,172.10  |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

GBF 4348R

TP/Lonpac

M/S : LONPAC INSURANCE BERHAD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
TEL: 62507388 FAX: 62963767  
ATTN: Motor Claim Department

WS Ref: TP/LONPAC/YS  
Claim Type: Third Party  
Accident Date: 18/04/2018  
TP Veh Reg No: SLQ4063K

Estimate No: ES1890426/YISHUN  
Date: 19 Apr 2018  
Policy No:  
Veh Reg No: GBF4348R  
Make/Model: TOYOTA HIACE VAN  
TURBO 5 DR MANUAL  
Chassis No: JTFHT02P800208896  
Engine No: 1KD2660294  
Reg. Date: 26/10/2016

## Estimate Repair Cost to Vehicle No :GBF4348R

| Description                               | U/Price  | Quantity | List Price | Amount     |
|-------------------------------------------|----------|----------|------------|------------|
| <b>List Price</b>                         |          |          | <b>S\$</b> | <b>S\$</b> |
| 1 REAR BUMPER                             | 373.65   | 1 PC     | 373.65     | ✓          |
| 2 REAR BUMPER CLIPS                       | 3.50     | 6 PCS    | 21.00      | ✓          |
| 3 REAR TAILGATE                           | 1,672.72 | 1 PC     | 1,672.72   | ✓          |
| 4 TAILGATE LOGO                           | 70.24    | 1 PC     | 70.24      | ✓          |
| 5 TAILGATE STICKER (TOYOTA)               | 39.02    | 1 PC     | 39.02      | ✓          |
| 6 TAILGATE INNER LOCK                     | 249.62   | 1 PC     | 249.62     | ✓          |
| 7 TAILGATE INNER RUBBER                   | 368.90   | 1 PC     | 368.90     | ✓          |
| 8 REAR END PANEL OUTER                    | 309.83   | 1 PC     | 309.83     | ✓          |
| 9 TAILLAMP RH                             | 256.90   | 1 PC     | 256.90     | ✓          |
|                                           |          |          | 3,361.88   |            |
|                                           | 2,683.15 | Less 25% | 840.47     | 2,012.35   |
|                                           | 670.78   |          |            | 2,521.41   |
| <b>Special Net</b>                        |          |          |            |            |
| 10 REAR WINDSCREEN GLASS GUM              | 40.0000  | 1 PC     | 40.00      | ✓          |
| 11 REVERSE SENSOR                         | 200.0000 | 1 SET    | 200.00     | ✓          |
| 12 STICKER - 70KM/H                       | 10.0000  | 1 PC     | 10.00      | ✓          |
|                                           |          |          | 250.00     | 250.00     |
| <b>Labour</b>                             |          |          |            |            |
| 13 REMOVE AND REFIX REAR WINDSCREEN GLASS | 100.0000 | 1 LA     | 100.00     | ✓          |
| 14 PANEL BEATING                          | 800.0000 | 1 LA     | 800.00     | ✓          |
| 15 PUTTY & RESPRAY PAINTING               | 800.0000 | 1 LA     | 800.00     | ✓          |
| 16 RUSTPROOFING                           | 80.0000  | 1 LA     | 80.00      | ✓          |
|                                           |          |          | 1,780.00   | 1,460      |
|                                           |          |          |            | 1,780.00   |

Total S\$ 4,551.41

Add GST @ 7% 318.60

Total Amount Payable S\$ 4,870.01

Parts #2,683.15  
Labour #670.78  
#2,012.37  
250  
1460  
#3,722.37

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBF4348R

TP/Lonpac

M/S : LONPAC INSURANCE BERHAD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

WS Ref: TP/LONPAC/YS

Claim Type: Third Party

Accident Date: 18/04/2018

TP Veh Reg No: SLQ4063K

Estimate No: ES1890426/YISHUN

Date: 19 Apr 2018

Policy No:

Veh Reg No: GBF4348R

Make/Model: TOYOTA HIACE VAN 1  
 TURBO 5 DR MANUAL

Chassis No: JTFHT02P800208896

Engine No: 1KD2660294

Reg. Date: 26/10/2016

*Not Notified*  
*1.B.1*  
*Recovery By claim*  
*5 days*

## Estimate Repair Cost to Vehicle No :GBF4348R

| Description                               | U/Price  | Quantity | List Price           | Amount       |
|-------------------------------------------|----------|----------|----------------------|--------------|
|                                           |          |          | <u>S\$</u>           | <u>S\$</u>   |
| <b>List Price</b>                         |          |          |                      |              |
| 1 REAR BUMPER                             |          | 1 PC     | 323.65               |              |
| 2 REAR BUMPER CLIP                        |          | 6 PC     | 3.5 x 6 = 21         |              |
| 3 REAR TAILGATE                           |          | 1 PC     | 1672.72              |              |
| 4 TAILGATE LOGO                           |          | 1 PC     | 70.24                |              |
| 5 TAILGATE STICKER (TOYOTA)               |          | 1 PC     | 39.02                |              |
| 6 TAILGATE INNER LOCK                     |          | 1 PC     | 249.62               |              |
| 7 TAILGATE INNER RUBBER                   |          | 1 PC     | 368.90               |              |
| 8 REAR END PANEL OUTER                    |          | 1 PC     | 309.83               |              |
| 9 TAILLAMP RH                             |          | 1 PC     | 286.90               |              |
|                                           |          |          | 0.00                 | 0.00         |
| <b>Special Net</b>                        |          |          |                      |              |
| 10 REAR WINDSCREEN GLASS GUM              | 40.0000  | 1 PC     | 40.00                |              |
| 11 REVERSE SENSOR                         | 200.0000 | 1 SET    | 200.00               |              |
| 12 STICKER - 70KM/H                       | 10.0000  | 1 PC     | 10.00                |              |
|                                           |          |          | 250.00               | 250.00       |
| <b>Labour</b>                             |          |          |                      |              |
| 13 REMOVE AND REFIX REAR WINDSCREEN GLASS | 100.0000 | 1 LA     | 100.00               |              |
| 14 PANEL BEATING                          | 800.0000 | 1 LA     | 800.00               |              |
| 15 PUTTY & RESPRAY PAINTING               | 800.0000 | 1 LA     | 800.00               |              |
| 16 RUSTPROOFING                           | 80.0000  | 1 LA     | 80.00                |              |
|                                           |          |          | 1,780.00             | 1,780.00     |
|                                           |          |          | Total                | S\$ 2,030.00 |
|                                           |          |          | Add GST @ 7%         | 142.10       |
|                                           |          |          | Total Amount Payable | S\$ 2,172.10 |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Thursday, 19 April, 2018 4:59 PM  
**To:** assignments@lkkauto.com  
**Cc:** chmotor@singnet.com.sg; MT\_Claim\_SG  
**Subject:** FW: Our Ref: 17/18/18/VP05/020555 Repair Survey (Single Joint Expert) - GBF4348R

Dear Catherine /Nivitha,

Kindly refer to your email below.

Please proceed to conduct a survey of the vehicle GBF 4348R on without Prejudice Basis.

Our Insured have not reported the accident.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

19042018 @ 507pm  
K Shun Nivitha  
Catherine

---

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]  
**Sent:** Thursday, 19 April, 2018 3:53 PM  
**To:** MT\_Claim\_SG; GERALD POH WEE BIN  
**Subject:** Repair Survey (Single Joint Expert) - GBF4348R

Dear Sir,

**OUR CLIENT – GBF4348R**  
**DOA – 18/4/18 @1435PM**  
**YOUR INSURED : SLQ4063K**

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards  
June  
Cheng Hoe Motor Pte Ltd  
Blk 1019 Yishun Ind Park A  
01-374, Singapore 768761  
Tel :67556142  
Fax : 67557719



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                              |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                      | Ref : CC4/LPC18007347/Kda3n2 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                      | Date : 10-01-2020            |  |  |
|                                                                                                                                        |                                                                                      | Code : LPC2                  |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                              |                                                                                     |  |
| Insured Veh.                                                                                                                           | SLQ 4063K                                                                            | Veh. Inspected               | GBF 4348R                                                                           |  |
| Policy No.                                                                                                                             | Z17VP05014884                                                                        | Coverage (\$)                | 0.00                                                                                |  |
| Claim No.                                                                                                                              | 17/18/18/VP05/020555                                                                 | Excess (\$)                  | 0.00                                                                                |  |
| Assign From                                                                                                                            | GERALD                                                                               | Assign Date                  | 19/04/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                              |                                                                                     |  |
| Make & Model                                                                                                                           | TOYOTA HIACE                                                                         | c.c                          | 2982                                                                                |  |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.                 | 2016                                                                                |  |
| Chassis No.                                                                                                                            | JTFHT02P800208896                                                                    | Colour                       | SILVER                                                                              |  |
| Odometer                                                                                                                               | 45822                                                                                | Steering                     | IN ORDER                                                                            |  |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification                 | NIL                                                                                 |  |
| General                                                                                                                                | GOOD                                                                                 |                              |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                              |                                                                                     |  |
|                                                                                                                                        | Size                                                                                 | Make                         | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         | 195 R15X8                                                                            | MICHELIN                     | 8 mm                                                                                |  |
| L/H Front Tyre                                                                                                                         | 195 R15X8                                                                            | MICHELIN                     | 8 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                          | 195 R15X8                                                                            | MICHELIN                     | 8 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                          | 195 R15X8                                                                            | MICHELIN                     | 8 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                              |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                      |                              |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                              |                                                                                     |  |
| Accident Date                                                                                                                          | 18/04/2018                                                                           | Inspection Date              | 20/04/2018                                                                          |  |
| Survey held at                                                                                                                         | CHENG HOE MOTOR PL<br>BLK 1019 YISHUN IND. PARK A<br>#01-374/382<br>SINGAPORE 768761 |                              |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                              |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                              |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                              |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      | <b>5 Working Days</b>        |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4348R

| Qty                                | Description of Parts                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                 |                      |                           |                   |
| 1                                  | REAR BUMPER                                                     | BENT                 | 373.65                    | 373.65            |
| 6                                  | REAR BUMPER CLIPS @\$3.50                                       | NECESSARY            | 21.00                     | 21.00             |
| 1                                  | REAR TAILGATE                                                   | BENT                 | 1,672.72                  | 1,672.72          |
| 1                                  | TAILGATE LOGO                                                   | NECESSARY            | 70.24                     | 70.24             |
| 1                                  | TAILGATE STICKER (TOYOTA)                                       | NECESSARY            | 39.02                     | 39.02             |
| 1                                  | TAILGATE INNER LOCK                                             | DENTED               | 249.62                    | 249.62            |
| 1                                  | TAILGATE INNER RUBBER                                           | SERVICEABLE          | 368.90                    | -                 |
| 1                                  | REAR END PANEL OUTER                                            | TO REPAIR SEE LABOUR | 309.83                    | -                 |
| 1                                  | TAILLAMP RH                                                     | CRACKED              | 256.90                    | 256.90            |
|                                    | LESS 25% DISCOUNT                                               |                      | -840.47                   | -670.79           |
|                                    |                                                                 |                      | 2,521.41                  | 2,012.36          |
| <b>SPECIAL NETT ITEMS</b>          |                                                                 |                      |                           |                   |
| 1                                  | REAR WINDSCREEN GLASS GUM (SN)                                  | NECESSARY            | 40.00                     | 40.00             |
| 1                                  | SET REVERSE SENSOR (SN)                                         | SHORTED              | 200.00                    | 200.00            |
| 1                                  | STICKER -70KM/H (SN)                                            | NECESSARY            | 10.00                     | 10.00             |
|                                    |                                                                 |                      | 250.00                    | 250.00            |
| <b>LABOUR</b>                      |                                                                 |                      |                           |                   |
|                                    | REMOVE AND REFIX REAR WINDSCREEN GLASS.                         |                      | 100.00                    | 100.00            |
|                                    | PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER. |                      | 800.00                    | 600.00            |
|                                    | PUTTY & RESPRAY PAINTING.                                       |                      | 800.00                    | 700.00            |
|                                    | RUSTPROOFING.                                                   |                      | 80.00                     | 60.00             |
|                                    |                                                                 |                      | 1,780.00                  | 1,460.00          |
| <b>GRAND TOTAL</b>                 |                                                                 |                      | <b>4,551.41</b>           | <b>3,722.36</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                 |                      |                           | <b>3,722.36</b>   |

Report Ref No. CC4/LPC18007347/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.