

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF4348R

TP/Lonpac

M/S : LONPAC INSURANCE BERHAD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Estimate No: ES1890426/YISHUN

Date: 19 Apr 2018

Policy No:

Veh Reg No: GBF4348R

Make/Model: TOYOTA HIACE VAN
TURBO 5 DR MANUAL

Chassis No: JTFHT02P800208896

Engine No: 1KD2660294

Reg. Date: 26/10/2016

WS Ref: TP/LONPAC/YS

Claim Type: Third Party

Accident Date: 18/04/2018

TP Veh Reg No: SLQ4063K

Not Notarised
1-B.1
Recovery Bypassing
5 days

Estimate Repair Cost to Vehicle No :GBF4348R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER <i>BM</i>		1 PC		
2 REAR BUMPER CLIP <i>mc</i>		6 PC		
3 REAR TAILGATE <i>BM</i>		1 PC		
4 TAILGATE LOGO <i>mc</i>		1 PC		
5 TAILGATE STICKER (TOYOTA) <i>mc</i>		1 PC		
6 TAILGATE INNER LOCK <i>DD</i>		1 PC		
7 TAILGATE INNER RUBBER <i>?</i>		1 PC		
8 REAR END PANEL OUTER <i>?</i>		1 PC		
9 TAILLAMP RH <i>ScR</i>		1 PC		
			0.00	0.00
Special Net				
10 REAR WINDSCREEN GLASS GUM	40.0000	1 PC <i>mc</i>	40.00	<i>—</i>
11 REVERSE SENSOR <i>shot</i>	200.0000	1 SET	200.00	<i>—</i>
12 STICKER - 70KM/H	10.0000	1 PC <i>mc</i>	10.00	<i>—</i>
			250.00	250.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.0000	1 LA	100.00	<i>✓</i>
14 PANEL BEATING	800.0000	1 LA	800.00	<i>600</i>
15 PUTTY & RESPRAY PAINTING	800.0000	1 LA	800.00	<i>700</i>
16 RUSTPROOFING	80.0000	1 LA	80.00	<i>60</i>
			1,780.00	1,780.00
Total			S\$ 2,030.00	
Add GST @ 7%			142.10	
Total Amount Payable			S\$ 2,172.10	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE