



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

G.

EQ INSURANCE COMPANY LIMITED

NO. 5

MAXWELL RD #17-00 SINGAPORE 069110

MND COMPLEX

SINGAPORE 069110

Attention: Agnes Low

Contact : 90903043

Fax No. : 62243903

Estimate : QUOT201804-000468(00)

Date : 19/04/2018

Vehicle No. : SLP1039G

Make/Model : HONDA JAZZ 1.3 CVT ABS
D/AIRBAG 2WD

Mileage (km) : 0

Chassis No. : JHMGK3850HX200458

Accident Date : 18/04/2018 00:00:00

Claim No. : YN1051B

Reference : SLP1039G

Policy No. : 10756389

*Not Authored
1. B.1
Resurvey By pain*

S/No	Particular	6 days	Quantity	Unit Price	Amount S\$
LIST ITEMS :					
1	Rear boot cover		1.0	716.30	716.30 ✓
2	Rear boot emblem - H		1.0	35.00	35.00 ✓
3	Rear boot emblem - Jazz		1.0	35.00	35.00 ✓
4	Rear boot shock absorber		2.0	192.10	384.20 X
5	Rear boot lock		1.0	157.10	157.10 ✓
6	Rear boot rubber		1.0	92.30	92.30 ✓
7	Rear boot inner board		1.0	198.00	198.00 X
8	Rear bumper		1.0	492.70	492.70 ✓
9	Taillamp	ols cpa	2.0	217.40	434.80 ✓
10	Rear bumper retainer		1.0	18.50	18.50 ✓
11	Rear end panel		1.0	314.00	314.00 ?
12	Rear boot outer garnish		1.0	182.00	182.00 ✓
13	Rear boot sticker		1.0	32.00	32.00 X
14	Rear boot inner handle		1.0	92.20	92.20 ✓
15	Rear boot lamp		2.0	86.30	172.60 ?
16	Rear windscreen glass moulding		1.0	82.00	82.00 ✓
17	Rear end top garnish		1.0	115.20	115.20 ✓
18	Spare tyre panel		1.0	583.40	583.40 X
19	Spare tyre top board		1.0	195.00	195.00 X
20	Rear deck tools carrier		1.0	233.20	233.20 ✓
21	Clip		8.0	4.00	32.00 ✓
22	Diffuser		2.0	68.80	137.60 ?
23	Rear number plate lamp		2.0	78.20	156.40 X
24	Rear wiper arm		1.0	92.00	92.00 X
25	Rear wiper motor		1.0	328.20	328.20 ?
26	Rear RH fender inner trim		1.0	192.80	192.80 ✓

List Total :

20% Discount S\$

SPECIAL NET :

- 1 Reverse sensor
- 2 Reverse camera
- 3 Rear number plate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE NEXT PAGE

Page 1 of 2

5,504.50

1,100.90

4,403.60

Not Res 2000

350.00 350.00

485.00 485.00 ?

25.00 25.00



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

EQ INSURANCE COMPANY LIMITED

NO. 5

MAXWELL RD #17-00 SINGAPORE 069110

MND COMPLEX

SINGAPORE 069110

Attention: Agnes Low

Contact : 90903043

Fax No. : 62243903

Estimate : QUOT201804-000468(00)

Date : 19/04/2018

Vehicle No. : SLP1039G

Make/Model : HONDA JAZZ 1.3 CVT ABS
D/AIRBAG 2WD

Mileage (km) : 0

Chassis No. : JHMGK3850HX200458

Accident Date : 18/04/2018 00:00:00

Claim No. : YN1051B

Reference : SLP1039G

Policy No. : 10756389

S/No	Particular	Quantity	Unit Price	Amount S\$
4	Rear number plate garnish	1.0	35.00	35.00
	SPECIAL NET Total S\$:			895.00
	LABOUR :			
	*To remove and install rear windscreen glass	1.0	150.00	150.00
	*To install reverse sensor and camera	1.0	80.00	80.00
	*To supply panel sealant and to seal off all weldspot seam and gaps	1.0	60.00	60.00
	*To check wiring and lighting	1.0	60.00	60.00
	*To remove trims and upholstery	1.0	80.00	80.00
	*To spray under coat	1.0	150.00	150.00
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,000.00	1,000.00
	- Spray painting on affected & replace parts	1.0	1,000.00	1,000.00
				2,580.00

E. & O.E.

Total S\$: 7,878.60

GST 7% S\$: 551.50

Amount Due S\$: 8,430.10

44

for CITY AUTO PTE LTD