ASS. REC. BY		REF:	CS/ASM180	107353/THb	er Specials	etruction		
Surveyor Smud Claim From (Person	Toufildy.  Winnie Ho			ENT (Office) ASM	1		20042U18	11)-13am
Estimated Co.				EGH to-	Little	CAMILES .	1-010	
To Inspect Vo	S / TP RES / OD R chicle No:	SKE ?	)6308	CS	Insured			
	m/s	Cydo &	Carrille		Tel: 91	86 t	5112	
of	- 3-	188 Itin	idan Lapp					
Policy No:			1	Claim No:	S8 MUU	HEJH		
Sum Insured				Excess;	\$ 600.00			
Make of Veh: (Client's Record							1042018	
^	/ REP. / REV 241	TRS						
Date/Time:	20045018 10.40	am Perso	on Contacted; _	Alan	Vehicle	D. Endo	DUT	
Date/Time	Action/Instruction	(1)	Estimate					
73.0	SKE 1530S-	CC3 / AT	a LUU18332	/Rimad I		DUA	250914	
-4XC	Revert	Via	Smart	dam.				
	Part by	Part	\$ 1518	18,45	CRed:	11,	644.67	:42%
	PV & Final	Bill	Submit-	ted to t	4XA. Fro	m l	vunre (	AXA)



# SKE2530S - SURVEY REPORT

Type

Question

Message

Hi all, repairer submit final invoice, pls update assessment urgently

Reply

Menu



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00EJH

Our Ref: CS/ASM18007353/T1tb

Date: 23/4/2018

The Motor Claims Department M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

# PRELIMINARY ADVICE OF VEHICLE NO SJV 3101M

We thank you for the instruction on 20/04/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/4/2018 at the premises of M/s Cycle and Carriage and have the following to report:

 Workshop Estimate Amount
 : \$\$\frac{25,912.14}{10,442.23}\$

 "Check" Items Amount
 : \$\$\$\frac{10,442.23}{10,989.66}\$

 Total
 : \$\$\$\frac{21,431.89}{21,431.89}\$

 Market Value
 : \$\$\$\frac{98,000.00}{20,95.00}\$

 LTA Reimbursement Value
 : \$\$\$\frac{62,095.00}{35,905.00}\$

 Nett Value
 : \$\$\$\frac{35,905.00}{35,905.00}\$

Description of Damage:

The vehicle sustained damages at the front portion.

nearside rear front offside

Comments/ Present Status:
Damages Consistent
Repair cost economical
We have authorize repair on 20/4 @ 1550hrs

Yours Faithfully, Taufikh Automotive Assessor



# Service Request Details

Claim

S8M00EJH

Reference

None 🥒

Loss Date

April 19, 2018

Request Date

April 20, 2018

Due Date

April 27, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

#### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

#### Vehicle Information

Incident Vehicle Registration #

SKE2530S

Make

**MERCEDES** 

Menu

Service Address

188 Pandan Loop Service Center, , , 128378

Primary Contact/Insured

JOHN LIM WENG FAI 36 ALMOND AVENUE, 677713, Singapore 96826687

### Claim Handler

HO Winnie 6568804833 winnie.ho@axa.com.sg Additional Instructions

Additional Instruction

1) XS-\$600

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



# SKE2530S - SURVEY REPORT

Type

**Q** Question

Message


Hi all, repairer submit final invoice, pls update assessment urgently

Reply

ehicle Owner Particula	bate for Registered Vehicle rs
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	4564C
Vehicle No.:	SKE2530S
Vehicle to be	No
Exported:	
Intended De- registration Date:	23 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SLK 200
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	27186130299712
Chassis No.:	WDD1724482F018042
Maximum Power	135.0 kW (181 bhp)
Output:	\$54,305.00
Open Market Value:	20 Feb 2012
Original Registration  Date:	
First Registration Date:	20 Feb 2012
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebat	\$54,305.00 re Details
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Feb 2022
PARF Rebate Amount:	\$35,298.00
Intended COE Rebate	19 Feb 2022
COE Expiry Date:	E - Open Category
COE Category:	10
COE Period(Years):	\$71,000.00
QP Paid:	\$26,797.00
COE Rebate Amount: Total Rebate Amount:	\$62,095.00

The information contained herein is correct as at 23 Apr 2018

ОК



### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aloresara.		
	ACCIDENT STATEMENT	
Date Of Report	19/04/2018 10:50	
Date Of Accident	19/04/2018 08:05	
Exact Location Of Accident	DUNEARN ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	STEEL STATE OF THE

Country/State of Loss		THE RESERVE OF THE PARTY OF THE
THE PROPERTY OF STREET	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKE2530S	
Insured/Policyholder		
Name Of Registered Owner	JOHN LIM WENG FAI	

Name Of Registered Owner S1404564C NRIC No NOEMAIL Email Address

(LOCAL) +65-96826687 Mobile Phone No OFFICE-96826687 Alternative Phone No

Vehicle Particulars MERCEDES-BENZ Manufacturer

SIK Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

AXA INSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy GA164970/1

Policy Number Cover Note Number

Driver JOHN LIM WENG FAI Name of Driver

S1404564C NRIC No 20/03/1960 Date Of Birth INDOOR Occupation 15/01/1997 Date Of Driving Pass

21 YEARS AND 3 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96826687 Mobile Number

Fax Number

OFFICE-96826687 Contact Number

NOEMAIL EMail Address

Address

36 ALMOND AVENUE

Postcode

677713

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

#### General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

AT APPROXIMATELY 0805 HRS ON 19 APR 2018, ALONG DUNEARN ROAD TRAFFIC WAS HEAVY AND SLOW. I WAS IN THE RIGHT LANE, ROAD SURFACE WAS DRY CLEAR VISION, TRAVELLING AT (60KM/HR). I HEARD A LOUD SOUND FROM THE FRONT, THEN I COLLIDED WITH THE CAR B (SLQ9887S) IN FRONT, NO PASSENGER INJURIES. WE EXCHANGED DETAILS. I GO TO CYCLE & CARRIAGE WORKSHOP FOR REPORTING, NO ROAD DAMAGED.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLQ9887S

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

WONG TING SOEN ALVIN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SHB8895B

TAXI

SEE GEE HUAT

# SINGAPORE ACCIDENT STATEMENT

	DENT STATEMENT
Accil	
Date Of Accident	19704718
Time Of Accident	Dubbary Bug 5
Exact Location Of Accident	Singapore/ Malaysia
Country/State of Loss	
DETAIL	S OF OWN VEHICLE
Vehicle Registration Number	SKE 2530 15
Insured/Policyholder	D. John lim Wone Fai
Name Of Registered Owner	Dr John Lim Wang Fai
NRIC No	5140436TC
Email Address	0/00///
Mobile Phone No	4985 9981
Alternative Phone No	
Vehicle Particulars	
Manufacturer	MEREDES-BENZ
Model	SLA
Exact Purpose for which vehicle was being used	Private use Committed use Hire & Face & Committed
at time of accident	Others - Please specify
Are you claiming under your own insurance policy for repair to your vehicle?	Yes No Other Third Party Claim Reporting Only
If No, Please state action to be taken	TO STONE TO TO CONTROL OF THE PROPERTY OF THE
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA.
Type Of Coverage	Comprehensive Others
Fleet Policy	Yes No 2
Policy Number	GA 1649 10/1
Cover Note Number	
Driver	Di Tuli Lim Wey Pai
Name of Driver	Dr. Juhn Lim Weng Pai
NRIC No	30107/1960
Date Of Birth	CO 10 7 1 100
Occupation	Indoor Outdoor
Date Of Driving Pass	15/01/1971
Driving Experience	Maie Female
Gender	9502 6607
Mobile Number	108 ( 008 )
Fax Number	_
Contact Number	
Email Address	36 Almond Avenue
Address	26 1/11-1025 1/16 work
Postcode	6777 13

* e	7
Sthe Jacuras's Company	Yes No
Was driver an employee of the Insured's Company	Owner Paid Driver Relative Friend Paren
If No. Relationship of the Driver with the Insured	Spouse Children Sibling Other:
Vehicle Registration Number of Driver's Own	_
Vehicle Insurance Company of Driver's Own Vehicle	
	5 to 10 to 1
General Information of the Accident	
Type Of Accident	Clear Raining Others
Weather Conditions	
Road Surface	Dry Wet Others
Details of Injured Persons	
Was anybody injured in the Accident?	No Yes
Name	/
Address	(I / A
Injuries Sustained If vehicle Occupants, state in which vehicle?	
Were seat belts worn?	No Nes -
Was injured conveyed to hospital by	No Yes
ambulance?	and the second s
Orlean formation	No ZVes
Was any foreign vehicle involved in this	No Yes
accident?  Number of vehicles involved in the accident	
Was any other material or property damaged?	No Yes
I have been approached by unknown	No Yes
person(s) soliciting/offering accident claims	
assistance.  Number of Passengers (Including Driver)	
Passenger 1	
Fasseriger	Male Female
	The state of the s
Passenger 2	
20	Male Female
Passenger 3	
And Sydne and Anguity (Anguity)	Male Female
Passenger 4	
, asserting of the	Male Female
Passenger 5	Male Female
	Male La remaie La
Details of Police Action	
Was the accident reported to the police?	No Yes
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No Yes
NO If Yes, against whom?	

	Circumstances of Accident	
	Attachment(s)	
	Are accident photos available for attachment? Was there any video captured by Car Camera?	No Yes Yes
	die engesdod?	FOTHER VEHICLE PROPERTY 1
	Vehicle Registration Number Vehicle Make/Model/Colour	SLQ 9887 5
	Details Of Properties	
	Vehicle Category	Ti ( a Alvi)
	Name of Driver	Mr Wong Ting Soen Alvin
	NRIC/Passport Number	3
	Contact Number	
	Address	
200	Postcode	
	Insurance Company Name Nature Of Damage	
	No. Of Passenger (Including Driver)	
	DETAILS	OF OTHER VEHICLE PROPERTY 2
	Vehicle Registration Number	SHB 8895 B
	Vehicle Make/Model/Colour	VIIIZ
	Details Of Properties	
	Vehicle Category	
	Name of Driver	Mr See Cree Hugt
	NRIC/Passport Number	
	Contact Number	
	Address	
	Postcode	
	Insurance Company Name	
	Nature Of Damage	
	No. Of Passenger (Including Driver)	
	Details of Witness	
	Was there any witness?	No Yes
	Name	
	Phone Number	
	Email Address	

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and (d) management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

plying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

Driver's Signature


(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Algh Quek Name:

NRIC/FIN No.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT APPROXIMATELY USOS HAS, 18/4/8, ALONG DUNEARN ROAD TRAFFIL WAS HEAVY/SLOW I WAS IN THE RIGHT LAWR. ROAD FURFACE WAS DRY CLARR VINION. TRAVELLEND AT COO KM/UR. I HEARD A coup sound FROM THE FROMP, THEN I COLLIDED BITH THE CAR IN FRANT. (0805 HRS | - SIQ 98875 AND A NEWND FOUND WAS TERRO

STOP EUPINE. JAT OND OR CAR. ALL BRIVERS/

PROSENIERS INVOLVED COMM NO PATTICEN

INJURIES. EXCHANGED DEFINES

JEJUR 70 CYCIR/ CARRIAGE WORKTOP FOR REPORTISI NO ROAD DAMAJE NOTRD

DECLARATION

IAWe declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

19/04/18

Reporting Centre Persoanel's Name: ALG OW

NRIC/FIN No.:

# REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S 1 4 0 4 5 6 4 C

Name

JOHN LIM WENG FAI

Birth Date: 20 Mar 1960 Issue Date: 01 Dec 2003

001028019G

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

15 Jan 1997

FOR C&C USE ONLY



NP 428A





1 of 3

Report No. T/20180419/2072

Police Station Of Origin: Bukit Panjang N.P.C 1 Segar Road #01-05 SINGAPORE 677738 Tel No: 1800-8929999

REPORT OF A TRAFFIC ACCIDENT  Date/Time Report Made:  19/04/2018 15:01			Vide Report No.:	Station Diary No. 85	
		Service of the Control of the Contro			
Name of	Informant:		Address: 36 ALMOND AVENUE SINGA	PORE 677713	
JOHN LIM WENG FAI ID Type / ID No.: NRIC NO / S1404564C			Contact No.: Home/Office:	Mobile: 96826687	
Nationality: SINGAPORE CITIZEN		C11/C1	Email:		
Sex: Male	Age: 58	Date of Birth: 20/03/1960	Type of Informant: Driver	La di di Cabaal Namo:	
Race: Chinese			Language:	Institution / School Name:	
Occupa	tion:		Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 19/04/2018 08:05	Type of Location Straight Road	
Location: Along Road DUNEARN F		Road Surface:		Road Speed Limit: 40 Km/h	
Clear		Dry		Traffic Volume:	
Traffic Flow:		Traffic Control: Not Controlled		Moderate	
One Way  Type of Coll	ision:	To Rear		Anyone conveyed by ambulance:	

Details of V	enicie ilivo		Model	Color	Condition	No of Passenger
Vehicle No.	Туре	Make	Model	COIOI		4
SHB8895B	Car				Slightly Damaged	7
SKE2530S	Car	MERCEDES	SLK 200	Grey	Slightly Damaged	0
SLQ9887S	Car	BENZ			Seriously Damaged	1

	ehicle Insurance			
Details of v	enicle ilisurance	I. No	Effective	Expiry Date
Vehicle No	Insurance Company	Insurance No	Lifective	LAPIT J





2 of 3

Report No. T/20180419/2072

Police Station Of Origin: Bukit Panjang N.P.C 1 Segar Road #01-05 SINGAPORE 677738

Tel No: 1800-8929999

CONTINUATION OF REPORT

	ehicle Insurance	Insurance No	Effective	Expiry Date
Vehicle No.	Insurance Company		20/02/2018	19/02/2019
SKE2530S	AXA INSURANCE SINGAPORE PTE	GA 104970		

Details of Person	1 involved							
Any Pedestrian Ir	volved: No	Use of	Use of Pedestrian Crossing: NA					
No. of Pedestrian	s Injured: NIL							
Driver			ID No.		S1404564C			
Name	JOHN LIM WENG FAI	1.5 110						
		Contac	et No	96826687				
Related Vehicle	SKE2530S (Car)		Contact 110.					
(Clatos	A HEROMODER - TON TON THE	Class	of	Class: 3 Date of Expiry: NIL				
Hospital/Clinic	NIL	Drivin						
1 103pitali Gii ii s	The state of the s	Licence						
			Expiry					
			NIL					
Date Treatment	NIL	Date	Discharge					
Date Heatment	nted Medical Leave NIL	Degr	ee of Injury	INIL				

On 19 April 2018 at abou 0805hrs, I was driving my vehicle (SKE2530S) along Dunearn Road and was on the extreme right lane. As, I was driving I suddenly heard a loud sound coming from infront and I also had tried to apply my brake however did not manage to avoid the collision on the front car(SLQ9887S). It was a chain collision accident involving 3 cars. My vehicle(SKE2530S) was the 3rd car followed by the 2nd car (SLQ9887S), and lastly the first car (SHB8895B). Due to the accident, the 1st car suffered slight damages to the rear bumper while the 2nd car suffered serious damages to the back bumper area and also the front bumper had slight damager. On the other hand, my car suffered slight damages to the front bumper. At that moment of time no one had any known injuries and all parties agreed to go our separate ways after we have exchange particulars. I also wish to state that no TP nor ambulance at scene. I also did not have any inbuilt video recorder. On the same day,I also received call at about 1241hrs from TP officer who informed me that someone from the 2nd car has been hospitalized and was advised to lodge an traffic accident report.





3 of 3

Report No. T/20180419/2072

Police Station Of Origin: Bukit Panjang N.P.C 1 Segar Road #01-05 SINGAPORE 677738 Tel No: 1800-8929999

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  J / Staff Sgt NIAZ MOHAMED OHAZALI	Signature Of Informant:
Signature Of Interpreter:  Not applicable	Date/Time: // 19/04/2018 15:01
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430 office hr S	Classification Of Case:



Cycle & Carriage

### **ESTIMATE FOR SKE2530S**

Dr John Lim Weng Fai

36 Almond Avenue Singapore 677713

Mobile: 96826687

Vehicle & Document Information

23011 WIP No

SKE2530S / 20/02/2012 Reg No/Reg Date

Date In/Mileage

Chassis No

WDD1724482F018042

1/10000

27186130299712 Engine No

MB/SLK 200 CGI ROADSTER R172 Make/Model

027 755 Tenorite Gr/ 042 208 Leather Gr Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	71 4			
CSM00128	Cash	20/04/2018/ 09:41	AQ	305 / Alan Quek A		Unit Price	Disc%	Amount
		Description of Goods			Qty			Fillionis
M BPNSUN_	- 10	A LOW MAN IS	B.I	SECTION	ITA	VIB	18//	AICE
POLICY !	NO/ACC DAT	TE :GA164970 // 19-04-2	2018	<b>DFFICIA</b>	1 1 1 1 1 1 1	LA HE	8 A A	UIUL
DRIVE I	N/EXCESS	:19-04-2018 // TBA						
DATE IN	/DATE SURV	/EY:				Δ.	200	1/200 00
	HRIZED ON	:				2	0.10	380.00
A BPILAB	TO CU	ECK CONTROL UNITS & RES	SET MEMOR	v TO	1/1	2	7	2000 500
USE XEN	TRY TO UNE	CK CUNIKUL UNLIG G III-	SET HERE	2018.	9/ 11	1		M 60.00
	RD SETTINGS	S.NETT			11 12			00.00
S BPNSUB	1 DC DEG	PLATE WITH HOUSING.NE	TI	1 M	11 -		0.07	? 500.00
				- [1] L	1 0		0.07	
REMOVE	TO CHECK	OR REPLACE RADIATOR, C	COOLING SYS	STEM, CONDENSER WITH	<b>V</b>			/
VACIUM	AND RECHA	ARGE OF REFRIGERANT.NET	T	1111/11/11/11				120.00
A RPTI AR			[7]	1111/11/11				2850.
CHECK	HEADLAMP W	WITH FOCUS ADJUSTMENT.N	IEIT \\	110				4800.00
			1 1 1	TOUT SENDED				305353556envo
	& REPLACE	FRONT BUMPER, FRONT B	SONNET, FR	ONT RIGHT FERUER,			1	2400.
FRONT	LEFT FENDE	ER & REMOVE FRONT SUPPO	JRT ASSY U	OMPONENTS & RELITION.			J	
		150					0.02	2800.00
A BPIRES		DANIET F	DON'T LEET	FENDED				
RESPRA	Y FRONT BU	UMPER, FRONT BONNET, FF	KONT LEFT	FENDER			- Name and	10 0000 00
	IT RIGHT FE	ANDER			1.00	1515.65		1515.65
M FRT BU		ACE			1.00		00.00	7 1095.16
M LICENS	SE PLATE BA	ASE MCOD			4.00	273.79	00.00	
M CT/F P	PARKING SEN PARKING SEN	NCUD CEVI			4.00		00.00	
M CI/F F	TOR GRILLE	CHIDDURT			1.00	177.06		
M KAUIAI	IMPACT ABSO	ODRED			1.00	127.85	00.00	4
M CT/F I	IMPACT ABSO	ORRER			1.00	90.21		0
M LD/F	IMPACT ABSO	ORRER			1.00		00.00	
M LH/F I	NUOW STRAG	ITING FOR BUMPER			1.00	78.68	00.00	ner-78.6
M RH/F B	RASIC MOUN	ITING FOR BUMPER			1.00		00.00	(iii)
M CT/F (	CLAMPING R	ATI			1.00	ALGINE	44.	* * * * * * * * * * * * * * * * * * *

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



### **ESTIMATE FOR SKE2530S**

Dr John Lim Weng Fai

36 Almond Avenue Singapore 677713

Mobile: 96826687

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

23011

/ 20/02/2012 SKE2530S

---

WDD1724482F018042

27186130299712

MB/SLK 200 CGI ROADSTER R172

027 755 Tenorite Gr/ 042 208 Leather Gr

Operator CSE Date/Time Printed Account No Terms 305 / Alan Quek Ai Lun 20/04/2018/ 09:41 AQ Cash CSM00128 Amount Unit Price Disc% Qty Description of Goods / Services an 142.35 142.35 00.00 1.00 RADAIATOR GRILLE GARINSH SUPPORT 72.06 72.06 00.00 1.00 RADIATOR GRILLE STAR HOLDER 130.65 00.00 1.00 MI/ 59.73 RADIATOR GRILLE STAR 1.00 59.73 00.00 11.76 FRT BUMPER TOP STAR 11.76 00.00 1.00 11.76 mn LH/F BUMPER BRACKET 00.00 ? 48.79 Le 11.76 1.00 RH/F BUMPER BRACKET 00.00 48.79 1.00 LH/F BOTTOM GRILLE 48.79 00.00 M 1.00 R>2160.25 RH/F BOTTOM GRILLE 1.00 2160.25 00.00 59.82 00.00 BONNET 2.00 29.91 67.10 BONNET SPRING 00.00 67.10 1.00 63.32 BONNET SAFETY HOOK 00.00 31.66 2.00 BONNET UPPER CATCH 189.68 189.68 00.00 1.00 1055.23 BONNET INSULATION 00.00 1055.23 M 1.00 1055.23 LH/F FENDER LKK Auto Consultants hence notify 00.00 1.00 1055.23 RH/F FENDER 00.00 10.11 M the Repairer of the following: 10.11 1.00 LH/F INTERMEDIATE LAYER 10.11 cra 77 1105.09 М 10.11 00.00 To teaurvey before/after apray painting 1.00 RH/F INTERMEDIATE LAYER To display darbaged part(s) during resurvey 00.00 1.00 1105.09 1105.09 М LH/F HEADLAMP 1105.09 00.00 \*Parts Mices are subject to confirmation 1.00 bt-912.63 RH/F HEADLAMP M 1.00 912.63 00.00 Third party survey is on a "Without Prejudice" basis 609.41 XV 00.00 FRT CROSS MEMBER 609.41 М 1.00 » No illegal modification(s) is allowed FRONT END SUPPORT MEMBER 100.01 00.00 100.01 1.00 · Supplementary item(s) must be resurveyed and LH/F HEADLAMP BRACKET 100.01 100.01 00.00 1.00 is subject to final approval from Insurance Company Q1298.41 RH/F HEADLAMP BRACKET 1298.41 00.00 M 1.00 119.08 00.00 M CONDENSER 119.08 Acknowledged by Repairer 1.00 7 1374.00 CONDENSER BRACKET M 1374.00 00.00 1.00 New 7 323.44 Signature: RADIATOR 323.44 00.00 M 1.00 Date: 108.75 FAN SHROUD 108.75 00.00 1.00 165.30~ TOP AIR BAFFLER 165.30 00.00 1.00 Alan Quek 7 1252.54 N Cycle & Carriage Industries Pie Ltd BOTTOM AIR BAFFLER 1252.54 00.00 1.00 Body Care & Regar Center INTERCOOLER DID: 6771 4377 HP: 9186 5 17 Pax: 6872 1272 Mauto com 97495749 Confirmed & accepted by 25,912.14 Nett 1813.85 25912.14 7% GST on 27,725.99 **Total Payable** Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



## **ESTIMATE FOR SKE2530S**

Dr John Lim Weng Fai

36 Almond Avenue Singapore 677713

\*Mobile: 96826687

Vehicle & Document Information

23011

WIP No SKE2530S / 20/02/2012 Reg No/Reg Date

23/04/2018/ 77651 Date In/Mileage

WDD1724482F018042 Chassis No

27186130299712 Engine No

MB/SLK 200 CGI ROADSTER R172 Make/Model

027 755 Tenorite Gr/ 042 208 Leather Gr

	T	Date/Time Printed	CSE	Operator				
Account No	Terms	18/06/2018/ 14:37	AQ	383 / Cheong		Unit Price	Disco%	Amount
SM00128	Cash	Description of Good	s / Services		Qty	Unit Price	Disch	7 and 1000
DRIVE IN DATE IN, BY/AUTHI X LH/F BUI X RH/F BUI X FRONT B X INFORMA	JEXCESS DATE SURVI RIZED ON MPER STIFF MPER STIFF UMPER UNDE TION LABEL TIME RUNNI TIME LIGHT	:LKK TAUFIKH // 20- ENING HOLDER ENING HOLDER R COVER	TAUFIKH 04-2018	FFIC	1.00 1.00 1.00 1.00 1.00 4.00 1.00	19.64 19.64 373.19 12.81 364.13 26.48 2.29	00.00 00.00 00.00	de 19.64 de 19.64 de 373.19 ne 364.13 aut 26.48 ne 9.16

Confirmed & accepted by

Nett 922.73 7% GST on

922.73 64.59

Total Payable

\$87.32

Authorized signatory and company stamp

Estimated costs quoted are excluding GST. Me would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required diver repair outs man commenced. Occasionally agent of south first occur, and account of the work. Payment for this may be made in cash, credit card or we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvortent breakage in the course of renewing the rubber seal or other repair requiring Pandan Loop Service Center the removal of the windscreen.



WE DRIVE FIRST CLASS

188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





### ESTIMATE FOR SKE2530S

Dr John Lim Weng Fai

36 Almond Avenue Singapore 677713

Vehicle & Document Information

23011 WIP No

SKE2530S / 20/02/2012 Reg No/Reg Date

Date In/Mileage

23/04/2018/ 77651

Chassis No

WDD1724482F018042

**Engine No** 

27186130299712

1.00

1.00

1.00

1.00

Make/Model Colour/Trim

MB/SLK 200 CGI ROADSTER R172

027 755 Tenorite Gr/ 042 208 Leather Gr

Operator CSE Date/Time Printed Terms Account No

383 / Cheong Chin Leong AQ

18/06/2018/ 14:37 Amount Disc% Cash Unit Price CSM00128 Qty Description of Goods / Services M BPNSUN :GA164970 AXA ///19-04-2018 :19-04-2018 // \$600 POLICY NO/ACC DATE DRIVE IN/EXCESS DATE IN/DATE SURVEY: 20-04-2018 // LKK TAUFIKH 380.00 :LKK TAUFIKH // 20-04-2018 0.10 BY/AUTHRIZED ON USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO A BPILAB 60.00 STANDARD SETTINGS.NETT S BPNSUB 120.00 SUPPLY 1 PC NO PLATE 2880.00

BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT RIGHT FENDER, FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.

RESPRAY FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER & FRONT RIGHT FENDER

X BPNEXC INSURANCE EXCESS FRT BUMPER

LICENSE PLATE BASE CT/F PARKING SENSOR SEAL RADIATOR GRILLE SUPPORT CT/F IMPACT ABSORBER

LH/F BASIC MOUNTING FOR BUMPER RH/F BASIC MOUNTING FOR BUMPER

CT/F CLAMPING RAIL RADAIATOR GRILLE GARINSH SUPPORT RADIATOR GRILLE STAR HOLDER

RADIATOR GRILLE STAR LH/F BUMPER BRACKET

Finalization

6.42 00.00 4.00 177.06 00.00 1.00 127.85 00.00 1.00 78.68 00.00 1.00 78.68 00.00 1.00 113.01 00.00 1.00 142.35 00.00 1.00 72.06 00.00 1.00 130.65 00.00

1515.65 00.00

89.45 00.00

11.76 00.00

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. Me would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring Pandan Loop Service Center the renoval of the windscreen.



WE DRIVE FIRST CLASS

188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



2400.00

-600.00

1515.65

89.45

25.68

177.06

127.85

78.68

78.68

113.01

142.35

72.06

130.65

11.76



#### **ESTIMATE FOR SKE2530S**

Dr John Lim Weng Fai

36 Almond Avenue Singapore 677713

Vehicle & Document Information

WIP No 23011

Reg No/Reg Date

SKE2530S / 20/02/2012

Date In/Mileage

Chassis No

23/04/2018/ 77/651

Engine No

WDD1724482F018042

27186130299712

Make/Model Colour/Trim

MB/SLK 200 CGI ROADSTER R172

027 755 Tenorite Gr/ 042 208 Leather Gr

Account No	Terms	Date/Time Print	ed	CSE	Opera	itor					
SM00128	Cash	18/06/2018/	14:37	AQ	383 /	Cheong	Chin Leor	ng			
		Description	of Good	s / Services				Qty	Unit Price	Disc%	Amount
RH/F BUME	PER BRACKE	T as at action area	n en		in. Here come	P elle H	20 m	1.00	11.76	00.00	11.76
RH/F BOT	TOM GRILLE	MI O DI	1	N C	)FF	1001	MI	1.00	48.79	00.00	48.79
	DER II	H A COR	HV	11/11 6	/ H H			1.00	1055.23	00.00	1055.23
Telephone (1970)	LAMP UNIT							1.00	1105.09	00.00	1105.09
FRT CROSS	S MEMBER							1.00	912.63	00.00	912.63
	TOP PANEL							1.00	627.65	00.00	bt - 627.65
	DLAMP BRACK	KET						1.00	3 100.01	00.00	100.01
TOP AIR E							Total	1.00	108.75	00.00	108.75
BOTTOM A	IR BAFFLER					· ·	1. 11	1.00//	165.30	00.00	165.30
INTERCOOL	LER					7 11	1	1,00	1252.54	00.00	1252.54
LH/F BUMF	PER STIFFE	NING HOLDER			~ 1	11 11	71.	1.700	19.64	00.00	19.64
RH/F BUMF	PER STIFFE	NING HOLDER			1112	111		1.00	19.64	00.00	19.64
FRONT BUI	MPER UNDER	COVER		Lamer	IIIIIV	MIL	1	1.00	373.19	00.00	373.19
INFORMAT	ION LABEL			EST	1111/	117.		1.00	12.81	00.00	12.81
LH/ HEADL	AMP UNIT		por many	11 "	11/7	6		1.00	1105.09	00.00	1105.09
RH/ DAYT	IME RUNNING	G LIGHT	(	- 11	7			1.00	364.13	00.00	364.13
RH/ DAYT	IME LIGHT !	MOULDING	1 min	-1 /c				1.00	26.48	00.00	26.48
RIVET		11	1	1)			1	4.00	2.29	00.00	9.16
SEAM SEAL		15	1	And the second				1.00	97.68	00.00	97.68
		1	and the same								C-001X3074

Finalization

Confirmed & accepted by

Nett

15,218.45

7% GST on 15218.45

1065.29

Total Payable

16,283.74

Authorized signatory and company stamp

Yalidity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

