

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Apr-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1227 R

1 pc	o/s headlamp	\$	1,531.57 <i>at</i>
1 pc	Front bumper tow cap	\$	60.10 <i>at</i>
1 [c	Front bumper o/s side bracket	\$	32.51 ?
1 pc	Front bumper	\$	811.11 <i>de</i>
1 pc	Bonnet grille	\$	566.89 <i>ry</i>
		\$	3,002.18
	Less 20%	\$	600.44
		\$	2,401.74
S/nett			
1 set	Front bumper clips	\$	48.00 <i>no</i>
1 pc	Front number plate	\$	50.00 x
	Sundry	\$	50.00 <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts. To panel beat on the support panel etc	\$	650.00 <i>300</i>
	To putty and spray painting on front bumper, Bonnet grille	\$	400.00 <i>300</i>
		\$	3,599.74

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



Tan Jiah 97495749
- WP -
24/4/18 2pm
Resurvey before paint.
3 days.
sur@lkkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: