

ASS. REC. BY:

REF:

CS/Smo18007361/Avbⁿ²

Special Instruction:

Survivor:

Action:

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

Smo

Date/Time:

20042018 9:47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 9879D

Insured:

SJK 5249R

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 ubi Rd 4

Policy No:

Claim No:

CMTD1801657 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

20042018 9:58am

Person Contacted:

Amy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 9879D - x

SJK 5249R - CC4/1AXA13004822 / Gth3c3

DUA 020812

23/4/18

Email preli revised to Grace Teo

31/5/18

Final fig \$ 13,996.78 confirmed by email (Reel 7540.06, 35/1)

REF: SMO

ASSIGNMENT

From: _____ Date: 20042018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 9879D

at Workshop m/s: Kah motor

of: 13 Ubi Rd 4

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Any

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE9879D Yr Regn: 2016

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey c.c. August.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 46997. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC18S06C205992

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17.

R: 215/55R17.

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/04/18

Survey held at Kah motor.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo

RECEIVED 31 MAY 2018

Date/Time, File Pass to?

☒ : Preli. ReportDays Of Repair: 10

1)

☐ : Final ReportResurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

2) 2/5- typistAdd Fee: ☐ Site Insp (\$)

) S + RS \$

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

)

Report Format: TPLump Sum / I.B.I. (\$) 13,996.78

TOTAL

450



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your ref: CMTD1801657/GPL
Our ref: CS/SMO18007361/Avb

Date: 23/4/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLE 9879D


We thank you for your instruction on 20/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle
20/4/2018 at the premises of M KAH MOTOR
and have the following to report:-

Workshop Estimate Amount	: S\$21,476.84
Revised Estimate Amount	: S\$13,617.14
"Check" Items Amount	: S\$1,979.73
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 20 April, 2018 9:47 AM
To: arychua@honda.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1801657/GPL - SJK5249R(SOMPO) & SLE9879D(LIBERTY) ACC ON 16.04.18
Attachments: 0884_001.pdf; 3.JPG; 4.JPG; 5.JPG; 6.JPG; 7.JPG; 8.JPG; 1.jpg; 2.jpg

Our Claim Reference: CMTD1801657/GPL
Your Reference: SLE9879D(LIBERTY)

Hi Ary,

We acknowledged receipt of your notification.

Please be informed that Mr. Gnoh Pau Loong the handler of this case.

We have appointed **LKK AUTO** to conduct the survey.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SLE9879D.

Please be informed that Mr. Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ary Chua [mailto:arychua@honda.com.sg]

Sent: Friday, April 20, 2018 8:47 AM

To: Claims - Motor Survey

Subject: TPDS: SLE9879D(LIBERTY) & SJK5249R(SOMPO), DOA:

Hi Sompoo-OIC,

Kindly Arrange for car Survey (Tow In at Ubi) & Establish this Case Liability. Owner got Video Footage.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 23 April 2018 11:43 AM
To: 'Teo, Grace'
Cc: 'Gnoh, Pau Loong'; 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1801657/GPL - SJK5249R(SOMPO) & SLE9879D(LIBERTY) ACC ON 16.04.18
Attachments: SLE 9879D PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SLE 9879D
Date of survey: 20/4/2018
Number of days: 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 20 April 2018 9:59 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801657/GPL - SJK5249R(SOMPO) & SLE9879D(LIBERTY) ACC ON 16.04.18

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Friday, 20 April, 2018 9:47 AM
To: arychua@honda.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801657/GPL - SJK5249R(SOMPO) & SLE9879D(LIBERTY) ACC ON 16.04.18

Our Claim Reference: CMTD1801657/GPL

Your Reference: SLE9879D(LIBERTY)

Hi Ary,

We acknowledged receipt of your notification.

Please be informed that Mr. Gnoh Pau Loong the handler of this case.

We have appointed **LKK AUTO** to conduct the survey.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SLE9879D.

Please be informed that Mr. Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ary Chua [<mailto:arychua@honda.com.sg>]

Sent: Friday, April 20, 2018 8:47 AM

To: Claims - Motor Survey

Subject: TPDS: SLE9879D(LIBERTY) & SJK5249R(SOMPO), DOA:

Hi Sompo-OIC,

Kindly Arrange for car Survey (Tow In at Ubi) & Establish this Case Liability. Owner got Video Footage.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 31 May 2018 10:19 AM
To: 'Ary Chua'; Adrian Ling (LKKAUTO); SUR
Subject: RE: Finalise TPDS: SLE9879D(Liberty) & SJK5249R(SOMPO), DOA: 16/04/2018@21.45PM

Dear Ary,

WITHOUT PREJUDICE

Confirmed finalize amount \$13,996.78 before GST @ 10 working days.

Final invoice and all supporting documents sent over to SOMO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua [mailto:arychua@honda.com.sg]
Sent: Wednesday, 30 May 2018 8:19 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalise TPDS: SLE9879D(Liberty) & SJK5249R(SOMPO), DOA: 16/04/2018@21.45PM

Hi Adrian Ling,
Kindly Finalise TPDS: SLE9879D(Liberty) & SJK5249R(SOMPO), DOA: 16/04/2018@21.45PM

Final Repair Costs (include GST)	\$13,996.78 + (\$979.75) = \$14,976.53
Repair Period* (Working Day)	10

*NOTES: The Repair Not Includes Public Holiday & Sunday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610
E-mail: aychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 11:24
Date Of Accident	16/04/2018 21:45
Exact Location Of Accident	SLIP RD TAMPINES AVE 2 (L/P59S2) TO TAMPINES AVE 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9879D
Insured/Policyholder	
Name Of Registered Owner	GEORGE NG
Co Reg No	53366463B
Email Address	GEORGE_NG.W.B@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96279455
Alternative Phone No	OFFICE-96279455

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 ABSOLUTE (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V08947/VPL/R00
Cover Note Number	

Driver

Name of Driver	NG WIE BOON, GEORGE
NRIC No	S7301742D
Date Of Birth	12/01/1973
Occupation	INDOOR
Date Of Driving Pass	20/06/1995
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96279455
Fax Number	
Contact Number	
Email Address	GEORGE_NG.W.B@HOTMAIL.COM

Address	BLK 519A TAMPINES CENTRAL 8 #09-05
Postcode	S521519
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NO 1 INQUIRY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK5249R
Vehicle Make/Model/Colour	SUZUKI/BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle No SLE 9879D.**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Vehicle No SLE 9879D

Annex E

Describe Circumstances of the Accident

ON THE EVENING OF 16 APR 2018 AT AROUND 9.45pm, I WAS TRAVELLING FROM TAMPINE AVE 2 TOWARDS TURNING TOWARDS AVE 7, UPON ENTERING THE SLIP ROAD, I SLOW DOWN AND STOP TO GIVE WAY TO THE VEHICLE ON MY RIGHT AND SUDDENLY, I FELT A BANG ON THE BACK OF MY CAR. CAR NO SJK 5249R HIT THE BACK OF MY CAR, THE BACK DOOR WAS

Declaration

(We declare the foregoing particulars are true in every respect.)



Qy

17 APR 2018
10.40 am.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

11:11am *ARY*
17 APR 2018 ARY CHUA

Witnessed by Reporting Centre Personnel

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of GEORGE NG (53366463B)

Date: 07/08/2017

The Following Are The Brief Particulars of :

Name of Business	GEORGE NG
Former Name(s) if any	
Date of Change of Name	
Registration No.	53366463B
Registration Date	12/07/2017
Commencement Date	12/07/2017
Status of Business	Live
Status Date	12/07/2017
Renewal Date	
Expiry Date	12/07/2018
Renewal via GIRO	NO
Constitution of Business	Sole-Proprietor
Principal Place of Business	519A TAMPINES CENTRAL 8 #09-05 CENTRALE 8 AT TAMPINES SINGAPORE (521519)
Date of Change of Address	

Principal Activities

Activities (I)	PASSENGER LAND TRANSPORT N.E.C. (EG PRIVATE CARS FOR HIRE WITH OPERATOR AND TRISHAWS) (49219)
Description	
Activities (II)	
Description	

Particulars of Authorised Representative(s)

Name	ID	Nationality	Address	Address Source	Date of Appointment
------	----	-------------	---------	----------------	---------------------

Existing Sole-Proprietor(s) / Partner(s)

Name	ID	Nationality/Place of Incorporation/Origin	Address	Address Source	Date of Entry	Position
------	----	---	---------	----------------	---------------	----------

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Business) of GEORGE NG (53366463B)

Date: 07/08/2017

Existing Sole-Proprietor(s) / Partner(s)

Name	ID	Nationality/Place of Incorporation/Origin	Address	Address Source	Date of Entry Position
GEORGE NG WIE BOON	S7301742D	SINGAPORE CITIZEN	519A TAMPINES CENTRAL 8 #09-05 CENTRALE 8 AT TAMPINES SINGAPORE (521519)	ACRA	12/07/2017 Owner

Withdrawn Partner(s)

Name	ID	Nationality/Place of Incorporation/Origin	Address	Address Source	Date of Entry Position	Date of Withdrawal
------	----	---	---------	----------------	---------------------------	-----------------------

Abbreviation

OSCARs - One Stop change of Address Reporting Service by Immigration & Checkpoint Authority.

PLEASE NOTE THE INFORMATION HEREIN CONTAINED IS EXTRACTED FROM FORMS/TRANSACTIONS FILED WITH THE AUTHORITY

FOR REGISTRAR OF COMPANIES AND BUSINESS NAMES
SINGAPORE

RECEIPT NO. : ACRA170807197700

DATE : 07/08/2017

This is computer generated. Hence no signature required.

To: Whom It May Concern


I GEORGE NG authorize GEORGE NG WIE BOON
of NRIC S7301742/P. to sign documents related to my vehicle no.
SCF 9879 D accident date 16 APR 2018 on my behalf.



George Ng
Signature of owner

NRIC: S7301742/P.

Insurance Company: LIBERTY INSURANCE PTE LTD.



Liberty Insurance Pte Ltd

Registration no. 199002791D

51 Club Street

#03-00 Liberty House

Singapore 069428

Tel: (65) 6221 8611 Fax: (65) 6226 3360

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD17V08947 /NPL /R00
From	MZ400B
Date Of Issue	28-JUL-2017
1. Index Mark and Registration No. of Vehicle:	SLE9879D
2. Chassis number of Vehicle:	JHMRC1890GC205992
3. Name of Policyholder:	GEORGE NG
4. Effective date of Commencement of Insurance for the purpose of the Act:	04-AUG-2017 00:00 AM
5. Date of Expiry of Insurance:	09-AUG-2018 23:59 PM
6. Persons or Classes of Persons entitled to drive*:	GEORGE NG
For Uber/Grabcar Usage :	
For Social, domestic & pleasure purposes : Any Authorised Drivers driving with the permission of the Policyholder.	
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.</p>	
7. Limitations as to use*:	
<p>A) Use for carriage of passengers or goods in connection with the Policyholder's business.</p> <p>B) Use for social, domestic and pleasure purposes.</p>	
8. Policy does not cover:	
<p>A) Use for racing, pace-making, reliability trials or speed-testing.</p> <p>B) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.</p>	
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.</p>	
<p>I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).</p>	
<p>For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers</p>	
<p> Authorised Signature</p>	
<p>For Information only: COVERAGE : Comprehensive, Unlimited Windscreen, Uber/Grabcar Extension (Geographical Area: Singapore only) SUM INSURED: MARKET VALUE AT THE TIME OF LOSS EXCESS: Section I - Singapore - S\$2000 / Outside Singapore S\$4000, Section II - Singapore - S\$1500 / Outside Singapore S\$3000 FINANCE COMPANY: KAH MOTOR COMPANY SDN BERHAD PRODUCER NAME:</p>	

SCHK 20170807

Ver.1.260705

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

63295770 Sompoo etc

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SLE9879D

Chassis No : JHMRC1890GC205992

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : GEORGE NG

Ins Policy No. : SD17V08947/VPL/R00

Date of Accident : 16/4/2018

Document No. : SQT18001577 Page 1

Date : 17. Apr 2018

Customer No. : WZH023

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72012643

Date | Time : 17. Apr 2018 10:21:50 AM

Surveyor Name : DID : +65 5845 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70329)						
	OWNER: GEORGE NG						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 16/04/2018@21.45PM						
	SURVEYED BY:						
	18-24 WORKING DAYS						
	REF NO:						
	TP INSURER: SOMPO INSURANCE SINGAPORE PTE LTD						
	TP VEH: SJK5249R						
BO-TOW-SW	TOWING SERVICE	1	60.00 ✓		60.00	4.20	64.20
	Sum Ext. Service				60.00	4.20	64.20
04656-T6A-310ZZ	PAN SET,3RD SEAT <i>new</i>	1	331.30	25	248.47 ✓	17.39	265.86
66100-T6A-Q00ZZ	PANEL COMP,REAR <i>replaced</i>	1	451.70	25	✓ 338.77 ✓	23.71	✓ 362.48
68100-T6A-Q10ZZ	TAILGATE COMP <i>replaced</i>	1	1049.80	25	✓ 787.35 ✓	55.11	✓ 842.46
74440-T6A-003	WEATHERSTRIPTAILGATE <i>at</i>	1	115.10	25	✓ 86.32 ✓	6.04	92.36
74800-TF0-J02	LOCKTAILGATE <i>replaced</i>	1	181.70	25	✓ 136.27 ✓	9.54	145.81
74820-T6A-013	STAY ASSYR.TAILGATE OPEN <i>green</i>	1	161.40	25	x 121.05	8.47	129.52
74870-T6A-013	STAY ASSYL.TAILGATE OPEN	1	161.40	25	x 121.05	8.47	129.52
74890-T6A-J01	GARNISH ASSYRR.LICENSE <i>cancel</i>	1	225.90	25	✓ 169.42 ✓	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN <i>at</i>	1	172.10	25	✓ 129.07 ✓	9.03	138.10
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	✓ 26.40 ✓	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>new</i>	1	16.60	25	✓ 12.45 ✓	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	✓ 12.45 ✓	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD <i>new</i>	4	3.90	25	✓ 11.70 ✓	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	2	8.30	25	✓ 12.45 ✓	0.87	13.32
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE <i>Deformed</i>	1	705.40	25	✓ 529.05 ✓	37.03	566.08
84665-T6A-N71ZD	LINING COMPL.RR.SIDE <i>Deformed</i>	1	748.60	25	✓ 561.45 ✓	39.30	600.75
84640-T6A-003ZA	LINING ASSYRR.PANEL <i>Deformed</i>	1	101.60	25	✓ 76.20 ✓	5.33	81.53

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SLE9879D

Chassis No : JHMRC1890GC205992

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : GEORGE NG

Ins Policy No. : SD17V08947/VPL/R00

Date of Accident : 16/4/2018

Document No. : SQT18001577 Page 2

Date : 17. Apr 2018

Customer No. : WZH023

Svc Advisor : ARY CHUA WAI NGE

Engine No : K24W72012643

Date | Time : 17. Apr 2018 10:21:50 AM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84643-T6A-Q01ZA	COMP LIDTOOL <i>del</i>	1	60.20	25	✓ 45.15	3.16	48.31
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER <i>del</i>	1	202.20	25	✓ 151.65	10.62	162.27
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL <i>del</i>	1	10.50	25	X 7.87	0.55	8.42
75701-T6A-000	EMBLEMH <i>del</i>	1	25.80	25	✓ 19.35	1.35	20.70
33500-T6A-003	TAILLIGHT ASSYR. <i>del</i>	1	821.70	25	? 616.27	X 43.14	659.41
33550-T6A-003	TAILLIGHT ASSYL. <i>del</i>	1	821.70	25	? 616.27	X 43.14	659.41
34150-T6A-003	LIGHT ASSYR.LID <i>del</i>	1	378.60	25	✓ 283.95	✓ 19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID <i>del</i>	1	378.60	25	✓ 283.95	✓ 19.88	303.83
38387-SLE-003	ANTENNA ASSY.L.RR. <i>del</i>	1	59.40	25	? 44.55	✓ 3.12	47.67
74940-TR0-003	BUZZER ASSYSMART <i>del</i>	1	58.90	25	? 44.17	✓ 3.09	47.26
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>del</i>	1	320.00		✓ 320.00	✓ 22.40	342.40
04715-T6A-900ZZ	FACERR BUMPER <i>del</i>	1	557.20	25	✓ 417.90	✓ 29.25	447.15
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>del</i>	1	44.50	25	✓ 33.37	✓ 2.34	35.71
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>del</i>	1	44.50	25	✓ 33.37	✓ 2.34	35.71
71502-T6A-003ZF	FACER.RR.BUMPER GARNISH <i>del</i>	1	75.30	25	✓ 56.47	✓ 3.95	60.42
71507-T6A-003ZF	FACEL.RR.BUMPER GARNISH <i>del</i>	1	75.30	25	✓ 56.47	✓ 3.95	60.42
71512-T6A-921ZF	SPOILER ASSYR.RR.SIDE <i>del</i>	1	111.80	25	✓ 83.85	✓ 5.87	89.72
71517-T6A-921ZF	SPOILER ASSYL.RR.SIDE <i>del</i>	1	111.80	25	✓ 83.85	✓ 5.87	89.72
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>del</i>	1	18.70	25	✓ 14.02	✓ 0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>del</i>	1	18.70	25	✓ 14.02	✓ 0.98	15.00
91505-TM8-003	CLIPBUMPER <i>del</i>	7	2.00	25	✓ 10.50	✓ 0.74	11.24
72841-SH3-315	OILSHEET <i>del</i>	1	39.90	25	✓ 29.92	✓ 2.09	32.01
Sum Item					6646.84	465.25	7,112.09
BOSUN	SUNDRIES	1	100.00		✓ 30 100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		✓ 100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		✓ 100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		✓ 180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	240.00		✓ 140 240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		✓ 250.00	17.50	267.50

Printed on 20/4/2018 8:32:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SLE9879D
Chassis No : JHMRC1890GC205992
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : GEORGE NG
Ins Policy No. : SD17V08947/VPL/R00
Date of Accident : 16/4/2018

Document No. : SQT18001577 Page 3
Date : 17. Apr 2018
Customer No. : WZH023
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W72012643
Date | Time : 17. Apr 2018 10:21:50 AM
Surveyor Name :
Survey Date : DID : +65 6846 5673
Authorisation Date : HP : +65 8100 6306
Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00	X ?	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE LANE CAMERA & CALIBRATION	1	350.00	✓ 300	350.00	24.50	374.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	350.00	✓ 300	350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	✓ 300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM DOORS	1	350.00	✓ 300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	✓ 280	450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	X	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST	1	550.00	✓ 450	550.00	38.50	588.50
BP01R	SPRAY PAINT ON REPAIRED/REPLACED AREAS.(10PX \$450)	1	4800.00	✓ 2700	4800.00	336.00	5136.00
BKRP21M	CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN	1	5800.00	✓ 3360	5800.00	406.00	6206.00
Sum Labor					14770.00	1,033.90	15,803.90

Survey By : Adrian Lim
Date & Time : 20/04/18.
Excess : _____
Status : _____
Signature : [Signature]

Total Amount 21,476.84 1,503.35 22,980.19
Total (Inclusive of GST) 21,536.84 22,980.19

108 njs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Printed on 20/4/2018 8:32:20 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380GCustomer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRC1890GC205992
License No: SLE9879D
Mileage: 47000
Engine No: K24W72012643Document No: SVO18024747
Printed By: ARYCHUA
Order Date: 30. April 2018
Order Time: 9:01:37 AM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70329)						
	OWNER: GEORGE NG						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 16/04/2018@21.45PM						
	SURVEYED BY: ADRAIN LING (LKKAUTO)20/04/2018@10.10						
	REF NO: CMTD1801657						
	TP INSURER: SOMPO INSURANCE SINGAPORE PTE LTD						
	TP VEH: SJK5249R						
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	331.30	25	248.47	17.39	265.86
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	451.70	25	338.77	23.71	362.48
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	225.90	25	169.42	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	172.10	25	129.07	9.03	138.10
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84665-T6A-N72ZD	LINING COMPL.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	101.60	25	76.20	5.33	81.53
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	202.20	25	151.65	10.62	162.27
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
34150-T6A-003	LIGHT ASSYR.LID	1	378.60	25	283.95	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID	1	378.60	25	283.95	19.88	303.83
38387-SLE-003	ANTENNA ASSY,L.RR.	1	59.40	25	44.55	3.12	47.67
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	44.50	25	33.37	2.34	35.71
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	44.50	25	33.37	2.34	35.71
71502-T6A-003ZK	FACE,R.RR.BUMPER	1	75.30	25	56.47	3.95	60.42
71507-T6A-003ZK	FACE,L.RR.BUMPER	1	75.30	25	56.47	3.95	60.42
71512-T6A-921ZF	SPOILER ASSYR.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71517-T6A-921ZF	SPOILER ASSYL.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20 nrc
	SUM PARTS:				5,146.78	360.25	5,507.03
BOSUN	0672	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	0672	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						

WD=10



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRC1890GC205992
License No: SLE9879D
Mileage: 47000
Engine No: K24W72012643

Document No: SVO18024747
Printed By: ARYCHUA
Order Date: 30. April 2018
Order Time: 9:01:37 AM
Service Advisor: ARY CHUA WAI NGEE

BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	140.00	9.80	149.80
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	250.00	250.00	17.50	267.50
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	280.00	280.00	19.60	299.60
BOMISC1	0672 REMOVE & INSTALL REVERSE LANE CAMERA & CALIBRATION	1	300.00	300.00	21.00	321.00
BKOT00R	EXT-YJ REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	300.00	300.00	21.00	321.00
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00	300.00	21.00	321.00
BOMISC1	0672 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM DOORS	1	300.00	300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BP01R	EXT-YBH SPRAY PAINT ON REPAIRED/REPLACED AREAS.(10PX\$450)	1	2,700.00	2,700.00	189.00	2,889.00
BKRP21M	EXT-YJ CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	3,360.00	3,360.00	235.20	3,595.20
		SUM LABOUR:		8,790.00	615.30	9,405.30
BO-TOW-SW	TOWING SERVICE	1	60.00	60.00	4.20	64.20
		SUM EXT SERVICE:		60.00	4.20	64.20
		TOTAL SGD		13,996.78	979.75	14,976.53

Total Payable (SGD)

14,976.53

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18007361/Avbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 04-06-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 5249R	Veh. Inspected	SLE 9879D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801657/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/04/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRC1890GC205992	Colour	BLACK
Odometer	46997	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/04/2018	Inspection Date	20/04/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 9879D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PAN SET,3RD SEAT (SN)	NECESSARY	248.47	248.47
1	PANEL COMP,REAR (SN)	DENTED	338.77	338.77
1	TAILGATE COMP (SN)	DISTORTED	787.35	787.35
1	WEATHERSTRIP TAILGATE (SN)	CUT	86.32	86.32
1	LOCK TAILGATE (SN)	DAMAGED	136.27	136.27
1	STAY ASSYR,TAILGATE OPEN (SN)	NOT NECESSARY	121.05	-
1	STAY ASSYL,TAILGATE OPEN (SN)	NOT NECESSARY	121.05	-
1	GARNISH ASSYRR LICENSE (SN)	CRACKED	169.42	169.42
1	MOLDING ASSYRR LICENSE GARN (SN)	CUT	129.07	129.07
2	MOLDINGRR WINDSHIELD SIDE (SN)	NECESSARY	26.40	26.40
1	MOLDINGR.RR WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
1	MOLDINGL.RR WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
4	SPACERRR W/SHIELD (SN)	NECESSARY	11.70	11.70
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.45	12.45
1	LINING COMP.R.RR SIDE (SN)	DEFORMED	529.05	529.05
1	LINING COMPL.RR SIDE (SN)	DEFORMED	561.45	529.05
1	LINING ASSYRR PANEL (SN)	DEFORMED	76.20	76.20
1	COMP LIDTOOL (SN)	NOT NECESSARY	45.15	-
1	LINING ASSYTAILGATE LOWER (SN)	DEFORMED	151.65	151.65
1	POCKETTAILGATE LINING PULL (SN)	NOT NECESSARY	7.87	-
1	EMBLEMH (SN)	NECESSARY	19.35	19.35
1	TAILLIGHT ASSYR (SN)	NOT NECESSARY	616.27	-
1	TAILLIGHT ASSYL (SN)	NOT NECESSARY	616.27	-
1	LIGHT ASSYR.LID (SN)	CRACKED	283.95	283.95
1	LIGHT ASSYL.LID (SN)	CRACKED	283.95	283.95
1	ANTENNA ASSY.L.RR (SN)	DAMAGED	44.55	44.55
1	BUZZER ASSYSMART (SN)	DAMAGED	44.17	44.17
1	4PCS ACT RR SENSOR (SN)	DAMAGED	320.00	320.00
1	FACERR BUMPER (SN)	DISTORTED	417.90	417.90
1	REFLECTOR ASSYR.RR (SN)	CRACKED	33.37	33.37
1	REFLECTOR ASSYL.RR (SN)	CRACKED	33.37	33.37
1	FACER.RR BUMPER GARNISH (SN)	DEFORMED	56.47	56.47
1	FACEL.RR BUMPER GARNISH (SN)	DEFORMED	56.47	56.47
1	SPOILER ASSY.R.RR SIDE (SN)	DEFORMED	83.85	83.85

Report Ref No. CS/SMO18007361/Avbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPOILER ASSYL.RR SIDE (SN)	DEFORMED	83.85	83.85
1	SPACERR.RR BUMPER SIDE (SN)	NECESSARY	14.02	14.02
1	SPACERL.RR BUMPER SIDE (SN)	NECESSARY	14.02	14.02
7	CLIPBUMPER (SN)	NECESSARY	10.50	10.50
1	OILSHEET (SN)	NECESSARY	29.92	29.92
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	WINDSCREEN SEALANT (ADDITIONAL)(SN)	NECESSARY	60.00	60.00
			6,806.84	5,176.78
	LABOUR			
	BODY UNDERSIDE COATING.		100.00	100.00
	BODY JOINT SEALANT.		100.00	100.00
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		180.00	180.00
	REMOVE & RENEW REVERSE SENSORS-4PCS.		240.00	140.00
	APPLY BODY UNDERSIDE COATING.		250.00	250.00
	REMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	350.00	-
	REMOVE & INSTALL REVERSE LANE CAMERA & CALIBRATION.		350.00	300.00
	REMOVE & RENEW RR FLOOR INSULATOR.		350.00	300.00
	REMOVE & INSTALL RR WINDSCREEN.		350.00	300.00
	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM DOORS.		350.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	280.00
	REMOVE & RENEW RR FLOOR INSULATOR.	NOT NECESSARY	450.00	-
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE & ADJUST.		550.00	450.00
	SPRAY PAINT ON REPAIRED/REPLACED AREAS.		4,800.00	2,700.00
	CUT OFF & RENEW RR PANEL RR FLOOR PANEL STRAIGHTEN.		5,800.00	3,360.00
	TOWING SERVICE.		60.00	60.00
			14,730.00	8,820.00
	GRAND TOTAL		21,536.84	13,996.78
	RECOMMENDED COST OF REPAIRS			13,996.78

Report Ref No. CS/SMO18007361/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.