



CO. REG. NO: 199402370D
 GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
 Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895
 Email: service@kkinhin.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPHQ18-000010	Date of Loss:	07/04/2018
Vehicle Reg. No.:	SDQ8178G	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE KANG MING	Contact No:	+6582862611
Driver:	LEE KANG MING		

Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	12/01/2012
Vehicle Colour:	GREY		
Engine No:	27186030390823	Chassis No:	WDD2120472A556208
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	21 ✓



*Not Authorised
 L/Sing @?
 Refusing After Repair
 Ex @ 300k*

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Remarks:	VEHICLE IS IN. KINDLY ARRANGE FOR SURVEY. THANK YOU.
Present Location:	K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	53,073.65
Miscellaneous Items	0.00
Labour	6,590.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	59,663.65
+ GST 7.00% (S\$)	4,176.46
Nett Amount (S\$)	63,840.11

This claim is handled by: **WONG SHU MAN**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2018)
Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: K Kim Hin Auto Pte Ltd/SDQ8178G/19/04/2018 17:38
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT NUMBER PLATE BASE GARNISH	CMA	0.00	0.00	*96.00 F	✓
2	1		*FRONT BUMPER	CMA	0.00	0.00	*800.00 F	✓
3	84		*FRONT BUMPER PARKING SENSOR	short	0.00	0.00	*990.00 F	✓
4	6		*FRONT BUMPER PARKING SENSOR SEAL	na	0.00	0.00	*30.00 F	✓
5	1		*FRONT BUMPER PARKING SENSOR WIREHARNES	Ta	0.00	0.00	*160.00 F	✓
6	1		*FRONT BUMPER CENTRE LOWER GRILLE	na	0.00	0.00	*50.00 F	✓
7	2		*FRONT BUMPER DAYLIGHT LAMP (LH/RH)	cls mgem	0.00	0.00	*300.00 F	✓
8	2		*FRONT BUMPER DAYLIGHT LAMP CHROME COVER (LH/RH)	cls rd	0.00	0.00	*160.00 F	✓
9	2		*FRONT BUMPER DAYLIGHT LAMP COVER (LH/RH)	cls dit	0.00	0.00	*100.00 F	✓
10	1		*FRONT BUMPER INSIDE PART CENTRE BRACKET	CMA	0.00	0.00	*65.00 F	✓
11	2		*FRONT BUMPER INSIDE PART SIDE BRACKET (LH/RH)	R1	0.00	0.00	*90.00 F	✓
12	2		*FRONT BUMPER SIDE BRACKET PLATE (LH/RH)	R1	0.00	0.00	*60.00 F	✓
13	1		*FRONT BUMPER LOWER CENTRE BRACKET	R1	0.00	0.00	*45.00 F	✓
14	2		*FRONT BUMPER LOWER SIDE BRACKET (LH/RH)	dit	0.00	0.00	*70.00 F	✓
15	1		*FRONT BUMPER REINFORCEMENT	R1	0.00	0.00	*290.00 F	✓
16	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH)	R1	0.00	0.00	*330.00 F	✓
17	2		*FRONT BUMPER REINFORCEMENT SIDE BRACKET (LH/RH)	dit	0.00	0.00	*70.00 F	✓
18	2		*FRONT BUMPER REINFORCEMENT BRACKET TOP L BRACKET (LH/RH)	mi	0.00	0.00	*40.00 F	✓
19	1		*FRONT BUMPER CENTRE INNER SPONGE	CMA	0.00	0.00	*70.00 F	✓
20	2		*FRONT BUMPER SIDE INNER SPONGE (LH/RH)	CMA	0.00	0.00	*70.00 F	✓
21	2		*FRONT BUMPER NOZZLE COVER C/W BRACKET (LH/RH)	CMA	0.00	0.00	*96.00 F	✓
22	2		*FRONT BUMPER NOZZLE COVER SPRING (LH/RH)	mi	0.00	0.00	*18.00 F	✓
23	2		*FRONT BUMPER NOZZLE PUMP (LH/RH)	cls mi	0.00	0.00	*270.00 F	✓
24	1		*FRONT GRILLE }	R1	0.00	0.00	*590.00 F	✓
25	1		*FRONT GRILLE LOGO }		0.00	0.00	-	
26	1		*FRONT GRILLE T BRACKET	R1	0.00	0.00	*18.00 F	✓
27	2		*FRONT FENDER (LH/RH)	R1	0.00	0.00	*960.00 F	✓
28	2		*FRONT FENDER CHROME MOULDING (LH/RH)	na	0.00	0.00	*60.00 F	✓
29	2		*FRONT FENDER BLUE EFFICIENCY EMBLEM (LH/RH)	na	0.00	0.00	*84.00 F	✓
30	2		*FRONT FENDER INNER SHIELD (LH/RH) - FRONT	CMA	0.00	0.00	*200.00 F	✓
31	2		*FRONT FENDER INNER SHIELD (LH/RH) - REAR		0.00	0.00	*210.00 F	?
32	2		*FRONT FENDER INNER PANEL (LH/RH)		0.00	0.00	*310.00 F	?
33	1		*BONNET	na	0.00	0.00	*1,400.00 F	✓
34	2		*BONNET LOCK-LOWER (LH/RH)	R1	0.00	0.00	*90.00 F	✓
35	2		*BONNET LOCK CATCH-TOP (LH/RH)	dit	0.00	0.00	*56.00 F	✓
36	1		*BONNET CENTRE LOCK-TOP	R1	0.00	0.00	*50.00 F	✓
37	2		*BONNET HINGES (LH/RH)	R1	0.00	0.00	*180.00 F	✓
38	2		*BONNET HINGES ACTUATOR (LH/RH)	Actuator	0.00	0.00	*420.00 F	✓
39	2		*BONNET DAMPER (LH/RH)	Ta	0.00	0.00	*170.00 F	✓
40	1		*BONNET CENTRE RUBBER SEAL	Ta	0.00	0.00	*18.00 F	✓
41	2		*BONNET SPRING STOPPER (LH/RH)	CMA	0.00	0.00	*24.00 F	✓
42	2		*BONNET RUBBER STOPPER (LH/RH)	mi	0.00	0.00	*18.00 F	✓
43	1		*BONNET LOGO	rd	0.00	0.00	*65.00 F	✓
44	1		*BONNET PULL LOCK CABLE	Ta	0.00	0.00	*47.00 F	✓
45	1		*BONNET PULL LOCK CABLE EXTENSION	R1	0.00	0.00	*35.00 F	✓

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
46	1		*BONNET INSULATION	Return	0.00	0.00	*145.00 F	✓
47	12		*BONNET INSULATION CLIPS	NA	0.00	0.00	*42.00 F	✓
48	1		*BONNET CENTRE LOCK CATCH	BA	0.00	0.00	*45.00 F	✓
49	1		*RADIATOR TOP PANEL	BA	0.00	0.00	*98.00 F	✓
50	2		*HEADLAMP PANEL (LH/RH)	BA	0.00	0.00	*290.00 F	✓
51	1		*FRONT BRACE PANEL	BA	0.00	0.00	*32.00 F	✓
52	1		*FRONT SUPPORT PANEL TOP GARNISH	MIY	0.00	0.00	*80.00 F	✓
53	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	NA	0.00	0.00	*27.00 F	✓
54	1		*TURBO COOLER	PR	0.00	0.00	*680.00 F	✓
55	1		*TURBO COOLER INLET HOSE	RY	0.00	0.00	*90.00 F	✓
56	1		*TURBO COOLER OUTLET HOSE	CM	0.00	0.00	*120.00 F	✓
57	1		*TURBO COOLER OUTER GARNISH	BR	0.00	0.00	*100.00 F	✓
58	1		*TURBO CHARGER	CM	0.00	0.00	*2,650.00 F	✓
59	1		*AIR CLEANER PIPE (TURBO TO AIR CLEANER)	CM	0.00	0.00	*235.00 F	✓
60	1		*AIR CON CONDENSER	BA	0.00	0.00	*650.00 F	✓
61	1		*AIR CON CONDENSER COWLING	BR	0.00	0.00	*55.00 F	✓
62	1		*AIR CON LIQUID PIPE-TOP	ND	0.00	0.00	*85.00 F	✓
63	1		*AIR CON LIQUID PIPE-LOWER	ND	0.00	0.00	*135.00 F	✓
64	1		*AIR CON DISCHARGE PIPE	PR	0.00	0.00	*175.00 F	✓
65	1		*AIR CON SUCTION PIPE		0.00	0.00	*380.00 F	?
66	1		*AIR CON COMPRESSOR		0.00	0.00	*1,100.00 F	?
67	1		*POWER STEERING COOLING PIPE	ND	0.00	0.00	*165.00 F	✓
68	1		*POWER STEERING PUMP	TA	0.00	0.00	*800.00 F	✓
69	1		*RADIATOR ASSY	BA	0.00	0.00	*500.00 F	✓
70	2		*RADIATOR TOP BUSH	MI	0.00	0.00	*32.00 F	✓
71	2		*RADIATOR TOP LOCKING PIN	NA	0.00	0.00	*20.00 F	✓
72	2		*RADIATOR LOWER BUSH	NA	0.00	0.00	*10.00 F	✓
73	1		*RADIATOR TOP HOSE	PR	0.00	0.00	*56.00 F	✓
74	1		*RADIATOR LOWER HOSE		0.00	0.00	*175.00 F	?
75	1		*RADIATOR SPARE TANK	ND	0.00	0.00	*90.00 F	✓
76	1		*RADIATOR SPARE TANK BYPASS HOSE-BIG		0.00	0.00	*38.00 F	?
77	1		*RADIATOR SPARE TANK BYPASS HOSE-SMALL		0.00	0.00	*58.00 F	?
78	1		*RADIATOR GEAR COOLER INLET HOSE	PR	0.00	0.00	*95.00 F	✓
79	1		*RADIATOR GEAR COOLER OUTLET HOSE		0.00	0.00	*185.00 F	?
80	1		*RADIATOR FAN ASSY	TA	0.00	0.00	*540.00 F	✓
81	1		*AUTO GEAR COOLER	BA	0.00	0.00	*340.00 F	✓
82	1		*OUTSIDE TEMPERATURE SENSOR	CM	0.00	0.00	*38.00 F	✓
83	2		*HORN	CM	0.00	0.00	*210.00 F	✓
84	2		*HEADLAMP ASSY (LH/RH)	CM	0.00	0.00	*3,700.00 F	✓
85	2		*HEADLAMP HID BALLAST UNIT (LH/RH)		0.00	0.00	*1,040.00 F	?
86	2		*HEADLAMP TOP SEAL (LH/RH)	NA	0.00	0.00	*70.00 F	✓
87	1		*WIPER WASHER TANK	ND	0.00	0.00	*95.00 F	✓
88	1		*WIPER WASHER TANK MOTOR		0.00	0.00	*35.00 F	?
89	1		*WIPER WASHER TANK WATER LEVEL SENSOR		0.00	0.00	*28.00 F	?
90	1		*WIPER WASHER TANK CAP COVER		0.00	0.00	*12.00 F	?
91	1		*AIR INTAKE DUCT	CM	0.00	0.00	*240.00 F	✓
92	1		*AIR INTAKE DUCT INNER HOSE	CM	0.00	0.00	*40.00 F	✓
93	1		*AIR CLEANER BOX ASSY	CM	0.00	0.00	*255.00 F	✓
94	1		*ABS PUMP	CM	0.00	0.00	*2,300.00 F	✓
95	1		*ABS PUMP BRACKET		0.00	0.00	*70.00 F	?
96	1		*ABS PUMP PIPE (1SET - 6PCS)		0.00	0.00	*380.00 F	?
97	1		*THROTTLE BODY		0.00	0.00	*400.00 F	?
98	1		*ENGINE TOP COVER }	CM	0.00	0.00	*95.00 F	✓
99	1		*ENGINE TOP COVER LOGO }		0.00	0.00	-	
100	2		*ENGINE MOUNTING (LH/RH)		0.00	0.00	*240.00 F	?
101	1		*GEARBOX MOUNTING		0.00	0.00	*65.00 F	?
102	1		*AIR INTAKE MANIFOLD		0.00	0.00	*580.00 F	?
103	1		*TIMING COVER	CM	0.00	0.00	*480.00 F	✓
104	1		*FAN BELT	TA	0.00	0.00	*65.00 F	✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
105	1		*MAIN PULLEY	0.00	0.00	*330.00	F ?
106	1		*TENSIONER PULLEY	0.00	0.00	*175.00	F ?
107	2		*IDEL PULLEY	0.00	0.00	*110.00	F ?
108	1		*TIMING COVER OIL SEAL	<i>Me</i> 0.00	0.00	*30.00	F ✓
109	1		*THERMOSTAT	<i>Me</i> 0.00	0.00	*185.00	F ✓
110	1		*WATER PUMP	0.00	0.00	*165.00	F ✓
111	1		*WATER PUMP PULLEY	0.00	0.00	*60.00	F ?
112	1		*ALTERNATOR	0.00	0.00	*750.00	F ?
113	4		*FUEL INJECTOR	0.00	0.00	*1,200.00	F ?
114	1		*FUEL INJECTOR RAIL	0.00	0.00	*280.00	F ?
115	1		*POSITIVE TERMINAL CABLE	0.00	0.00	*185.00	F ?
116	1		*BATTERY (ORIGINAL)	0.00	0.00	*400.00	F ?
117	1		*ENGINE UNDER COVER	<i>CMA</i> 0.00	0.00	*240.00	F ✓
118	1		*THROTTLE BODY BREATHER HOSE	0.00	0.00	*55.00	F ?
119	1		*O/S FRONT WINDSCREEN SIDE MOULDING	<i>Me</i> 0.00	0.00	*210.00	F ✓
120	1		*FRONT WINDSCREEN GLASS }	<i>CMA</i> 0.00	0.00	*1,100.00	F ✓
121	1		*FRONT WINDSCREEN GLASS MOULDING }	0.00	0.00	-	
122	1		*THERMOSTAT HOUSING	<i>Me</i> 0.00	0.00	*280.00	F ✓
123	1		*AIR INTAKE HOUSING }	<i>CMA</i> 0.00	0.00	*150.00	F ✓
124	2		*AIR INTAKE HOUSING CLIP }	0.00	0.00	-	
125	1		*FIRE WALL HEAT INSULATION	0.00	0.00	*165.00	F ?
126	1		*FIRE WALL ALUMINIUM PARTITION	0.00	0.00	*150.00	F ?
127	1		*FUSE RAIL REGULATOR	0.00	0.00	*900.00	F ?
128	1		*OIL FILTER COOLER	0.00	0.00	*460.00	F ?
129	1		*STEERING AIR BAG	<i>Prv</i> 0.00	0.00	*1,190.00	F ✓
130	1		*AIR BAG CLOCK SPRING	<i>Me</i> 0.00	0.00	*660.00	F ✓
131	1		*DASHBOARD ASSY	<i>Tn</i> 0.00	0.00	*2,650.00	F ✓
132	1		*DASHBOARD AIR BAG	<i>Prv</i> 0.00	0.00	*1,150.00	F ✓
133	1		*AIR BAG CONTROL UNIT	<i>Me</i> 0.00	0.00	*520.00	F ✓
134	2		*AIR BAG SENSOR	<i>Me</i> 0.00	0.00	*150.00	F ✓
135	1		*DRIVER SEAT BELT	<i>Tn</i> 0.00	0.00	*740.00	F ✓
136	1		*FRONT PASSENGER SEAT BELT	<i>Tn</i> 0.00	0.00	*740.00	F ✓
137	2		*REAR PASSENGERS SEAT BELT (LH/RH)	<i>Tn</i> 0.00	0.00	*540.00	F ✓
138	1		*FRONT NUMBER PLATE	<i>Prv</i> 0.00	0.00	*40.00	FS ✓
139	2		*POWER STEERING OIL	<i>Me</i> 0.00	0.00	*56.00	FS ✓
140	1		*RADIATOR COOLANT	<i>Me</i> 0.00	0.00	*48.00	FS ✓
141	1		*FRONT WINDSCREEN GLASS SEALANT	<i>Me</i> 0.00	0.00	*40.00	FS ✓
142	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	<i>Me</i> 0.00	0.00	*20.00	FS ✓
143	1		*ERP BRACKET	<i>Me</i> 0.00	0.00	*26.00	FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **46,181.00**
+ Margin on L,N Items 15.00% (\$\$) **6,892.65**

Total Parts (\$\$) 53,073.65

K Kim Hin Auto Pte Ltd/SQ8178G/19/04/2018 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			<i>2200</i>
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	2,800.00
2	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS	New	<i>100</i> 120.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	120.00 ✓
4	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS.	New	<i>280</i> 300.00
5	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM.	New	<i>250</i> 300.00
6	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	350.00 ✓
7	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	320.00 ?
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	80.00 ✓
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.	New	<i>250</i> 300.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	<i>1200</i> 1,400.00
11	TO CONDUCT ON-LINE PROGRAMMING FOR AIR BAGS AND RESETTING FAULT CODES.	New	<i>250</i> 450.00
12	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	50.00 ✓
Gross Labour Cost (S\$)			6,590.00

K Kim Hin Auto Pte Ltd/SDQ8178G/19/04/2018 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >