

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANET TAN

Date: 23 Apr 2018

**Preliminary Advice**

Vehicle No	: SDQ8178G	Accident Date	: 07/04/2018
Make	: MERCEDES-BENZ E250	Policy No.	: DMPPHQ18-000010
Assignment Date	: 20/04/2018	Excess	: S\$300.00
Date of Inspection	: 20/04/2018	Est. Duration of Repair	: 21.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,663.65
Revised Amount	:S\$	45,052.25
Check Items (Estimated)	:S\$	12,614.65
Total	:S\$	57,666.90

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	62,181.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,819.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer asking for Lump Sum \$28,000/-.