

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 23 Apr 2018

Preliminary Advice

Insured Vehicle No : SKL104R

TP Vehicle No : SLW8269B

Accident Date : 13/04/2018

Make : TOYOTA WISH

Assignment Date : 19/04/2018

Date of Inspection : 20/04/2018

Est. Duration of Repair : 6.00

Inspection At : BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ)
TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT
SINGAPORE 128462

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,703.78
Revised Amount	:S\$	5,555.46
Check Items (Estimated)	:S\$	364.30
Total	:S\$	5,919.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.