

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 25 Apr 2018

Preliminary Advice

Insured Vehicle No : SKW8648C

TP Vehicle No : SJM5803E

Make : TOYOTA ESTIMA

Date of Inspection : 24/04/2018

Inspection At : Carz Auto Services Pte Ltd - Woodlands (HQ)
NO 61, WOODLANDS INDUSTRIAL PARK E9,
#04-04 E9 PREMIUM SINGAPORE 757047
Singapore 757047

Accident Date : 18/04/2018

Assignment Date : 23/04/2018

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,406.28
Revised Amount	:S\$	1,020.00
Check Items (Estimated)	:S\$	206.63
Total	:S\$	1,226.63

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.