ASS. REC. BY:		REF:	cs/ms(1	18008L	5/5	364	1	int Instruction	MC:	
Staveyor :	Straition		ASSIGN	MENT (	Offic	e) /				
From (Person):	Monica Chi	M/A	c#	msili		1		Inte/Time	23042018	11.1200
Estimated Cost		J		Bill	10:			4.444		spir
	/TP RES / OD R		1805E	//cs			înared:		SKW 861	18C
at Workshop n	vs(	arz Au	to				Tel:	9380	SKW 861 19969	
of	No.	61 WOOD	llands Ir	ru Park	E9	#0	4-04			
Policy No:	A2883756	Damy		CI	aim No	00	556	U55 -		
Sum Insured:					Excess					
Make of Velv. (Client's Record)								.O.A	18045	018
CA / REV /	REP. / REV 24	HRS 'NP	1	24.04.3	618	0	12pm	DUPER W	alting	
Date/Time 2	304108 1144	im Pers	on Contact	ad:	Alex		Ve	hicle IN I	OUT	
Date/Time	Action/Instruction	(1	) Estim	ate						
	3]m - 9805 E				Illar	u.			DEG: 33 17	7011
	3KM 36H8 -	х •				7				
25/04/18	@ 13:18 pa		ed to	o Mon	ca C	Kur	Pi Z	hen vie	a memin	10.
03/05/18	@9:390	n. S.	den to	o Mr.	Ale	×	due	with 1	neig W	andler
	liability 1	ot cle	ar. So	vehic	e h	as	not	Send	in to	remir.
03/05/18	Submit Pre	li rea	ort	1.0.112			-7.90		1	9

# ...CLAIM SUBFOLDER...(New Assignment)

	BFOLDER TRAC	00000001					
Cirse	Notified	Est Submitted	Adj Assigned	Adl Rpt	Ad) Submitted	Ins Auth'ed	Status
Main	19 Apr 2018		23 Apr 2018 11:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created	by insurer]
Insured:	CHNG SOO SOO AMY, ID:	S7147254Z, Tel: +6598288168	Fmail: amychnoss@o	mail com
Main Claimant:	IDRIVE AUTOMOBILE, C	o. Reg. No.: 533641468	The state of the s	THOR. SOTT
Vehicle Reg. No.:	SJM5803E	Date of Loss:		3 13:00 - :59 hs and <b>9</b> Days From LT/ Man Yr)]
Claim Type:	TP / 556055	Policy/Cover Note No.:	A28837560 Coverage: 17/11/2019	QMY (Comprehensive) 18/11/2017 -
Vehicle Reg. No. (Insured):	SKW8648C	Policy No. (Claimant):	3.77.47.47.4	
		Excess		
Repairer:	Carz Auto Services Pte Ltd PREMIUM SINGAPORE 75704	f - Woodlands (HQ) NO 61, WOO 7, 757047 Woodlands - Tel:	DLANDS INDUSTRIAL PA	RX E9, #04-04 E9
Handling Insurer:		re) Pte. Ltd. (HQ) - Tel: +65 682	7 7888 [Handled by F	Ionica Chung Pei
Adjuster:	LKK Auto Consultants Pte	Ltd (HQ) - Tel: 6256-3561 [In	nm Advice due 24/	14/20183
Driver/Custodian (Insured):	CHNG 500 500 AMY (46 / FI	emale), NRIC: 57147254Z, Tel	: +6598288168	Mentol .
Adj Asg. Remarks:	ON WP. Survey on 24/04/18.	12pm, Owner waiting. Please cont t able to attend this appt, pls conti	act workshop (Alex) opc	e receive this
ASSOCIATED MAIL RECEIVED			View All I	Compose Case Mail
There are no mail for this case.				Compose Case Flas
E ALL ASSOCIATED TASKS		View All Seam	th Tasks   Create No	w Task   Complete
Due Date Priority Type No results.	Task Group Subject	Handler Assigned By	Completed On	Created On Done?

- Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	ZAT40322,72.
Owner ID Type:	Business
Owner ID:	4146B
Vehicle Details	
Vehicle No.:	SJM5803E
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	2AZC347195
Chassis No.:	ACR500062235
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$27,489.00
Original Registration Date:	09 Jan 2009
First Registration Date:	09 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$27,489.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2019
PARF Rebate Amount:	\$13,744,00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$15,058.00
COE Rebate Amount:	\$1,014.00
Total Rebate Amount:	\$14,758.00

The information contained herein is correct as at 25 Apr 2018

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Monica Chung Pel Zhen

Date: 25 Apr 2018

### Preliminary Advice

Insured Vehicle No : SKW8648C

TP Vehicle No

: SJM5803E

Accident Date

: 18/04/2018

Make

Assignment Date

: 23/04/2018

Date of Inspection : 24/04/2018

: TOYOTA ESTIMA

Est. Duration of Repair

: 3 days

Inspection At

: Carz Auto Services Pte Ltd - Woodlands (HQ)

NO 61, WOODLANDS INDUSTRIAL PARK E9.

#04-04 E9 PREMIUM SINGAPORE 757047

Singapore 757047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,406.28
Revised Amount	:S\$	1,020.00
Check Items (Estimated)	:S\$	206.63
Total	:S\$	1,226,63

:SS Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:5\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any willul misrepresentation or witholding of material facts may allow insurance compenies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCID	ENT	STA	TEM	ENT
PATRICULAR SALES			_	-

Date Of Report 19/04/2018 17:51 Date Of Accident 18/04/2018 13:30

Exact Location Of Accident BUKIT TIMAH ROAD B/S KKH

Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SJM5803F

Insured/Policyholder

Name Of Registered Owner **IDRIVE AUTOMOBILE** 

Co Reg No 53364146B Email Address NOEMAIL

Mobile Phone No.

Alternative Phone No. OFFICE-88888888

Vehicle Particulars

Manufacturer TOYOTA

Model ESTIMA-2.4 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 17-MI001555-R00

Cover Note Number

Driver

Name of Driver LIM KIEN LYE NRIC No. S2005012H Date Of Birth 01/04/1954 Occupation OUTDOOR

Date Of Driving Pass 13/03/2012

Driving Experience 6 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-97585530

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 923 JURONG WEST ST 92

#09-31

Postcode

640923

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

7

#### General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

#### Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes against whom?

#### Circumstances of Accident

ON 18/04/2018 AT ABOUT 1.30PM, I WAS TRAVELLING ALONG BUKIT TIMAH ROAD BESIDE KKH IN LANE 2. THE TRAFFIC WAS TRAFFIC AS THERE WAS ROAD WORKS IN LANE 3. SUDDENLY I HEARD A LOUD BANG FROM THE RIGHT SIDE OF MY VEHICLE. WHEN I ALIGHT, I REALISED THAT IT WAS VEHICLE (B) WHO HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY VEHICLE, CAUSING DAMAGES TO MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKW8648C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Sketch Plan Pg. 2

SKETCH PLAN



A-SJM5803E B-SKW8648C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The transfer of
on 1814/2018 at about 1-30pm, I was travelling along
Bakit Tournh Road beside KKH in lane 2. The traffice as
heavy as there was road works in time 3. guddenly
I heard a loud born from the right cide of any which
When I alight, I realised that it was liet (B) who
had collided onto the rear right portion of my connect
causing domages to my whicle

DECLARATION

I/We getiage the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.

### CARZ AUTO SERVICES PTE LTD

NO 61, WOODLANDS INDUSTRIAL PARK E9

#04-04 E9 PREMIUM

S(757047)

Tel:90236692 Allan /93809969 Alex

Office 69093080 GST: 201409457D

MSIG INSURANCE

4, SHENTON WAY, 01 SGX Centre

SINGAPORE 068807

TEL:+65 6827 7660

FAX:+65 6225 6371

claims a sg. msig-asia.com

#### Estimate

Date: 04/21/2018

Vehicle No.: SJM 5803 E Make/Model: TOYOTA ESTIMA-2.4(A)

Chassis ACR500062235

Date of Accident: 18/4/2018 Date of Register: 9/1/2009

No.	Parts (List Price)		Parts (List Price)		QTY	Lis	Price (S)	Parts Discount		Final price (\$)
1	REAR BUMPER F		1	S	985.60	25%	5	739.20		
2	REAR BUMPER SIDE RETAINER (FRT) RH	3	I	S	85.20	25%	S	63.90		
3	REAR BUMPER SIDE RETAINER (REAR) RH	7	1	S	85.20	25%	5	63.90		
4	REAR FENDER SHIELD RH	7	1	S	105.10	25%	5	78.83		
5	REAR BUMPER REFLECTOR RH SYL-	×	1	S	80.60	25%	S	60.45		
		Net I	tem Total:		\$1,341.70		5	1,006.28		

No.	Special Nett Items	QTY	Lis	Price (\$)	Parts Discount		Final price (\$)
1	REAR BUMPER CLIP VNEC.	10	5	50.00	**	\$	30 - 50:90
2	REAR REVERSE SENSOR X 514	1	\$	350.00	+	5	350.00
3	REAR FENDER SHIELD CLIP RH → N°C	4	S	20.00	9	5	20.00
4	REAR TYRE X SVL	1	S	250.00	#	5	250.00
-5	REAR TYRE RIM	1	S	480.00	*	S	480.00
		ett Items Total:		\$1,150.00		S	1,150.00

No.	Labour Charges	Price (S)			)
1	To renew damaged parts, replace and realign fender, and aligned all parts	5		300	200,00
2	To respray affected areas	5		500	800:00
3	To tuffcoat affect areas	\$	+111	×	250.00
4	To remove and refit interrior upholstery	5		20	126:00
5	To remover/ refit wiring check	5		30 -	750:00
- 6	To remove/replace reverse sensors	\$	HH.	×	120.00
7	To wheel 4 alignment	5	776	60	T00:00
	Total:	5			2,250.00

GrandTotal SS: | S 4,406.28

Singapore Dollars Four Phousand Four Hundred Six and Cents Twenty Eight.

for Carz Auto Services Pte Ltd

Sebastian. 3414/2018 -- Lups Repair. - Question Durk Item Photo .

- Photo After Paint Goods121 Schisterypay @ lthouter co-

3 days.

LKK Auto Consultants hence notify

- the Repairer of the following: . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No megal modification(s) is allowed
- . Supplementary liem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Merimen e-Claims Page 1 of 1

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Rpt Adj Subn		Ins Auth'ed	Star	tus	
Main	9 Apr 2018 23 Apr 2018 11:12 Edit Adj Rpt		11:12 S\$1,020.00 S\$1,0		:12   S\$1,020.00   S\$1,020.0			Rep	oding for port ancel Case	Survey
,	fain	∏ R	eference	Claim C	etaiis		Docume	ents	1	Show All
CLAIM SUE	FOLDER DE	TAILS				[Created	by insurer]			
insured:	CHNG SO	O SOO AMY, ID	: S7147254Z, Tel	+6598288168,	Email: ar	mychngss@	gmail.com			
Main Claimant:	IDRIVE A	UTOMOBILE,	o. Reg. No.: 53364	146B						
/ehicle Reg. Vo.:	SJM5803E				of Loss:		3 13:00 - :59 ns and <b>9</b> Days	From LTA F	teg Date	(Man Yr)]
Claim Type:	TP / 556055				/Cover		QMY (Comprei 18/11/2017 -			
Vehicle Reg. No. (Insured):	SKW8648C				No. nant):	Corologo		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
				Exces						
Repairer:	757047, 7	Services Pte Lt 57047 Woodlands	d - Woodlands (H0	2) NO 61, WOODL	ANDS IN	DUSTRIAL P	ARK E9, #04-	04 E9 PREM	IUM SIN	GAPORE
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65 6827	] BB87	Handled by	Monica Chun	g Pei Zhen	- 6594	2552]
Adjuster:	23/05/20	Consultants Pte 18]	Ltd (HQ) - Tel: 62	56-3561 [Hand	led by Se	ebastian Ye	ang Wai Kee	n) {Fin	al Rpt	tue
Driver/Custo dian (Insured):	and the property of the control of the control	500 AMY (46 / F	emale), NRIC: S7	147254Z, Tel:	6598288	8168				
Adj Asg. Remarks:	ON WP. Su able to att	rvey on 24/04/18 end this appt, pis	, 12pm, Owner wait contact us ASAP	ing. Please contac	t worksh	op (Alex) on	ce receive this	assignmen	t and if y	ou are not
ASSOCIATI	ED MAIL RE	CEIVED						View All	Compos	e Case Mai
There are no	mail for this	case.								
ALL ASSO	CIATED TAS	ks⊟			V	iew Ali S	earch Tasks	Create Ne	w Task	Complete
Due Date	Priority	Type Task	Group Subjec	t Handler	Assigne	ed By	Completed O	n Cre	ated Or	Done

Merimen e-Claims Page 1 of 2

### Claim Documents

\*SJM5803E (556055)

[SKW8648C]

TP

IDRIVE AUTOMOBILE

Apr 18 2018 1:00PM

[CHNG SOO SOO AMY]

Carz Auto Services Pte Ltd - Woodlands

Assessment Reports			1 per	page 🔍	2
Nα	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	The second	Thumbnail	
1	23/04/18 10:24	Accident Statement From:SC - Reg. No: SKW8648C, Claimant: OHNG 500 500 AMY	0	Load HTM	
Νo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/18 13:18	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per p	page [V]	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	03/05/18 09:51	General View	0	Load JPG	V
2	03/05/18 09:51	General View	0	Load JPG	V
3	03/05/18 09:51	General View	0	Load JPG	V
4	03/05/18 09:51	General View	0	Load 3PG	V
5	03/05/18 09:51	General View	0	Load JPG	V
6	03/05/18 09:51	General View	0	Load JPG	V
7	03/05/18 09:51	General View	0	Load JPG	V
5	03/05/18 09:51	General View	0	Load JPG	V
9	03/05/18 09:51	General View	0	Load JPG	V
10	03/05/18 09:51	General View	0	Load JPG	V
11	03/05/18 09:51	General View	0	Load JPG	V
12	03/05/18 09:51	General View	0	Load JPG	V
13	03/05/18 09:51	General View	0	Load JPG	2
14	03/05/18 09:51	General View	0	Load JPG	<b>V</b>
15	03/05/18 09:51	General View	0	Load JPG	12
16	03/05/18 09:51	General View	0	Load JPG	V
17	03/05/18 09:51	General View	0	Load JPG	V
18	03/05/18 09:51	General View	0	Load JPG	V
19	03/05/18 09:51	General View	0	Load JPG	V
20	03/05/18 09:51	General View	0	Load JPG	<b>V</b>
1	03/05/18 09:51	General View	0	Load JPG	V
22	03/05/18 09:51	General View	0	Load JPG	1
23	03/05/18 09:51	Odometer Reading	0	Load 3PG	V
14	03/05/18 09:51	General View	0	Load 3PG	V
25	03/05/18 09:51	Chassis Number	0	Load 3PG	3
6	03/05/18 09:51	General View	0	Load JPG	V
27	03/05/18 09:51	General View	0	Load JPG	V
8	03/05/18 09:51	General View	0	Load JPG	V
9	03/05/18 09:51	General View	0	Load JPG	<b>S</b>
10	03/05/18 09:51	General View	0	Load 3PG	V
1	03/05/18 09:51	General View	0	Load 3PG	V
12	03/05/18 09:51	General View		Load JPG	

Merimen e-Claims Page 2 of 2

Assessment Reports			1 per page		V
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
		Por Portor Tiber State Atlanta	0		V
33	03/05/18 09:51	General View	0	Load JPG	1
Doc	cumentation		1 per	page 🗸	<b>Z</b>
	cumentation Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per	page v	-
No		MSIG Insurance (Singapore) Pte. Ltd. (HQ) SJMS803E E FILE REPORT From:SC - Reg. No: SKW8848C, Claimant: CHNG SOO SOO AMY	1 per		-
No.	Finalized On	SJM5803E E FILE REPORT		Thumbnail	-

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset   Save   Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

### LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18007415/SS3BQ2

Date:

09/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28837560QMY

Claimant Vehicle

SJM5803E

Insured Vehicle No:

SKW8648C

No: Date of Loss:

18/04/2018

Nature of Claim:

TP

Claim No: 556055

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SJM5803E

Make & Model:

TOYOTA ESTIMA, 2.4 AERAS (A) 09/01/2009 (Man. Year: 2008)

Engine No:

2AZC347195

Reg. Date: Colour

White

Chassis No: Odometer:

ACR500062235 176812 km

Engine Capacity: Market Value/New Car Price:

2362 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Front Right Side: West Lake 6 mm

Rear Left Side: Rear Right Side: West Lake 6 mm West Lake 6 mm

West Lake 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,156.27	50.00	2,106.27	97.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	970.00	1,280.00	56.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,406.27	1,020.00	3,386.27	76.85
+ GST 7.00/7.00% (S\$)	308.44	71.40	237.04	76.85
Nett Amount (S\$)	4,714.71	1,091.40	3,623.31	76.85

INSPECTION

Date of Assignment:

23/04/2018

Date Inspected:

24/04/2018 Inspected At:

Carz Auto Services Pte Ltd - Woodlands

NO 61, WOODLANDS INDUSTRIAL PARK E9. #04-04 E9 PREMIUM

SINGAPORE 757047 Singapore 757047

Estimated Period of Repair:

3.0 days

Adjuster Report Page 2 of 5

Adjuster: Sebastian Yeang Wai Keen Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$206.62 NETT) Adjuster Report Page 4 of 5

### REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2018)
Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM5803E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	985.60 FL	*-FL
2	1		*REAR BUMPER SIDE RETAINER (FRT)RH	*Check	85.20 FL	*-FL
3	1		*REAR BUMPER SIDE RETAINER (REAR)RH	*Check	85.20 FL	*-FL
4	1		*REAR FENDER SHIELD RH	*Check	105.10 FL	*-FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	80.60 FL	*-FL
6	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
7	1		*REAR REVERSE SENSOR	Serviceable	350.00 FS	*-FS
8	4		*REAR FENDER SHIELD CLIP RH	Necessary	20.00 FS	*20.00 FS
9	1		*REAR TYRE	Serviceable	250.00 FS	*-FS
10	1		*REAR TYRE RIM	Repair	480.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	2,491.70	50.00
			<ul> <li>List Item Discount on L Items 25.</li> </ul>	00/25.00% (S\$)	335.43	0.00
			T	otal Parts (S\$)	2,156.27	50.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW DAMAGED PARTS , REPLACE AND REALI FENDER , AND ALIGNED ALL PARTS	GN New	800.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	500.00
3	TO TUFFCOAT AFFECT AREAS	New	250.00	0.00
4	TO REMOVE AND REFIT INTERIOR UPHOLSTERY	New	120.00	80.00
5	TO REMOVE/REFIT WIRING CHECK	New	60.00	30.00
6	TO REMOVE/REPLACE REVERSE SENSORS	New	120.00	0.00
7	TO WHEEL 4 ALIGNMENT	New	100.00	60.00
	Gros	s Labour Cost (S\$)	2,250.00	970.00
	Report was unsubmitte	d during this print-out.		

< END OF ESTIMATES >