

ASS. REC. BY:

REF: CS3 / CTL18007416 / G2465e

Special Instruction:

Surveyor
Mehmet

60

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTL

Date/Time:

20042018 4:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBJ 8090K

Insured:

PC 1730P

at Workshop in/s

King's Auto

Tel:

of

176 Sin Ming Drd #02-10

Policy No:

DMB1SN3018171800

Claim No:

SNM18002020C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17042018

(Client's Record)

CA / REV / REP. / REV 24 HRS W/P

H.O.D. Endorsement:

Date/Time:

23042018 10am

Person Contacted:

Ms. Ng

Vehicle

OUT

Date/Time	Action/Instruction (X) Estimate
	SBJ 8090K - X
25/4/18	Dismantled .

Catherine Chong (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Friday, 20 April, 2018 4:09 PM
To: Kuru & Co
Cc: assignments@lkkauto.com; SUR; Admin A
Subject: OUR REF: PRS/SNM18D02020C02/0 & YR REF: L.18.0667.AT -TO CONDUCT PRE REPAIR SURVEY SBK8090K
Attachments: Alex-K.pdf

Without Prejudice
Save As To Costs

Dear Anne,

We refer to your email on even date.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus/Kalvin,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Friday, 20 April, 2018 3:56 PM

To: Angie Foo

Cc: Jowyn Tay

Subject: Re: OUR REF: L.18.0667.AT -//YOUR REF: PRS/SNM18D02020C02/0 & TO CONDUCT PRE REPAIR SURVEY SBK8090K

Hi Angie

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Best regards

Anne

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

From: Angie Foo <angie.foo@sg.cntaiping.com>

To: Kuru & Co <kurulegal@yahoo.com.sg>

Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>

Sent: Friday, 20 April 2018, 14:33

Subject: OUR REF: PRS/SNM18D02020C02/0 & YR REF: L.18.0667.AT -TO CONDUCT PRE REPAIR SURVEY SBK8090K

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Anne,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE

SAMUEL PHUN

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

DEREK OH SIONG WEE

KALVIN ANG

MARCUS CHUA

SIMON HO

LOW SAR HUEI

HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: Friday, 20 April, 2018 9:34 AM
To: Claims Dept of CTI
Subject: Our Ref: L.18.0667.AT// Your Ref: PC1730P//PRS

Dear Sirs

**ACCIDENT INVOLVING SBJ 8090K & PC 1730P ON 17.04.2018
ALONG JUNCTION OF SHEARES AVE & MARINA BOULEVARD
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Quek Miew Im**, whose vehicle registration number **SBJ 8090K** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Régards
Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2018		23 Apr 2018 15:36 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	M/S MEGA TOURS PTE LTD, Co. Reg. No.: -								
Main Claimant:	QUEK MIEW IM, ID: S0064077H								
Vehicle Reg. No.:	SBJ8090K	Date of Loss:	17/04/2018 11:00 - :59 [339 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02020C02	Policy/Cover Note No.:	DMB15N3018171800						
Vehicle Reg. No. (Insured):	PC1730P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/05/2018]								
Adj Asg. Remarks:	PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBJ8090K (SNM18D02020C02)**
[PC1730P]
TP
QUEK MIEW IM
Apr 17 2018 11:00AM
[M/S MEGA TOURS PTE LTD]
King's Auto Air-Conditioning Service

Upload Documents Upload Photos Compose New Letter

View View in Browser ▾

Documentation			1 per page ▾	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/04/18 15:38	THIRD PARTY SAS REPORT SBJ8090K	Load PDF	
2	23/04/18 15:38	THIRD PARTY SBJ8090K -PRS EMAIL BTW CIC AND KURU & CO	Load PDF	
3	23/04/18 15:38	INSURED SAS REPORT PC1730P	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 14:59	LKKPhotosIn6-1	Load PDF	
2	25/04/18 14:59	LKKPhotosIn6-2	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18007416/GZ4BS2

Date: 07/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3018171800		
Claimant Vehicle No :	SBJ8090K	Insured Vehicle No :	PC1730P		
Date of Loss:	17/04/2018	Nature of Claim:	TP	Claim No:	SNM18D02020C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBJ8090K			
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	HIDDEN	
Reg. Date:	01/01/1990 (Man. Year: 1990)	Chassis No:	WDD2050402R058554	
Colour:	Black	Odometer:	44641 km	
Engine Capacity:	0 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/04/2018		
Date Inspected:	23/04/2018	Inspected At:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10 Singapore 575721
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/7/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 May 2018)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBJ8090K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >