

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5730H**AAD1804-204***Not Notified
L1 Sing & 120d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5730H

VF1ABL15AUC280380

RENAULT

LATITUDE

18.4.2018

AIG**PART****LIST**

1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 <i>X</i>
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45 <i>X</i>
1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47 <i>X</i>
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 <i>✓</i>
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 <i>X</i>
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 <i>X</i>
1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99 <i>X</i>
1	BUMPER BEAM REAR	\$	<i>R</i> 777.52 <i>X</i>
1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 <i>X</i>
1	TAILLAMP LH	\$	<i>Sn</i> 552.55 <i>X</i>
1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70 <i>X</i>

\$ 9,092.5410% **\$ 909.25****\$ 8,183.28****Specical Nett**

1SET	BUMPER CLIP REAR	\$	<i>na</i> 66.00 <i>✓</i>
1	BUMPER BRACKET CLIP REAR LH	\$	<i>na</i> 12.00 <i>X</i>
1	BUMPER SUPPORT CLIP REAR LH	\$	<i>na</i> 10.50 <i>X</i>
1SET	WHEELARCH CLIP REAR LH	\$	<i>na</i> 30.50 <i>X</i>

TOTAL \$ 119.00**TOTAL PARTS \$ 8,302.28**

Trans-cab Auto Services Pte Ltd

AAD1804-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5730H

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00 ²⁰⁰⁰
Putty and spray painting of the affected portion.	\$	2,200.00 ²²⁰⁰
To rust-proofing of the affected areas.	\$	na 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	na 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00 X

TOTAL \$ 6,140.00**Over All Total** \$ 14,442.28**LUMP SUM (REPAIR DAY)**~~7~~ DAYS

2 days

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
