

Not Whashed
 11 Lyr 81
 Resurvey After Paint
 3 days



ESTIMATE TO REPAIR

VEHICLE NO. : SJS 5664 H
 MAKE : B.M.W.
 MODEL : 318i 2.0L A/T ABS D/AIRBG 2WD 4DR
 YEAR : 2009
 CHASSIS NO : WBAPF72030A143227

SURVEYOR NAME : Kenneth
 DATE OF SURVEY : 09.07.2018
 TIME OF SURVEY : 10.15am

DATE : 12-Jun-18
 DATE OF ACCIDENT : 29-Mar-18
 THIRD PARTY REF : SJR 5266 D / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			\$ 898.50	
1 pc	O/S Front Fender			\$ 648.35	
1 pc	O/S Front Bumper Retainer			\$ 30.05	
1 pc	O/S Front Headlamp			\$ 1,108.65	
1 pc	O/S Front Sport Rim			\$ 701.20	
				\$ 3,386.75	
1 pc	O/S Front Tyre	S.Nett		\$ 380.00	
	To putty & spray painting.			\$ 500.00	
	To check wheel alignment.			\$ 60.00	
	Labour Charges.			\$ 450.00	
					3200
TG-RA/-	TOTAL				\$ 4,776.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Website: www.LTM.sg
 Co.Reg No. 199307277D GST Reg No. M2-0019086-0