

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA INTERNATIONAL INSURANCE PTE L	DATE	: 20-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLR 5285A	NH 1707088352	
MODEL	: TOYOTA SIENTA 1.5A	Aches	
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 19-Apr-18
		TIME	: 11:40HRS
THIRD PARTY REQUESTOR / CONTACT	:	DEON	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER LH <i>Dented</i>	1	\$ 420.00	\$ 420.00
2	FRONT WHEEL COWLING LH <i>Deformed</i>	1	\$ 195.45	\$ 195.45
3	FRONT FENDER EMBLEM LH "HYBRID" <i>New</i>	1	\$ 70.50	\$ 70.50
4	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,200.00	\$ 1,200.00
5	FRONT DOOR HINGE (UPPER) LH <i>3 new</i>	1	\$ 90.30	\$ 90.30
6	FRONT DOOR HINGE (LOWER) LH	1	\$ 90.30	\$ 90.30
7	FRONT DOOR LOCK <i>Damaged</i>	1	\$ 501.20	\$ 501.20
8	FRONT DOOR LOCK CATCH <i>new</i>	1	\$ 62.00	\$ 62.00
9	FRONT DOOR INNER BOARD LH <i>Cracked</i>	1	\$ 800.30	\$ 800.30
10	FRONT DOOR WEATHERSTRIP LH <i>New</i>	1	\$ 90.30	\$ 90.30
11	FRONT POWER WINDOW MOTOR LH <i>New</i>	1	\$ 563.40	\$ 563.40
12	FRONT POWER WINDOW REGUALTION LH <i>Damaged</i>	1	\$ 422.30	\$ 422.30
13	ROCKER PANEL LH <i>Dented</i>	1	\$ 890.00	\$ 890.00
14	CENTER PILLAR LH <i>Dented</i>	1	\$ 630.00	\$ 630.00
15	REAR SLIDING DOOR LH <i>Dented</i>	1	\$ 1,950.00	\$ 1,950.00
16	REAR DOOR LOCK LH <i>Damaged</i>	1	\$ 960.30	\$ 960.30
17	REAR DOOR LOCK CATCH LH <i>New</i>	1	\$ 60.30	\$ 60.30
18	REAR DOOR INNER BOARD LH <i>Cracked</i>	1	\$ 750.30	\$ 750.30
19	REAR SLIDING DOOR GARNISH LH <i>Wt</i>	1	\$ 260.00	\$ 260.00
20	REAR SLIDING DOOR MOTOR LH <i>Damaged</i>	1	\$ 1,850.00	\$ 1,850.00

1232.80
38040
980

21	SLIDING DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 680.20	\$ 680.20	x.
22	REAR WINDOW POWER WINDOW MOTOR <i>3rd</i>	1	\$ 650.30	\$ 650.30	x
23	REAR WINDOW POWER WINDOW REGULATION <i>2nd</i>	1	\$ 530.00	\$ 530.00	x
24	FRONT KNUCKLE ARM WITH BEARING LH <i>2nd</i>	1	\$ 605.40	\$ 605.40	—
25	FRONT LOWER ARM LH <i>Best</i>	1	\$ 616.70	\$ 616.70	—
26	FRONT STABILIZING LINK LH <i>new</i>	1	\$ 180.50	\$ 180.50	x
27	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 490.30	\$ 490.30	x.

9955.35
7466.51

TOTAL PRICE \$ 15,610.35
LESS 25% \$ 3,902.59

SUB TOTAL PRICE \$ 11,707.76

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	—
2	FRONT DOOR INNER BOARD CLIPS(SET) <i>2nd</i>	1	\$ 25.00	\$ 25.00	—
3	REAR DOOR GARNISH CLIPS	1	\$ 25.00	\$ 25.00	—
4	REAR DOOR INNER BOARD LH(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	—
5	WHEEL TYRE <i>new</i>	1	\$ 450.00	\$ 450.00	x.
6	WHEEL RIM <i>new</i>	1	\$ 850.00	\$ 850.00	400
		500	TOTAL	\$ 500.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	1000	
3	TUFF COAT	\$80.00	60	
4	TO REMOVE AND REFIX FRONT AND REAR DOOR FITTING	\$280.00	160	
5	WIRING CHECK	\$80.00	30	
6	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$350.00	200	
7	WHEEL ALIGNMENT	\$100.00	80	
TOTAL		\$3,890.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,207.76
TOTAL LABOUR COST : \$ 3,890.00
TOTAL REPAIR COST : \$ 16,097.76

APPROVED DETAILS

Admin King total: 1068651
H/s 24/04/18. H/s 8.5K
08 days.

SURVEYOR :
CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

FAX

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: