

INS. CASE OWNER:

CC 4/FWD1800 9432, K e b 3 9 / 1

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT
27/4/18

Date / Time:

27/4/18

Registered in Merimen:

27/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SK 87907

Claim No.:

1201800004996

Name of Insured:

ABDUL RAHIM BIN GOLF MOHAMMED

Policy No.:

PNPV2017-00007915

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

20/4/18

Place of Accident:

LTE NEAR MAJUMBEIN EXIT

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SK 87907

SK 9059K

SGY. 5199M



INSRS:

WSP:

Tel:

Liability:

RMKS: 61



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

27/4/18
19:44

25.4.18

08.11.18

SK 9059K - 7

SK 87907 - 7

Email WSP LIABILITY CONC.

FOR DATA TO INPUT TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CR:

After call ltr to CR:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to G:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GRA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

SS 11,400.00

(10 days) Reduction:

50 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 21-12-18

Confirm with: Yousuf

Email ☒ Call ☐

Final Liability:

SS 11,400.00

(Agreed / Assessed) BOLA S/N No. : 3

If NO or B 28, Ass. Lia : 100%

Repair Cost:

SS 11,400.00

Loss of Rental (LOR):

SS -

(10 days)

Loss of Use (LOU):

SS 1,100.00

(\$ 100 x 11 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost:

SS -

Total:

SS 12,999.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 12-12-18

Confirm with: Yousuf

Email ☒ Call ☐

Payee 1:

SS 12,999.00

Name 1:

City Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD18007432/Keb3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 23-04-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 8790Z	Veh. Inspected	SKK 5059K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/04/2018	Inspection Date	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



CITY AUTO PTE LTD

One Stop Automotive Solutions

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9896

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

FWD SINGAPORE PTE LTD

NO. 6

TEMASEK BLVD

SUNTEC CITY TOWER 4

SINGAPORE 038986

Contact : 62208751/62208751

Fax No :

Estimate : QUOT201804-000508(00)

Date : 21/04/2018

Vehicle No : SKK5059K

Make/Model : TOYOTA ESTIMA AERAS 2.4 A

Mileage (km) : 0

Chassis No : ACR500162091

Accident Date : 23/04/2018 00:00:00

Claim No : SJK8790Z

Reference : TP FWD

Policy No : MSD/VPCP/17-001497

*Not Authorized
11 Days 87
Paying After Point
10 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bumper	1.0	576.20	576.20 ✓
2	Front bumper sponge	1.0	78.80	78.80 ?
3	Front bumper reinforcement	1.0	425.90	425.90 ✓
4	Front bumper towing cover	2.0	31.60	63.20 X
5	Front bumper lower grille	1.0	242.12	242.12 ✓
6	Front bumper lower grille chrome moulding	1.0	192.70	192.70 ✓
7	Front bumper hole cover RH	1.0	75.70	75.70 ✓
8	Front bumper clip	12.0	3.89	46.68 ✓
9	Front bumper retainer	2.0	82.30	164.60 X
10	Front bumper side seal	2.0	81.70	163.40 ?
11	Front grille assy	1.0	353.20	353.20 ?
12	Front grille logo	1.0	61.20	61.20 ?
13	Front bonnet	1.0	683.40	683.40 ✓
14	Front bonnet lock	1.0	101.73	101.73 ?
15	Front bonnet lock stay	1.0	198.00	198.00 ?
16	Support top garnish	1.0	196.70	196.70 ✓
17	Support top garnish clip	5.0	4.21	21.05 ✓
18	Support top panel	1.0	322.70	322.70 ?
19	A/C condenser	1.0	1,455.20	1,455.20 ?
20	A/C suction pipe	1.0	566.40	566.40 ?
21	A/C discharge pipe	1.0	412.79	412.79 ?
22	A/C liquid pipe	1.0	711.60	711.60 ?
23	Radiator	1.0	2,009.00	2,009.00 ?
24	Radiator top garnish	1.0	102.73	102.73 ?
25	Fan cowling	1.0	246.70	246.70 ?
26	Fan motor	2.0	510.70	1,021.40 ?
27	Fan blade	2.0	177.40	354.80 ?
28	Headlamp - HID	2.0	1,981.40	3,962.80 ?
29	Rear bumper	1.0	576.20	576.20 ✓
30	Rear bumper clip	12.0	3.89	46.68 ✓
31	Rear bumper retainer	2.0	55.30	110.60 ✓
32	Rear bumper support bracket	2.0	115.20	230.40 ?
33	Rear bumper sponge	2.0	91.70	183.40 ?
34	Rear bumper reflector LH	1.0	58.70	58.70 X

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

FWD SINGAPORE PTE LTD

NO. 6
TEMASEK BLVD
SUNTEC CITY TOWER 4
SINGAPORE 038986

Contact : 62208751/62208751

Fax No. :

Estimate : QUOT201804-000508(00)

Date : 21/04/2018

Vehicle No. : SKK5059K

Make/Model : TOYOTA ESTIMA AERAS 2.4 A

Mileage (km) : 0

Chassis No. : ACR500162091

Accident Date : 23/04/2018 00:00:00

Claim No. : SJK8790Z

Reference : TP FWD

Policy No. : MSD/VPCP/17-001497

S/No	Particular	Quantity	Unit Price	Amount S\$
35	Rear bumper towing cover LH	1.0	31.70	31.70 X
36	Tailgate weatherstrip	1.0	396.10	396.10 X
37	Rear end panel	1.0	711.60	711.60 ?
38	Rear end panel top garnish	1.0	268.90	268.90 ?
39	Rear end panel lower garnish	1.0	251.60	251.60 ✓
40	Luggage compartment trim	1.0	1,090.90	1,090.90 ?
List Total :				18,767.48
25% Discount S\$				4,691.81
				14,075.67

NET ITEMS :

- 1 Coolant

List Total :

10% Discount S\$

1	Coolant	30.00	60.00	60.00 ?
List Total :				60.00
10% Discount S\$				6.00
				54.00

SPECIAL NET :

- 1 Front number plate
2 Front number plate casing
3 Reverse sensor

SPECIAL NET Total S\$:

1	Front number plate	25.00	25.00	25.00 } 45.00
2	Front number plate casing	35.00	35.00	35.00
3	Reverse sensor	350.00	350.00	350.00 200.00
SPECIAL NET Total S\$:				410.00

LABOUR :

- *To remove rear trims, upholstery and 3rd row seats
- *To change a/c parts and recharge a/c gas
- *To check wiring and lighting
- *To supply panel sealant to seal off all weld spot seam gaps
- *To spray under coating
- *To remove and install rear a/c unit
- *To install reverse sensor
- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts
- Spray painting on affected & replace parts

1.0	180.00	180.00
1.0	65.00	65.00
1.0	60.00	60.00
1.0	80.00	80.00
1.0	120.00	120.00
1.0	140.00	140.00
1.0	30.00	30.00
1.0	1,500.00	1,500.00
		12
1.0	1,300.00	1,300.00
		<hr/>
		3,475.00

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

FWD SINGAPORE PTE LTD
NO. 6
TEMASEK BLVD
SUNTEC CITY TOWER 4
SINGAPORE 038986

Contact : 62208751/62208751

Fax No. :

Estimate : QUOT201804-000508(00)

Date : 21/04/2018

Vehicle No. : SKK5059K

Make/Model : TOYOTA ESTIMA AERAS 2.4 A

Mileage (km) : 0

Chassis No. : ACR500162091

Accident Date : 23/04/2018 00:00:00

Claim No. : SJK8790Z

Reference : TP FWD

Policy No. : MSD/VPCP/17-001497

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$ 18,014.67

GST 7% S\$ 1,261.03

Amount Due S\$ 19,275.70

AAA

for CITY AUTO PTE LTD



CITY AUTO PTE LTD

One-Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Your ref: SJK8790Z

Our ref: SKK5059K

01/10/2018

WITHOUT PREJUDICE

Attn: Motor Claim Dept.

FWD SINGAPORE PTE LTD

NO. 6

TEMASEK BLVD

SUNTEC CITY TOWER 4

SINGAPORE 038986

Dear Sir/Mdm,

Accident involving SKK5059K and SJK8790Z on 2 /04/2018

We refer to the above said accident.

We enclosed here with relevant documents as stated below:-

- Repair tax invoice
- Letter of authorization
- GIA search receipt

As instructed, we are claiming the following as stated below:-

Cost of Repair	:	S\$11,877.00
Loss of use (11 Days x \$100.00)	:	S\$ 1,100.00
LTA Search Fee	:	S\$ 2.00
		<u>S\$12,979.00</u>

We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thanks & regards

Veronica Law (Claim dept.)

Tel: 6453 1235

Fax: 64537944

Email: cityauto@singnet.com.sg



CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643.
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9822 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

RE: LETTER OF AUTHORIZATION

Name of owner: TOKYO CENTURY LEASING (S) PTE LTD NRIC: 1979015356

Address: —

Name of Driver: SUHAIMI BIN MOHAMED SARIP NRIC: 519718626

Address: —

Accident on 20/04/2013 Involving SAT 5199M & SJK 8790Z AND SKK 5059K

At/along CTE TOWARDS ORCHARD BEFORE TUNNEL

In consideration of City Auto Pte Ltd, repair my/our Motor Vehicle Toyota Estima Atrias at my/our request I/We the above owner of Motor Vehicle No: SKK5059K do authorize them to demand claims, settle and received whatever amount payable by the Insurance Co or Third Party or to commence legal proceeding if necessary in my/our name for the cost or repair and the loss of use/rental, etc and to any of there appointed solicitors to act for me/us in respect of the said accident/claim and all amounts claimed or settled shall be belong to them absolutely. I/We further authorize them to give an absolute discharge on my/our behalf.

I/We hereby authorize City Auto Pte Ltd, my/our repairer to give further instruction on my/our behalf concerning the said claim and such, all future correspondence should be addressed to the said firm/co.

My/Our repairer authorize to receive on my/our behalf monies claims, correspondence and give a valid discharge voucher or any other documents in connection with this on my/our behalf and for me/us.

I/We further agree to fully co-operate and attend all court hearing that are necessary and subject to prosecution and claim maintained by City Auto Pte Ltd.

I/We further agree to undertake to indemnify them against my/our claim for the cost which arises therewith.

In the event that my/our unsuccessful claim, I/We undertake to pay the repairer for the cost of repairs to my motor vehicle.

Owner Signature: —

Name: —

Date: —



Witness Signature: —

Name: —

Date: —

CITY AUTO PTE LTD

Blk 8 Sin Ming Road
#01-60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

RELEASE

Claim Reference:	1201800004956
Surveyor's Reference:	CC4/FWD18007432/Keb3
TP Reference:	SKK 5059K

We, **CITY AUTO PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SKK 5059K** ("Vehicle") to accept the sum of **\$12,979.00**, being the amount claimed for **\$11,877.00** (repair costs), **\$1,100.00** (loss of rental-use), **\$ -** (loss of income), **\$2.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **20/04/2018** (date of accident) at / along **CTE TOWARDS ORCHARD BEFORE TUNNEL** (location) involving vehicle no/s. **SKK 5059K** and **SJK 8790Z**.

This is pursuant to the inspection conducted on **23/04/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SJK 8790Z** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 04th day of January 2018

CITY AUTO PTE LTD
CLAIMANT
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1234 Fax: 6453 7944
(Claims Section)

[Signed by the "Workshop" with Co. Stamp]
For and on behalf of the "Claimant"



KSC

[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.



CITY AUTO PTE LTD

One-Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

TAX INVOICE

FWD SINGAPORE PTE LTD

NO. 6

TEMASEK BLVD

SUNTEC CITY TOWER 4

SINGAPORE 038986

Attention: Motor Claim Department

Contact : 62208751/62208751 Fax No. :

Tax Invoice : I2018-006907

Date : 01/10/2018

Vehicle No. : SKK5059K

Make / Model : TOYOTA ESTIMA AERAS 2.4 A

Mileage (km) : 195483

Chassis No. : ACR500162091

Accident Date : 23/04/2018

Claim No. : SJK8790Z

Reference : JO201804-0575

Policy No. : MSD/VPCP/17-001497

S/No. Particular	Amount
	S\$
* Lumpsum repair	11,100.00

Total S\$:	11,100.00
GST @ 7% S\$:	777.00
Grand Total S\$:	11,877.00

CASH / NETS / CREDIT CARD PAYMENT ONLY

Customer's Signature/Co. Stamp

for CITY AUTO PTE LTD

Please note all works performed by City Auto Pte Ltd as performed in this invoice is subjected to the following Warranty conditions:

- 1) Any replacement of electrical components will carry 1 month warranty period from date of this invoice.
- 2) Any replacement of mechanical components will carry 3 months warranty period.

Please note that all warranty does not cover wear and tear conditions regardless of any components.

City Auto Pte Ltd reserves the right to determine any warranty conditions.

Thank You For Your Business !

Third Party Insurer Enquiry

Our Ref No: GR-18-060681

Date of Request: 23/04/2018

Your Ref No: Online Purchase

City Auto Pte Ltd
160 Sin Ming Drive #05-01,
Sin Ming AutoCity,
Singapore 575722

Dear Sir/Madam,

Enquiry Date 23/04/2018

Enquiry By Jason Quak Leng Hui

TP Vehicle No. SJK8790Z

Accident Date 20/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJK8790Z	FWD Singapore Pte. Ltd.	14/12/2017-13/12/2018	6727 5700

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-060681

Date of Request: 23/04/2018

Your Ref No: Online Purchase

City Auto Pte Ltd
160 Sin Ming Drive #05-01,
Sin Ming AutoCity,
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 23/04/2018

Enquiry By: Jason Quak Leng Hui

TP Vehicle No: SJK8790Z

Accident Date: 20/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018 Edit Reg		23 Apr 2018 00:00 Edit Adj Rpt	S\$11,100.00 Edit Estimates	S\$11,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Abdul Jalil Bin Sidik Mohamed Rasheed, ID: S0073387C								
Main Claimant:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G								
Vehicle Reg. No.:	SKK5059K	Date of Loss:	20/04/2018 06:00 - :59 [56 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800004956	Policy/Cover Note No.:	PNPV2017-00007915 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJK8790Z	Policy No. (Claimant):	MSD/VPCP/17-001497						
		Excess:							
Repairer:	City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est, 575643 Sin Ming - Tel: 64531235								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (26/12/2018): Alert - Adj Mandate Approved (S\$12979.00) - SKK5059K - Claim Handler: Lionel Tan FWD_SG (26/12/2018): Alert - Adj Mandate Approved (S\$12979.00) - SKK5059K - Claim Handler: Lionel Tan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK5059K (1201800004956)

[SJK8790Z]































TP

TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

Apr 20 2018 6:00AM

[Abdul Jalil Bin Sidik Mohamed Rasheed]

City Auto Pte Ltd (Sin Ming)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/04/18 14:06	Adjuster Immediate Advice	 Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/12/18 17:16	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
26	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/12/18 17:16	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 15:17	EMAIL FROM FWD DD 23042018	 Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	24/04/18 09:29	TP GIA REPORT		Load PDF	
3	24/04/18 09:30	FWD EMAIL TO INSURED DD 23042018		Load PDF	
4	24/04/18 18:30	TP ESTIMATE- MARKED		Load PDF	
5	10/12/18 11:14	WORKSHOP INVOICE		Load PDF	
6	10/12/18 11:14	LOD		Load PDF	
7	08/01/19 09:05	Release Voucher		Load PDF	
8	08/01/19 09:05	AUTHORISATION TO ACT FORM		Load PDF	
9	08/01/19 09:05	GIA SEARCH		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	23/04/18 19:07	OI GIA Report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJK8790Z (Insd veh)	Model:	TOYOTA ESTIMA 2.4 AERAS
	SKK5059K (TP veh)		- ACR50 (A)
Date of Accident:	20/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		19,275.63
Final Repair Cost	:	\$		11,877.00
Loss of Use	:	\$		1,100.00
				11.00 days at \$100.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		12,979.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	City Auto Pte Ltd	:	\$ 12,979.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

08 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18007432/KEB3Q2

Date: 08/01/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007915
Claimant Vehicle No : SKK5059K **Insured Vehicle No :** SJK8790Z
 Date of Loss: 20/04/2018 Nature of Claim: TP Claim No: 1201800004956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK5059K**
 Make & Model: TOYOTA ESTIMA, 2.4 AERAS - ACR50 (A) Engine No: 2AZH985284
 Reg. Date: 25/07/2013 (Man. Year: 2013) Chassis No: ACR500162091
 Colour: Metallic Pearl White Odometer: 195483 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Falken 7 mm Rear Left Side: Falken 5 mm
 Front Right Side: Falken 7 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,539.61	11,313.02	3,226.59	22.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,475.00	2,595.00	880.00	25.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,014.61	13,908.02	4,106.59	22.80
Approved Total (Overridden) (S\$)		11,100.00		
(S\$)	18,014.61	11,100.00	6,914.61	38.38
+ GST 7.00/7.00% (S\$)	1,261.02	777.00	484.02	38.38
Nett Amount (S\$)	19,275.63	11,877.00	7,398.63	38.38
+ Loss of Use (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,979.00		

INSPECTION

Date of Assignment: 23/04/2018
 Date Inspected: 23/04/2018 Inspected At: City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin

Ming Est
Singapore 575643

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS - ACR50 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK5059K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Buckled	576.20 FL	*576.20 FL
2	1	*FRONT BUMPER SPONGE	Cracked	78.80 FL	*78.80 FL
3	1	*FRONT BUMPER REINFORCEMENT	Bent	425.90 FL	*425.90 FL
4	2	*FRONT BUMPER TOWING COVER	Serviceable	63.20 FL	*- FL
5	1	*FRONT BUMPER LOWER GRILLE	Distorted	242.12 FL	*242.12 FL
6	1	*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Cracked	192.70 FL	*192.70 FL
7	1	*FRONT BUMPER HOLE COVER RH	Distorted	75.70 FL	*75.70 FL
8	12	*FRONT BUMPER CLIP	Necessary	46.68 FL	*46.68 FL
9	2	*FRONT BUMPER RETAINER	Serviceable	164.60 FL	*- FL
10	2	*FRONT BUMPER SIDE SEAL	Serviceable	163.40 FL	*- FL
11	1	*FRONT GRILLE ASSY	Cracked	353.20 FL	*353.20 FL
12	1	*FRONT GRILLE LOGO	Necessary	61.20 FL	*61.20 FL
13	1	*FRONT BONNET	Bent	683.40 FL	*683.40 FL
14	1	*FRONT BONNET LOCK	Distorted	101.73 FL	*101.73 FL
15	1	*FRONT BONNET LOCK STAY	Bent	198.00 FL	*198.00 FL
16	1	*SUPPORT TOP GARNISH	Dented	196.70 FL	*196.70 FL
17	5	*SUPPORT TOP GARNISH CLIP	Necessary	21.05 FL	*21.05 FL
18	1	*SUPPORT TOP PANEL	Buckled	322.70 FL	*322.70 FL
19	1	*A/C CONDENSER	Punctured	1,455.20 FL	*1,455.20 FL
20	1	*A/C SUCTION PIPE	Serviceable	566.40 FL	*- FL
21	1	*A/C DISCHARGE PIPE	Serviceable	412.79 FL	*- FL
22	1	*A/C LIQUID PIPE	Serviceable	711.60 FL	*- FL
23	1	*RADIATOR	Punctured	2,009.00 FL	*2,009.00 FL
24	1	*RADIATOR TOP GARNISH	Cracked	102.73 FL	*102.73 FL
25	1	*FAN COWLING	Cracked	246.70 FL	*246.70 FL
26	2	*FAN MOTOR	Jammed	1,021.40 FL	*1,021.40 FL
27	2	*FAN BLADE	Jammed	354.80 FL	*354.80 FL
28	2	*HEADLAMP -HID	Mtg Cracked	3,962.80 FL	*3,962.80 FL
29	1	*REAR BUMPER	Bent	576.20 FL	*576.20 FL
30	12	*REAR BUMPER CLIP	Necessary	46.68 FL	*46.68 FL
31	1	*REAR BUMPER RETAINER	N/S Distorted	110.60 FL	*55.30 FL
32	2	*REAR BUMPER SUPPORT BRACKET	Repair	230.40 FL	*- FL
33	1	*REAR BUMPER SPONGE	N/S Cracked	183.40 FL	*91.70 FL
34	1	*REAR BUMPER REFLECTOR LH	Serviceable	58.70 FL	*- FL
35	1	*REAR BUMPER TOWING COVER LH	Serviceable	31.70 FL	*- FL
36	1	*TAILGATE WEATHERSTRIP	Serviceable	396.10 FL	*- FL
37	1	*REAR END PANEL	Buckled	711.60 FL	*711.60 FL
38	1	*REAR END PANEL TOP GARNISH	Buckled	268.90 FL	*268.90 FL
39	1	*REAR END PANEL LOWER GARNISH	Buckled	251.60 FL	*251.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LUGGAGE COMPARTMENT TRIM	Serviceable	1,090.90 FL	*- FL
41	2		*COOLANT	Necessary	54.00 FS	*20.00 FS
42	1		*FRONT NUMBER PLATE)	Dented	25.00 FS	*45.00 FS
43	1		*FRONT NUMBER PLATE CASING)	Dented	35.00 FS	*- FS
44	1		*REVERSE SENSOR	Dented	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 19,231.48 14,995.69
 - List Item Discount on L Items 25.00/25.00% (S\$) 4,691.87 3,682.67

Total Parts (S\$) 14,539.61 11,313.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REAT TRIMS ,UPHOLSTERY AND 3RD ROW SEATS	New	180.00	80.00
2	TO CHARGE A/C PARTS AND RECHARGE A/C GAS	New	65.00	65.00
3	TO CHECK WIRING AND LIGHTING	New	60.00	40.00
4	TO SUPPLY PANEL SEALANT TO SEAL OFF ALL WELD SPOT SEAM GAPS	New	80.00	60.00
5	TO SPRAY UNDER COATING	New	120.00	120.00
6	TO REMOVE AND INSTALL REAR A/C UNIT	New	140.00	0.00
7	TO INSTALL REVERSE SENSOR	New	30.00	30.00
8	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	1,500.00	1,000.00
9	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,300.00	1,200.00
Gross Labour Cost (S\$)			3,475.00	2,595.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >