

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
 160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
 TEL: 6475 2112 FAX: 6475 4666
 WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: **LEE YONG CHONG JASON**
 BLK 448 BRIGHT HILL DRIVE
 #10-143
 S(570448)
 H/P: 92293068

LKK Auto Consultants hereby certify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • To provide subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

NO: **WQT0800847**
 DATE: 05 Apr 2018
 A/C CODE: C006814
 TERMS: COD
 YOUR REF: SDF2286A
 VEH REG NO: SDF2286A
 MAKE/MODEL: TOYOTA COROLLA
 AXIO 1.5X A
 SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 21/03/2018 ACCIDENT INVOLVING: SDF2286A & SHB9697A CLAIM TYPE: 3RD PARTY CLAIM AGAINST SHB9697A (INSURED WITH TRANS CAB) <i>AXA Ins</i>				
1 FRONTBUMPER <i>/ ee - photo.</i>	1 PC	499.50		499.50
2 FRONT BUMPER REINFORCEMENT	1 PC	363.40		363.40
3 FRONT BUMPER SPONGE	1 PC	78.90		78.90
4 FRONT BUMPER SIDE RETAINER LH <i>- nec.</i>	1 PC	53.50		53.50
5 FRONT GRILLE WITH EMBLEM <i>- C/A</i>	1 PC	409.30		409.30
6 FRONT BUMPER CLIPS <i>/ nec.</i>	10 PCS	3.50		35.00
7 FRONT NUMBER PLATE WITH HOLDER (NETT ITEM) <i>/ scr</i>	1 PC	45.00		45.00
8 TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	1 SVC	500.00	<i>200</i>	500.00
9 TO SPRAY PAINT ON REPAIRED AREA.	1 SVC	750.00	<i>400</i>	750.00
10 TO FOCUS HEADLAMP	1 SVC	30.00	<i>?</i>	30.00
Total				S\$ 2,764.60
Add GST @ 7%				193.52
Grand Total				S\$ 2,958.12

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED FIFTY EIGHT AND CENTS TWELVE ONLY

LEE YONG CHONG JASON

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

*3 Days.
 Imp Sum Repair.
 After repair photos.
 Que Qiang @ lkk Auto. com
 Que Qiang - 8288 0282
 03/5/18.*

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 19810Z182M
BLK 20 SIN MING INDUSTRIAL ESTATE #01-30 SINGAPORE 575678
TEL: 6475 2112 FAX: 6475 4666
EMAIL: <http://www.ricardo.com.sg>

**QUOTATION****M/S : TAN YANZAI**

BLK 570 HOUGANG STREET 51
#13-103
SINGAPORE 530570

NO: WQT0800735
DATE: 29 Dec 2016
A/C CODE: C010179
YOUR REF: SKU7459Z
VEH REG NO: SKU7459Z
MAKE/MODEL: VOLKSWAGEN NEW
GOLF 1.4 TSI AT
5K14Q5

H/P: 97709731**SALESMAN:**

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$

WE SUBMIT HERewith OUR SUPPLEMENTARY ITEM TO ABOVE MENTIONED VEHICLE.

DOA: 23/12/2016 @0820 HRS

ACCIDENT INVOLVING: SKU7459Z & FBB9586H

CLAIM TYPE: 3RD PARTY CLAIM AGAINST FBB9586H (FBB9586H INSURED WITH AXA INS)

1	FRONT DOOR GLASS SOLAR FILM RH (NETT ITEM) ✓ NEC	1 PC	80.00	80.00
2	REAR DOOR GLASS SOLAR FILM RH (NETT ITEM) ✓ NEC	1 PC	80.00	80.00
Total				S\$ 160.00
Add GST @ 7%				11.20
Grand Total				S\$ 171.20

TOTAL: SINGAPORE DOLLAR ONE HUNDRED SEVENTY ONE AND CENTS TWENTY ONLY

TAN YANZAI**For RICARDO AUTO CENTRE PTE LTD**

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

RESURVEY
PAUL CHAN
from LTR
30/12/2016 @ 1440HRS
