RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M

160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722

LKK Auto Consultants hen Creek TATTON

TEL: 6475 2112 FAX: 6475 4666 WEBSITE: http://www.ricardo.com.sg



M/S	BLK 448 BRIO #10-143 S(570448)	Hose pairs of the following: To resurvely before/after spray painting To display damaged part(s) during resurvey HF HH frictor Vicect to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	NO: WQT0800847 DATE: 05 Apr 2018 A/C CODE: C006814 TERMS: COD YOUR REF: SDF2286A VEH REG NO: SDF2286A MAKE/MODEL: TOYOTA COROLLA			
H/P:	92293068	Acknowledged by Repairer Signature: Date:	MAKE/MO SALESMAI	AXIO 1.		
	Description		Quantity	Unit Price	%	PAGE:1
	Description		Quantity	S\$	70	S\$
	DOA: 21/03/2018 ACCIDENT INVO CLAIM TYPE: 3R	REWITH OUR ESTIMATED COST OF REP DLVING: SDF2286A & SHB9697A D PARTY CLAIM AGAINST SHB9697A (1		AXA Inc	VEHICL	С.
1	FRONTBUMPER	X X / Photo Repair	1 PC	499.50		499.50
2	FRONT BUMPER	REINFORCEMENT X SVC	1 PC	363.40		363.40
	FRONT BUMPER		1 PC	78.90		78.90
4	FRONT BUMPER	SIDE RETAINER LH / MC.	1 PC	53.50		53.50
5	FRONT GRILLE	WITH EMBLEM / CLA	1 PC	409.30		409.30
6	FRONT BUMPER	CLIPS / NEC.	10 PCS	3.50		35.00
7	FRONT NUMBER	SUR 1 PC	45.00		45.00	
8	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.			500.00	200	> 500.00
9	TO SPRAY PAIN	Γ ON REPAIRED AREA.	1 SVC	750.00	400	750.00
10	TO FOCUS HEAD	DLAMP X nn	1 SVC	30.00	7	30.00
				Total	S\$ 2	2,764.60
			Ad	d GST @ 7%		193.52

LEE YONG CHONG JASON

CONFIRMED & ACCEPTED BY

3 Days.

Lipsim lepan. For RICARDO AUTO CENTRE PTE LTD

After nepar photos.

Authorised Signature

Guo Qiang - 8288 0282

03/5/18.